

ASS. REC. BY:

REF:

CS3/FCI19013208/Hcf3^{SV}

and Instruction:

Surveyor: Hui Ann

ASSIGNMENT (Office)

CWS

From (Person): Karen Tam

of

FCI

Date/Time: 11:59am @ 26/7/19

Estimated Cost:

Bill to:

OD / LT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 8861G

Insured:

SHD 3446L

at Workshop m/s

My Car Consultant

Tel:

88668832

of

53 ubi Ave 1 # 01-25

Policy No:

Claim No:

D19004808MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:15pm @ 26/7/19

Person Contacted:

Hui Qin

Vehicle IN OUT

Date/Time

Action/Instruction

Estimated (X)

SLT 8861G X

SHD 3446L CC3/AIG16005840/H1ha392-1 DOA = 29/3/16

19/8/19 @ 4:20pm Hui Qin will check & arrange.

Dismantle: 28/8/2019

After repair: 29/8/2019

PRS

10951

MOTOR SURVEY ASSIGNMENT

Date	23-07-2019	Our Ref No. D19004808MFSH
Accident Date	19-07-2019	Claim Type. Third Party
Insured Vehicle	SHD3446L	Third Party Vehicle. SLT8861G
Survey Location	53 Ubi Ave 1 #01-25 Paya Ubi Industrial Park	
Contact Person.	HUIQIN	
Contact No.	88668832/ 88668832	Fax No. 69255219
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MY CAR CONSULTANT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2019 14:36
Date Of Accident	✓ 19/07/2019 21:30
Exact Location Of Accident	ORCHARD TURN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT8861G
Insured/Policyholder	
Name Of Registered Owner	AMOS TAY
NRIC No	S7902015Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90888925
Alternative Phone No	OFFICE-90888925

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 XT CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00433377/01
Cover Note Number	

Driver

Name of Driver	ESTEE LIM SWEE CHIN
NRIC No	S8000758B
Date Of Birth	14/01/1980
Occupation	INDOOR
Date Of Driving Pass	25/04/2003
Driving Experience	16 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97474449
Fax Number	
Contact Number	
Email Address	ESTEETAY@GMAIL.COM

Address	BLK 23 PUNGGOL FIELD WALK #16-20
Postcode	828750
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LOH PECK JIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3446L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Orchard Turn Road, suddenly, Vehicle B came out from Ngee Ann City carpark and hit onto my vehicle A - front right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Officer's Signature
(If driver is not the policyholder)
Date & Time: 20/7/2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	015Z
Vehicle Details	
Vehicle No.:	SLT8861G
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	FA20CB40457
Chassis No.:	JF1SJGK85JG101341
Maximum Power Output:	177.0 kW (237 bhp)
Open Market Value:	\$16,320.00
Original Registration Date:	13 Dec 2017
First Registration Date:	13 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$16,320.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2027
PARF Rebate Amount:	\$12,240.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$47,551.00
Total Rebate Amount:	\$59,791.00

The information contained herein is correct as at 30 Aug 2019

OK

Balance = 8 year 5 months

Depreciation = 10000 -

$10000 \div 12 = 833 \text{ month}$

$8000 + 4165 + 8160$

$= 92325$

MV - 92000

PV - 59791

NV - 32200

MV - 91-92

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLT8861G
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme:	Normal
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0XT CVT AWD SR
Chassis No.:	JF15JGK85JG101341
Propellant:	Petrol
Engine No.:	FA20CB40457
Engine Capacity:	1998 cc
Maximum Power Output:	177.0 kW (237 bhp)
Maximum Laden Weight:	2110 kg
Unladen Weight:	1682 kg
Year Of Manufacture:	2017
Original Registration Date:	13 Dec 2017
Lifespan Expiry Date:	-
COE Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium:	\$57,414.00
COE Expiry Date:	12 Dec 2027
Road Tax Expiry Date:	12 Dec 2019
PARF Eligibility Expiry Date:	12 Dec 2027
Inspection Due Date:	12 Dec 2020
Intended Transfer Date:	30 Aug 2019
CO2 Emission:	197.00 (g/km)
CEV/VES Rebate Utilised	-
Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Extensive selection of new & used cars | Genuine mileage | No chassis or structural damage | STA evaluation welcomed

SGCARMART CARNIVAL
31 AUG - 1 SEP 2019
@ DOWNTOWN EAST

SG 54 PRE-OWNED DEALS

- 1 Year Warranty
- 2 Years Paint Protection
- Low Downpayment & Interest Rates

Subaru Forester

Price Range ▼

Depreciation ▼

2017 ▼

Vehicle Type ▼



Advanced Search

Home » Used Cars » AA Trust Automotive » Subaru Forester 2.0XT Sunroof

Subaru Forester 2.0XT Sunroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$98,800

Depreciation ⓘ \$11,100 /yr
View models with similar depreReg Date 26-Oct-2017
(8yrs 1mth 25days COE left)

Mileage 54,000 km (29.3k /yr)

Manufactured ⓘ 2017

Road Tax ⓘ \$1,210 /yr

Transmission Auto

Dereg Value ⓘ \$51,598 as of today (change)

OMV ⓘ \$16,462

COE ⓘ \$48,109

ARF ⓘ \$16,462

Engine Cap 1,998 cc

Power 177.0 kW (237 bhp)

Curb Weight ⓘ 1,682 kg

No. of Owners ⓘ 1

Type of Vehicle SUV

Features

Powerful 2.0L Turbocharged Engine Producing 237HP, Responsive Linear Tronic CVT Auto Gearbox, AWD, ABS, Airbags, Keyless Entry/Start, Auto Headlights. View specs of the Subaru Forester (2013-2019)

Accessories

Panoramic Sunroof, Dual Electric Seats, Built In Reverse Camera, 18" Sports Rims, Electric Tailgate, Keyless Entry.

Description

AA Trust Certified Quality Pre-Owned Vehicle! With 5 Years Warranty And 3 More Servicing Package With Subaru (Motor Image)! Battery And Aircon Condenser Just Change As It Is Provided In The Package! 1 Owner Fully Utilize This Free Service Given To Make Sure His Forester Is In Tip Top Condition! Flexible Bank And In House Loan Available! Trade In Most Welcome! Call Now To Book An Appointment!

Category

PARF Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on

Updated on: 29-Aug-2019

Compare



Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

AA Trust Automotive



• dealer's pricelist

• 80 vehs sold | 103 vehs available

★ PREMIUM DEALER 2019 ★

Address

73 Mackenzie Road Lot 03/04/07/08

Search cars nearby this location

Location

Mackenzie Used Car Centre

Office No

63450381

Contact Person(s)

Dave	98500051
Clement	93365036
Wiley	91692071
Andra	92221331

Extensive selection of new & used cars | Genuine mileage | No chassis or structural damage | STA evaluation welcomed

31 AUG - 1 SEP 2019
@ DOWNTOWN EAST

SG 54 PRE-OWNED DEALS

- 1 Year Warranty
- 2 Years Paint Protection
- Low Downpayment & Interest Rates

Subaru Forester

Price Range ▾

Depreciation ▾

2018 ▾

Vehicle Type ▾

Advanced Search

Home » Used Cars » Autotrust Traders Pte Ltd » Subaru Forester 2.0i-L Sunroof

Subaru Forester 2.0i-L Sunroof

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Price \$94,800

Depreciation \$9,450 /yr
View models with similar depreReg Date 20-Dec-2018
(9yrs 3mths 19days COE left)

Mileage 14,000 km

Manufactured 2018

Road Tax \$1,208 /yr

Transmission Auto

Dereg Value \$39,164 as of today (change)

OMV \$13,602

COE \$31,101

ARF \$13,602

Engine Cap 1,995 cc

Power 110.0 kW (147 bhp)

Curb Weight 1,591 kg

No. of Owners 1

Type of Vehicle SUV

Features

Responsive 2.0L FB20 Boxer Engine, Linear CVT Transmission With Paddle Shifter, SI-Drive, AWD With X-Mode Intelligence System, Cruise Control, Airbags View specs of the Subaru Forester (2013-2019)

Accessories

Panoramic Sunroof, Keyless Entry/Start-Stop, Reverse Camera/Sensors, Auto Headlights And Wipers, Multi-Functions Steering, Dual Zone Climatic A/C.

Description

Lowest Interest Rates At 2.28% Only! Full Loan Available! Very Low Mileage! Full Agent Service With On Going Warranty With Motor Image! Call Us Now For A Non-Obligation Viewing!

Category

PARF Car, Almost New Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 16-Aug-2019 | Last Updated on: 29-Aug-2019


Up Compare

» more Financial info



Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Autotrust Traders Pte Ltd



» dealer's pricelist

» 82 vehs sold | 30 vehs available

★ PREMIUM DEALER 2019 ★

MOTOR CAR (UC)

Undercarriage

Vehicle No: SLT 8861 7

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1407	993719	Rear LH Shock Absorber			
1408	993723	Rear LH Shock Absorber Mounting			
1409	993170	Rear LH Coil Spring			
1410	993550	Rear LH Knuckle Arm			
1411	993551	Rear LH Knuckle Arm Bearing			
1412	993597	Rear LH Lower Arm			
1413	993884	Rear LH Upper Arm			
1414	995161	Rear LH Drive Shaft			
1415	995216	Rear LH Control Arm			
1416	993881	Rear LH Trailing Arm			
1417	993573	Rear LH Leaf Spring			
1418	992941	Rear LH Brake Disc Rotor			
1419	992937	Rear LH Brake Caliper Assy			
1420	990434	Rear LH Brake Pipe			
1421	992946	Rear LH Brake Hose			
1422	993819	Rear Sub Frame			
1423	993820	Rear Sub Frame Mounting			
1424	992813	Rear Anti Roll Bar			
1425	990168	Rear Anti Roll Bar Linkage			
1426	990202	Axle Beam			
1427	990170	Rear Axle Panhard Rod			
1428	990810	Differential Assy			
1429	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			
		wheel alignment			

No of Items: _____

Assessor: _____

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI19013208/Hcf3s2

Date: 13-09-2019



Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHD 3446L	Veh. Inspected	SLT 8861G
Policy No.		Coverage (\$)	0.00
Claim No.	D19004808MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	26/07/2019

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER 2.0XT AT	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1SJGK85JG101341	Colour	SILVER
Odometer	032392 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	5 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	5 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	5 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.	
---	--

5. General Information

Accident Date	19/07/2019	Inspect Date / Time	27/08/2019 (02:43 PM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$92,000.00
--

Report Ref No. CS3/FCI19013208/Hcf3s2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.