

ASS. REC. BY:

REF:

CS/ICS19013012/64 d3⁵²

Special Instructions:

Surveyor: na

ASSIGNMENT (Office)

From (Person): Crystabelle Tan

of

ICSDate/Time: 26/7/19 @ 10:51am

Estimated Cost:

Bill to:

OD ① WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL5142K

Insured:

SLS 754M

at Workshop m/s

Tan Chong Motor

Tel:

67038916

of

913 Bukit Timah Road

Policy No:

Claim No:

DMPC1900179H/02/CT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:44am @ 26/7/19

Person Contacted:

zuhriVehicle IN ① OUT

Date/Time

Action/Instruction

Estimate ✓SLL 5142K xSLS 754M x14/8/19 @ 2:56pm revised to Crystabelle Tan via Merimen.

ICS

TOTAL

The **U/C / Chassis frame / Body Structure** affected due to collision.

L#S. CASE OWNER:

CC 4 / 1CS 190 13212 /

ha3

LKK:
IDAC:**ASSIGNMENT**

Surveyor:

DOI:

Date / Time:

26/07/2019

Registered in Merinien:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLJ 754 M

Claim No.:

DMP C1900179H 10/10/19

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

9/7/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLL 5142K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Zan Chong.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SLL 5142K - X ; SLJ 754M - X	Non-Reporting ltr (1st):	
	Downstairs case	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA:	<input type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
		LOD	<input type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days)	Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:		If NO or B 28, Ass. Lia:
Repair Cost:	S\$			
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	S\$			
Medical:	S\$			
Disbursement:	S\$	(e.g. Tow/ Independent)		
Legal Cost	S\$			
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

Nivitha (LKK Auto)

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle_Tan@ecics.com.sg>
Sent: Friday, 26 July 2019 10:51 AM
To: Muhammad Zuhri; 'assignments'
Cc: ECICS Claims
Subject: RE: ACCIDENT INVOLVING SLL5142K & SLJ754M ON 09.07.2019
INS/IC/ZHR/0370/2019 DIRECT SETTLEMENT - Ref : DMPC1900179H/02/CT
Attachments: SLL5142K_SAS.PDF; est.pdf

11:44am @ 26/7/19
VNI
person @ zuhri

Dear Zuhri

We are agreeable to have direct settlement.

Rental \$100/day Or Loss of use \$60/day.

Aside to LKK – Please arrange survey.

Best regards

Crystabelle Tan

Senior Associate | Claims



DID (65) 6303 0190

Tel (65) 6337 4779

Email crystabelle_tan@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunus Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Muhammad Zuhri [mailto:zuhri@tanchong.com]

Sent: Thursday, 25 July, 2019 3:13 PM

To: ECICS Claims

Subject: ACCIDENT INVOLVING SLL5142K & SLJ754M ON 09.07.2019 INS/IC/ZHR/0370/2019 DIRECT SETTLEMENT

Dear Office In Charge,

Our customer, KOI WEI TER (CAI WEIDE) the owner of SLL5142K is insured with AIG Insurance at the material time of the accident. The 3rd party SLJ754M is insured with you at the material time of the accident.

Our customer holds your insured driver liable for the accident and would like to claim against your insured driver. On behalf of our customer, we hereby enquire whether you would like to have a Direct Settlement with our customer.

Our customer's claiming for Cost Of Repair and Loss Of Rental \$110.00 / Use \$70.00..GIA Report / Estimate attached for your action.

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLJ754M		
TP Vehicle No	: SLL5142K	Accident Date	: 09/07/2019
Make	: NISSAN QASHQAI	Assignment Date	: 26/07/2019
Date of Inspection	: 08/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: TAN CHONG MOTOR SALES PTE LTD (BUKIT TIMAH) 911, BUKIT TIMAH ROAD SINGAPORE 589622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,598.88
Revised Amount	:S\$	1,740.52
Check Items (Estimated)	:S\$	1,867.28
Total	:S\$	3,607.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

S/C
DS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 09/07/2019 11:46
Date Of Accident 09/07/2019 10:15
Exact Location Of Accident PIE TWDS JURONG
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL5142K

Insured/Policyholder

Name Of Registered Owner KOI WEI TER (CAI WEIDE)
NRIC No S8002495I
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97321462
Alternative Phone No OFFICE-97107778

Vehicle Particulars

Manufacturer NISSAN
Model QASHQAI-1.2 DIG-T (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 2100502668-02
Cover Note Number

Driver

Name of Driver KOI WEI TER (CAI WEIDE)
NRIC No S8002495I
Date Of Birth 27/01/1980
Occupation INDOOR
Date Of Driving Pass 06/06/2002
Driving Experience 17 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-97321462
Fax Number
Contact Number OFFICE-97107778
Email Address NOEMAIL

Address	966 DUNEARN RD #07-03
Postcode	589488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ754M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE MING DA SHAUN
NRIC/Passport Number	
Contact Number	91504254
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

Vehicle No: SLL5142 K

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

1105 HRS
9 JULY 2019
GIARMC SketchPlanForm_V3




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: SLL 5142K

Accident Location: ALONG PIE TOWARDS JURONG, AFTER RKE ENTRANCE, BEFORE DUNEARN RD EXIT

Accident Date: 9 JULY 2019

Time: 1015 (am) pm

- Brief Details Of Accident -

I was travelling along PIE on the most right lane. There was a maintenance truck ^(STATIONARY) on the right lane, traffic already slowed down. I signal left to change lane, slowly cutting in as traffic on my left passed me. One Volkswagen black vehicle SLJ 754M hit my rear, while I was changing lane.

- Other Vehicle Involve Details -

(B) Veh No: SLJ 754M Hp: 91504254 Pax: Driver Name: LEE MING DA, SHAUN

(C) Veh No: Hp: Pax: Driver Name:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

9 JULY 2019

1120 HR

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	495I
Vehicle No.:	SLL5142K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	HRA2327066A
Chassis No.:	SJNFEAJ11U1757251
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	28 Feb 2017
First Registration Date:	28 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2027
PARF Rebate Amount:	\$10,293.00
COE Expiry Date:	27 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$37,293.00
Total Rebate Amount:	\$47,586.00

The information contained herein is correct as at 12 Aug 2019

OK



CERTIFICATE OF INSURANCE

NISSAN AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Koi Wei Ter (Cai Weide)
 Period of Insurance : 28 Feb 2019 To 27 Feb 2020
 Engine No. : HRA2327066A
 Chassis No. : SJNFEAJ11U1757251

Vehicle No. : SLL5142K
 Policy No. : 2100502668-02
 Endorsement No. :
 Issued Date : 15 Jan 2019

ABOUT THE COVER

Make/Model : NISSAN QASHQAI 1.2 DIG-TURBO
 Engine Capacity/Tonnage : 1,197.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Koi Wei Ter (Cai Weide) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. TC AutoClinic Add: No 1, Sixth Lok Yang Road Singapore 628099 62622212
 2. Autolion Industrial Add: 19 Ubi Road 4 Singapore 408623 64909666
 3. TC AutoClinic Add: 25 Leng Kee Road Singapore 159097 67038511 67038512 67038513
 4. Tan Chong Motor Sales Add: 813 Bukit Timah Road Singapore 589823 64694091 64694092 64694093
 5. Tan Chong Motor Sales Add: 17 Lorong 8 Toa Payoh Singapore 319254 83570753 63570754

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500610516

TAN CHONG CREDIT PTE LTD
 911 BUKIT TIMAH ROAD TAN CHONG MOTOR CENTRE
 SINGAPORE 589622 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE
 AIGSGMOBILEAPP

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0370/2019
DATE : 25-JUL-2019

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 63374779
FAX : 63389267
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR KOI WEI TER (CAI WEIDE)
ADDRESS : 966 DUNEARN ROAD
#07-03
S(589488)
TELEPHONE NO : 97321462

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

25.07.2019

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP - SLJ754M
VEHICLE NO : SLL5142K
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2327066A
CHASSIS NO : SJNFEAJ11U1757251
MILEAGE : 1 KM
DATE IN : 25/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 09/07/2019

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL5142K

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	✓
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X NN
4 22/001	CHECK LIGHTING	48.00	✓ 780
5 22/002	REPAIR REAR TAILGATE & REAR END PANEL RENEW RR BUMPER	1170.00	⁷⁸⁰ 390 (+390) 8 ✓
6 22/003	S/PAINT RR BUMPER (2 TONE), RR END PANEL & TAILGATE RR FENDER RH & LH SIDE	1350.00	250 500 625
TOTAL LABOUR CHARGES		2898.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL5142K

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SUNDRIES / <i>mc</i>	NPN		20 / 40.00
2	ORNAMENT-BACK D X	90892-4EA0A	87.00 X	
3	EMBLEM-REAR X <i>nn</i>	90890-4EA0A	59.70 X	
4	BRACKET-BUMPER LH X	85221-4EA0A	35.90 X	
5	BRACKET-BUMPER RH / <i>el</i>	85220-4EA0A	35.90 ✓	
6	STAY ASSY-RH X <i>nn</i>	H5210-4EAMA	126.00 X	
7	REINF-BUMPER RR X	H5030-4EAMA	619.20 X	
8	ENERGY ABSORBER X	85090-4EA0A	126.40 X	
9	FINISHER-REAR B /	85071-4EA0A	16.80 /	
10	CLIP(7.4X3) / <i>mc.</i>	85284-JD00A	22.20 /	
11	GROMMET(2.5X2) /	63846-5V000	5.00 /	
12	FASCIA-RR BUMP / <i>Cut</i>	85022-4EA0H	717.00 /	
13	REVERSE SENSOR(J11) / <i>DM</i>	SENSOR-TE5140		250 / 180.00
SUB TOTAL			1851.10	0.00 220.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			370.22	0.00 0.00
GRAND TOTAL			1480.88	0.00 220.00
OVERALL TOTAL			1700.88	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

796.9 270

-20%: 677.52

2590.52

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL5142K

TOTAL LABOUR CHARGES	2898.00
TOTAL SPARE PARTS CHARGES	1700.88
GRAND TOTAL	4598.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:
SURVEYED DATE	:
AUTHORIZED DATE	:
EXCESS CLAUSE	:
LIABILITY	:
REMARKS	:

Guo Qiao . - 82880282
08/8/19.

4 Days .

before paint photos.

4668.78

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4594091
REFERENCE : INS/IC/ZHR/0370/2019
DATE : 25-JUL-2019

DS \Rightarrow Gus Qiong

ECICS LIMITED
7 TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
S(038987)
TEL : 63374779
FAX : 63389267
ATTN:MOTOR CLAIM MANAGER

ZHR

OWNER'S NAME : MR KOI WEI TER (CAI WEIDE)
ADDRESS : 966 DUNEARN ROAD
#07-03
S(589488)
TELEPHONE NO : 97321462

Recommend Repair

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP - SLJ754M
VEHICLE NO : SLL5142K
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2327066A
CHASSIS NO : SJNFEAJ11U1757251
MILEAGE : 1 KM
DATE IN : 25/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 09/07/2019

4 Payer

LOR \Rightarrow \$90 x 4 Payer

\Rightarrow \$385.20

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL5142K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	110.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	ZZ/001	CHECK LIGHTING	48.00	48.00
5	ZZ/002	REPAIR REAR TAILGATE & REAR END PANEL RENEW RR BUMPER	1170.00	780.00
6	ZZ/003	S/PAINT RR BUMPER (2 TONE), RR END PANEL & TAILGATE RR FENDER RH & LH SIDE	1350.00	625.00
TOTAL LABOUR CHARGES			2898.00	1583.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL5142K

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	STAY ASSY-RH	H5210-4EAMA	126.00			X
2	SUNDRIES	NPN			20.00	OK
3	ORNAMENT-BACK D	90892-4EA0A	87.00			X
4	BRACKET-BUMPER LH	85221-4EA0A	35.90			X
5	BRACKET-BUMPER RH	85220-4EA0A	35.90			OK
6	REINF-BUMPER RR	H5030-4EAMA	619.20			X
7	ENERGY ABSORBER	85090-4EA0A	126.40			X
8	FINISHER-REAR B	85071-4EA0A	16.80			OK
9	CLIP(7.4X3)	85284-JD00A	22.20			OK
10	CROMMET(2.5X2)	63846-5V000	5.00			OK
11	FASCIA-RR BUMP	85022-4EA0H	717.00			OK
12	REVERSE SENSOR(J11)-WRONG \$180	SENSOR-TE5140			250.00	OK
13	EMBLEM-REAR	90890-4EA0A	59.70			X
SUB TOTAL			796.90	0.00	270.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			159.38	0.00	0.00	
GRAND TOTAL			637.52	0.00	270.00	
OVERALL TOTAL			907.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLL5142K

NETT ITEM	796.90
LESS 20.00%	-159.38
NETT AMOUNT	637.52
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	270.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	270.00
TOTAL LABOUR CHARGES	1683.00
TOTAL SPARE PARTS CHARGES	907.52
TOTAL CHARGES	2590.52
ADD 7 % GST	181.34
GRAND TOTAL	2771.86

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2019 14:52 Edit Reg		26 Jul 2019 00:00 Edit Adj Rpt	\$2,590.52 Edit Estimates	\$2,590.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured: -, Co. Reg. No.: -, Email: NOEMAIL@EMAIL.COM	
Main Claimant: KOI WEI TER (CAI WEIDE), ID: S80024951	
Vehicle Reg. No.: SLL5142K	Date of Loss: 09/07/2019 10:00 - :59 [28 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type: TP	Policy/Cover Note No.:
Vehicle Reg. No. (Insured): SLJ754M	Policy No. (Claimant): 2100502668-02
Excess:	
Repairer: Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road, 589622 Bukit Timah - Tel:	
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178	
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 06/08/2019]	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL5142K
[SLJ754M]

TP

KOI WEI TER (CAI WEIDE)

Jul 9 2019 10:00AM

[-]


Tan Chong Motor Sales Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼



























Assessment Reports

1 per page ▼ ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/19 14:56	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>




Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	12/12/19 12:15	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	12/12/19 12:15	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	12/12/19 12:15	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	12/12/19 12:15	BEFORE PAINT PHOTOS	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	12/12/19 12:15	BEFORE PAINT PHOTOS	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	12/12/19 12:15	BEFORE PAINT PHOTOS	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	12/12/19 12:15	BEFORE PAINT PHOTOS	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Documentation

1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/07/19 16:47	TP ESTIMATE	 Load PDF	<input type="checkbox"/>
2	26/07/19 16:47	TP GIA REPORT	 Load PDF	<input type="checkbox"/>
3	26/07/19 16:47	ACKNOWLEDGEMENT EMAIL TO ICS DD 26.07.2019	 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS19013212/GQD3S2

Date: 20/12/2019

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLL5142K	Insured Vehicle No :	SLJ754M
Date of Loss:	09/07/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL5142K	Engine No:	HRA2327066A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Chassis No:	SJNFEAJ11U1757251
Reg. Date:	28/02/2017 (Man. Year: 2016)	Odometer:	51553 km
Colour:	Brown		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,770.88	907.52	863.36	48.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,898.00	1,683.00	1,215.00	41.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,668.88	2,590.52	2,078.36	44.52
+ GST 7.00/7.00% (S\$)	326.82	181.34	145.48	44.51
Nett Amount (S\$)	4,995.70	2,771.86	2,223.84	44.52

INSPECTION

Date of Assignment:	26/07/2019	
Date Inspected:	08/08/2019	Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road Singapore 589622
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Dec 2019)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL5142K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ORNAMENT - BACK D	Not Necessary	87.00 FN	*- FN
2	1		*EMBLEM - REAR	Not Necessary	59.70 FN	*- FN
3	1		*BRACKET - BUMPER LH	Not Necessary	35.90 FN	*- FN
4	1		*BRACKET - BUMPER RH	Deformed	35.90 FN	*35.90 FN
5	1		*STAY ASSY - RH	Not Necessary	126.00 FN	*- FN
6	1		*REINF - BUMPER RR	Not Necessary	619.20 FN	*- FN
7	1		*ENERGY ABSORBER	Not Necessary	126.40 FN	*- FN
8	1		*FINISHER - REAR B	Necessary	16.80 FN	*16.80 FN
9	3		*CLIP	Necessary	22.20 FN	*22.20 FN
10	2		*GROMMET	Necessary	5.00 FN	*5.00 FN
11	1		*FASCIA - RR BUMP	Cut	717.00 FN	*717.00 FN
12	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
13	1		*REVERSE SENSOR (J11)	Damaged	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,141.10	1,066.90
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	370.22	159.38
Total Parts (\$\$)	1,770.88	907.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	New	120.00	120.00
2	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.	New	110.00	110.00
3	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	New	100.00	0.00
4	CHECK LIGHTING.	New	48.00	48.00
5	REPAIR REAR TAILGATE & REAR END PANEL RENEW RR BUMPER.	New	1,170.00	780.00
6	S/PAINT RR BUMPER (2 TONE), RR END PANEL & TAILGATE RR FENDER RH & LH SIDE.	New	1,350.00	625.00
Gross Labour Cost (\$\$)			2,898.00	1,683.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >