SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

aforesaid.	iona to the distinting of the report at the sound that to explod of the report being made available
	ACCIDENT STATEMENT
Date Of Report	26/07/2019 19:54
Date Of Accident	26/07/2019 13:30
Exact Location Of Accident	ORCHARD TURN
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SME4213X
Insured/Policyholder	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	VELLFIRE ELEGANCE MOONROOF (AUTO)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	
Driver	

Name of Driver

TAN HONG TUCK

NRIC No

S9473611J

Date Of Birth

Occupation

Outdoor

Date Of Driving Pass

25/04/2013

Driving Experience 6 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90666320

Fax Number

Contact Number OFFICE-90666320

EMail Address NOEMAIL

Address BLK 431B YISHUN AVENUE 1

#08-599

Postcode 762431

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

insurance Company of Driver's Own Venicle

-

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 7

Number of Passengers (Including Driver)

Passenger 1

NAME: : -

GENDER: : MALE

Passenger 2

NAME: :

GENDER: : MALE

Passenger 3

NAME: : -

GENDER: : MALE

Passenger 4

NAME: : -

GENDER: : FEMALE

Passenger 5

NAME: :

GENDER: : FEMALE

Passenger 6

NAME: :

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHF477G

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN HONG TUCK

Approximate Age

Injuries Sustain NECK & BACK Injured person in which vehicle? SME4213X

Were seat belts worn? YES

Was this injured conveyed to hospital by

ambulance?

Address Postcode NO

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- This form must be completed by the policy holder and/or the authorised driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding
 of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the police for investigation.
- 5) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre
 and to copies of the report being made available aforesaid.
- 8) Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) Investigations the accident and/or my claims;
 - (III) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/mail packages); and/or
 - (V) Complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (II) For complying with requirements under my regulations, laws or court orders.

THE SERVICES OF THE STATE OF THE SERVICES OF T

Policy holder's signature Date / time: Driver's signature (if driver is not policy holder) Date / time: reporting centre personnel's Signature Date / time:

Accident Sketch Plan

urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage		DESCRIBE CIRCUMSTANCES OF THE ACCIDENT I was travelling valong 2 Orchard Turn. When I was travelling straight. Thicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he oblided onto left portion of my vehicle. I have video bootage								H	П	H	П	П	П	H	П	П	П
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage										I			Į.	9:5	ME	42 I 477	3) G
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage								1	tal		+	1	\blacksquare				H
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage									V				-	H		H	H
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage									12/				#	Ħ			
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly urned out without checking the main road is clear. Hence, he ollided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage					\blacksquare			#						Ħ			
I was travelling valong 2 Orchard Turn. When I was travelling straight. Thicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. Thicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. Thicle B which was exiting from Ion Orchard Mall suddenly wrong out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage																	
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage											Ш						
I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage	I was travelling valong 2 Orchard Turn. When I was travelling straight. whicle B which was exiting from Ion Orchard Mall suddenly uned out without checking the main road is clear. Hence, he allided onto left portion of my vehicle. I have video bootage								#		\pm							
1			and C	11102					-			- 22							
			urned Ullided	out d on	with to let	out 4 poi	check	ing -	the n	nain	roo	d	13						
			urned ullided	out d on	with to let	out 4 poi	check	ing -	the n	nain	roo	d	13						
			urned ollided	out d on	with to let	out 4 poi	check	ing -	the n	nain	roo	d	13						
			urned ollided	out d on	with to let	out 4 poi	check	ing -	the n	nain	roo	d	13						
			urned ullided	out d on	with to let	out 4 poi	check	ing -	the n	nain	roo	d	13						

Driver's signature (if driver is not policy holder)

Date & time:

Policy holder's signature

Date & time:

Page 6

reporting centre personnel's Signature Name:

NRIC/FIN No.:



































