

ASS. REC. BY:

REF: CS3/MSG19013252/EA3

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): *Chhā Myk Pū* of *MSG* Date/Time: *29.7.19 9.55a.m*

Estimated Cost: Bill to:

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: *GBF 6137U* Insured: *SMH 714C*

at Workshop m/s *Long New motor* Tel: *96651775*

of *Blt 4 Kranj Loop #01-17*

Policy No: *29114745* Claim No: *600660*

Sum Insured: Excess:

Make of Veh: D.O.A. *21.7.19*  
(Client's Record)

CA / REV / REP. / REV 24 HRS *mp* H.O.D. Endorsement:


Date/Time: *29.7.19 9.58a.m* Person Contacted: *ANTHIAN* Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	<i>GBF 6137U X</i>
	<i>SMH 714C X</i>

*mm/mm*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 at \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt. Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBF 6137U Yr Regn: 13/1/17  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota Dyna 150 C.C. 2982  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 77175 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 Ci/No: JTFAT3SY90K297302  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/75 R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front		Rear
R/Bal. <u>5</u> mm		R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm		L/Bal. <u>5</u> mm
D.O.A. <u>21/7/19</u>		D.O.I. <u>29/7/19</u>

Survey held at \_\_\_\_\_  
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : Action / Instruction

MV - 50K  
 repair longer  
 Days - 7  
 SK-TK  
 30/7/2019

Date/Time. File Pass to?  : Prol. Report  
 : Final Report

Days Of Repair: 7  
 Resurvey No. of Trip: 2

Date/Time. File Return to? \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:  
 Transportation  
 ) S + RS (\$)  
 1. Photos  
 1. Labor  
 1. \_\_\_\_\_

Report Format: PRS  
 Lump Sum / I.B.F. (\$)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/07/2019 14:21
Date Of Accident	21/07/2019 11:30
Exact Location Of Accident	KJE EXIT TOWARDS WOODLANDS RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF6137U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	POON BROTHERS DESIGN & CONTRACT
Co Reg No	53164186D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91999110
Alternative Phone No	OFFICE-91999110

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097196547-01
Cover Note Number	

### Driver

Name of Driver	POON WAI HONG
NRIC No	S7470691F
Date Of Birth	18/01/1974
Occupation	OUTDOOR
Date Of Driving Pass	22/08/1996
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91999110
Fax Number	
Contact Number	OFFICE-91999110
EEmail Address	NOEMAIL

Address	508 JELAPANG ROAD #08-92
Postcode	S670508
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG KJE GOING TOWARDS THE EXIT OF BKE, THE VEHICLE INFRONT OF ME BRAKE AND I FOLLOWED TO BRAKE, ALL OF A SUDDEN, A VEHICLE CAME FROM BEHIND AND HIT ONTO THE REAR PORTION OF MY VEHICLE, DUE TO THE IMPACT MY VEHICLE WAS BEING PUSHED TOWARDS THE FRONT AND THE FRONT PORTION OF MY VEHICLE HIT ONTO THE REAR PORTION OF THE VEHICLE INFRONT OF ME.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMH714C
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SME1041U

Vehicle Make/Model/Colour

HONDA FIT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



22 JUL 2019

**IDAC BUKIT BATOK (MAG)**  
511 Bukit Batok Street 23  
Singapore 659445  
Tel: 6550 3312 Fax: 6563 0722  
Email: vaebhg@singapore.com

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 186D

### Vehicle Details

Vehicle No.: GBF6137U  
Vehicle to be Exported: No  
Intended Deregistration Date: 29 Jul 2019  
Vehicle Make: TOYOTA  
Vehicle Model: DYNA 150 5MT  
Primary Colour: White  
Manufacturing Year: 2016  
Engine No.: 1KD2673386  
Chassis No.: JTFAT35Y90K207302  
Maximum Power Output: -  
Open Market Value: \$26,436.00  
Original Registration Date: 13 Jan 2017  
First Registration Date: 13 Jan 2017  
Transfer Count: 1  
Actual ARF Paid: \$1,322.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 12 Jan 2027  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 10  
PQP Paid: \$45,310.00  
COE Rebate Amount: \$33,775.00  
**Total Rebate Amount: \$33,775.00**

The information contained herein is correct as at 29 Jul 2019

OK

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jul 2019		29 Jul 2019 09:55 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G		
Main Claimant:	<b>POON BROTHERS DESIGN &amp; CONTRACT</b> , Co. Reg. No.: 53164186D		
Vehicle Reg. No.:	<b>GBF6137U</b>	Date of Loss:	21/07/2019 11:00 - :59 [30 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 600660</b>	Policy/Cover Note No.:	29114745 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	<b>SMH714C</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Long View Motor Works (HQ)</b> Blk 4 Kranji Loop, #01-17, 739540 Kranji - Tel:		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Imm.Advice due 30/07/2019]		
Driver/Custodian (Insured):	WANG WILSON (), NRIC: S26311821, Tel: +6587818442 Email:		
Adj Asg. Remarks:	on WP. OI:Grab. Liab: 100%. Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ah Thiam @ 9665 1775.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*GBF6137U (600660)**  
**[SMH714C]**  
**TP**  
**POON BROTHERS DESIGN & CONTRACT**  
**Jul 21 2019 11:00AM**  
**[GRAB RENTALS PTE LTD]**  
**Long View Motor Works**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			View	View in Browser ▼	
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/07/19 16:04	<b>Accident Statement</b> From: SC - Reg. No: SMH714C, Claimant: GRAB RENTALS PTE LTD	1	Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	29/07/19 18:53	<b>Odometer Reading</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	29/07/19 18:53	<b>Chassis Number</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
19	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
20	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
21	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
22	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
23	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
24	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
25	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
26	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
27	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
28	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
29	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
30	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
31	29/07/19 18:53	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
33	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
34	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
35	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
36	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
37	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
38	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 18:53	General View	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
67	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 18:54	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
80	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
81	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
82	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
83	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
84	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
85	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
86	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
87	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
88	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
89	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
90	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
91	29/07/19 18:54	Photographs of Damaged Items		Load JPG <input checked="" type="checkbox"/>
92	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
93	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
94	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
95	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
96	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
97	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
98	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
99	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
100	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
101	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
102	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
103	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
104	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
105	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
106	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
107	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
108	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
109	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
110	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
111	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
112	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
113	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
114	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
115	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
116	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
117	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
118	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
119	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
120	02/08/19 14:54	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	25/07/19 16:08	TP SME1041U E-FILE REPORT 1/3		Load PDF
2	25/07/19 16:10	TP GBR6137U E-FILE REPORT 2/3		Load PDF
3	25/07/19 16:10	PRI from Vision Law LLC		Load PDF
4	26/07/19 17:58	Disagree on SJE		Load PDF
5	26/07/19 17:58	Workshop Details		Load PDF

# Documents Checklist

## DOCUMENTS CHECKLIST

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19013252/ECF3S2  
Date: 05/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29114745  
Claimant Vehicle No: GBF6137U Insured Vehicle No: SMH714C  
Date of Loss: 21/07/2019 Nature of Claim: TP Claim No: 600660

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF6137U**  
Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2673386  
Reg. Date: 13/01/2017 (Man. Year: 2016) Chassis No: JTFAT35Y90K207302  
Colour: White Odometer: 77175 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75R15 Rear Tyre Size: 195/75R15  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 29/07/2019  
Date Inspected: 29/07/2019 Inspected At: Long View Motor Works (HQ)  
Blk 4 Kranji Loop, #01-17  
Singapore 739540  
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 05 Aug 2019)

**Parts:** N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBF6137U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >