

22/06/2019

ASS. REC'D BY:

REF:

CS/CTI/19013259/G1302

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)From (Person): Chong Boon Sen

of

CTI

Date/Time:

29/7/19 @ 8:41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBD 7740G

Insured:

SLG 1631T

at Workshop m/s

Pain Eun Bikes

Tel:

6299 4929

of

21 Moonstone Lane #01-01 Poh Leng Building

Policy No:

DMPCSN31098317022

Claim No:

SNM19D202828C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:40am 29/7/19

Person Contacted:

Kin Wah

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Polimald</u> ✓
	<u>FBD 7740G X</u>
	<u>SLG 1631T CC4/1118012037/UHb3 DOA = 27/6/18</u>

ASS. REC. BY:

EAL.

REF: CTF

## ASSIGNMENT

(2029)

From:

Date:

31/7/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBD 7740G

at Workshop m/s

Puneuro Bike

of

21 Moonstore Lane # 01-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Moming

Make of Veh:

Kin wah @ 7731 7133

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

cup

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

FBD 7740G

Yr Regn:

29 Jul 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Tloc

Make:

Triumph Bonneville 865

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

56000

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SMTTJ9157 G 9382476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 100/90-19

R:

160/70 B17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal.

5 mm

R/Bal.

5

mm

L/Bal.

5 mm

L/Bal.

5

mm

D.O.A.

D.O.I.

31-07-19

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/7 Finalized \$ 1138 with Kin wah

(Red: 221.54; 16%)

*[Signature]*  
11/8/2019

RECEIVED 02 AUG 2019

Date/Time, File Pass to?



: Prel. Report

1) 218 Typst



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

210

Transportation:

3 + RS, SI

Photos

Others

TOTAL

210

Report Format:

TP

Lump Sum / 1138 (\$)

0

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 29 July 2019 8:41 AM  
**To:** PanEuroBikes  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** PanEuroBikes [mailto:paneurobikes@singnet.com.sg]

**Sent:** Saturday, 27 July, 2019 12:54 PM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Ehhhh I sent you a reply 22<sup>nd</sup> already bro, please see attached.

Or are you a sis.....

Best Regards,

Kin Wah

Pan Euro Bikes Pte Ltd

Tel : +65 6299-4929

Fax : +65 6299-4430

Mobil : +65 9731-7133, +65 8121-2173

Email : [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

**Sent:** Friday, July 26, 2019 4:28 PM

**To:** PanEuroBikes

**Subject:** RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Who you choose??

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** PanEuroBikes [<mailto:paneurobikes@singnet.com.sg>]

**Sent:** Monday, 22 July, 2019 11:14 AM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject:** RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Dear Boon Sen,

Thank you for the arrangement. Kindly assign at your discretion as we have no preference. However do get your appointed surveyor to contact myself for the date arrangement, as my client is currently using the vehicle.

Good Day ahead, & Best Regards,

Kin Wah

Pan Euro Bikes Pte Ltd

Tel : +65 6299-4929

Fax : +65 6299-4430

Mobil : +65 9731-7133, +65 8121-2173

Email : [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

**Sent:** Monday, July 22, 2019 9:09 AM

**To:** [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

**Subject:** RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 22 July, 2019 8:59 AM

To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

Cc: Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>

Subject: FW: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Dear Boon Sen,

Please assist.

Thanks,  
shumin

From: PanEuroBikes [<mailto:paneurobikes@singnet.com.sg>]

Sent: Friday, 19 July, 2019 6:18 PM

To: Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Irene Tay <[irene.tay@sg.cntaiping.com](mailto:irene.tay@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

Subject: RE: OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Dear Claims & Everyone,

Can someone reply?

This is a request for PRI?

Many thanks.

Kin Wah

---

Dear All,

My client has returned from his trip. Can we arrange the survey on Tuesday 16<sup>th</sup> July?

Many thanks, & Best Regards,

Kin Wah

Pan Euro Bikes Pte Ltd

Tel : +65 6299-4929

Fax : +65 6299-4430

Mobil : +65 9731-7133, +65 8121-2173

Email : [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

---

**From:** Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

**Sent:** Wednesday, June 19, 2019 10:33 AM

**To:** Irene Tay; Chee So Chow; [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

**Subject:** OUR REF: SNM19D202828 - 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Dear Irene,

Please conduct PRS – FBD7740G soonest possible.

File with Officer-In-Charge – Irene Tay – 63896192

Thank you

**Lim Shu Min**

Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** PanEuroBikes [<mailto:paneurobikes@singnet.com.sg>]

**Sent:** Tuesday, 18 June, 2019 7:07 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** 3rd Party Survey request - Accident Between FBD 7740G/SLG 1631T on 15.06.2019 on 367 Onan Rd.

Dear Claimsdept,

Pertaining to this request, please note that my client is flying out of town tonight for 3 weeks. As such, I will inform and liaise again on survey arrangement when he has returned and can bring the motorcycle down; it is currently still with him.

Thank you All again, & Best Regards,  
Kin Wah

---

Dear Claims,

Kindly arrange for a 3<sup>rd</sup> Party claim survey for our vehicle FBD 7740G, please find estimate & GIA report attached.

Thank You All, & Best Regards,

Kin Wah

Pan Euro Bikes Pte Ltd

Tel : +65 6299-4929

Fax : +65 6299-4430

Mobil : +65 9731-7133, +65 8121-2173

Email : [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	013N
Vehicle Details	
Vehicle No.:	FBD7740G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	TRIUMPH
Vehicle Model:	BONNEV T100
Primary Colour:	Black
Secondary Colour:	White
Manufacturing Year:	2008
Engine No.:	7376597
Chassis No.:	SMTTJ9157G9382476
Maximum Power Output:	-
Open Market Value:	\$8,780.00
Original Registration Date:	29 Jul 2009
First Registration Date:	29 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$1,317.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$3,267.00
COE Rebate Amount:	\$3,264.00
<b>Total Rebate Amount:</b>	<b>\$3,264.00</b>

The information contained herein is correct as at 31 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/06/2019 15:25
Date Of Accident	15/06/2019 23:30
Exact Location Of Accident	367 ONAN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBD7740G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DIXON MARK JAMES
NRIC No	G3046013N
Email Address	MARKJDIXON@ME.COM
Mobile Phone No	(LOCAL) +65-98076225
Alternative Phone No	OFFICE-98076225

### Vehicle Particulars

Manufacturer	TRIUMPH
Model	BONNEVILLE-865CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MC/00191067/04
Cover Note Number	

### Driver

Name of Driver	DIXON MARK JAMES
NRIC No	G3046013N
Date Of Birth	25/02/1971
Occupation	INDOOR
Date Of Driving Pass	24/09/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98076225
Fax Number	
Contact Number	OFFICE-98076225
Email Address	MARKJDIXON@ME.COM

Address	NO
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO TO ACCIDENT STATEMENT IN THE SKETCH PLAN ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG1631T
Vehicle Make/Model/Colour	BMW / 320I / SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident\* (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


17 06/19 14:24

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Tan Chuan Wei  
NRIC/FIN No.: G7715326

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

APPROXIMATELY AT 11-15pm - 11 30pm I HEARD A LOUD CRASH FROM MY LIVING ROOM. I WENT TO FRONT DOOR. OPENED IT AND SEEN MY MOTORCYCLE ON ITS SIDE AND A SILVER BMW 320i PULLING AWAY FROM MY MOTORCYCLE. I PROCEEDED TO APPROACH THE VEHICLE AND TOLD THE DRIVER TO STOP THE CAR AS SHE WAS BEGINNING TO START TO DRIVE AWAY. EVENTUALLY THE DRIVER PULLED OVER THE CAR AND GOT OUT. THE DRIVER AT FIRST CLAIMED SHE DIDNT REALISE THAT SHE HAD REVERSED INTO MY MOTORCYCLE BUT AS WE SWAPPED DETAILS SHE ADMITTED SHE HAD DONE IT AND WAS AT FAULT AND APOLOGISED.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

*MJZ*

Policyholder's Signature

Date & Time:

17.06.19 14:24

BARMC SketchPlanForm\_V3

Driver's Signature

(if driver is not the policyholder)

Date & Time:

*[Signature]*  
Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Tom Chua Wei  
B7711335R

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
CHINA TAIPING INS. (S) PTE LTD

DATE: 19.06.2019

## ESTIMATED COST OF REPAIRS TO TRIUMPH BONNEVILLE T100

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FBD 7740G ACCIDENT ON : 15.06.2019  
INSURED : MARK DIXON JAMES

1 PC	BAR END WEIGHT - <i>cut</i>	S	38.00	
1 PC	BRAKE LEVER ASSY - <i>cut</i>	S	118.00	
1 PC	BRAKE PEDAL - <i>cut</i>	S	155.00	
1 PC	RH FRONT FOOTREST - <i>BR</i>	S	178.00	<i>local repair</i>
1 PC	RH EXHAUST MUFFLER, CHROME - <i>cut</i>	S	414.00	<i>300 (SN)</i>
1 PC	LH FRONT SIGNAL ASSY - <i>cut</i>	S	95.00	
1 PC	LH HEADLAMP STAY - <i>cut</i>	S	118.00	
1 PC	RH HEADLAMP STAY - <i>cut</i>	S	118.00	
TOTAL		S	1,234.00	<i>820</i>
LESS 10%		S	123.40	
SUB TOTAL		S	1,110.60	<i>738</i>

### NETT ITEMS:

#### LABOUR CHARGE

#### TOTAL

S 160.00 *100*  
S 1,270.60

### REMARKS:

For a 3rd Party claim against your insured  
SLG 1631T.

Thank You.

Kin Wah: 9731-7133

#### ADD 7% GST

S 88.94

#### GRAND TOTAL

S 1,359.54

Total : 1138

Guo Qiang - 82880282

31/7/19.

After repair photos.

2 days.

part by mt.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2019		01 Aug 2019 18:24 <a href="#">Edit Adj Rpt</a>	<b>S\$1,138.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,138.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>DIXON MARK JAMES</b> , ID: G3046013N								
Vehicle Reg. No.:	<b>FBD7740G</b>	Date of Loss:	15/06/2019 23:00 - :59 [118 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202828C02</b>	Policy/Cover Note No.:	DMPCSN31098318022						
Vehicle Reg. No. (Insured):	<b>SLG1631T</b>	Policy No. (Claimant):	MC/00191067/04						
		Excess:	S\$0.00						
Repairer:	<b>Pan Euro Bikes Pte Ltd (HQ)</b> 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>Direct Asia Insurance (Singapore) Pte Ltd (HQ)</b> - Tel: 65322888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 14/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*FBD7740G (SNM19D202828C02)**

**[SLG1631T]**

**TP**

**DIXON MARK JAMES**






























**Jun 15 2019 11:00PM**

**[-]**










**Pan Euro Bikes Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 15:39	<b>Accident Statement</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	17/06/19 15:35	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	02/08/19 08:47	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
12	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 08:47	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 15:39	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 15:39	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 15:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 15:35	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)		Thumbnail Print
9	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
14	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
15	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
16	17/06/19 15:35	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ban Hock Hin Co. Pte Ltd (HQ)		Thumbnail Print
1	17/06/19 15:39	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	17/06/19 15:39	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013259/GTF3E2

Date: 05/08/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN31098318022

Claimant Vehicle  
No : FBD7740GInsured Vehicle  
No : SLG1631T

Date of Loss: 15/06/2019

Nature of Claim: TP

Claim  
No: SNM19D202828C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBD7740G

Make &amp; Model: TRIUMPH BONNEVILLE, 865cc

Engine No: 7376597

Reg. Date: 29/07/2009 (Man. Year: 2008)

Chassis No: SMTTJ9157G9382476

Colour: Black

Odometer: 56000 km

Engine Capacity: 865 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 100/90-19

Rear Tyre Size: 160/70 B17

Front Left Side: Metzeler 5 mm

Rear Left Side: Metzeler 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,110.60	1,038.00	72.60	6.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	160.00	100.00	60.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,270.60</b>	<b>1,138.00</b>	<b>132.60</b>	<b>10.44</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>88.94</b>	<b>79.66</b>	<b>9.28</b>	<b>10.43</b>
<b>Nett Amount (S\$)</b>	<b>1,359.54</b>	<b>1,217.66</b>	<b>141.88</b>	<b>10.44</b>

## INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 31/07/2019 Inspected At:

Pan Euro Bikes Pte Ltd (HQ)  
21 Moonstone Lane #01-01 Poh Leng  
Building  
Singapore 328462

Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 05 Aug 2019)

**Parts:** N/A TRIUMPH BONNEVILLE 865cc (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for FBD7740G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAR END WEIGHT	Cut	38.00 FL	*38.00 FL
2	1		*BRAKE LEVER ASSY	Cut	118.00 FL	*118.00 FL
3	1		*BRAKE PEDAL	Cut	155.00 FL	*155.00 FL
4	1		*RH FRONT FOOTREST	Broken	178.00 FL	*178.00 FL
5	1		*RH EXHAUST MUFFLER, CHROME (LOCAL REPAIR)	Cut	372.60 FS	*300.00 FS
6	1		*LH FRONT SIGNAL ASSY	Cracked	95.00 FL	*95.00 FL
7	1		*LH HEADLAMP STAY	Bent	118.00 FL	*118.00 FL
8	1		*RH HEADLAMP STAY	Bent	118.00 FL	*118.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,192.60</b>	<b>1,120.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>82.00</b>	<b>82.00</b>

<b>Total Parts (S\$)</b>	<b>1,110.60</b>	<b>1,038.00</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	160.00	100.00
Gross Labour Cost (\$\$)			160.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >