

27/03/2003

ASS. REC. BY:

REF:

CS3/CT119013262/16/13/2

Special Instruction:

Senior: Ram

Mehar

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time: 26/7/19 @ 5:33pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMF 1626C

Insured:

CB 7764L

at Workshop m/s

Toh Motor

Tel:

9748 3351

to

160 Sin Ming Drive #05-16

Policy No:

DMBISN18191319011

Claim No:

SNM19D203481

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10am @ 29/7/19

Person Contacted:

Yishan

Vehicle IN OUT

Date/Time	Action/Instruction
	Delivered X
	SMF 1626C NPA/CT119013165/Y DOA = 25/7/19
	CB 7764L "
	Disassemble: 15/8/2019.
	DS

PRS

ASSIGNMENT

From:

Date:

14/8/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMF 1626C

at Workshop m/s

Toh Motor

of

160 8th Ming Drive # 05-16

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

11 up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMF1626C

Yr Regn: OCT / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius Plus (auto) c.c 1798

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

71395

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDZS3EU00J034156*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205 / 60 R16 Firenza

R: 205 / 60 R16 Yokohama

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

25/7/2019

D.O.I.

14/8/19

Survey held at

Toh motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$2500 - \$3000
	Repair days: 4 days
	Tailgate (NC)
	MV: \$90000
	PV: \$46817
	NV: \$43000 *

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

PRS

Lump Sum / L&J: (\$

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2019		29 Jul 2019 10:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer]				
Insured:				
Main Claimant: LUMENS AUTO PTE LTD, Co. Reg. No.: 201426961K				
Vehicle Reg. No.: SMF1626C		Date of Loss:	25/07/2019 08:00 - :59	
Claim Type: TP / SNM19D203481C02		Policy/Cover Note No.:	DMB1SN18191319011	
Vehicle Reg. No. (Insured): CB7764L		Policy No. (Claimant):	18-MJ001357-R00	
		Excess:	S\$0.00	
Repairer: Toh Motor Enterprise (SIN MING) BLK 12 SIN MING INDUSTRIAL ESTATE #01-61 SECTOR B, 575656 Sin Ming - Tel:				
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]				
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/08/2019]				
ASSOCIATED MAIL RECEIVED View All Compose Case Mail				
There are no mail for this case.				
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All Search Tasks Create New Task Complete</div> <div> <div>Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?</div> <div>No results.</div> </div> </div> </div>				

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 26 July 2019 5:33 PM
To: Serene Tan
Cc: assignments; Tan Kah Leong
Subject: RE: OUR REF: SNM19D203481/TANKL - FW: PRE-REPAIR SURVEY SMF1626C

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Serene Tan [mailto:serene.tan@mneduco.com.sg]
Sent: Friday, 26 July, 2019 5:01 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: OUR REF: SNM19D203481/TANKL - FW: PRE-REPAIR SURVEY SMF1626C

Hi,

Please let us know the appointed surveyor who will attend the PRS.

Thanks & regard,
Serene

From: Serene Tan
Sent: Friday, 26 July 2019 3:03 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: RE: OUR REF: SNM19D203481/TANKL - FW: PRE-REPAIR SURVEY SMF1626C

Our Ref : MN.IG.T1.1913189.st

WITHOUT PREJUDICE
SAVE AS TO COSTS

NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS PROVIDED WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 2.6 OF THE STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)

Hi Boon Sen,

1. We refer to your email below.
2. We are instructed by LUMENS AUTO PTE LTD, the claimant and/or TOH MOTOR ENTERPRISE, the motor workshop for SMF 1626C that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

- | | |
|---|---|
| 1. NICKY SEAH (Absolute Appraisal Services) | 6. ANDREW HOW (Prominent Appraiser Services) |
| 2. MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd) | 7. NG KONG BENG PATRICK (Carlink Consultancy) |
| 3. DIXON YEO (Treasure Appraisal Services) | 8. ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd) |
| 4. LOI BOON JUAN (Par Automotive Consultancy Pte Ltd) | 9. DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd) |
| 5. AMAS ONG (AEON Auto Consultants LLP) | 10. ANDY YAP TECK LEE (LCW Appraiser Pte Ltd) |

4. Please let us know within two (2) working days whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)
Serene Tan (Ms)
M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office:
11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel: 6509-8480 / 6509-8481
Fax: 6509-8482
Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Friday, 26 July 2019 3:01 PM
To: Serene Tan <serene.tan@mneduco.com.sg>
Subject: RE: OUR REF: SNM19D203481/TANKL - FW: PRE-REPAIR SURVEY SMF1626C

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, 26 July, 2019 10:19 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>;

serene.tan@mneduco.com.sg

Subject: OUR REF: SNM19D203481/TANKL - FW: PRE-REPAIR SURVEY SMF1626C

Dear Boon Sen,

Please assist to conduct PRS for SMF1626C.

Note : officer in charge is Kah Leong 63896193.

Thanks,
shumin

From: Serene Tan [<mailto:serene.tan@mneduco.com.sg>]

Sent: Thursday, 25 July, 2019 2:18 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: PRE-REPAIR SURVEY

URGENT

WITHOUT PREJUDICE

Our Ref: MN.IG.T1.1913189.st

Dear Sirs,

Notice of Accident dated **25/7/2019** attached herein.

Thanks & Best Regards,
(For and on behalf of Mr Nedumaran Muthukrishnan)

Serene Tan (Ms)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office:

11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel: 6509-8480 / 6509-8481

Fax: 6509-8482

Email : serene.tan@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	961K
Vehicle Details	
Vehicle No.:	SMF1626C
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	2ZR0C53807
Chassis No.:	JTDZS3EU00J034156
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,006.00
Original Registration Date:	30 Oct 2018
First Registration Date:	30 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$24,009.00 $\times 50\% = \$12,004.50$
Intended PARF Rebate Details	
PARF Eligibility:	Yes ✓
PARF Eligibility Expiry Date:	29 Oct 2028
PARF Rebate Amount:	\$18,006.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,302.00
COE Rebate Amount:	\$28,811.00
Total Rebate Amount:	\$46,817.00

The information contained herein is correct as at 15 Aug 2019

DOA: 25/07/2019

OK

Remaining: 9 years 3 months 4 days (111.1 months)

Depn: \$8500/- (yearly) \$708.33 (monthly)

$111.1 \times \$708.33 = \$78,695.46$

$\$78,695.46 + \$12,004.50 = \$90,699.96$



DAVANTI
Proven Performance Tyre
FREE 16G apply



SGCARMART CARNIVAL
31 Aug & 1 Sep 10am - 8pm
Downtown East Carpark B
SEE YOU @ BOOTH 2!



SPARKO KAFIS @ \$356 Includes GST
FREE 1 Essential Servicing & 1 Grooming (worth \$236 total)
Plus Many Other Benefits!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

High Loan & Trade In, Free Choice Of Spray!



Warranty & Free Servicing
Provided!
StarAd



HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

1 vehicles

toyota PRIUS PLUS

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota	PRIUS PLUS	Any	Any	2018	Any	Any	Any	Available
	Toyota	Prius Hybrid 1.8A Plus	\$98,800	\$9,530 /yr	20-Sep-2018	1,798 cc	10,268 km	MPV	Available
Fuel Type: Petrol-Electric Non Pte Hire, Borneo Motors Warranty, Well Kept With Low Mileage, Environmentally Friendly, Go For Battery Electric Drive System To Increase Fuel Economy And Reduce Emissions, Gasoline Efficient, Spacious MPV.									
Posted: 27-Jul-2019 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota									

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota PRIUS PLUS, toyota PRIUS PLUS Singapore, used toyota PRIUS PLUS Singapore, used toyota PRIUS PLUS, used vehicles Singapore or even buy used toyota PRIUS PLUS Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart, All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2019 12:05
Date Of Accident	25/07/2019 08:20
Exact Location Of Accident	ALONG CO-OPERATION RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF1626C
Insured/Policyholder	
Name Of Registered Owner	LUMENS AUTO PTE LTD
Co Reg No	201426961K
Email Address	OPERATIONS@LUMENS.SG
Mobile Phone No	
Alternative Phone No	OFFICE-87781765
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	18-MJ001357-R00
Cover Note Number	

Driver

Name of Driver	ABDUL WAHAB BIN AWANG
NRIC No	S1136569H
Date Of Birth	07/07/1955
Occupation	OUTDOOR
Date Of Driving Pass	20/09/1978
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98630879
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK524, JURONG WEST ST5, #03-245
Postcode	640524
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7764L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may/can be shared with:
 - (i) third insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, laws or statutes.



Printed Name (Signature)
Date & Time




Printed Name
(Must be the policyholder or authorised driver)
Date & Time

CITY AUTO PTE LTD
Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Printed Name (Must be Sin Ming Road)
Name
NRIC No.

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary stop behind S B S Bus
Vehicle B when turning out from a Condo
accidentally hit onto my rear bumper

DECLARATION

By the Driver
Signature
Date & Time



Signature of witness
All have read the accident report
Date & Time



CITY AUTO PTE LTD
B/k 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 1235 Fax: 6453 7944
(Claims Section)

Signature of City Auto Pte Ltd
Date & Time

...CLAIM SUBFOLDER...(Pending for Survey Report)


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2019		29 Jul 2019 10:37 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case














































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LUMENS AUTO PTE LTD , Co. Reg. No.: 201426961K								
Vehicle Reg. No.:	SMF1626C	Date of Loss:	25/07/2019 08:00 - :59 [8 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203481C02	Policy/Cover Note No.:	DMB1SN18191319011						
Vehicle Reg. No. (Insured):	CB7764L	Policy No. (Claimant):	18-MJ001357-R00						
		Excess:	S\$0.00						
Repairer:	Toh Motor Enterprise (SIN MING) BLK 12 SIN MING INDUSTRIAL ESTATE #01-61 SECTOR B, 575656 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 07/08/2019]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

















*SMF1626C (SNM19D203481C02)
[CB7764L]
TP
LUMENS AUTO PTE LTD
Jul 25 2019 8:00AM
[-]
Toh Motor Enterprise

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	City Auto Pte Ltd (HQ)							Thumbnail			Print		
1	25/07/19 12:19	Video - Accident [Linked Accident Report Documents]										Load MP4		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	City Auto Pte Ltd (HQ)							Thumbnail			Print		
1	25/07/19 12:22	Accident Statement										Load HTM		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	City Auto Pte Ltd (HQ)							Thumbnail			Print		
1	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
2	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
3	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
4	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
5	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
6	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
7	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
8	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
9	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
10	25/07/19 12:18	Accident Photo [Linked Accident Report Documents]										Load JPG <input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
2	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
3	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
4	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
5	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
6	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
7	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
8	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
9	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
10	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
11	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
12	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
13	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
14	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
15	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		
16	20/08/19 12:25	General View										Load JPG <input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
17	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
27	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
28	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
29	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
30	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
31	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/19 12:25	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
66	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	20/08/19 12:25	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 12:16	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 12:16	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 12:16	IC [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 12:17	IC & DL [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 12:19	Video - Accident	 Load MP4	<input checked="" type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 12:22	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	25/07/19 12:18	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	City Auto Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 12:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 12:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 12:16	IC	 Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 12:17	IC & DL	 Load TIF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013262/FCF3E2

Date: 22/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN18191319011

Claimant Vehicle
No : SMF1626CInsured Vehicle
No : CB7764L

Date of Loss: 25/07/2019

Nature of Claim: TP

Claim
No: SNM19D203481C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF1626C**

Make & Model: TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)

Engine No: 2ZR0C53807

Reg. Date: 30/10/2018 (Man. Year: 2018)

Chassis No: JTDZS3EU00J034156

Colour: Grey

Odometer: 71395 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Firenza 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/07/2019

Date Inspected: 14/08/2019	Inspected At:	Toh Motor Enterprise (SIN MING) 160 SIN MING DRIVE #05-16 SIN MING AUTOCITY SINGAPORE 575722
----------------------------	---------------	---

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF1626C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >