

2202041

ASS. REC. BY:

REP: C1/FCI19013265/N d3

Special Instructions:

Assigner: Naz

ASSIGNMENT (Office)

From (Person): Joanne Yong

of FCI

Date/Time: 15/7/19 @ 9.34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7767A

Insured:

at Workshop m/n

Comfort Delgro

Tel:

6214 8398

of

51 Layney Drive

Policy No:

Claim No:

CT19070293

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/07/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Mr. HM

Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimated (✓)
	SHA 7767A - CS3/FCI19007343/ECd32	2019.18/4/2019

(08/11/13)

Surveyor: Kahin

REF: _____

No 8

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 77 67AYr Regn: 18/2/2015

Type: M/Car / M/Cycle / Bus / Van / Lorry / T6 / Prime Mover /

Truck / Trailer or _____

Make: Hyundai 240

D/C

1685Colour: Blue

A/C:

Insured / Std / NI / NA

Sp. Reading _____

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLOBK14AF9069J8X

Gen. Cond: Good / Fair / Poor / Burt

Steering: Inorder / Jammed / Leaked / Burt or

Brake: Inorder / Jammed / Leaked / Burt or

Modi: Nil / S/Rim / STD A/Rim or BurtTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Ren-HuketFront-Burt

Front

Rear

R/Bal. _____

mm

R/Bal. 6

mm

L/Bal. _____

mm

L/Bal. 6

mm

D.O.A. 11/7/19D.O.I. 15/7/19Survey held at CPGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Burt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Vel caught fireunsure to repairRecommended to scrapBurt note, Post 3 months since Record.FCZ

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp. (\$

Interview (\$

Test Drive (\$

Survey Fee: 500Transportation: 500Phone: 500Fuel: 500Other: 500

Return Form

Nivitha (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Monday, 15 July 2019 9:34 AM
To: assignments
Subject: FW: New (FIRE CASE) - CT19070293 SHA7767A DOA: 11/07/2019
Attachments: SHA7767A.pdf

Importance: High

Naz !!

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Bk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joanne Yong <Joanneyong@msfirstcapital.com.sg>
Sent: Monday, 15 July 2019 9:33 AM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: New (FIRE CASE) - CT19070293 SHA7767A DOA: 11/07/2019
Importance: High

Dear Bryan,

Pls survey the vehicle.

Please find the attached GiA report.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Mr Lim@ 62148398 if you need any other information.

Thank you

Regards,

Joanne Yong
Motor Claim Department



Change of email address
joanneyong@msfirstcapital.com.sg

MS First Capital Insurance Limited
A Member of **MS&AD** Insurance Group
36 Robinson Road
#16-01 City House
Singapore 068877
Tel: 6507 3846
Fax: 6507 3849

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3821R

Vehicle Details

Vehicle No.: SHA7767A

Vehicle to be Exported: Yes

Intended Deregistration Date: 12 Jul 2019

Vehicle Make: HYUNDAI

Vehicle Model: I40 1.7L CRDI AT ABS AIRBAG 4DR

Primary Colour: Blue

Manufacturing Year: 2015

Engine No.: D4FDFU530730

Chassis No.: KMHLB41UMFU069584

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$19,888.00

Original Registration Date: 18 Jun 2015

First Registration Date: 18 Jun 2015

Transfer Count: 0

Actual ARF Paid: \$12,388.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 Jun 2023

PARF Rebate Amount: \$9,291.00

Intended COE Rebate Details

COE Expiry Date: 17 Jun 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$52,886.00

COE Rebate Amount: \$25,983.00

Total Rebate Amount: \$35,274.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jul 2019

OK

Date: 15.07.2019
YTSS11F

TAXI SERVICE HISTORY

Time: 16:47:12
Page: 1

Taxi Nos: SHA7767A Model: I-40 Reg Date: 18.06.2015 Workshop: LY

Serviced on: 12.04.2019 / 08:34:00 Time Out: 12.04.2019 / 11:18:33
Remarks: (Next PM-30/05/2019 time-08:30 [INSP])
Job Card Nos: 602961024 Type: JP Odometer Reading: 625,889

PM/PROBLEM REPORTED

HI2 HYUNDAI I-40 DOCKING 2
INSP PRE-VICOM INSPECTION
17.1 Wiper Blade/Washer [wiper blade change]
H000 Mechanic Team Repair - Ng Jui Chun
S010 All Belts (except T/Belt)
S011 Engine/Transmission Service
S020 All Hoses & Clips (Check/Adjust/Replace)
S010 Brake System
S011 Tyres (Pressure Check)
S012 Tyre Rotation
S011 Undercarriage, Steering linkage & joints
S010 All Lightings
S021 All harness & connectors
S022 (i40) Check top hose bracket
S023 Check diesel / engine oil leakage
S025 Check vehicle boot hinges
S030 Illegal fittings, modifications & fusebox
S031 All seat belts & camera
S050 Check battery lines & squareclip secured
S051 Check battery terminal secured
S052 Check Hi/Low fan relay
S053 Check engine harness pastic bracket
S054 Check top hose scuffing
S055 Check control harness (injector side)
S056 Check injector fuel return hose and clip
S057 Check fusebox connector (driver side)
S011 All coolant, fluid, water
S021 Service A/C filter and Radiator
S022 Clear A/C drain pipe
QC QC TEST BY LAT - Ho Wee Beng
S010 Fire Extinguisher - Ng Jui Chun

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC OIL FILTER	1.000 EAC
2	HYUNDAI INJECTOR GASKET(33818-27000)	4.000 EAC
3	I40VC V-RIBBED BELT	1.000 EAC
4	I40VC FILTER-AIR CLEANER	1.000 EAC
5	I40VC/IONIQ WIPER BLADE 26" (DRIVER)	1.000 EAC
6	I40VC/IONIQ WIPER BLADE 16" (PASSENGER)	1.000 EAC
7	I40V2 BRKT ASSY-ROLL ROD	1.000 EAC
8	SHELL SYN ENGINE OIL SAE 5W-30	4.510 L

REMARKS

SN	DESCRIPTION
1	HI2 - 40,000 KM

Remarks: (Next PM-18/07/2019 time-08:30)

Job Card Nos: 602987699

Type: JP

Odometer Reading:

643,177

PM/PROBLEM REPORTED

HI3 HYUNDAI I-40 DOCKING 3
 10.1 Lighting - External [CHECK ALL LIGHTING]
 14.1 Tyre Bald/Uneven Wear [CHECK ALL TYRES]
 15.5 Undercarriage Noisy - Fron- Phuah Boon L[iWHEN MOVING ON UNEVEN ROAD
]
 H000 Mechanic Team Repair - Phuah Boon Lai
 S010 AllBelts (except T/Belt)
 S011 Engine/Transmission Service
 S020 All Hoses & Clips (Check/Adjust/Replace)
 S010 Brake System
 S011 Tyres (Pressure Check)
 S012 Tyre Rotation
 S011 Undercarriage, Steering linkage & joints
 S010 All Lightings
 S021 All harness & connectors
 S022 (i40) Check top hose bracket
 S023 Check diesel / engine oil leakage
 S025 Check vehicle boot hinges
 S030 llegal fittings, modifications & fusebox
 S031 All seat belts & camera
 S050 Check battery lines & squareclip secured
 S051 Check battery terminal secured
 S052 Check Hi/Low fan relay
 S053 Check engine harness pastic bracket
 S054 Check top hose scuffing
 S055 Check control harness (injector side)
 S056 Check injector fuel return hose and clip
 S057 Check fusebox connector (driver side)
 S011 All coolant, fluid, water
 S021 Service A/C filter and Radiator
 S022 Clear A/C drain pipe
 QC QC TEST BY LAT - Ho Wee Beng

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40VC OIL FILTER	1.000 EAC
2	I40VC DIESEL FUEL FILTER	1.000 EAC
3	I40VC PAD KIT-RR DISC BRAKE	1.000 SET
4	I40VC HANKOOK 205/60R16 H724	1.000 EAC
5	SHELL SYN ENGINE OIL SAE 5W-30	4.650 L

REMARKS

SN	DESCRIPTION
2	HI3 - 60,000 KM

 Date: 15.07.2019
 YTSS11F

TAXI SERVICE HISTORY

 Time: 16:47:12
 Page: 3

 Serviced on: 24.06.2019 / 08:30:00 Time Out: 24.06.2019 / 15:46:20
 Date: 24.06.2019 / 15:46:20

17.0 Mechanical Team Repair - Eyok Shenn Chaw
17.8 Others [A/T]
QC QC TEST BY LAT - Lim Say Aik

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	I40V3 COMPLETE AUTOMATIC TRANSMISSION	1.000 EAC
2	I40VC CONVERTER ASSY-TORQUE	1.000 EAC
3	TEXAS FULLY SYN ATF SP IV	4.050 L
4	TEXAS FULLY SYN ATF SP IV	4.960 L
5	I40SOV2 FRONT WHEEL BEARING	2.000 EAC

REMARKS

SN	DESCRIPTION
3	

Serviced on: 11.07.2019 / 16:10:00 Time Out: 00.00.0000 / 00:00:00
Remarks: (OD 11.07.19 -FIRE CASE)
Job Card Nos: 305310762 Type: OD Odometer Reading: 0

Serviced on: 11.07.2019 / 17:05:32 Time Out: 11.07.2019 / 17:55:18
Remarks: (FIRE CASE TOW-CXL FEE)
Job Card Nos: 305310796 Type: 21 Odometer Reading: 0

Serviced on: 11.07.2019 / 19:14:22 Time Out: 11.07.2019 / 20:00:00
Remarks: (FIRE CASE TOW-KD)
Job Card Nos: 305310784 Type: 21 Odometer Reading: 0

Verify by: _____

*****End of report*****

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to renege policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2019 11:48
Date Of Accident	11/07/2019 16:10
Exact Location Of Accident	ALONG MIDDLE RD TWDS NICOLL HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7767A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	YEO WAY PIENG
NRIC No	S1307888B
Date Of Birth	15/04/1958
Occupation	OUTDOOR
Date Of Driving Pass	13/07/1979
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90214204
Fax Number	
Contact Number	
Email Address	YEOWP@GMAIL.COM.SG

Address	BLK 30 JALAN ENAM #05-06
Postcode	390030
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- FIRE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GiA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CD. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **Luke Wei Yang**
NRIC/FIN No.:

COMFORT TRANSPORTATION PTE LTD

1-1 6-1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached
(Annex A1)

I/We declare the foregoing particulars are true in every respect.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wai Yiang
NRIC/PIN No.:

SKETCH PLAN

Not able to provide
taxi on fire case

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per attached
(Annex A1)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Loke Wai Yiang
NRIC/TIN No.:

Annex A1

Statement

Date: 12/7/19

To: Officer-in charge,

I, YEO WAY PIENG ^{Relief's}
(hijer's name) NRIC S1307888/B, of vehicle SHA 7747

would like to share my experience of the accident/ incident as follows:

Arrived 4pm my Hiner Mr Peh Eng Hong handed over the vehicle to me to start my shift. I drove for about 10-20km. Vehicle was in good condition. Arrived 4.20pm I received a booking to Beach Road. Upon arriving to the destination white smoke started to come out of the exhaust. I had to cancel my booking. After cancelling my booking I drove to middle road and park along the road towards Nicoll high way before Beach road traffic light junction. I call my Hiner to tow or not to tow as the white smoke was getting worse. While asking he advised a pedestrian where a flame lit up in front of the vehicle grill. I quickly took my valuable items and got out of the vehicle. The pedestrian engaged the Fire department.

During my driving before the incident I did not smell, feel and see anything wrong with the vehicle.

Your sincerely,

Yao

(Signature)

Name of Hijer:

Date: 12/7/19

Hiner - PA

PEH ENG HENG

Investigating Officer SPR OKE BAY

Witness - OSWALD EDWARDS

Team: ARC Repair OD(CLSO)1

JOB CARD

Sales Order:


JC NO: 305310762

STOMER:		REGN NO.	SHA7767A	MILEAGE
RMS		MAKE:	HYUNDAI	FUEL
STOMER NO. 7010045		MODEL	I-40	E 1/2 F
DRESS: 383 SIN MING DRIVE		YR OF MANU	18.06.2015	DATE/TIME IN
Singapore SINGAPORE 575717		CHASSIS CODE	KMHLB41UMFU069584	11.07.2019 16:10
65508755		TARGET DATE		COMPLETION DATE/TIME
ACCOUNT CARD NO.				

Accident Date: 11.07.2019
NATURE: OD 11.07.19 -FIRE CASE

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgment Slip

Exit Pass

Vehicle No.: **SHA7767A** **JU**

Vehicle No.: **SHA7767A**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7767A

MAKE :

MODEL : HYUNDAI i40

Fire Case

DATE 15/7/2019

Total 05 pages

JU

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,265.90
	Bonnet Rubber (LH)			\$ 12.40
	Bonnet Rubber (RH)			\$ 12.40
	Bonnet Hinge (LH/RH)	\$	41.00	\$ 82.00
	Bonnet Lock			\$ 36.90
	Bonnet Absorber	\$	58.10	\$ 116.20
	Bonnet Insulator			\$ 196.50
	Bonnet Seal			\$ 38.30
	Bonnet Insulator Clips			\$ 8.40
	Bonnet Cable			\$ 28.60
	Radiator Grille			\$ 1,110.10
	Radiator Grille H Emblem			\$ 39.50
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 99.20
	Front Bumper Reinforcement			\$ 402.10
	Front Bumper Grille (LH/RH)	\$	93.60	\$ 187.20
	Front Bumper Grille Airduct (LH/RH)	\$	26.20	\$ 52.40
	Front Bumper Centre Grille			\$ 178.60
	Front Bumper Centre Grille Top Garnish			\$ 80.00
	Front Bumper Lip			\$ 54.90
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH)	\$	24.60	\$ 49.20
	Front Bumper Side Bracket	\$	14.30	\$ 28.60
	Front Bumper Retainer Mounting	\$	9.20	\$ 18.40
	Headlamp Support Top Cover			\$ 222.60
	Headlamp Support Panel Assy			\$ 907.40
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	Headlamp Halogen Bulb (LH/RH)	\$	14.40	\$ 28.80
	Radiator			\$ 698.30
	Radiator Fan Blade,Cowling,Motor Assy			\$ 792.95
	Radiator Bracket (RH/LH)	\$	6.50	\$ 13.00
	Radiator Hose Upper			\$ 36.50
	Radiator Hose Lower			\$ 36.50
	Radiator Expansion Tank			\$ 28.30
	Radiator Guard	\$	20.00	\$ 40.00
	Horn Unit (LH/RH)	\$	73.80	\$ 147.60
	Horn Wire			\$ 156.50
	Front Fender (LH/RH)	\$	566.30	\$ 1,132.60
	Front Fender Apron Panel (LH/RH)	\$	637.00	\$ 1,274.00
	Front Fender Shield (LH/RH)	\$	174.90	\$ 349.80
	Front Fender Mudflap (LH/RH)	\$	16.20	\$ 32.40
	Front Fender Signal Lamp (LH/RH)	\$	47.40	\$ 94.80
	Front Fender Retainer	\$	24.60	\$ 49.20
	Front Fender Guard	\$	120.00	\$ 240.00
	Air Cleaner Assy			\$ 118.60
	Air Filter			\$ 63.70

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Air Cleaner Cover			\$ 47.80
	Air Duct			\$ 134.60
	Air Flow Sensor			\$ 285.50
	Resonator Tank Hose			\$ 151.00
	Air Cleaner Bottom Assy			\$ 325.00
	Resonator Tank Hose			\$ 151.00
	Aircon Blower Motor Unit			\$ 1,056.40
	Aircon Expansion Valve			\$ 219.50
	Aircon Sensor Pressure - Suc/Liq			\$ 238.10
	Aircon Condenser			\$ 927.50
	Aircon Receiver			\$ 71.50
	Aircon Suction & Liquid Hose			\$ 624.00
	Aircon Discharge Hose			\$ 162.60
	Aircon Blower Motor			\$ 271.90
	Aircon Compressor			\$ 2,578.00
	Aircon Evaporation Coil & Heater Unit			\$ 2,077.00
	Aircon Control Assy			\$ 983.70
	Battery Tray			\$ 52.00
	Battery Stay			\$ 20.90
	Front Door (LH/RH)	\$	2,256.40	\$ 4,512.80
	Front Door Rubber	\$	290.50	\$ 581.00
	Front Door Glass (LH/RH)	\$	228.20	\$ 456.40
	Front Door Gear / Regulator (LH/RH)	\$	250.60	\$ 501.20
	Front Door Hinge Upper (LH/RH)	\$	36.10	\$ 72.20
	Front Door Hinge Lower (LH/RH)	\$	41.10	\$ 82.20
	Front Door Check (LH/RH)	\$	39.20	\$ 78.40
	Front Door Inner Lock (LH/RH)	\$	290.80	\$ 581.60
	Front Door Key Lock Set (LH/RH)	\$	186.50	\$ 373.00
	Front Door Inside Handle (LH/RH)	\$	42.50	\$ 85.00
	Front Door Outer Handle (LH/RH)	\$	36.30	\$ 72.60
	Front Door Outer Moulding (LH/RH)	\$	47.10	\$ 94.20
	Front Door Mirror Assy (LH/RH)	\$	670.00	\$ 1,340.00
	Front Door Power Motor, LH			\$ 172.70
	Front Door Power Motor, RH			\$ 296.40
	Front Door Module, LH			\$ 250.60
	Front Door Module, RH			\$ 250.60
	Front Door Trim Board (LH/RH)	\$	973.50	\$ 1,947.00
	Door Centre Pillar Outer (LH/RH)	\$	2,527.80	\$ 5,055.60
	Door Centre Pillar Inner (LH/RH)	\$	254.70	\$ 509.40
	Door Pillar Inner Garnish	\$	31.70	\$ 63.40
	Frt Safety Belt (Assy) (LH/RH)	\$	475.40	\$ 950.80
	Frt Safety Belt Buckle	\$	53.00	\$ 106.00
	Front Pillar Upper Cover	\$	83.50	\$ 167.00
	Front Windscreen Glass			\$ 1,017.80
	Front Windscreen Moulding			\$ 113.30
	Front Windscreen Pillar Outer (LH/RH)	\$	1,745.50	\$ 3,491.00
	Front Windscreen Pillar Inner (LH/RH)	\$	310.70	\$ 621.40
	Front Windscreen Enforcement (LH/RH)	\$	1,163.30	\$ 2,326.60
	Front Windscreen Pillar Inner Garnish (LH/RH)	\$	117.60	\$ 235.20
	Sun Visor	\$	282.00	\$ 564.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Wiper Blade		\$ 73.60	\$ 147.20
	Wiper Motor			\$ 576.00
	Wiper Arm		\$ 56.00	\$ 112.00
	Wiper Panel Top Garnish			\$ 91.20
	Wiper Link			\$ 426.00
	Wiper Container			\$ 61.90
	Wiper Container Motor			\$ 75.00
	Front Wheel Rim (LH/RH)		\$ 325.30	\$ 650.60
	Front Wheel Hub Cap (LH/RH)		\$ 107.10	\$ 214.20
	Front Wheel Bearing		\$ 150.90	\$ 301.80
	Front Shock Absorber (Assy) (LH/RH)		\$ 342.20	\$ 684.40
	Front Shock Absorber Mounting (LH/RH)		\$ 108.80	\$ 217.60
	Front Drive Shaft (LH/RH)		\$ 1,030.80	\$ 2,061.60
	Rack & Pinion Assy			\$ 969.60
	STG Tie End		\$ 62.60	\$ 125.20
	Stabilizer Bar			\$ 252.30
	Stabilizer Bar Bush (LH/RH)		\$ 16.40	\$ 32.80
	Stabilizer Bar Link		\$ 61.10	\$ 122.20
	Brake Caliper (LH/RH)		\$ 677.15	\$ 1,354.30
	Stabilizer Bracket		\$ 24.00	\$ 48.00
	Front Suspension Lower Arm (LH/RH)		\$ 529.30	\$ 1,058.60
	Front Chasis Member		\$ 1,060.70	\$ 2,121.40
	Knuckle Arm (LH/RH)		\$ 552.00	\$ 1,104.00
	Timing Cover Assy			\$ 535.80
	Timing Cover Upper			\$ 485.30
	Timing Cover Lower			\$ 454.20
	Timing Gear			\$ 213.00
	Timing Belt			\$ 244.50
	Timing Tensioner Assy			\$ 260.80
	Fan Belt			\$ 116.20
	Fan Idler Pulley			\$ 179.70
	Fan Belt Tensioner Bearing			\$ 263.40
	Brake Master Pump			\$ 411.80
	Brake Booster Pump			\$ 664.10
	Engine Mounting			\$ 456.30
	Oil Sump			\$ 435.60
	Oil Pump			\$ 1,089.85
	Engine Under Cover			\$ 334.60
	Engine Crossmember			\$ 2,094.40
	Engine Lower Cover			\$ 56.30
	Front Cushion Seat (LH)			\$ 3,151.20
	Front Cushion Seat (RH)			\$ 5,992.00
	Engine Mtg (Front)			\$ 235.30
	Engine Mtg (Rear)			\$ 279.60
	Engine Support Bracket Assy			\$ 546.60
	Gearbox			\$ 14,808.00
	Gearbox Mounting			\$ 215.40
	Gearshift Assy			\$ 969.60
	Roof Panel			\$ 1,463.00
	Roof Moulding		\$ 46.80	\$ 93.60

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Roof Upholstery			\$ 2,875.00
	Instrumental Panel			\$ 1,664.40
	Dashboard Complete			\$ 852.20
	Dashboard Re-Inforcement Bar			\$ 658.80
	Console Box Assy			\$ 1,920.00
	Console Box Cover			\$ 427.45
	Dashboard Speedo Meter Assy			\$ 2,880.00
	P/Stg Hose & Bracket			\$ 76.45
	Power Steering Pump			\$ 754.20
	Power Steering Tank			\$ 181.70
	Power Steering Pressure Hose Assy			\$ 614.30
	Power Steering Outlet Hose & Bracket			\$ 76.45
	Power Steering Pipe Assy			\$ 76.45
	Power Steering Pulley			\$ 68.15
	Water Pump			\$ 812.40
	Alt / P.Stg V-Belt CRDI			\$ 74.05
	Alternator Assy			\$ 1,115.50
	Fuel Pump Rubber Seal & Hose			\$ 192.00
	Fuel Injector			\$ 1,680.00
	Starter Motor Assy			\$ 790.60
	Vacum Pump Relay			\$ 288.00
	Vacum Pump (1)			\$ 539.30
	Steering Wheel			\$ 871.90
	Steering Shaft			\$ 1,440.00
	Steering Column & Shaft Assy			\$ 1,264.55
	Steering Column			\$ 504.00
	Steering Flexible Joint			\$ 552.00
	Steering Wheel Horn Button Assy			\$ 864.00
	ECU Bracket			\$ 81.70
	ECU Unit			\$ 2,817.80
	Oil Cooler - Tube Assy-P/Stg			\$ 267.10
	Inter Cooler			\$ 1,032.50
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	Hose B To Inter Cooler			\$ 229.70
	Hose C To Inter Cooler Inlet			\$ 294.50
	Pipe To Inter Cooler			\$ 167.05
	Pipe To Inter Cooler Outlet			\$ 244.55
	Controller (PWN)			\$ 504.70
	ABS Sensor	\$	234.00	\$ 468.00
	Wiring-Engine			\$ 3,326.00
	Wiring-Front			\$ 1,960.80
	Wiring-ECM			\$ 3,243.00
	Wiring-FEM	\$	168.00	\$ 336.00
	Wiring Battery			\$ 1,191.30
	Actuator - Swirl Control			\$ 814.60
	Inhibitor Switch			\$ 104.40
	MTV Set Assy			\$ 2,760.00
	Engine Assy			\$ 19,267.80
	Auto Gear Oil			\$ 110.40
	Engine Top Cover			\$ 386.00

