

22/01/2002

ASS. REC. BY:

REF: CS/CTI 19013272/UTP302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ong Chin Piat

of CTI

Date/Time: 29.1.19 13.30pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: WC 8911E

Insured: WC 61185

at Workshop m/s Focus Auto

Tel: 6886 9097

of 1 Kaki Bukit Ave 6 #102-48

Policy No: DM CV SN/6297719033

Claim No: SVM190203379102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17.7.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 29.1.19 1.50p.m.

Person Contacted: Mr Lan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

WC 8911E NA/CTI19012660/24 DOA = 17/7/19

WC 61185

"

"

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

27A31371

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

have video. Rear drum dented.

15/8/19 2/2 & 4020 confirmed with MR Wong
(Red: 312: 43%)

RECEIVED 19 AUG 2019

Veh No: WC8911EYr Regn: 4 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU C/H 525

c.c

15681

Colour

white/silver

A/C:

Insured / Std / NI / NA

Sp. Reading

113755

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JALCYH 525E7000205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Order~~ / Jammed / Leaked / Burnt orBrake: ~~Order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

295/2022-5

R:

Kapsen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Chao Yang

Front

Rear

R/Bal.

6/6

mm

R/Bal.

6/6 6/6

mm

L/Bal.

6/6

mm

L/Bal.

6/6 6/6

mm

D.O.A.

17/7/19

D.O.I.

30/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1/5 Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Preli. Report

1) 19/8 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS, \$

) Photos

) Others

Report Format:

TP

Lump Sum / I.B.I. (\$ 4020)

TOTAL

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2019		29 Jul 2019 13:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by insurer]				
Insured:	YA HUAN TRANSPORT PTE LTD, Co. Reg. No.: 201610485W			
Main Claimant:	SAAY ENGINEERING PTE. LTD., Co. Reg. No.: 201607121K			
Vehicle Reg. No.:	WC8911E	Date of Loss:	17/07/2019 12:00 - :59 [51 Months and 4 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D203379C02	Policy/Cover Note No.:	DMCVSN16297719033	
Vehicle Reg. No. (Insured):	WC6118S	Policy No. (Claimant):	CV1/GA400381/1	
		Excess:	S\$0.00	
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/08/2019]			
Driver/Custodian (Insured):	CUI AIDONG (47 / Male) , NRIC: G2037155U Email:			
Adj Asg. Remarks:	please assign Mr Marcus Chua to conduct SJE. to contact Mr Lau LC at 6886 9097 / claims@focusauto.com.sg to arrange for survey. thank you			
ASSOCIATED MAIL RECEIVED View All Compose Case Mail				
There are no mail for this case.				
<div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div>				
No results.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	121K

Vehicle Details

Vehicle No.:	WC8911E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	6WG1422730
Chassis No.:	JALCYH52SE7000205
Maximum Power Output:	-
Open Market Value:	\$86,512.00
Original Registration Date:	13 Apr 2015
First Registration Date:	13 Apr 2015
Transfer Count:	2
Actual ARF Paid:	\$4,326.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	12 Apr 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$55,011.00
COE Rebate Amount:	\$31,371.00
Total Rebate Amount:	\$31,371.00

The information contained herein is correct as at 30 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/07/2019 17:05
Date Of Accident	17/07/2019 12:50
Exact Location Of Accident	PUNGGOL TIMOR PLOT #28 (SELETAR NORTH LINK)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	WC8911E
Insured/Policyholder	
Name Of Registered Owner	SAAY ENGINEERING PTE. LTD.
Co Reg No	201607121K
Email Address	SAAYENGINEERING@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-96786657
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CV1/GA400381/1
Cover Note Number	
Driver	
Name of Driver	SUBRAMANIAN SUDHAGAR
Passport No/FIN	G7981584K
Date Of Birth	06/02/1986
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2018
Driving Experience	0 YEAR AND 8 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83444606
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	570 CHOA CHU KANG STREET 52 #09-236 LIMBANG GREEN SINGAPORE
Postcode	680570
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

(1) Please refer to SKETCH PLAN (2) I, SUBRAMANIAN SUDHAGAR works for SAAY ENGINEERING PTE. LTD. and using the vehicle for work at the time of accident. (3) TYPE OF ACCIDENT shall be REAR COLLISION WHILE REVERSING

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WC6118S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



VEH A: WC8911E

VEH B: WC6118S

CEMENT PLANT

Punggol Timor Plot #28

(sektor North link)


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17/09/2019 around 1250 pm inside cement plant, punggol Timor Plot #28, I was inside my WC8911E for clearance to move forward^{toward exit} after loading. Suddenly I felt impact hitting my lorry (left side). After checking with site video recording, WC6118S was reversing backward & hit my lorry left side portion. & mixer drum badly damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder
Date & Time:


 Driver's Signature
(If driver is not the policyholder)
Date & Time:

 Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6886 9095 Email: focus.autopte ltd@yahoo.com.sg
GST:201004495R RCB NO:201004495R

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 6389 6111 FAX: 6222 1033

ATTN: Motor Claim Department

Your Ref No: WC 8911 E

Claim Type: Third Party

Accident Date: 17/07/2019

TP Veh Reg No: WC 6118 S

Estimate No: EST - 8911 - 1

Date: 06 Aug 2019

Policy No: CV1/GA400381/1

Veh Reg No: WC 8911 E

Make/Model: Isuzu CYH52S

Chassis No: JALCYH52SE7000205

Engine No: 6WG1422730

Reg. Date: 13 Apr 2015

Estimate Repair Cost for Vehicle No :WC8911E

PAGE:1/1

Description	U/Price	Quantity	Net Price S\$	Amount S\$
Net Price				
1 Fuel Tank	1,200.00	1 PC	1,200.00	
2 Fuel Tank Bracket	120.00	1 PC	120.00	
3 Fuel Tank Support	420.00	1 PC	420.00	
4 Air Tank Cover	380.00	1 PC	380.00	
			2,120.00	
	Less 15%		318.00	1802.00
Special Net				
5 Fuel Tank Protector Bar	980.00	1 PC	980.00	
			980.00	980.00
Labour				
6 Remove & Replace Fuel Tank	150.00	1	150.00	
7 Repair & Knocking Cement Drum	3,200.00	1	3,200.00	
8 Spray Painting	1,000.00	1	1,000.00	
			4,350.00	4,350.00
			Total	S\$ 7,132.00

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED THIRTY TWO FIFTY ONLY

For FOCUS AUTO PTE LTD

No 1 Kaki Bukit Ave 6 Auto Bay
#02-50 Singapore 417883
Tel: 6886 9095

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)





CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Jul 2019		29 Jul 2019 13:26 Edit Adj Rpt	S\$4,020.00 Edit Estimates	S\$4,020.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YA HUAN TRANSPORT PTE LTD, Co. Reg. No.: 201610485W								
Main Claimant:	SAAY ENGINEERING PTE. LTD., Co. Reg. No.: 201607121K								
Vehicle Reg. No.:	WC8911E	Date of Loss:	17/07/2019 12:00 - :59 [51 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203379C02	Policy/Cover Note No.:	DMCVSN16297719033						
Vehicle Reg. No. (Insured):	WC6118S	Policy No. (Claimant):	CV1/GA400381/1						
		Excess:	S\$0.00						
Repairer:	Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/08/2019]								
Driver/Custodian (Insured):	CUI AIDONG (47 / Male) , NRIC: G2037155U Email:								
Adj Asg. Remarks:	please assign Mr Marcus Chua to conduct SJE. to contact Mr Lau LC at 6886 9097 / claims@focusauto.com.sg to arrange for survey. thank you								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

































Claim Documents






*WC8911E (SNM19D203379C02)
[WC6118S]
TP
SAAY ENGINEERING PTE. LTD.
Jul 17 2019 12:00PM
[YA HUAN TRANSPORT PTE LTD]
Focus Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Focus Auto Pte Ltd (HQ)						Thumbnail	Print	
1	18/07/19 17:39	Accident Statement					1	Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
2	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
3	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
4	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
5	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
6	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
7	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
8	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
9	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
10	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
11	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
12	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
13	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
14	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
15	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
16	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
17	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
18	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
19	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
20	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
21	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
22	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
23	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
24	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
25	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
26	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
27	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
28	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
29	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
30	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
31	19/08/19 10:45	General View					1	Load JPG	<input checked="" type="checkbox"/>	
32	19/08/19 10:46	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
33	19/08/19 10:46	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	
34	19/08/19 10:46	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	19/08/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	19/08/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	19/08/19 10:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/07/19 13:23	INSD WC6118S GIA REPORT	 Load PDF	

Linked Accident Report Documents

			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 18:08	Accident Site Scene Recorder	 Load MP4	
2	17/07/19 18:12	Damage on Mixer Drum	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
1	18/07/19 17:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/07/19 18:02	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
9	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
10	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
11	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
12	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
13	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
14	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
15	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
16	17/07/19 18:03	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
17	17/07/19 18:04	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
18	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
19	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
20	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
21	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
22	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
23	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
24	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
25	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
26	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
27	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
28	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
29	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
30	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
31	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
32	17/07/19 18:05	Accident Vehicle	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Focus Auto Pte Ltd (HQ)	Thumbnail	Print
1	17/07/19 17:59	Sketch Plan	 Load TIF	
2	17/07/19 17:59	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013272/UTF3E2

Date: 22/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN16297719033

Claimant Vehicle
No : WC8911EInsured Vehicle
No : WC6118S

Date of Loss: 17/07/2019

Nature of Claim: TP

Claim
No: SNM19D203379C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC8911E**

Make & Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1422730

Reg. Date: 13/04/2015 (Man. Year: 2014)

Chassis No: JALCYH52SE7000205

Colour: White/Blue

Odometer: 113755 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5 (D)	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	CHAO YANG 6/6 mm	Rear Left Side:	KAPSEN 6/6/6/6 mm
Front Right Side:	CHAO YANG 6/6 mm	Rear Right Side:	KAPSEN 6/6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,782.00	800.00	1,982.00	71.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	3,220.00	1,130.00	25.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,132.00	4,020.00	3,112.00	43.63
+ GST 7.00/7.00% (S\$)	499.24	281.40	217.84	43.63
Nett Amount (S\$)	7,631.24	4,301.40	3,329.84	43.63

INSPECTION

Date of Assignment: 29/07/2019

Date Inspected: 30/07/2019 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Aug 2019)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC8911E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FUEL TANK	Repair	1,200.00 FL	*- FL
2	1		*FUEL TANK BRACKET	Not Necessary	120.00 FL	*- FL
3	1		*FUEL TANK SUPPORT	Not Necessary	420.00 FL	*- FL
4	1		*AIR TANK COVER	Not Necessary	380.00 FL	*- FL
5	1		*FUEL TANK PROTECTOR BAR	Bent	980.00 FS	*800.00 FS
					Sub Total (S\$)	3,100.00 800.00
					- List Item Discount on L Items 15.00/15.00% (S\$)	318.00 0.00
					Total Parts (S\$)	2,782.00 800.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REPLACE FUEL TANK	New	150.00	40.00
2	REPAIR & KNOCKING CEMENT DRUM	New	3,200.00	2,500.00
3	SPRAY PAINTING	New	1,000.00	680.00
Gross Labour Cost (S\$)			4,350.00	3,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >