

ASS. REC. BY:

REF:

CS/SHO19013285/ATP3

02

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Groh Pan Long

of

SMO

Date/Time:

29/7/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP5581E

Insured:

FBL 8737T

at Workshop m/s

96 Motor Sport Pte Ltd

Tel:

6702 6996

of

62 Kaki Bukit Ave 6 The Ark @ K13 S (417893)

Policy No:

D19MTMCA002942

Claim No:

CMTD1903627

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/7/19

CA / REV / REP. / REV 24 HRS

WPI

H.O.D. Endorsement:

A

Date/Time:

29/7/19 1630 HRS

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLP5581E X

FBL 8737T X

30/7 @ 10:27am - sent menimen pending estimate

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT

Person Contacted: \_\_\_\_\_

Veh No: SLP5581E Yr Reg: 6 17

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit. C.C. 1317

Colour: Pink AC: Insured / Std / Nil / NA

Sp. Reading 12535 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: GK 31221410

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: 185/55R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 29/07/19

Survey held at 96 Motorsports

Des. of Damages: Frl / Rear / O/S N/S U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Smpo.

lump sum \$21001 (Red: 5082.16 : 70%)  
5 days

mv:

pv:

Nett:

RECEIVED 02 SEP 2019

Date/Time, File Pass to?

Date/Time, File Return to?

1) 2/9 Typist

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic &amp; Add.

250

S + RS. SI

11

Photos

Others

TOTAL

261

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jul 2019		29 Jul 2019 15:49 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	JULYDEE BIN OMAR, ID: S8303228F								
Main Claimant:	MUHAMMAD QAIRUL AZIZ BIN ABDUL RAHMAN, ID: S8409129D								
Vehicle Reg. No.:	SLP5581E	Date of Loss:	28/07/2019 00:00 - :59						
Claim Type:	TP / CMTD1903627	Policy/Cover Note No.:	D19MTMC01002942 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	FBL8737T	Policy No. (Claimant):							
	Excess:								
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... (Handled by GNOH PAU LOONG - 63295217)								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 07/08/2019]</b>								
Adj Ass. Remarks:	WS: 67026996 JADE LIM -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SLP5581E (CMTD1903627)  
[FBL8737T]**

TP  
MUHAMMAD QAIRUL AZIZ BIN ABDUL RAHMAN  
Jul 28 2019 12:00AM  
[JULYDEE BIN OMAR]  
96 Motorsports Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 30/07/2019 10:27 AM.  
**To** pauloong.gnoh@sompo.com.sg  
**Subject** \*SLP5581E (CMTD1903627) [FBL8737T]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLP 5581E on 29/07/2019  
We are pending estimate from repairer.

Best Regards,  
**Denise Tay** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	175A
<b>Vehicle Details</b>	
Vehicle No.:	SLP5581E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G F PACKAGE A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	L13B1324508
Chassis No.:	GK31221410
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,686.00
Original Registration Date:	09 Jun 2017
First Registration Date:	09 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$9,686.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Jun 2027
PARF Rebate Amount:	\$7,264.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$35,520.00
<b>Total Rebate Amount:</b>	<b>\$42,784.00</b>

The information contained herein is correct as at 30 Jul 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/07/2019 14:16
Date Of Accident	28/07/2019 15:35
Exact Location Of Accident	BKE (AFTER WOODLANDS CENTRE ROAD)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5581E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUHAMMAD QAIRUL AZIZ BIN ABDUL RAHMAN
NRIC No	S8409129D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91089311
Alternative Phone No	OFFICE-91089311

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G F PACKAGE A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109973181 CLASSIC
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD QAIRUL AZIZ BIN ABDUL RAHMAN
NRIC No	S8409129D
Date Of Birth	22/03/1984
Occupation	OUTDOOR
Date Of Driving Pass	24/09/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91089311
Fax Number	
Contact Number	OFFICE-91089311
Email Address	NOEMAIL

Address	BLK 668A #08-704 EDGEFIELD PLAINS
Postcode	821668
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NUR AISAH BTE MOHD NAZARI GENDER: : FEMALE
Passenger 2	NAME: : MUHD SHAZIQ BIN MUHD QAIRUL AZIZ GENDER: : MALE
Passenger 3	NAME: : MUHD SHADZIN BIN MUHD QAIRUL AZIZ GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL8737T
Vehicle Make/Model/Colour	KYMCO / XCITING 400i ABS
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	

Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name MUHAMMAD QAIRUL AZIZ BIN ABDUL RAHMAN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLP5581E  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name NUR AISAH BTE MOHD NAZARI (PASSENGER)  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLP5581E  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**Muhammad Qairul Aziz (S3354175A)**  
 668A Edgefield Plains #08-704 S821888  
 Private Hire (M9-0008879-T)  
 Hp no. 81089311

Policyholder's Signature:  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:



**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Reporting to: [report@idac.com.sg](mailto:report@idac.com.sg)  
 Name:  
 NRIC/FIN No.:

29 JUL 2019

SKETCH PLAN

A: SLP5581E B: FBL8737T

Location: BKE (After woodland's Gate)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I was travelling straight on the stated venue. While driving, vehicle 'B' suddenly collided on to the left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.  
 Muha Qairul Aziz (53354175A)

888A Edgefield Plains #08-704 S&21686

Private Hire (M9-0008879-T)

Policyholder's Signature

Date & Time:

Driver's Signature  
 (If driver is not the policyholder)

Date & Time: 29 JUL 2019

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: [info@idac.com.sg](mailto:info@idac.com.sg)

Reporting Centre Personnel Signature

Name:

NRIC/FIN No.:

TP Sample

Deisel

VEHICLE NUM:

SLP 5581 E

MAKE & MODEL:

HONDA.FIT

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

GK3-1221410

ATTN:

NO.	DESCRIPTION - PARTS	QTY	UNIT	ADJUSTED PRICE
1	FRT SIDE MIRROR LH <i>Regr</i>	1	\$ 89.00	<i>+</i>
2	FRT SIDE MIRROR ASSY LH <i>Regr</i>	1	\$ 345.00	<i>+</i>
3	FRT DOOR LH <i>Regr</i>	1	\$ 804.60	<i>+</i>
4	FRT DOOR W/STRIP LH <i>Regr</i>	1	\$ 192.00	<i>+</i>
5	REAR DOOR LH <i>Deisel</i>	1	\$ 762.40	<i>✓</i>
6	REAR DOOR W/STRIP LH <i>Regr</i>	1	\$ 189.00	<i>+</i>
7	REAR ABSORBER LH <i>Regr</i>	1	\$ 210.00	<i>+</i>
8	REAR KUNCKLER AND BEARING LH <i>Regr</i>	1	\$ 235.70	<i>+</i>
9				
10				
11				
12				
13				
14				
31				
SUBTOTAL			\$ 2,827.70	\$ -
20%			\$ 565.54	\$ -
PARTS TOTAL			\$ 2,262.16	\$ -
SPECIAL NETT		QTY	PRICE	PRICE
1	REAR RIM LH <i>lot</i>	1	\$ 600.00	<i>480.</i>
2	STICKER ( CHROME RED ) <i>New</i>	1	\$ 1,000.00	<i>600.</i>
SPECIAL NETT 1			\$ 1,600.00	\$ -
LABOUR		QTY	PRICE	PRICE
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$ 1,400.00	<i>300</i>
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 1,200.00	<i>500</i>
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 150.00	<i>+</i>
4	TO R&R FRT DOOR ASSY <i>Fitting</i>	1	\$ 120.00	<i>+</i>
5	TO R&R REAR DOOR ASSY <i>Fitting</i>	1	\$ 120.00	<i>80.</i>



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19013285/ATF3N2

Date: 05/09/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01002942
Claimant Vehicle No :	SLP5581E	Insured Vehicle No :	FBL8737T
Date of Loss:	28/07/2019	Nature of Claim:	TP
		Claim No:	CMTD1903627

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLP5581E	Engine No:	L13B1324508
Make & Model:	HONDA FIT, 1.3 G F-Package (A)	Chassis No:	GK31221410
Reg. Date:	09/06/2017 (Man. Year: 2016)	Odometer:	112535 km
Colour:	Pink		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,862.16	1,689.92	2,172.24	56.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	960.00	2,360.00	71.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,182.16</b>	<b>2,649.92</b>	<b>4,532.24</b>	<b>63.10</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,100.00</b>		
<b>(\$\$)</b>	7,182.16	2,100.00	5,082.16	70.76
<b>+ GST 7.00/7.00% (\$\$)</b>	502.75	147.00	355.75	70.76
<b>Nett Amount (\$\$)</b>	<b>7,684.91</b>	<b>2,247.00</b>	<b>5,437.91</b>	<b>70.76</b>

## INSPECTION

Date of Assignment:	29/07/2019	
Date Inspected:	29/07/2019	Inspected At: 96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB Singapore 417893
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2019)
Parts: 144	HONDA FIT 1.3 G F-Package (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP5581E)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT SIDE MIRROR LH	Repair	89.00 FL	*.FL
2	1		*FRT SIDE MIRROR ASSY LH	Not Necessary	345.00 FL	*.FL
3	1		*FRT DOOR LH	Repair	804.60 FL	*.FL
4	1		*FRT DOOR W/STRIP LH	Not Necessary	192.00 FL	*.FL
5	1		*REAR DOOR LH	Dented	762.40 FL	*762.40 FL
6	1		*REAR DOOR W/STRIP LH	Not Necessary	189.00 FL	*.FL
7	1		*REAR ABSORBER LH	Not Necessary	210.00 FL	*.FL
8	1		*REAR KNUCKLER AND BEARING LH	Not Necessary	235.70 FL	*.FL
9	1		*REAR RIM LH	Cut	600.00 FS	*480.00 FS
10	1		*STICKER (CHROME RED)	Necessary	1,000.00 FS	*600.00 FS

F=Franchise part, S=SpotNet, L=ListItemDisc.

Sub Total (\$\$)	4,427.70	- List Item Discount on L Items 20.00/20.00% (\$\$)	565.54	1,842.40	152.48
Total Parts (\$\$)	3,862.16			1,689.92	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items  
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab. Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,400.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,200.00	500.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	150.00	0.00
4	TO R&R FRT DOOR ASSY FITTING	New	120.00	0.00
5	TO R&R REAR DOOR ASSY FITTING	New	120.00	80.00
6	TO R&R REAR UNDER CARRIAGE	New	150.00	0.00
7	TO CHECK AND ALIGH FOUR WHEEL ALIGNMENT	New	180.00	80.00
Gross Labour Cost (\$\$)			3,320.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >