

22/05/2002

ASS. REC. BY:

REF:

CS3/CT119013296/RC301

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

C12

Date/Time: 29.7.19 3.18pm

Estimated Cost:

Bill to:

OD-TP-WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKD 1030E

Insured: YP 4627K

at Workshop m/s Ama Autorail

Tel: 87783636

of 36 Toh Guan Road East #01-36

Policy No: DMCVSN18311118000

Claim No: SNMMD 203509C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.7.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 29.7.19 5.07p.m

Person Contacted: Melvin

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKD 1030E CS/FC116003425/KAbc2 DOA: 17/2/16

YP 4627K NA/MC17006612/h4 DOA 3/4/17

Dismantle: 2/8/2019

After repair: 6/8/2019

Form

REF: C71

ASSIGNMENT

0368
COE XPIRY: 2028/July

From: _____ Date: 30.7.2019

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SKD 1030E

at Workshop m/s Anna Autocare

of 36 Toh Guan Road East #01-36

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Akr 10-00A.M

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD 1030E Yr Pagn: 2008 July

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Mercedes Benz C200 Komp 1796

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 281809 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W002040412A166374

Gen. Cond: Good ☒ Fair ☐ Poor ☐ Burnt

Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or

Modi: Nil ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 235/35R19
R: _____

BS ☒ DUN ☐ EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>28/07/19</u>		D.O.I. <u>30/07/19</u>	

Survey held at AMA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range + Days
	Range - 4,000 - 5,000
	Repair Day - 5 days
	10/9/2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

) S + RS, _____ \$

) Photos

) Others

TOTAL

Report Format: PRQ

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

190

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		21 Aug 2019 11:16 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:				
Main Claimant:	NG XIN HUI, ID: S8772036E			
Vehicle Reg. No.:	SKD1030E	Date of Loss:	25/07/2019 17:00 - :59	
Claim Type:	TP / SNM19D203509C02	Policy/Cover Note No.:	DMCVSN18311118000	
Vehicle Reg. No. (Insured):	YP4627K	Policy No. (Claimant):	192300014M	
		Excess:	S\$0.00	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/08/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 29 July 2019 3:18 PM
To: Weng Kit
Cc: 'Jerone'; assignments
Subject: RE: OUR REF: SNM19D203509/CHONGBS -FW: Our Ref: SKD 1030E (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25 JULY 2019

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: Monday, 29 July, 2019 3:17 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Jerone' <jerone@chiaarul.com>
Subject: RE: OUR REF: SNM19D203509/CHONGBS -FW: Our Ref: SKD 1030E (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25 JULY 2019

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

Sincere Appraisal - Mr Dave
SK Auto Consultants - S. Kumanan

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Monday, July 29, 2019 3:02 PM

To: wengkit@chiaarul.com

Subject: RE: OUR REF: SNM19D203509/CHONGBS -FW: Our Ref: SKD 1030E (wk) PRE-REPAIR SURVEY NOTICE
ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25 JULY 2019

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 29 July, 2019 2:20 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; wengkit@chiaarul.com

Subject: OUR REF: SNM19D203509/CHONGBS -FW: Our Ref: SKD 1030E (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25 JULY 2019

Dear Boon Sen,

Please conduct PRS for SKD1030E.

Note : officer in charge is Boon Sen 63896171.

Thanks,
shumin

From: Weng Kit [<mailto:wengkit@chiaarul.com>]

Sent: Friday, 26 July, 2019 5:34 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: 'Jerone' <jerone@chiaarul.com>

Subject: Our Ref: SKD 1030E (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25 JULY 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 26 July 2019 for your attention.

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as

information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S • A. RAVIDASS • DON TAN

Our Ref : SKD 1030E (wk)

Your Ref : To be advised

26 July 2019

China Taiping Insurance (S) Pte. Ltd.

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : NG XIN HUI
ACCIDENT INVOLVING SKD 1030E & YP 4627K ALONG SIMS AVENUE ON 25
JULY 2019
PRE-REPAIR SURVEY NOTICE

1. We act for Ng Xin Hui, the owner of motor vehicle no. SKD 1030E which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. YP 4627K for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	AMA Autocare Pte Ltd
Address	36 Toh Guan Road East #01 - 36 Singapore 608580
Contact Person	Mr. Melvin (8778 3636)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	036E
Vehicle Details	
Vehicle No.:	SKD1030E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200 KOMPRESSOR
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	27195031077793
Chassis No.:	WDD2040412A166374
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$43,065.00
Original Registration Date:	23 Jul 2008
First Registration Date:	23 Jul 2008
Transfer Count:	2
Actual ARF Paid:	\$43,065.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$36,888.00
COE Rebate Amount:	\$33,090.00
Total Rebate Amount:	\$33,090.00

The information contained herein is correct as at 02 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2019 08:43
Date Of Accident	25/07/2019 17:50
Exact Location Of Accident	ALONG SIMS AVE TOWARDS PAYA LEBAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD1030E
Insured/Policyholder	
Name Of Registered Owner	NG XIN HUI
NRIC No	S8772036E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94780374
Alternative Phone No	OTHERS-94780374

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	192300014M
Cover Note Number	

Driver

Name of Driver	TEO KIT HWEE
NRIC No	S8710374I
Date Of Birth	17/04/1987
Occupation	INDOOR
Date Of Driving Pass	17/10/2005
Driving Experience	13 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94780374
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 416D BUKIT BATOK WEST AVENUE 8 # 08-758
Postcode	654461
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP4627K
Vehicle Make/Model/Colour	MITSUBISHI CANTER
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PALLHAMY BALAMURUGAN
NRIC/Passport Number	G8200539R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TEO KIT HWEE
------	--------------

Approximate Age	32
Injuries Sustain	
Injured person in which vehicle?	SKD1030E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 461D BUKIT BATOK WEST AVENUE 8 #08-758
Postcode	654461


Accident Sketch Plan

ALONG SIMS AVE TOWARDS ALIGNED ROAD

SKETCH PLAN

A = SKD1030E

B = YP4627K



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25/07/2019 @ around 1750HRS, I was driving Vehicle A (SKD1030E) on the 3rd lane along Sims Ave TOWARDS ALIGNED ROAD. Suddenly I felt an impact and realised that Vehicle B (YP4627K) had collided onto my right hand side of my vehicle A (SKD1030E). It was congested at that time and we both drives to the side of the road to exchange particulars for insurance claim. I felt pain on my neck and back after the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

Common Statement


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8710374I



Name

TEO KIT HWEE
(ZHANG JIEHUI)

張傑輝

Race

CHINESE

Date of birth

17-04-1987

Sex

M

Country/Place of birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8710374I

Name

TEO KIT HWEE
(ZHANG JIEHUI)

Birth Date 17 Apr 1987

Issue Date 17 Oct 2005



5504267



NRIC No. S8710374I



Date of issue

09-07-2015

APT BLK 4610 BUKIT BATOK WEST AVENUE 8 #08-758
SINGAPORE 654461

NRIC No. S8710374I

Date: 05/08/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

Class 2B Motorcycles <= 200 CC
Class 2 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the
driver; and motor tractors/vehicles <= 2500 kg

17 Oct 2005
17 Apr 2006

S/No. 9000047091

S8710374I

NP 42BA



Licence No. S8710374I

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8772036E



Name

NG XIN HUI

黄欣惠

Race

CHINESE

Date of birth

02-06-1987

Sex

F

Country of birth

INDONESIA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of NG XIN HUI

License Number: S8772036E

Name: NG XIN HUI

Birth Date: 02 Jun 1987

Issue Date: 16 Nov 2005

Barcode: 001380787E



4260157

NRIC No. S8772036E



Date of issue

08-08-2008

APT BLK 481D BUKIT BATOK WEST AVENUE 6 #08-158
SINGAPORE 654461

NRIC No. S8772036E

Date: 05/08/2018

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars <= 3000 kg with <= 7 passengers,
exclusive of the driver, and motor tractors
<= 2500 kg

PASS DATE
16 Nov 2005



NP 428A

...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2019		21 Aug 2019 11:16 Edit Adj Rpt	\$S\$0.00 Edit Estimates	\$S\$0.00 View Rpt		Pending for Survey Report Cancel Case






















Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	NG XIN HUI, ID: S8772036E								
Vehicle Reg. No.:	SKD1030E	Date of Loss:	25/07/2019 17:00 - :59 [132 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203509C02	Policy/Cover Note No.:	DMCVSN18311118000						
Vehicle Reg. No. (Insured):	YP4627K	Policy No. (Claimant):	192300014M						
		Excess:	\$S\$0.00						
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











Claim Documents

*SKD1030E (SNM19D203509C02)
[YP4627K]
TP
NG XIN HUI
Jul 25 2019 5:00PM
[-]
Ama Autocare Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	27/07/19 08:57	Accident Statement		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	27/07/19 08:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	27/07/19 08:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	27/07/19 08:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	27/07/19 08:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	27/07/19 08:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
2	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
3	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
4	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
5	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
6	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
7	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
8	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
9	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
10	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
11	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
12	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
13	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
14	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
15	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
16	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
17	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
18	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
19	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
20	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
21	21/08/19 16:11	General View		Load JPG	<input checked="" type="checkbox"/>
22	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
23	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
24	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
25	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
26	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
27	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
28	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
29	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
30	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
31	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	21/08/19 16:12	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
33	21/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	21/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	21/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	21/08/19 16:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 16:13	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	27/07/19 08:56	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/07/19 08:56	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	27/07/19 08:56	Driving License [Linked Accident Report Documents]	 Load TIF	
4	27/07/19 08:56	Owner ID [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	27/07/19 08:57	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	27/07/19 08:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/07/19 08:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/07/19 08:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/07/19 08:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/07/19 08:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	27/07/19 08:56	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/07/19 08:56	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
3	27/07/19 08:56	Driving License	 Load TIF	
4	27/07/19 08:56	Owner ID	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19013296/R1CF3E2

Date: 17/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18311118000

Claimant
Vehicle No : SKD1030EInsured
Vehicle No : YP4627K

Date of Loss: 25/07/2019

Nature of Claim: TP

Claim
No: SNM19D203509C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD1030E**

Make & Model: MERCEDES-BENZ C200, 1.8 Kompressor (A)

Engine No: 27195031077793

Reg. Date: 23/07/2008 (Man. Year: 2008)

Chassis No: WDD2040412A166374

Colour: Grey

Odometer: 281809 km

Engine Capacity: 1796 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19

Rear Tyre Size: 235/35 R19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 30/07/2019 Inspected At:

Ama Autocare Pte Ltd (HQ)
36 Toh Guan Road East, #01-36
Singapore 608580

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	143	MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD1030E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >