ASS, REC. B	r R	ER CS CT	1190133	33/R/V	d3n2	Initroctions	
gaven: -	Kasul	ASSI	GNMENT	(Office)			- n
From (Perror	i): Chong Boon 8	n of	CT	1	Du	e/Time: 23	7/1985.479
Estimated Co	ost:		Bil	to:			, , , , , , , , , , , , , , , , , , , ,
OD TP W	STTP RES / OD RES	EVA/INV/	MV /-CS				
To Inspect V	chicle No:	SGY !	5409H		Insured:	GBB	6258A
	m/s	Borneo	Motor		Tel:	9336	6875
of	2	penden	Cresces	4		1	,
Policy No:	DMCVSH3	5149 1900	00	Isim No:	SHI	EDCEPIN	283002
Sum Insured				Excess;			
Makz of Veh (Client's Recor					D.0	D.A. 13/0	7/2019
CA / REV	/ REP. / REV 24 HR	S				LO,D. Endorseme	447
Date/Time:	04/7/10/01/3UM	Person Cont	ngted:	guyhi.		cle_IN_OUT	)
Date/Time	Action/Instruction	Tolomolt					
28/8/19	final fig &	9511.11.0	(Do.1	300/- 6	21190	C	( L. mail
	8	1011.140	( KeCı	3000.6	0, 5419	CONTINK	of by email

220

Lung-Sum / TLUFTS

9511-40

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

And the state of t	Northed	Test Submitted	Adli Assigned	Adj Rpt	Adt Subr	miled	20% Authled	Status	
Main	30 Jul 2019	Est Subrimites	30 Jul 2019 12:46 Edit Adj Rpt					Pending for Report Cancel Case	Survey
	Main	Re	ference		Claim Details		Documen	ts	Show All
CLAIM S	UBFOLDER D	ETAILS				[Create	ed by insurer]		
Insured:									
Main Claimant:	MAK KIE	N WEI, ID: S77	20874G						
Vehicle Re No.:	9- SGY540	5409H			Date of Loss:	13/07/2	2019 10:00 - :59		
Claim Typ	e: TP / SN	M19D203283C0	)2		Policy/Cover Note No.: DMCVSN30514919000				
Vehicle Re No. (Insured)	GBB625	BA			Policy No. (Claimant):	AZRRZI 19U DMT			
(11120100)					Excess:	5\$0.00			
Repairer:	Borneo I	Motors (S) Pte Lt	d (Pandan) 2 P	andan Cresci	ent, 128462 Wes	t Coast -	Tel: 66311857		
Handling Insurer:	China Ta	iping Insurance	(Singapore) Pt	e. Ltd. (HQ	) - Tei: 6389 611	1 [Har	ndled by Chong Be	oon Sen]	
Claimant's Insurer:	MSIG In	surance (Singapo						1 - 00/0/	1/20103
Adjuster:	LKK Aut	o Consultants Pte	Ltd (HQ) - Tel	6256-3561	[Handled by I	MOHD R	ASUL] [Final	Rpt due 08/08	9/2019]
ASSOCIA	ATED MAIL R	ECEIVED						View All Com	pose Case Mail
There are	no mail for thi	s case.							
ALL ASS	OCIATED TA	sks <sup>[]</sup>				View	All Search Tasks	Create New Ta	sk Complete
Due Da	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	y Type Task	Group Sub	ject Har	idler Assign	ned By	Completed O	n Created	On Done

## Nivitha (LKK Auto)

From: Chong Boon Sen < boonsen.chong@sg.cntaiping.com>

Sent: Tuesday, 23 July 2019 5:47 PM

To: Ashlyn Chng

Cc: Suraidah B Saidi PTCBC; 'assignments'

Subject: RE: Direct Settlement (ST) - Accident involving SGY5409H & GBB6258A DOA

13/07/2019

### WITHOUT PREJUDICE

Dear Sir.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK.

Please proceed to survey the third party vehicle on WP basis.

Thank you.

## Chong Boon Sen

Claims Executive Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sq.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Ashlyn Chng [mailto:Ashlyn.Chng@inchcape.com.sg]

Sent: Tuesday, 23 July, 2019 4:46 PM

To: Chong Boon Sen <br/>
<br/>boonsen.chong@sg.cntaiping.com>

Cc: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>

Subject: RE: Direct Settlement (ST) - Accident involving SGY5409H & GBB6258A DOA 13/07/2019

Importance: High

Dear Boon Sen,

We would like to choose XING QUO QIANG to conduct the assessment.

Appreciate if you can revert on the liability the soonest.

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

From: Tan Kah Leong < Kahleong Tan@sg.cntaiping.com>

Sent: Wednesday, 17 July 2019 3:12 PM

To: Ashlyn Chng < Ashlyn. Chng@inchcape.com.sg>

Ce: Suraidah B Saidi PTCBC < Suraidah B. Saidi aincheape.com.sg>

Subject: RE: Direct Settlement (ST) - Accident involving SGY5409H & GBB6258A DOA 13/07/2019

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

## Without Prejudice

Dear Ashlyn,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIA	N LING
LOW S	AR HUEI
SEE CH	EW SENG
MOHD	FADHILAH BIN OSMAN
XING C	UO QIANG
KENNE	TH KONG
HONG	FOOK CHOY
CHUA	WEIJIE
MARCU	JS CHUA
HENRY	NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

## Tan Kah Leong

Assistant Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited, if you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, 17 July, 2019 3:11 PM

To: Tan Kah Leong < Kah Leong . Tan @sg.cntaiping.com>

Subject: FW: Direct Settlement (ST) - Accident involving SGY5409H & GBB6258A DOA 13/07/2019

From: Ashlyn Chng [mailto:Ashlyn.Chng@inchcape.com.sg]

Sent: Tuesday, July 16, 2019 10:03 AM

To: Claims Dept of CTI Ce: Suraidah B Saidi PTCBC

Subject: Direct Settlement (ST) - Accident involving SGY5409H & GBB6258A DOA 13/07/2019

Hi.

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured GBB6258A thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$130 per day x no. of days as recommended by your appointed surveyor.

Kindly have your in-house surveyor to contact our Motor Claim Assessor, Shashi @ 9336 6875 / 6631 1864 located at 2 Pandan Crescent / Level 4 for an appointment to inspect our client's vehicle (currently vehicle is NOT in the workshop).

## As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Regards, Ashlvn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.lexus.com.sg | www.hino.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

## Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 28 August 2019 9:06 AM

To:

Shashitharan PTCBC; Rasul (LKKAuto); SUR

Subject:

RE: SGY5409H final bill

Dear Shashi,

## WITHOUT PREJUDICE

Confirm amount \$9511.40 before GST @ 6 working days.

# Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shashitharan PTCBC <Shashitharan@borneomotors.com.sg>

Sent: Tuesday, 27 August 2019 2:28 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR

<sur@lkkauto.com>

Subject: RE: SGY5409H final bill

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Thursday, August 22, 2019 5:32 PM To: Shashitharan PTCBC; Rasul (LKKAuto); SUR

Subject: RE: SGY5409H PHOTOS

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Shashi.

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

-Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 15 August 2019 3:35 PM

To: Shashitharan PTCBC < Shashitharan@borneomotors.com.sg >; Rasul (LKKAuto) < Rasul@lkkauto.com >; SUR

<sur@lkkauto.com>

Subject: RE: SGY5409H PHOTOS

Dear Shashi,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----

From: Shashitharan PTCBC <Shashitharan@borneomotors.com.sg>

Sent: Friday, 2 August 2019 11:09 AM

To: Rasul (LKKAuto) < Rasul@lkkauto.com >; SUR < sur@lkkauto.com >

Subject: SGY5409H PHOTOS

Your message is ready to be sent with the following file or link attachments:

20190802\_110631

20190802 110641

20190731 161152

20190731\_161156

20190731 161201

20190731 161219

20190731\_161328

20190731\_161330

20190731\_161351

20190731 161354

20190802\_110532

20190802\_110549

20190802\_110626

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled. This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and

	MOTOR ACCIDENT REPORT
note Of Parish 16 - 1 - 10	OS Les Date Of Accident: 13 Jul 2017 Time: [0.5
	78 by pare of Accident: 12 27 501.1
Exact Location Of Accident Ang me Kin Ave 1	/ Selangor Darul Ehsan □ / Negeri Sembilan □ / Melaka □ / Pahang □
	LE DETAILS (INSURED/POLICY HOLDER)
Vehicle Registration Number: S645401H	Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No :
Name Of Registered Owner: Mak Kun Wes  Mobile Number: 9/9/4/970 3 Alternative No:	Empli Address & 1770 colour - co
10.17.17.3	Email Address: Kienwei 770 yahuu con sg
Vehicle Particulars  Manufacturer: Toyota ☐ Lexus ☐ Suzuki ☐ Hino ☐	Model: Lacela
Exact Purpose for which vehicle was being used at time of accid	00.1211
Are you claiming under your own insurance policy for repair to	in the contract of the contrac
Vehicle Category: Private Car ☑ Commercial Vehicle □	Others   Reporting Only   Third Party (1)
Insurance Company	United Li
Name of Insurance Company: Ph 516 on the max of	y c
Type Of Coverage: Comprehensive ☑ Third Party ☐ Fleet Policy: Yes ☐ No ☐	Third Party Fire and/or Theft □  Policy / Cover Note No:
1 Mary 1	Policy / Cover Note No: A 288 7 1394 GMY
THE RIGHT WAR	NRIC/ Passport / FHHNo: 577 208 74 6- Occupation: Indoor ≥ Outdoor □
Date Of Birth: 27 Jul 1977 Date Of Driving Pass: 11 DC 1998	Gender Male Female   Gender
	Alternative No.
15141113	
With the A P. Howard Court	
Email Address: VIEWWE, 770 jq hoo-Com- Was driver an employee of the Insured's Company? Yes	the transport of the state of t
	61.17
Vehicle Registration Number of Driver's Own Vehicle (if applica	ole):
Insurance Company of Driver's Own Vehicle (if applicable):	
WILLIAM STATES	L INFORMATION OF THE ACCIDENT
Type Of Accident: Rear collision	
Number of Passengers in the above vehicle (Including Driver):	2 / If more than 2 Pax Please fill ANNEX B
INVESTIGATION CONTRACTOR	PASSENGER 1
Name: MAK Har Teng Chio	Gender Male 🗆 Female 🗵
Weather Conditions: Clear Ø Raining □ Others □ (If oth	
Road Surface: Wet □ Dry Ø Others □ (If others, please s	state condition):
Was any body injured in the Accident? No ☑ Yes □	
DUSTRICHER PROGRAM DE MAN DE MAN	
Was any injured conveyed to hospital by ambulance? No 🖾	Yes □
Was any injured conveyed to hospital by ambulance? No 🗹 Was any foreign vehicle involved in this accident? No 🗹	
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗹 Number of vehicles involved in the accident:	Yes D Vehicle No Vehicle type:
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗹 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furn	Yes □ Vehicle No Vehicle type:
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🖾 Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn Witness Name:	Yes  Vehicle No Vehicle type:  iish witness details column below   Email:
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗹 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furm Witness Name:   Contact No. Was there any other vehicle or property damaged? No 🔎	Yes □ Vehicle No Vehicle type:  Sish witness details column below    Email:  Yes □
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🖾 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furm Witness Name:   Contact No Was there any other vehicle or property damaged? No 🖾 Was there any video captured by Car Camera? No 🗷 Yes	Yes □ Vehicle No: Vehicle type:  hish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗹 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furm Witness Name:   Contact No. Was there any other vehicle or property damaged? No 🖾 Was there any video captured by Car Camera? No 🖾 Yes Was the accident reported to the police? No 🖂 Yes	Yes □ Vehicle No Vehicle type:  It witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑     (If yes, please state which Police Station):
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗷 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furm Witness Name:   Contact No. Was there any other vehicle or property damaged? No 🗵 Was there any video captured by Car Camera? No 🗵 Yes Was the accident reported to the police? No 🗵 Yes 🗆 Was notice of intended Prosecution given? No 🗵 Yes	Yes □ Vehicle No: Vehicle type:  Itish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑ (If yes, please state which Police Station):   (If yes, please state against whom):
Was any injured conveyed to hospital by ambulance? No 🗵 Was any foreign vehicle involved in this accident? No 🗹 Number of vehicles involved in the accident: Was there any witness? No 🗵 Yes 🗆 If yes, please furm Witness Name:   Contact No. Was there any other vehicle or property damaged? No 🖾 Was there any video captured by Car Camera? No 🖾 Yes Was the accident reported to the police? No 🖂 Yes	Yes □ Vehicle No: Vehicle type:  Itish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑ (If yes, please state which Police Station):   (If yes, please state against whom):
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗹  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furning the second of the s	Yes □ Vehicle No: Vehicle type:  Itish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑ (If yes, please state which Police Station):   (If yes, please state against whom):
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗵  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗵  Was there any video captured by Car Camera? No 🗵 Yes  Was the accident reported to the police? No 🗵 Yes 🗆  Was notice of intended Prosecution given? No 🗵 Yes 🗆  I have been approached by unknown person(s) soliciting/offeni  DETAILS OF OTHER VEHICLE P	Yes □ Vehicle No: Vehicle type:  hish witness details column below    Email:  Yes □  Are accident scene photos available for attachment? No □ Yes ☑  (If yes, please state which Police Station):  (If yes, please state against whom):  Ing accident claims assistance. No ☑ Yes □
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗹  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furning the second of the s	Vehicle No:  Vehicle type:  Ish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑     (If yes, please state which Police Station):   (If yes, please state against whom):   ng accident claims assistance   No □ Yes □     ROPERTY 1 (Please fill Annex A if more vehicles involved)
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗹  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗵  Was there any video captured by Car Camera? No 🗵 Yes  Was the accident reported to the police? No 🗵 Yes 🗆  Was notice of intended Prosecution given? No 🗵 Yes 🗆  I have been approached by unknown person(s) soliciting/offerin  DETAILS OF OTHER VEHICLE P  Vehicle Registration Number: 1 5 5 6 2 5 8 74  Details Of Properties Damage in Accident:  Vehicle Category:	Vehicle type:  Ish witness details column below    Email:   Yes       Are accident scene photos available for attachment? No   Yes       (If yes, please state which Police Station):   (If yes, please state against whom):   ng accident claims assistance   No     Yes       ROPERTY 1 (Please fill Annex A if more vehicles involved)    Vehicle Make/Model/Colour:
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗹  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗵  Was there any video captured by Car Camera? No 🗵 Yes  Was the accident reported to the police? No 🗵 Yes 🗆  Was notice of intended Prosecution given? No 🗵 Yes 🗆  I have been approached by unknown person(s) soliciting/offerin  DETAILS OF OTHER VEHICLE P  Vehicle Registration Number: 1 5 5 6 2 5 8 74  Details Of Properties Damage in Accident:  Vehicle Category:	Vehicle type:  Ish witness details column below    Email:   Yes       Are accident scene photos available for attachment? No   Yes       (If yes, please state which Police Station):   (If yes, please state against whom):   ng accident claims assistance   No     Yes       ROPERTY 1 (Please fill Annex A if more vehicles involved)    Vehicle Make/Model/Colour:
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗵  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗵 Yes  Was there any video captured by Car Camera? No 🗵 Yes  Was the accident reported to the police? No 🗵 Yes 🗆  Was notice of intended Prosecution given? No 🗵 Yes 🗆  I have been approached by unknown person(s) soliciting/offerin  DETAILS OF OTHER VEHICLE P  Vehicle Registration Number: 155 & 258 PA  Details Of Properties Damage in Accident:  Vehicle Category:	Vehicle type:    Sign
Was any injured conveyed to hospital by ambulance? No 🗵  Was any foreign vehicle involved in this accident? No 🗹  Number of vehicles involved in the accident:  Was there any witness? No 🗵 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗵 Yes  Was there any video captured by Car Camera? No 🗷 Yes  Was the accident reported to the police? No 🗷 Yes 🗆  Was notice of intended Prosecution given? No 🗵 Yes 🗆  I have been approached by unknown person(s) soliciting/offerin  DETAILS OF OTHER VEHICLE P  Vehicle Registration Number: 155 6 258 P  Details Of Properties Damage in Accident:  Vehicle Category:	Vehicle type:  Ish witness details column below    Email:   Yes       Are accident scene photos available for attachment? No   Yes       (If yes, please state which Police Station):   (If yes, please state against whom):   ng accident claims assistance   No     Yes       ROPERTY 1 (Please fill Annex A if more vehicles involved)    Vehicle Make/Model/Colour:
Was any injured conveyed to hospital by ambulance? No 🗷  Was any foreign vehicle involved in this accident? No 🗷  Number of vehicles involved in the accident:  Was there any witness? No 🗷 Yes 🗆 If yes, please furn  Witness Name:   Contact No.  Was there any other vehicle or property damaged? No 🗷  Was there any video captured by Car Camera? No 🗷 Yes  Was the accident reported to the police? No 🗷 Yes 🗆  Was notice of intended Prosecution given? No 🗷 Yes 🗆  I have been approached by unknown person(s) soliciting/offerin  DETAILS OF OTHER VEHICLE P  Vehicle Registration Number: F 55 & 2 5 8 P  Details Of Properties Damage in Accident:  Vehicle Category:  Name of Driver: TAN Lichard (Clay III)  NRIC/Passport/FIN Number: S 7 5 0 4 4 5 9 (Chard	Vehicle No:  Vehicle type:  Ish witness details column below    Email:   Yes □     Are accident scene photos available for attachment? No □ Yes ☑     (If yes, please state which Police Station):   (If yes, please state against whom):   ng accident claims assistance. No ☑ Yes □     ROPERTY 1 (Please fill Annex A if more vehicles involved)   Vehicle Make/Model/Colour:   Contact Number   8 222 4 4 5 9
Nas any injured conveyed to hospital by ambulance? No 🗷  Nas any foreign vehicle involved in this accident? No 🗷  Number of vehicles involved in the accident:  Nas there any witness? No 🗷 Yes 🗆 If yes, please furnily in the second of th	Vehicle No: Vehicle type:    Signature   Final     Ves       Are accident scene photos available for attachment? No       Ves       (If yes, please state which Police Station):     (If yes, please state against whom):     (If yes, please state against whom):     (If yes, please fill Annex A if more vehicles involved)     Vehicle Make/Model/Colour:       Contact Number:                             Contact Number:                           Contact Number:                         Contact Number:                         Contact Number:                       Contact Number:                       Contact Number:                       Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                       Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                     Contact Number:                       Contact Number:                       Contact Number:                         Contact Number:                             Contact Number:                               Contact Number:

## SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
  facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No ::


Bishan Rd	AMK AVE 8
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 Ses 525814 real ended my car a two stationary as that time due to roof (glt Juith whichs and traffic all staining)
DESCRIBE CIRCUMSTANCES OF THE ACCIDE	ENT
Pate: 13th Jul 2019	
Time : 10.50 Am	
Weather consision clear	
Location along pany molein	u Ave 1 at junction of Rishan Rd & Amit Mores
my car was stationa	my at the above location due to said light
	des in first of me all waiting for red 1961.
All & a sudden Lo	my GRA 62584 masted into the back
of my our The Im	part was not big and there were no injury
but - there are so	me damages to my year atoo but and
himper.	
DECLADATION	
DECLARATION	

Policyholder's Signature Date & Time:

I/We declare the foregoing particulars are true in every respect.

SKETCH PLAN

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:











Co Reg No : 196700086Z GST Reg No : MR-8500000-9

Online Service Booking: www.toyota.com.sg Toyota Bodycare Centre No. 2 Fandan Crescent Singapore 128462 Tel no.: 6631 1188

Borneo Motors (Singapore) Pte Ltd

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail			Account No S1000020 / TPCLAIM		Customer Detail		
THIRD PARTY CLAIM			Document No 404B 0 #06-		Mak Kien Wei (Mai Jianwei) B Fernvale Lane -135 gapore 792404		
			Document Date 15/07/2019	Mobile	: 96949793		
ear:	Make Model	Reg Date	Veh Reg No Kilometer	s WIP h	io Ord	er No/Remarks	
HPXN	IP S6 ZGE	20R 26/01/2016	SGY5409H	0 467	70 6TP/	SGY5409H/15071	
hassis No	u Engine №	io.	Terms Service Engi	neer Vehic	de In Coll	ected On	
DGG20	W20J003406 2	ZR1682285	60 Shashitharan	//	/ 0.00	// 0.00	
Cd		Job/Parts Descri	ption	Qty	Unit Proprietis	Amount	
3 B B 5 S L B 5 S L B B 5 S L	BP-LAB2 R. BP-LAB2 TI CAEMRA BP-WS2 R. BP-LPO SI BP-LAB2 DI BP-LAB2 R. STRAIGHTEN ANI BP-RES2 R. BP-SLANT SI BP-MECH2 R. T21000-20 T21000-22 T52576-68020	DATE SURVIDAYS:  AUTHORISED OF THE CONTROL OF THE C	ON: ONDUCT LEAK TEST R MECHANISM AND REVERSE EN (PO# ) TALL REVERSE SESNOR AND PANEL F AREA EA	29/6 Rewry P 2.00 1.00 1.00	90010068 Lays 7/19 PILS Solve 108.00 200.00 46.00	180.00, 180.00, 540.00, 350.00, 180.00, 180.00, 180.00, 180.00, 216.00, 200.00, 46.00	
	Borneo Motors	Customer's Signat Please acknowledge receip			ess.		
			Others				

TO SECURITY GUARD

3939222

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES. DATE TIME

15/07/2019 10:50

VEHICLE NO:

SGY5409H

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTELTO



**Borneo Motors** 



Co Reg No : 196700086Z GST Reg No : MR-8500000-9

## ESTIMATE

Online Service Booking; www.toyota.com.sg Toyota Bodycare Centre No. 2 Pandan Crescent Singapore 128462 Tel no.: 6631 1188

Borneo Motors (Singapore) Pte Ltd

Download "My Toyota 56" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	/TPCLAIM		Custo	mer Detall	
THIRD PARTY CLAIM	Document No	Document No 0		Mr Mak Kien Wei (Mai Jianwei) 404B Fernvale Lane #06-135 Singapore 792404		
	Document Date 15/07/2	2019	Mobi	le: 96949	793	
Year Make Model Reg Date	Veh Reg No	Kilometers	)WI	PNo	Order No.	Remarks
5 HPXNP S6 ZGE20R 26/01/201	6 SGY5409H	0	4	6770 -6	TP/SGY5	409H/15071
Chassis No Engine No	Terms.	Service Enginee	r Ve	hicle in	Collected	On
PDGG20W20J003406 2ZR1682285	60 Shas	hitharan	/-	-/ 0.	00/-	-/ 0.00
. Cd Job/First Do	escription		Qty	Unit Price	Disc %	Amount
6 5 T52156-68030 L/RR BUMPE 7 6 T52159-68907 REAR BUMPE 8 7 T68105-68071 REAR BACK 9 8 T67005-68041 PANEL ASSY 0 9 T90975-02086 TOYOTA SYP 1 0 T75444-68010 LUGGAGE TOYOTA SYP 2 1 T81591-68020 LENS & BOI 3 2 T81561-68062 LENS, RR CO 4 3 T76811-68130 GARNISH, I 5 4 SP2061-12010 24 IG3 SENSOR  LICK Auto Consultants hence notify the Repairer of the following:  - To resurvey between the spray parting - To despite damaged parts of the following:  - The damy survey is on a "Without Particle of the following sensor of the following sens	maintain your Toyota. Serv	Con LH  XSVZ	5.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	354.70 290.30		20.56 97.46 591.86 1045.06 1477.36 72.26 41.16 294.16 354.76 290.36 151.66
For 6 an penalt of Borneo Mators Customer's S	Agnature	Change Summor	y	Total		12,518.0
Please acknowledge of	Lisbour	6	,898.00	GST 7.00		876.2
	Lubrica Others	mon/Fluid	0.00			

PLANETEAR ALONG PERFORATED LINE

3939223

TO SECURITY GUARD

3939223

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/07/2019

TIME 10:50

VEHICLE NO SGY5409H

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors** 

# TOYOTA

Co Reg No : 196700086Z GST Reg No : MR-8500000-9

THIRD PARTY CLAIM

Make

Download "My Toyota SG" app on Playstore or Appstore to access yo ESTIMATE count & more!

## Borneo Motors (Singapore) Pte Lt

Online Service Booking: www.toyota.com.sg

Toyota Bodycare Centre No. 2 Pandan Grescent Singapore 128462

Tel hustones Details

Mr Mak Kien Wei (Mai Jianwei) 4048 Fernvale Lane

#06-135

Singapore 792404

Mobile: 96949793

03/08/2019 Veh Reg No Reg Date

Kilometers

WIP No.

Order No/Remarks

These No.

Year

Engine No

Model

Account Detail

26/01/2016

2575409H

Account No

Document Date

DocumentMO20 / TPCLAIM

Service Engineer

Vertille In

6TE/SEY5409H/15071

	GZC Cd	304E00003406	22R16B22B5 60 Job/Parts Description	Shashitharan	29/0 Qty	7/2019 8.00 0 Unit Price Disc	03/08/2019 18:00 96 Amount
	Z	BP-SUNDRY	SUNDRIES				50.0
3	-	TP VEH NO.:	GBB 6258A ACC DATE: 13/07/	/19			13 Sept 4 Le
56		DATE-IN:	DATE SURVEY:		315		I Beech B
81		NO OF REPAIL BY: rasul 1k					
2	В	BP-LABZ	CHECK WIRING AND CONDUCT LA	KAK TEST			180.0
000000	00	BP-LAB2	R/1 BOOTLID SPOILER				180.0
5075-011	B	BP-LAB2	TRANSFER BOOT LID MECHANISH	M AND REVERSE			540.0
		CAEMRA					100 0
5	S	BP-WS2	REPL REAR WINDSCREEN				460.0
6	L	BP-LPO	SUPPLY SOLAR FILM (PO#				180.0
7	B	BP-LAB2	DRILL HOLE AND INSTALL REV		917		1440.0
B	В.	DP-LAB2	REPL ACC AFF PARTS AND PAN	E1-			
			AND REALLIGN ACC AFF AREA	The state of the s			1770.0
- 54	B	BP-RES2 BP-SLANT	RESRPAY ACC AFF AREA SUPPLY SEALANT (NETT)				80.0
COIII	20.00	BP-MECH2	RESET ECU UPON COMPLETION	OF REPAIR	19.0	AND DESCRIPTION	180:0
12	D S	721000-20	SIRA 210002-0 TACK G	O! (BLACK) SG	2.00	108.00	216.0
13	2	T21000-22	SIMA 210002-2 G+P 207 ADHESIVE PRI)			200.00	200.0
14	3	T52576-68020	RETAINER RR BUMPER		1.00	46.00	46.0
		Borneo Motors is the 6 months or 10,00	only authorised workshop to maintain your Toy 00 km (whichever comes first) to enjoy warranty	ota, Service your Toyota every benefits. Conditions apply.			
		For & on behalf of Borneo Motors	Customer's Signature	Change Summary	4 1 1	Total	
8			Please acknowledge receipt of whicle	Parts Labour Materials		Less	

Lubrication/Fluid Others.


404256

404256

03/08/2019 10:17



Amount Due



# **TOYOTA**

Co Reg No : 196700086Z GST Reg No : MR-8500000-9

THIRD PARTY CLAIM

Download "My Toyota SG" app on Playstore or Appstore to access yo ESTIMATE count & more!

## Borneo Motors (Singapore) Pte Lt

Online Service Booking : www.toyota.com.sg

Toyota Bodycare Centre No. 2 Fandan Crescent

singapore 1/0450

Mr Mak Kien Wei (Mai Jianwei) 4048 Fernvale Lane

#06-135

Singapore 792404

Mobile: 96949793

Vear Make Model Reg Date Veh Reg No V

Kilometers

WIPNO

Order No/Remarks

15 HPXNP 86 Chassis No. Engine No

Account Detail

26/01/2016

SGY5409H

Account No.

Document Date

DOSINGADARO / TPCLAIM

Service Engineer

4 6770 Vehicle In 6TP/SGY5409H/15071 Collected On

TTRSG20W20J003406	27R1682285 Job/Parts Description	Shashitharan 29/	07/2019 8:00 03/ Unit Price Disc %	08/2019 18.00 Amount
15 4 S52161-0K040 16 5 T52156-68030 17 6 T52159-68907 18 7 T68105-68071 19 8 T67005-68041 20 9 T90975-02086 21 0 T75444-68010 22 1 T81591-68020	PIECE, RR BUMPER SUPPORT RR BUMPER LR COVER RR BUMPER GLASS BACK DOOR FANEL ASSY, BACK DOOR EMBLEM, SYNBOL PLATE, LUGGAGE COMPT LENS & BCDY, RR	1:00 1:00 1:00 1:00 1:00	97.40 591.80 1045.00 1477.30 72.20 41.10	20.50 97.40 591.80 1045.00 1477.30 72.20 41.10 294.10
For 6 on behalf of	00 km (whichever comes first) to enjoy warranty Customer's Signature	Change Summary	Total	
Barneo Motars	Please acknowledge receipt of webicle	Parts Labour	700 7 00	9,511.4

Materials

Others

Lutrication/Fluid

4042570

665.80

0.00

4042570

03/08/2019



4,101.40

4,500.00


810.00

0.00

0.00

EST 7.00%

Amount Due



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19013333/R1VD3N2

Date:

19/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMCVSN30514919000

Claimant Vehicle No :

SGY5409H

Insured Vehicle No :

GBB6258A

Date of Loss:

13/07/2019

Nature of Claim:

TP

Claim No:

SNM19D203283C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGY5409H

Make & Model:

TOYOTA WISH, 1.8 CVT (A) 26/01/2016 (Man. Year, 2015)

Engine No: Chassis No: Odometer: 2ZR1682285 JTDGG20W20J003406

44398 km

Reg. Date: Colour:

Grey

Engine Capacity: Market Value/New Car 1798 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** 

Steering (Serviceable): Yes Engine Modification: Yes Footbrake (Serviceable): No Pre-accident Condition: Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Item		Repairer's 5,078.00 0.00	Adjuster's 4,231.40 0.00	Difference 846.60 0.00	Diff % 16.67
Labour Paintwork Labour	5	7,440.00 0.00	5,280.00 0.00	2,160.00 0.00	29.03
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	12,518.00	9,511.40	3,006.60	24.02
	+ GST 7.00/7.00% (S\$)	876.26	665.80	210.46	24.02
	Nett Amount (SS)	13 394 26	10 177 20	3.217.06	24 02

INSPECTION

Date of Assignment:

30/07/2019

Date Inspected:

29/07/2019 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)

2 Pandan Crescent Singapore 128462

Estimated Period of Repair:

6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Referen	ce					
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2019)				
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)				
Labour:	Repairer's	(Price-denominated Standard List)				
Print Code:		no print-code for SGY5409H)				
Validity:	These estimat numbers with	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info	: Items/values r	ot in reference catalogue are prefixed with an asterisk *.				

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SEALANT	Necessary	80.00 FS	*80.00 FS
3	2		*SIKA 182010 SIKA TACK GO (BLA) *SIKA 207. G+P ADHESIVE PRIMER	Necessary Necessary	216.00 FS 200.00 FS	*216.00 FS *200.00 FS
5 6	1		*L/R SIDE BPR RETAINER *PIECE ,RR BUMPER	Necessary Necessary	46.00 FS 20.50 FS	*46.00 FS *20.50 FS
7	1		*L/RR BUMPER SUPPORT *REAR BUMPER COVER	Necessary Deformed	97.40 FS 591.80 FS	*97.40 FS *591.80 FS
9	1		*REAR BACK DOOR GLASS	Necessary	1,045.00 FS	*1,045.00 FS
10	1		*PANEL ASSY ,BACK DOOR	Bent	1,477.30FS	*1,477.30 FS
11	1		*TOYOTA SYMBOL EMBLEM	Necessary	72.20 FS	*72.20FS
12	1		*LUGGAGE VALVE MATIC	Necessary	41.10FS	*41.10FS
13 14	1		*LENS & BODY ,LH *LENS ,RR COMB LH	Cracked Serviceable	294.10 FS 354.70 FS	*294.10 FS
15 16	1		*GARNISH ,BACK DOOR *1G3 SENSOR	Serviceable Serviceable	290.30 FS 151.60 FS	*-FS
F=Fn	nchise	part. S=SpcNe	ett.			F. 225 1225
				Total Parts (S\$)	5,078.00	4,231.40

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK WIRING AND CONDUCT LEAK TEST	New	180.00	180.00
2	R/I BOOTLID SPOILER	New	180.00	180.00
3	TRANSFER BOOT LID MECHANISM AND REVERSE CAMERA	New	540.00	540.00
4	REPL REAR WINDSCREEN	New	460.00	460.00
5	SUPPLY SOLAR FILM	New	350.00	350.00
6	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
7	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	New	3,600.00	1,440.00
8	RESPRAY ACC AFF AREA	New	1,770.00	1,770.00
9	RESET ECU UPON COMPLETION OF REPAIR	New	180.00	180.00
	Gross Labour Cost (S\$)		7,440.00	5,280.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >