

ASS. REC. BY:

REF: CS/MSG K1013336/k9f3

Special Instruction:

Surveyor: Kenny M

ASSIGNMENT (Office)

From (Person): Mund Ashik B Modiof MSIGDate/Time: 29.7.19 16.46p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 8682LInsured: YP 9349Eat Workshop m/s Supr/mx Auto ServiceTel: 64520715 - Winnie /of 176 sin Ming Drive #102-0192368619 Uncle ChewPolicy No: 29098105 MKCClaim No: 604197

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.7.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 30.7.19 9.29a.m

Person Contacted:

YukyiVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLS 8682L-X</u>
	<u>YP 9349E - CS/MSG K1013336/ TICF3 ROA - 22.7.2019</u>
<u>31/7/19 @</u>	<u>11.10am revised to Mund Ashik via Merimen.</u>
<u>18/07/20</u>	<u>Mr Chew said the vehicle had repaired & used check liability.</u>
<u>18/07/20 @</u>	<u>3.28pm checked with Ashik, OI have reporting & liability not clear.</u>
	<u>LS \$900, 2 days. (Red \$824.63, 48%)</u>

REF: MS19

ASSIGNMENT

From: _____ Date: 30.7.2019

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SLS 8682L

at Workshop m/s Supreme Auto Servis

of 176 Sin Ming Drive # 02-01

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLS 8682L Yr Regn: 09/10/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Priv

Colour: M. Grey

Sp. Reading: 24568P

Eng/No: _____

C/No: ZVW 50

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 14.5/1x 195/65R15

R: Agend 9

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. S mm

L/Bal. S mm

D.O.A. 1/1P

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

GIA not ready

Date/Time. File Pass to?

☐ : Preli. Report

1) 20/05 Typist

☐ : Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : MER-TP

Lump Sum H.B. (\$) 900

...CLAIM SUBFOLDER...(New Assignment)


CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2019 13:43		29 Jul 2019 16:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ZERO SPOT LAUNDRY SERVICE PTE LTD, Co. Reg. No.: 199707580W								
Main Claimant:	MCQUEENS RENTALS PTE LTD, Co. Reg. No.: 0								
Vehicle Reg. No.:	SLS8682L	Date of Loss:	21/07/2019 00:00 - :59 [21 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29098105MKC Coverage: 28/09/2018 - 27/09/2019						
Vehicle Reg. No. (Insured):	YP9349E	Policy No. (Claimant):							
		Excess:							
Repairer:	Supreme Auto Service Pte Ltd (HQ) 176 Sin Ming Drive #02-01, Sin Ming Autocare, 575721 Sin Ming - Tel: 6452 0715								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/07/2019]								
Adj Asg. Remarks:	on WP. Liab: dispute (NR) TP agree on SJE - assign LKK. Contact: 6452 8211								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

A: SLS 8682 L
B: YP 9349 E
C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving from Carrubill Road into Grange Road, turning right into service lane which leads to the drop off point of Mandarin Gallery beside Cinceleisure. Vehicle C stop along the side which is a double zig zag line to drop off passenger. I have no choice but to wait for vehicle C before I can move off. While waiting for vehicle C, a lorry, YP 9349 E made a right turn from the side lane into Grange Road. Vehicle B knocked onto the right rear side of my vehicle, causing damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

