

...CLAIM SUBFOLDER...(Pending for Survey Report)





























CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Pending for Survey Report
Main	25 Jul 2019		31 Mar 2020 12:00 Edit Adj Rpt	S\$533.30 Edit Estimates	S\$533.30 View Rpt		Cancel Case























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MUHAMMAD RIDHUWAN BIN MAJID , ID: S80035171								
Vehicle Reg. No.:	FBN2657U	Date of Loss:	22/07/2019 07:00 - :59 [10 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203471C02	Policy/Cover Note No.:	DMPCSN30618318000						
Vehicle Reg. No. (Insured):	SFE188U	Policy No. (Claimant):	MSD/VMS/18-388236-CA						
		Excess:	S\$0.00						
Repairer:	A.s.phoon Pte Ltd (HQ) BLK 36 TOH GUAN ROAD EAST, ENTERPRISE HUB #01-35, 608580 West Coast - Tel: 65150770								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/04/2020]								
View All Compose Case Mail									
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents















***FBN2657U (SNM19D203471C02)**
[SFE188U]















TP
MUHAMMAD RIDHUWAN BIN MAJID
Jul 22 2019 7:00AM
[-]
A.s.phoon Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	27/07/19 08:41	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
2	04/09/19 01:56	Accident Statement	 Load HTM	
3	04/09/19 01:58	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 09:00	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
9	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
21	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
22	31/03/20 12:55	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/07/19 09:04	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 09:04	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 09:05	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 09:05	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 09:05	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	27/07/19 08:41	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	27/07/19 08:41	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	27/07/19 08:41	Common Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	27/07/19 08:41	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
2	04/09/19 01:56	Accident Statement	 Load HTM	
3	04/09/19 01:58	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
12	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
16	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	24/07/19 09:00	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	24/07/19 09:04	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	24/07/19 09:04	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	24/07/19 09:05	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
4	24/07/19 09:05	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
5	24/07/19 09:05	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
6	27/07/19 08:41	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
7	27/07/19 08:41	Common Statement	 Load JPG	<input checked="" type="checkbox"/>
8	27/07/19 08:41	Common Statement	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013344/T1YF3E2
Date: 31/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30618318000
Claimant Vehicle No: FBN2657U Insured Vehicle No: SFE188U
Date of Loss: 22/07/2019 Nature of Claim: TP Claim No: SNM19D203471C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBN2657U Engine No: H336E0037479
Make & Model: YAMAHA CZD300A / XMAX300, 292cc Chassis No: MH3SH0841JK004722
Reg. Date: 28/08/2018 (Man. Year: 2018) Odometer: 0 km
Colour: Grey
Engine Capacity: 292 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R15 Rear Tyre Size: 140/70 R14
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	397.00	303.30	93.70	23.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	740.00	230.00	510.00	68.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	1,137.00	533.30	603.70	53.10

INSPECTION

Date of Assignment: 31/03/2020
Date Inspected: 31/07/2019 Inspected At: A.s.phoon Pte Ltd (HQ)
BLK 36 TOH GUAN ROAD EAST,
ENTERPRISE HUB #01-35
Singapore 608580
Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2020)
Parts:	N/A YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN2657U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PROTECTOR, MUFFLER	Cut	72.00 F	*72.00 FL
2	1		*COVER, SIDE 2	Cut	75.00 F	*75.00 FL
3	1		*FRONT FOOTBOARD RH	Cut	85.00 F	*85.00 FL
4	1		*MOLE, SIDE COVER 2	Cut	45.00 F	*45.00 FL
5	1		*REAR FOOTREST ASSY RH	Broken	60.00 F	*60.00 FL
6	1		*FRONT FENDER	Not Necessary	60.00 F	*- FL
Sub Total (\$\$)					397.00	337.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	33.70
Total Parts (\$\$)					397.00	303.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WORKMANSHIP	New	250.00	150.00
2	BODY CHASSIS REPAIR	New	250.00	0.00
3	TRANSPORTION TP-IDAC-WORKSHOP	New	120.00	80.00
4	TRANSPORTION 2 WAY TO REPAIR CHASSIS	New	120.00	0.00
Gross Labour Cost (S\$)			740.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >