

ASS. REC. BY: TanpinREF: EQI

ASSIGNMENT

From: _____

Date: 31/07/2019Veh No: SLZ 6875ZYr Regn: 2018, May

Estimated Cost: _____

Type: MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspection Vehicle No: SLZ 6875ZMake: Volkswagen Golf 1.0 C.C999at Workshop m/s volkswagenColour: whiteA/C: Insured / Std / NI / NAof 247 Alexandra RoadSp. Reading: 14873T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: WVW 333 443 JW 225250

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____

Excess: _____

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt orMake of Veh: 3pm (waiting)Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/55R16

R: _____

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: \$80K

Front

Rear

IDAC Accident Rpt: _____

Consistent? : Yes or No

R/Bal. 6 mmR/Bal. 6 mm

GIA / PR Seen: _____

Consistent? : Yes or No

L/Bal. 6 mmL/Bal. 6 mm

Est. Repairs: _____

days

Res.: Yes or No

D.O.A. _____

D.O.I. 31/7/19 3pm

Lum Sum: _____

%

3 Val.: Yes or No

Survey held at VW AlexandraCA / REV / REP. / 24 HRS sup

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____

Person Contacted: _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rebate: \$47,818

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐

Site Insp (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I: (\$)

☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)