

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. : B1 1384807

Page No. : 1 of 3

Date IN : 02/08/2019

Invoice Number : 2148204 / WSB

Cust. Svc. Advisor: Joseph Yaguel

Invoice Date : 11/09/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

## - CUSTOMER INFORMATION -

Mdm Wenny Tan  
Blk 564 Hougang Street 51  
#13-430

Singapore 530564

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. /  
SKE1819S

CHASSIS NO.  
EG22916

REGN. DATE  
31/08/2018

MODEL  
X1 SDRIVE18I

MILEAGE  
13588

## - - - - LABOUR 1 - - - -

To replace rear bumper and attachments, rear boot lid  
and attachments, tail end panel and interior tail trim  
etc including to pull and

NETT  
3,400.00

straighten trunk floor and knock out dented area caused by the  
accident. To remove and install body parts in order to carry out  
painting job.

To respray rear bumper, rear boot lid, tail end panel and  
trunk floor panel etc.

3,079.00

To tow accident vehicle to PML workshop.

195.00

To conduct water leak tests.

75.00

To remove and install rear windscreen glass to facilitate  
the repair job.

487.00

To replace rear silencer and clamping bush including  
alignment system and conduct checks for leak.

451.00

To remove and install rear hat-tray, rear seat, carpet  
and roof top lining to facilitate repairs.

742.00

To check electrical wiring systems and lightings at the  
rear section for proper function.

150.00

To carry out body cavity preservation.

451.00

(For cut panel).

Sundries

150.00

To mount accident vehicle on speed bench to facilitate pulling &  
re-alignment of body/chassis according to BMW specification

564.00

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

0.00

DATE OF ACCIDENT : 27.7.2019. 3RD PARTY CAR : SCR9982B.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO  
CONSULTANTS PTE LTD ON 1.8.2019 AT 3.00 PM. AUTHORISED

REPAIR BY MR VIC ALPEH FROM LKK ON 1.8.2019 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X10. THE AMOUNT IS SUBJECTED

0.00

TO INSURANCE COMPANY CONFIRMATION.

Total Labour 1: **9,744.00**

## - - - - PARTS - - - -

Retail  
Qty Price NETT

**Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**Repair Order No. : **B1 1384807**Page No. : **2 of 3**Date IN : **02/08/2019**Invoice Number : **2148204 / WSB**Cust. Svc. Advisor: **Joseph Yaguel**Invoice Date : **11/09/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**

TAILPIPE TRIM BLACK CHROME	1	110.55	110.55
RR BUMPER LH CORNER MOUNTING	1	141.90	141.90
EMBLEM GROMMET	2	0.80	1.60
BMW PLAQUE WITH ADHESIVE FILM	1	71.25	71.25
BOOTLID	1	1,230.50	1,230.50
INTERIOR TAIL TRIM	1	315.65	315.65
TAIL PANEL	1	401.75	401.75
RR BUMPER CARRIER	1	493.85	493.85
LETTERING S DRIVE 18I	1	96.15	96.15
LETTERING X1	1	64.10	64.10
BOOTLID SEALING	1	165.55	165.55
REAR BUMPER HEAT INSULATION	1	69.55	69.55
RR BUMPER RH CORNER MOUNTING	1	141.90	141.90
BLIND RIVET AVIBVLB	10	0.55	5.50
SCREW (SF PLUS M5X15)	5	0.55	2.75
PUNCH RIVET N4	20	0.55	11.00
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(S/L) SEAM SEAL 300ML	1	33.80	33.80
BLIND RIVET AVIBVLB	30	0.55	16.50
REAR BUMPER PANEL PRIMED (M/PDC)	1	1,185.70	1,185.70
REAR BUMPER TRIM PANEL BOTTOM (M/PD	1	297.80	297.80
MOUNTING SMART OPENER (M)	1	45.30	45.30
LOADING SILL COVER	1	143.95	143.95
EXPANDING RIVET	6	2.50	15.00
THERMAL PROTECTION LUGGAGE COMP. FL	1	48.90	48.90
STORAGE TROUG. LUGGAGE TRUNK FLOOR	1	224.20	224.20
(DG/SL) SOUND DEADENER 1160X700MM	1	105.55	105.55
EXPANDING RIVET WHITE	19	1.85	35.15
BLIND RIVET NUT M6	5	2.55	12.75
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG) CLEANER R1 (100ML)	1	26.15	26.15
BUMP STOP	6	3.50	21.00
EXPANDING RIVET WHITE	1	1.85	1.85
REAR SILENCER	1	1,465.05	1,465.05
SILENCER CLAMPING BUSH	1	54.30	54.30

Total Parts : **7,373.60**

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**Repair Order No. : **B1 1384807**Date IN : **02/08/2019**Cust. Svc. Advisor: **Joseph Yaguel**Page No. : **3 of 3**Invoice Number : **2148204 / WSB**Invoice Date : **11/09/2019**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**

Labour Charges :	<b>9,594.00</b>	Total Labour & Parts Charges :	<b>S\$ 17,117.60</b>
Parts Charges :	<b>7,373.60</b>	Less Insurance Excess :	<b>S\$ 0.00</b>
Lubricant/Misc :	<b>150.00</b>	Invoice Total Amount Exclude GST :	<b>S\$ 17,117.60</b>
		GST @ 7% :	<b>S\$ 1,198.23</b>
		Invoice Total Amount Include GST :	<b>S\$ 18,315.83</b>

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 18,315.83**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. Mr. Tan Fik from LKK ("name of surveyor") with respect to the amount claimed for S\$ 18315.83 (repair costs), S\$ 1000.00 (loss of use/rental) S\$ \_\_\_\_\_ (search fees) for vehicle no. SKE 1819S that was damaged pursuant to the accident which occurred on 27.7.2019 (date) along KPE Towards ECP P79K (location) involving vehicle no/s SCR 9981B.

This is pursuant to the inspection conducted on 1.8.2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Nenny Tan ("third party claimant") of vehicle no. SKE 1819S to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKE 1819S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_ day of \_\_\_\_\_ (month) 20\_\_\_\_ (year)

Signed by AIG appointed surveyor

  
Performance Motors Limited  
101 Alexandra Road  
Prime Darby Performance Centre  
Singapore 159941  
Chopped & Signed by "the workshop"



**AUTHORIZATION TO ACT**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**


I, WENNY TAN ("the third party claimant")  
of BLK 564 HOUGANG ST. 51 # 13-430 S (530564) (address),  
owner of SKE1819S (vehicle no.) hereby authorize  
Performance Motors Ltd  
("the workshop") to act for me with respect to my claim for repair costs and/or  
rental and/or loss of use ("claim") for my vehicle no. SKE1819S that was  
damaged pursuant to the accident which occurred on 27.7.2019 (date) along  
KPE towards ECP P79K (location)  
involving vehicle no/s SCR9982B ("the accident").

I further authorize the workshop to settle the above mentioned claim in a  
manner that they deem fit and the workshop is further authorized to receive  
payment further to settlement of my claim with payment cheque/s being made in  
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my  
behalf is on a without prejudice and without admission of liability basis insofar  
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this \_\_\_\_\_ day of \_\_\_\_\_ (month) 20\_\_\_\_ (year)

  
Signed by "the third party claimant"

  
Signed by "the workshop"

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SKE 1819 S	Model:	BMW
Date of Accident:	27.7.2019		

Global Sum Settlement:	[ ] Yes	[ ] No	
Repair Estimate	: \$	22088.38	
Final Repair Cost	: \$	18315.83	
Loss of Use	: \$	1000.00	10 days at \$ 100 per day
Rental (if any)	: \$		days
LTA / GIA Search Fee	: \$		
Others	: \$		
	: \$		
Final Settlement Sum	: \$	19315.83	

Is Third Party Workshop GIA Registered? [ ] YES [ ] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No  
BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	18315.83
2)	Wenny Tan	: \$	1000.00
3)		: \$	

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;

Survey Report; Medical Report / Bill (if any)



## Your booking confirmation JOZSUE

1 message

<booking@singaporeair.com.sg>  
To: desleendecinda@gmail.com

Sun, 7 Apr 2019 at 22:45

This is an automatically generated message. Please do not reply to this address.


## Your booking is confirmed

Booking Reference JOZSUE



Dear Ms Desleen Decinda Yeo Ying Fang,

You're all set for your trip! This email has all the details of your booking on singaporeair.com, and your e-ticket and receipt are attached. Remember to print these, or be sure you have easy access to them when you travel.

 [Manage booking](#)

 [View KrisFlyer account](#)

### Itinerary

Flight	Departs	Arrives
--------	---------	---------

1. Singapore to Jakarta - Total travel time: 1hrs 45mins

Status: Confirmed  
**ECONOMY LITE(K)**

<b>SQ 962</b>	<b>SIN 16:25</b>	<b>CGK 17:10</b>
Airbus	28 Jul (Sun)	28 Jul (Sun)
Industrie	Singapore, Changi , Terminal 2	Jakarta, Soekarno Intl , Terminal 3
A350-900		
Singapore		
Airlines	Flying time: 1hrs 45mins	

Cabin class: Economy (K)

2. Jakarta to Singapore - Total travel time: 1hrs 50mins


Status: Confirmed  
**ECONOMY LITE(K)**

Dear Sir/Mdm,

I am the driver of SKE 1819S when the accident took place on Saturday 27<sup>th</sup> July 2019 at around 645pm. My brother and grandmother were passengers.

I will be overseas in Jakarta from Sunday 28<sup>th</sup> July till Friday 2<sup>nd</sup> August but the accident report needs to be made on Monday 29<sup>th</sup> July 2019. My brother, Owen Yeo, will thus be making the accident report on my behalf.

Thanks and regards,

A handwritten signature in black ink, appearing to be 'Desleen Yeo', with a stylized, flowing script.

Desleen Yeo

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/07/2019 17:21
Date Of Accident	27/07/2019 18:45
Exact Location Of Accident	KPE TOWARDS ECP P79K
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE1819S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WENNY TAN
NRIC No	
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90283793
Alternative Phone No	OTHERS-93852981

### Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	

### Driver

Name of Driver	YEO YING FANG DESLEEN
NRIC No	
Date Of Birth	17/12/1990
Occupation	INDOOR
Date Of Driving Pass	15/01/2013
Driving Experience	6 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81896128
Fax Number	
Contact Number	
Email Address	DESLEENDECINDA@GMAIL.COM

Address	BLK 564 HOUGANG STREET 51 #13-430
Postcode	530564
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	SCR9982B (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : YEO YING LONG OWEN OCKMINDO GENDER: : MALE
Passenger 2	NAME: : ONG KIM ING GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCR9982B
Vehicle Make/Model/Colour	KIA CERATO BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SONG LIANGKAI LEONARD
NRIC/Passport Number	
Contact Number	97505153
Address	229 COMPASSVALE WALK #14-410

Postcode	540229
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	2
Passenger 1	NAME:       :
	GENDER:     :

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

29/07/19 4:46PM

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

### SKETCH PLAN



KPE towards ECP

A: SKF 18195  
B: JCR 9982B

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

was on KPE lane 1. Car in front braked sharply, our car also braked accordingly. Was about to move off again when our car got hit at the back.

I am submitting the report for Perleen Yeo as she went overseas on 28 July

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

for Beltrami  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 29/07/19 4:40 PM

Reporting Centre Personnel's Signature

Name: Performance Motors Limited

NRIC/FIN No.: 303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941