



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM19013377/Utd3e2

C/O : SEAH ONG & PARTNERS LLP
36 ROBINSON ROAD #12-03 CITY HOUSE
SINGAPORE 068877

Date : 16-09-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	PC 3239D	Veh. Inspected	SJG 2210S
Policy No.		Coverage (\$)	0.00
Claim No.	19.26285 S.CK.xy	Excess (\$)	0.00
Assign From	XIN YI	Assign Date	03/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JTDER12W503000240	Colour	GREY
Odometer	314024	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	FALKEN	5 mm
L/H Front Tyre	215/45 R17	FALKEN	5 mm
R/H Rear Tyre	215/45 R17	FALKEN	5 mm
L/H Rear Tyre	215/45 R17	FALKEN	5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	20/04/2018	Inspection Date	11/09/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR(O/S BODY):	5 Working Days
ESTIMATED NORMAL PERIOD FOR REPAIR (REAR):	2 Working Days