



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM19013377/Utd3e2

C/O : SEAH ONG & PARTNERS LLP  
36 ROBINSON ROAD #12-03 CITY HOUSE  
SINGAPORE 068877

Date : 16-09-2019



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

<b>Insured Veh.</b>	PC 3239D	<b>Veh. Inspected</b>	SJG 2210S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	19.26285 S.CK.xy	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	XIN YI	<b>Assign Date</b>	03/07/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1794
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	JTDER12W503000240	<b>Colour</b>	GREY
<b>Odometer</b>	314024	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/45 R17	FALKEN	5 mm
<b>L/H Front Tyre</b>	215/45 R17	FALKEN	5 mm
<b>R/H Rear Tyre</b>	215/45 R17	FALKEN	5 mm
<b>L/H Rear Tyre</b>	215/45 R17	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/04/2018	<b>Inspection Date</b>	11/09/2019
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>7 Working Days</b>
--	-----------------------