

Date: 26.07.2019
 Vehicle No: SLD8891D
 Model: VOLKSWAGEN SHARAN 2.0 - 2013
 Chassis: WVWZZZ7NZDV026205
 Reg.Year: 2013

Third Party Insurer: AIG
 Third Party Veh No: SMD7328J
 Date of Accident: 25.07.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR RH			REPAIR
2	REAR DOOR RH			REPAIR
			SUB TOTAL	\$0.00
			LESS 25%	\$0.00
			PARTS TOTAL	\$0.00

LABOUR CHARGES:

LABOUR CHARGES FOR KNOCKING, REPAIR, READJUST FRONT DOOR RH, REAR DOOR RH & ETC BACK TO PROPER CONDITIONS

2501
\$350.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT DEOR DOOR RH, REAR DOOR RH & ETC

4001
\$700.00

TO TUFF KOTE & UNDERSEAL MATERIALS

200 \$100.00 X

LABOUR TOTAL \$1,150.00

ONG TOTAL \$1,150.00

not wither
Recovery After Paint
3 days