(0871/1/3)

Surveyor: Tanjh | REF: AIG | 13396 | T1 (C)

ASSIGNMENT

From: | Date: 14.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 7756K

at Workshop m/s Performance

of 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: | Consistent? : Yes or No

GIA / PR Seen: | Consistent? : Yes or No

Est. Repairs: days | Res.: Yes or No

Lum Sum: % | 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: | Person Contacted: Han.

Veh No: SKV 7756K | Yr Regn: 2015, Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: BMW 420I | c.c 1997

Colour Brown. | A/C: Insured / Std / NI / NA

Sp.Reading 55165 | T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA 4A12806K07743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	C mm	R/Bal.	C mm
L/Bal.	C mm	L/Bal.	C mm
D.O.A.		D.O.I.	14/8/19 @ 11am

Survey held at PML

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) [ ] : Preli. Report [ ] : Final Report

Date/Time, File Return to? 2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: [ ] : Site Insp ($) [ ] : Interview ($) [ ] : Tech. Invs ($) [ ] : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: S + RS, SI

Photos

Others

TOTAL