

Denise Tay (LKKAuto)

From: MTCL@income.com.sg
Sent: Tuesday, 20 August 2019 4:00 PM
To: Denise Tay (LKKAuto)
Subject: FW: REQUEST CLAIM NUMBER

Hi,

All claims created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, 20 August 2019 11:23 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Request claim number

Date : 20/8/2019

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1057597-002	COMFORT DELGRO	SHD 6801A	GBH 3504C	14/8/2019	07:45	2706.00	1850
2	MT/1055681-002	SMRT TAXIS	SHC 4391J	SKX 2070C	29/7/2019	14:55	3287.18	700

Best Regards,

Denise Tay | Case Handler

Hello, NAC_PAYA_UBI_800601

[Change Language](#)

[Change Password](#)

[Log Out](#)

[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="29/07/2019 08:57"/>
Vehicle No. (For Motor)	<input type="text" value="SKX2070C"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5096069014-01		ANDREW LEONG KOK HUP	50339729G	GPC	AutoSecure Premium	SKX2070C	SKX2070C	30/11/2018	29/11/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 16:05
Date Of Accident	29/07/2019 14:55
Exact Location Of Accident	LORONG 2 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4391J
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	LIM BOO YONG
NRIC No	S1270725H
Date Of Birth	06/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	03/11/1976
Driving Experience	42 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 802
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG LORONG 2 TOA PAYOH AT THE SECOND RIGHT LANE AND HAD STOPPED DUE TO RED TRAFFIC LIGHT AHEAD. WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM BEHIND, THE VEHICLE SKX2070C FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKX2070C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Banyo
29/7/19
Driver's Signature
(If driver is not the policyholder)
Date & Time:

du 29/7/19
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 369K

Vehicle Details

Vehicle No.: SHC4391J
Vehicle to be Exported: No
Intended Deregistration Date: 30 Jul 2019
Vehicle Make: TOYOTA
Vehicle Model: PRIUS TAXI (SMRT)
Primary Colour: Maroon
Manufacturing Year: 2014
Engine No.: 2ZR5910259
Chassis No.: JTDKN36UX05742334
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$33,120.00
Original Registration Date: 16 May 2014
First Registration Date: 16 May 2014
Transfer Count: 0
Actual ARF Paid: \$8,368.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 15 May 2022
PARF Rebate Amount: \$5,857.00

Intended COE Rebate Details

COE Expiry Date: 15 May 2022
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$60,414.00
COE Rebate Amount: \$21,071.00
Total Rebate Amount: \$26,928.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Jul 2019

OK

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 30/07/2019

User ID : TuckFoo

Section A - Accident Details	
Registration Number	SHC4391J
Case Reference Number	TAX/07/19/2117
Registration Date	5/16/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM BOO YONG
Type of Accident	Head to Rear
Accident Date and Time	7/29/2019 2:55 PM
Accident Reported Date and Time	7/29/2019 4:08 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102605
Special Instruction to ARC, if any	TP
Prepared Date and Time	7/29/2019 11:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$0.00
Total Spray Cost	\$558.00	\$0.00
Total Spare Part Cost	\$1,489.74	\$0.00
Total Other Cost	\$360.00	\$0.00
TOTAL COST	\$2,914.74	\$0.00
Lump Sum Total	\$2,900.00	\$0.00
Number of Repair Days	4.0	5 days
Prepared / Adjusted By	Kim Ming Chin	
ARC / Surveyor Sign Off Date	29/07/2019 11:11 PM	
Signature		
Remarks	L/S repair, take after spray Finalize sent to spec@lkk.com	

Steve
Survey 30/7/19, 2:30pm

27/19

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 85 Woodlands Industrial Park East, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662823
 Accident Reporting Number : 88602572

Date Generated : 17/08/2019
 User ID : PehSuan

Section A - Accident Details	
Registration Number	SHC4391J
Case Reference Number	TAX07/19/2117
Registration Date	16/5/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LIM BOO YONG
Type of Accident	Head to Rear
Accident Date and Time	29/7/2019 2:55 PM
Accident Reported Date and Time	29/7/2019 4:08 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102605
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/7/2019 11:01 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,862.18	\$476.03
Total Other Cost	\$360.00	(\$176.03)
TOTAL COST	\$3,287.18	\$700.00 (LS)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kim Ming Chin	STEVE CHEN (LKK) / NTUC
ARC / Surveyor Sign Off Date	01/08/2019 3:30 PM	01/08/2019 1:45 PM
Signature		
Remarks		lump sum repair / after paint photo / FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR Steve Chen (LKK) / HP : 8322 8813 & Email:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 80 Woodlands Industrial Park EA, Singapore 737705
 FAX Number 63665582
 Estimator Telephone Number 63662621
 Accident Reporting Number 636621

Date Generated : 17/08/2019
 User ID : PehJoon

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1908-0178	Invoice Number	
Quotation Date	14.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$196.03)
Total Other Costs	\$360.00	(\$176.03)

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.81	25.00	\$12.08	Replace	Replace <i>nec</i>
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace <i>nec</i>
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check <i>NN</i> X
		52018-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given <i>NN</i> X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given <i>NN</i> X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check <i>NN</i> X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check <i>NN</i> X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check <i>NN</i> X
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given <i>NN</i> X
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given <i>NN</i> X
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given <i>NN</i> X
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given <i>NN</i> X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace <i>DD</i>
Total					\$2,308.41		\$476.03		

476.03
 + 200.00
 + 220.00

 896.03
 - 20%

 716.82
 4/5 \$700/-

3807.90

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 30/07/2019

User ID : TuckFoo

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	200
Total Labour	\$507.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY BUMPER BEAM	\$180.00	X
Total Spray Painting & Panel Beating	\$558.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	X
TO REPLACE SUNDRY PARTS	\$100.00	X
TO WASH AND VACUUM	\$60.00	X
Total Other Costs	\$360.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	✓ N/A
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	✓ N/A
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.27	Replace	? X N/A
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	X N/A
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	X N/A
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	? X N/A
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	? X N/A
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	? X N/A
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$72.20	25.00	\$54.15	Replace	X N/A
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.57	Replace	X N/A
		76891-47020	BUMPER LIP REAR	1.00	\$226.90	25.00	\$171.68	Replace	X N/A
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	1.00	\$514.50	25.00	\$385.88	Replace	X N/A
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	X N/A
Total					\$2,308.41		\$1,862.18		✓ DD

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

37 35.41



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19013398/Etf3s2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 22-08-2019
	Code: INC4



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 2070C	Veh. Inspected	SHC 4391J
Policy No.	5096069014-01	Coverage (\$)	0.00
Claim No.	MT/1055681-002	Excess (\$)	0.00
Assign From		Assign Date	30/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36UX05742334	Colour	MAROON
Odometer	743445	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R15	FIRENZA	5 mm
L/H Front Tyre	195/50 R15	FIRENZA	5 mm
R/H Rear Tyre	195/50 R15	FIRENZA	5 mm
L/H Rear Tyre	195/50 R15	FIRENZA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/07/2019	Inspection Date	30/07/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4391J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @ \$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	NOT NECESSARY	139.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
			2,382.90	476.03
LABOUR				
PANEL BEATING & BODYWORK.			507.00	200.00
SPRAY PAINT.			558.00	200.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM.			120.00	-
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			1,425.00	420.00
GRAND TOTAL			3,807.90	896.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				700.00

Report Ref No. NS/INC19013398/Etf3s2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.