

ASS. REC. BY:

REF: CS/C11190134351 PVF301 Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Elaine Cheong of C12 Date/Time: 31.7.19 1448 p.m

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKD 8348T Insured: SMH 5779H

at Workshop m/s Chuan Ho Auto Tel: 91992365

of 160 Sin Ming Drive #07-09

Policy No: DMP CSN 3013911900 Claim No: SNM19D20352102

Sum Insured: Excess:

Make of Veh: D.O.A. 28.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS 1.8.2019

Date/Time: 31.7.19 3.21 p.m. Person Contacted: Justin H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 8348T - X
	SMH 5779H - X
20/8/19	@ 1040am Spoken to Sharin, will ask surveyor to revert again
16/9/19	@ 317pm Sharin said vehicle not repair yet, .. front bumper issue.

REF: C12

PRS

ASSIGNMENT

From: Date: 1. 8. 2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKD 8348T

at Workshop mis Chuan Ho Auto
of 160 Sin ming Drive #07-09

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKD 8348T Yr Pagn: MAY / 2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Private Mover /

Truck / Trailer or:

Make: Nissan GTR R35 cc 3799

Colour: Red A/C: Insured / Std / Nil / NA

Sp. Reading: 118249 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: R35-003839

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285/35 R20

R: 285/35 R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 4 mm R/Bal: 5 mm

L/Bal: 4 mm L/Bal: 5 mm

D.O.A: 28/07/2019

D.O.L: 1/8/2019

Survey held at Chuan Ho auto

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$7000-\$8000

Repair day: 5 days (5days)

* Repairer doesn't accept the amount

L/S unconfirm

TOD to Submit repairer report to insurance

2/10/19 Recd email from Justin TP withdraw claim

MV: \$190 000

PV: \$34 101

NV: \$150 000

RECEIVED 11 OCT 2019

Date/Time: File Pass to?



: Preli. Report



: Final Report

Date/Time: File Return to?

2) 3/10 - typist

Report Format:

Lump Sum / L.B.I: (\$)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + P.S. \$

Phone:

Cable:

TOTAL

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Invs \$☐ Weekend \$

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019		31 Jul 2019 14:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: TAN YEW CHOON									
Vehicle Reg. No.:		SKD8348T	Date of Loss:	28/07/2019 00:00 - :59					
Claim Type:		TP / SNM19D203527C02	Policy/Cover Note No.:	DMPCSN3013911900					
Vehicle Reg. No. (Insured):		SMH5779H	Policy No. (Claimant):						
		Excess:	S\$3,500.00						
Repairer: Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/08/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	202G
Vehicle Details	
Vehicle No.:	SKD8348T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	GT-R 3.8 A
Primary Colour:	Red
Secondary Colour:	Black
Manufacturing Year:	2008
Engine No.:	VR38005150A
Chassis No.:	R35003839
Maximum Power Output:	353.0 kW (473 bhp)
Open Market Value:	\$91,003.00
Original Registration Date:	25 May 2008
First Registration Date:	25 May 2008
Transfer Count:	4
Actual ARF Paid:	\$100,104.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$38,712.00
COE Rebate Amount:	\$34,101.00
Total Rebate Amount:	\$34,101.00

The information contained herein is correct as at 02 Aug 2019

DOA: 28/07/2019

Remaining: 8 years 9 months 287 days (105.9 months) ^{OK}

Depri: \$21,920 (yearly) \$1,826.66 (monthly)

$105.9 \text{ months} \times \$1,826.66 = \$193,443.29$



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal Coe Toyota Vios 1.5L



2.88% Monthly 90 Down Monthly
From 1408.2 Year Warranty, S&A
Credit & No Make Damage
GV Credit Pte Ltd

AutoInn
As Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

[Browse by Category](#)
[Back \(1 2 \) Next >](#)
[Sort by Date Posted](#)
[20 results/page](#)

24 vehicles

Nissan GTR

Advanced Search

	Model	Price	Depreciation	Reg Form	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan GTR	Any	Any	> 10 year(s) old	Any	Any	Any	Available



Nissan GTR 3.8A (COE till 10/2028)

\$178,888

\$19,460 /yr

09-Oct-2008

3,799 cc

Sports

Available

Well Maintain By RMS Ray Motorsports, Best Performance Supercar With Comfort And Daily Driven, Viewing Available By Appointment Only Trade In Welcome. Loan Available. Godzilla

Posted: 01-Aug-2019 Tags: 2008 Nissan GTR, 2008 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan



Nissan GTR 3.8A (COE till 07/2027)

\$192,888

\$24,110 /yr

28-Aug-2008

3,799 cc

20,000 km

Sports

Available

Tip Top Condition And Well Maintain By RMS Ray Motorsports. Garage Show Car, Track And Drag Ready And More Than 1000 Hp. New Engine Block, Timing Chain And Tensioner, Torque Cam, Handling Mod, Whiteline, Superpro, Full Bodykit Done And More. Warranty By R...

Posted: 01-Aug-2019 Tags: 2008 Nissan GTR, 2008 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan



Nissan GTR 3.8A (COE till 09/2028)

\$188,800

\$20,710 /yr

12-Sep-2008

3,799 cc

94,650 km

Sports

Available

Consignment Unit. Comes With Full Custom Made Carbon Interior, Headlamp And Tail Lamp Changed To 2011 Type. Injectors, Engine Timing Chain And Etc All Done! New On Board Display! Pristine Condition (10/10). View To Believe. Call To Arrange Viewing. Indeed A B...

Posted: 31-Jul-2019 Tags: 2008 Nissan GTR, 2008 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan



Nissan GTR 3.8A (COE till 09/2027)

\$188,800

\$23,120 /yr

12-Jun-2008

3,799 cc

Sports

Available

Probably One Of The Best Maintained Units, Serviced And Checked At Very Reputable GTR Specialist Workshop. This Is Your Chance To Own The Legendary Godzilla. High Trade In Available As Well. Call Now For Viewing!

Monster Motors Pte Ltd

Posted: 31-Jul-2019 Tags: 2008 Nissan GTR, 2008 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Nissan GTR 3.8A (COE till 03/2028)

\$190,000

\$21,920 /yr

02-Dec-2008

3,799 cc

Sports

Available

LB Style GT Wing, New Version Front And Rear Light, Interior Alcantara And New Pearl Yellow Paintwork. Well Maintain By RMS Ray Motorsports. Viewing Available By Appointment Only. Loan Available. Optional Add On Warranty Coverage By RMS Ray Motorsports Pte...

Posted: 30-Jul-2019 Tags: 2008 Nissan GTR, 2008 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan



Nissan GTR 3.8A (COE till 12/2028)

\$180,000

\$19,100 /yr

04-Jun-2009

3,790 cc

Sports

Available

100% Accident Free! Flawless Decal Works, Super Clean And Flashy Look, Best Looking GTR In Town! Pristine Engine And Transmission. Parked Under Shade And With Car Cover. Low Genuine Mileage. Loaded With Accessories! Viewings And Test Drives Are Strictly By Appo...

DM Pre-Owned Pte Ltd

Posted: 30-Jul-2019 Tags: 2009 Nissan GTR, 2009 nissan gtr, Nissan GTR, nissan gtr, Nissan, GTR, gtr, Used Nissan

isan GTR 3.8A (New 10-yr E)

\$189,800

\$18,960 /yr

09-Sep-2008

3,799 cc

Sports

Available

Complete

[COMMENT](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 14:43
Date Of Accident	28/07/2019 12:15
Exact Location Of Accident	BLK 241A COMPASSVALE WALK MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD8348T
Insured/Policyholder	
Name Of Registered Owner	TAN YEW CHOON
NRIC No	S7401202G
Email Address	ANDYTAN@ENGHUATHENG.COM.SG
Mobile Phone No	(LOCAL) +65-94558587
Alternative Phone No	OTHERS-94558587

Vehicle Particulars

Manufacturer	NISSAN
Model	GT-R 3.8 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M0011278
Cover Note Number	25/05/2019 - 24/05/2020

Driver

Name of Driver	TAN YEW CHOON
NRIC No	S7401202G
Date Of Birth	18/01/1974
Occupation	INDOOR
Date Of Driving Pass	01/09/2004
Driving Experience	14 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94558587
Fax Number	
Contact Number	OTHERS-94558587
E Mail Address	ANDYTAN@ENGHUATHENG.COM.SG

Address	BLK 237 COMPASSVALE WALK #05-536
Postcode	540237
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SMH5779H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG KIM YONG
NRIC/Passport Number	S7242840D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Date of accident: 28/07/19 Time: 12.15 PM Location: BK 241A COMPASSVALE WALK
 My Vehicle A: SKD8348T Vehicle B: SMH 5779H Vehicle C: —

mscp

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My Car was parked at the Multistorey carpark
 Blk 241A 5th storey lot number 280, the car SMH 5779H
 reversed and hit onto my front part.

Vehicle B: Wong Kim Tong / S 72428403

Type: Third Party.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 29/07/19

1.29 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

AH LIM MOTOR COMPANY

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 29/07/19
1-29 pm

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:



Car Owner - Henry Miller 11611
Driver - Michael Miller 11611
677 425400

Re - Ins. claim

Dear Randy

Pls proceed to claim our ins for
your car repair cost

Edgar
file 571425400

eTiQa

Insurance

INTERVIEW FORM

Name (Driver): TAN YEW HOON

Policy No: M0011278

Vehicle No: SKD 8348T

Place of Accident: BK 241A COMPASSVALE WALK N.E. C. 22

Insured Driver's relationship with Insured: - Owner

Drink Driving of Insured and/or Insured Driver: -

No of passenger(s) in Insured vehicle: -

Injury to Insured and/or Insured driver, please indicate which hospital: -

Third Party Vehicle No (if any): SMH 8779H

No of passenger(s) in Third Party Vehicle: -

Injury to Third Party driver and/or passenger(s), please indicate which hospital: -

Type of collision and the extensiveness of the damages to all vehicles/Third Party property involved:

Rear to front

Any witness to the accident (if yes, please indicate Name, Contact No and a copy of the statement): -

Traffic Police report (enclosed): Yes / ☒ No

Please obtain a copy of the driving licence of Insured driver and/or work permit (where foreign worker is involved)

[Signature]

Driver (Name & Signature) / Date
I, affirmed the above information is given to
my best knowledge

[Signature]

Attended by (Name & Signature) / Date

Workshop Name: -

eTiQa Insurance Pte Ltd
One Raffles Quay
#12-01 North Tower
Singapore 058583

T +65 63360477
F +65 63392109

www.etiqa.com.sg
Company Reg. No. 200314498

A Member of  Maybank

REPUBLIC OF SINGAPORE
IDENTITY CARD NO: S7401202G



TAN YEW CHOON
(CHEN YOUCHUN)

Race: CHINESE
Date of Birth: 18-01-1974
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: S7401202G

TAN YEW CHOON
(CHEN YOUCHUN)

Date of Birth: 18 Jan 1974
Valid Date: 01 Sep 2004

17



STRICTLY FOR WORKSHOP USAGE
USE FOR ACCIDENT REPORTING ONLY

Hp: 94 55 8 587

Email: andyfan@enghuat heng.com.sg

STRICTLY FOR WORKSHOP USAGE
USE FOR ACCIDENT REPORTING ONLY



IRIC No: S7401202G



Valid Date: 02-07-2001

Address:
APT BLK 237 COMPASSVALE WALK
#05-538
SINGAPORE 540237

TO DRIVE VEHICLES WITH PERMITS

Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

Dry
wy. no
ca. NW
Total 0

• MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) • MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 • ROAD TRANSPORT ACT, 1987 (MALAYSIA) • MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



MOTOR CAR (Frt)

Front Portion

Vehicle No: SKD 8348T

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991323	Frt Bumper Bracket - Centre mounting			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	993074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

CHUAN HO AUTO SERVICE
SIN MING AUTO CITY
160 SIN MING DRIVE #07-09
SINGAPORE 575722

ESTIMATE : SKD 8348 T

Vehicle & Document Information

Date: 28/08/2019

Vehicle No: SKD 8348 T

Make/Model: NISSAN SKYLINE GTR

S/N	Description	Qty	Repairer's Est	Revised Es
1	FRONT BUMPER (VARIS JAPAN) (TO BE ORDERED) PIS provide invoice aft purchase	1	\$ CRA 24,000.00 \$ 10000 24,000.00	
2	FRONT BUMPER LH RETAINER hec ✓	1	\$ 225.00 \$ 8195 225.00	
3	FRONT BUMPER RH RETAINER hec ✓	1	\$ 225.00 \$ 8195 225.00	
4	FRONT BUMPER RH DRL xnn	1	\$ 2,800.00 \$ 2,800.00	
5	FRONT BUMPER RH CARNARD (VARIS JAPAN) (TO BE ORDERED) PIS provide invoice aft purchase	1	\$ SCV 5,000.00 \$ 3000 5,000.00	
6	FRONT BUMPER RH HEADLAMP CRA ✓	1	\$ 4,600.00 \$ 3600 4,600.00	
7	FRONT BUMPER LH HEADLAMP xnn check	1	\$ 4,600.00 \$ 4,600.00	
8	FRONT BUMPER CENTER TOP PLATE CRA ✓	1	\$ 1,400.00 \$ 932 1,400.00	
9	FRONT BUMPER RE-INFORCEMENT BAR xnn	1	\$ 1,800.00 \$ 1,800.00	
10	FRONT BUMPER SPONGE BR ✓	1	\$ 475.00 \$ 475.00	
11	FRONT BUMPER SUPPORT REINFORCMEENT CRA ✓	1	\$ 1,125.00 \$ 700 1,125.00	
			Total : \$ 18,097.90 46,250.00	
			30% -20% \$ 5729.1 9,250.00	
			Parts Total : \$ 13367.9 37,000.00	

1	TO CHECK LIGHTING, WIRING & FUSES	\$ 80 400.00
1	LABOUR TO DISMANTLE, REPAIR, REPLACE PARTS AND ALIGN FRONT PORTION	\$ 750 1,800.00
1	TO PUTTY, PRIMER, SPRAY PAINT FRONT BUMPER (DUAL COLOUR)	\$ 500 1,500.00

Labour Total :	\$ 1330 3,700.00
Parts Total :	\$ 13367.90 37,000.00
Total :	\$ 14697.9 40,700.00
-20%	\$ 2939.58 8,140.00
Grand Total :	\$ 32,560.00
Lump Sum :	\$ 12,000 29,168.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CHUAN HO AUTO SERVICE



Ram (LKK)
88622728

4/9/19
45 = \$10600

Veron Chen (LKKAUTO)

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Sent: Monday, 19 August 2019 5:11 PM
To: Veron Chen (LKKAUTO)
Subject: Re: SKD 8348 T

Hi,

Our owner disagree the amount of the Varis Bumper.
We are able to provide invoice.
And the Carnard is damaged as well.
Please give us a revised copy.
Thank you.

Best Regards,
Sharin Lim
+65 9069 1985



On Mon, Aug 19, 2019 at 5:06 PM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Justin,

Refer surveyor's marking.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Sent: Tuesday, 6 August 2019 2:56 PM

To: SUR <sur@lkkauto.com>

Subject: SKD 8348 T

Hi, here's the attached of the GIA and the estimate bill. Thanks.

--

Best Regards,

Justin Ho | Company Director

+65 9189 2365



Parasuram (LKK Auto)

From: CHUAN HO AUTO SERVICE <chuanhoautoservice@gmail.com>
Sent: Wednesday, 2 October, 2019 5:43 PM
To: Parasuram (LKK Auto); Elaine Cheong; Claims Dept of CTI
Subject: Withdrawal Of Case: SKD8348T

Hi Miss Elaine,

We would like to withdraw the claims for SKD8348T.

The survey prices are lower than our costings, hence owner decided to proceed this case elsewhere.

Thank you!

Best Regards,
Justin Ho
+65 9189 2365



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019		31 Jul 2019 14:48 Edit Adj Rpt	S\$27,265.00 Edit Estimates	S\$27,265.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WONG KIM YONG , ID: 57242840D								
Main Claimant:	TAN YEW CHOON								
Vehicle Reg. No.:	SKD8348T	Date of Loss:	28/07/2019 00:00 - :59 [134 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203527C02	Policy/Cover Note No.:	DMPCSN3013911900						
Vehicle Reg. No. (Insured):	5MH5779H	Policy No. (Claimant):							
		Excess:	S\$3,500.00						
Repairer:	Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity, 575722 Sin Ming - Tel: 91892365								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 13/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKD8348T (SNM19D203527C02)
[SMH5779H]
TP
TAN YEW CHOON
Jul 28 2019 12:00AM
[WONG KIM YONG]
Chuan Ho Auto Service

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
2	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
3	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
4	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
5	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
6	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
7	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
8	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
9	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
10	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
11	05/08/19 11:19	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
12	05/08/19 11:19	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
13	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
14	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
15	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
16	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
17	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
18	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
19	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
20	05/08/19 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
21	05/08/19 11:19	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	31/07/19 14:49	PRS - SKD8348T		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013435/FVF3E2

Date: 16/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3013911900
Claimant Vehicle No :	SKD8348T	Insured Vehicle No :	SMH5779H
Date of Loss:	28/07/2019	Nature of Claim:	TP
		Claim No:	SNM19D203527C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD8348T	Engine No:	VR38005150A
Make & Model:	NISSAN GTR, 3.8 (A)	Chassis No:	R35003839
Reg. Date:	25/05/2008 (Man. Year: 2008)	Odometer:	118249 km
Colour:	Red		
Engine Capacity:	3799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/35 R20	Rear Tyre Size:	285/35 R20
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,000.00	25,935.00	11,065.00	29.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,330.00	2,370.00	64.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	40,700.00	27,265.00	13,435.00	33.01

INSPECTION

Date of Assignment:	31/07/2019	
Date Inspected:	01/08/2019	Inspected At: Chuan Ho Auto Service (Sin Ming) 160 Sin Ming Drive, #07-09, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 16 Oct 2019)
Parts:	192	NISSAN GTR 3.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKD8348T)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (VARIS JAPAN)	Cracked	24,000.00 FL	*24,000.00 FL
2	1		*FRONT BUMPER LH RETAINER	Necessary	225.00 FL	*225.00 FL
3	1		*FRONT BUMPER RH RETAINER	Necessary	225.00 FL	*225.00 FL
4	1		*FRONT BUMPER RH DRL	Not Necessary	2,800.00 FL	*- FL
5	1		*FRONT BUMPER RH CARNARD (VARIS JAPAN)	Scratched	5,000.00 FL	*5,000.00 FL
6	1		*FRONT BUMPER RH HEADLAMP	Cracked	4,600.00 FL	*4,600.00 FL
7	1		*FRONT BUMPER LH HEADLAMP	Not Necessary	4,600.00 FL	*- FL
8	1		*FRONT BUMPER CENTER TOP PLATE	Cracked	1,400.00 FL	*1,400.00 FL
9	1		*FRONT BUMPER RE-INFORCEMENT BAR	Not Necessary	1,800.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Broken	475.00 FL	*475.00 FL
11	1		*FRONT BUMPER SUPPORT REINFORCEMENT	Cracked	1,125.00 FL	*1,125.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	46,250.00	37,050.00
- List Item Discount on L Items 20.00/30.00% (S\$)	9,250.00	11,115.00
Total Parts (S\$)	37,000.00	25,935.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHTING, WIRING & FUSES	New	400.00	80.00
2	LABOUR TO DISMANTLE, REPAIR, REPLACE PARTS AND ALIGN FRONT PORTION	New	1,800.00	750.00
3	TO PUTTY, PRIMER, SPRAY PAINT FRONT BUMPER (DUAL COLOUR)	New	1,500.00	500.00
Gross Labour Cost (\$\$)			3,700.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >