

ASS. REC. BY:

REF: C8/A1919013437/Atd3

Special Instruction: ¹⁷²Survey: Ashdn

ASSIGNMENT (Office)

From Person: M. Jinnalhpr Yinnal

of

ATG

Date/Time:

31/7/19 @ 12.55pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 1371U

Insured:

SKW 3829E

at Workshop m/s

Yap Lee Motor

Tel:

6441555.

of

1 kaki Bukit Ave 6 #01-26

Policy No:

0999994238

Claim No:

8075345394SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2.12pm @ 31/7/19

Person Contacted:

Shirley

Vehicle:

IN/OUT

Date/Time	Action/Instruction	Submit
	SLB 3829E - X	✓
	SKW 3829E - NBA / A1919013437 / Y	
		D.O.A. 28/7/19
	lump sum \$10,000 - (Red: 31441.70; 75%)	
	26 days	

ASS. REC. BY:

REC:

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____
 at Workshop m/s _____

of _____
 Insured: _____

Policy No. _____

Claims No _____

Sum Insured: _____ Excess: _____
 (Client's Record)

Make of Veh: _____

(Policy Condition)

/	
N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB1371U Yr Regn: 2010 Sept.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish c.c 1987

Colour Bronze A/C: Insured / Std / NI / NA

Sp.Reading 165264 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDGJ20WXS002899

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 31/07/19.

Survey held at Yap Lee

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP A16.</u>
	<u>MV : 28K</u>
	<u>PV : 17.2K</u>
	<u>Nett: 10.8K</u>

Date/Time, File Pass to?	Date/Time, File Return to?
1) <u>3818 Typist</u>	2) _____
3) _____	4) _____
5) _____	4) _____
Prak. Report:	
Final Report:	

Part Prices Check:	
IN	OUT

Survey Fee:	Date:
Basic & Add.	<u>200</u>
S + P.S. SI	<u>11</u>
Photos	
Others	
TOTAL	<u>261</u>

RE: PRE-REPAIR INSPECTION REQUEST – SLB3829E vs SKW3829E (OI) on D.O.A.: 28/07/2019

From: Hor, Yinnul
To: assignments@lkkauto.com; Admin A
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Sent: 7/31/2019 12:55:03 PM
Attachments:  20190731124656.pdf

Dear LXX,

Attached herewith the contact details of TP workshop for your necessary action.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: Hor, Yinnul
Sent: Wednesday, July 31, 2019 12:48 PM
To: 'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: aigencrypt PRE-REPAIR INSPECTION REQUEST – SLB3829E vs SKW3829E (OI) on D.O.A.: 28/07/2019

Hi,

Please refer to the enclosed request from **Vision Law LLC**.

Claim no : 8075345394SG003
Case Owner : Loh Chee Heng

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: Margaret Tan [mailto:margarettan@visionlawllc.com]
Sent: Wednesday, July 31, 2019 12:34 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW3829E AND SLB3829E ON 28/07/2019

This message is from an external sender; be cautious with links and attachments.

Dear Viviane,

Our client would like to select your surveyor Adrian Ling from LXX.

Thank you.

Thanks & Best Regards,
Margaret Tan
(Secretary)
Vision Law LLC
Tel: 6534 2811 Fax: 6535 6802

From: Hor, Yinnul [mailto:Yinnul.Hor@aig.com]
Sent: Wednesday, 31 July, 2019 11:57 AM
To: margarettan@visionlawllc.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKW3829E AND SLB3829E ON 28/07/2019
Importance: High



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่าน
มันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-08-07 11:57 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the
addressee. Please notify the sender if you have received this email in error or simply delete it.

Scanned by Protonmail Encryption. Copyright © 2009-2017 Protonmail, Inc. All rights
reserved.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors – Notaries Public – Commissioners for Oaths
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

Head Office: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Lorong 6 Toa Payoh
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE

TEL : (65) 6534 2811 (Hunting)
FAX : (65) 6535 6802
E-Mail: margaretan@visionlawllc.com

BRANCH (TOA PAYOH)

TEL : (65) 6358 0703
FAX : (65) 6358 0448 (Conveyancing)

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE – Please reply to HEAD OFFICE for this matter

Our Ref : PY.mt.Ins.Y41.111149.19

Your Ref : SKW 3829E

Date : 31st July 2019

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07 – 16 AIG Building
Singapore 079120
Attention: Motor-claims Department

BY EMAIL: claims.docmanagement@aig.com

Dear Sir,

CLAIMANT : KEK CHII CHUAN
VEHICLE NO. : SLB 1371U (4TH)
YOUR INSURED VEHICLE NO. SKW 3829E (5TH)
ACCIDENT ON 28TH JULY 2019 ALONG CENTRAL EXPRESSWAY TOWARDS CTE (AYE)
BRADDELL EXIT AT ABOUT 1315 HOURS

We refer to your email dated 31st July 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Please be informed that the said vehicle can be inspected at:

YAP LEE MOTOR
1 Kaki Bukit Ave 6
#01-26 Autobay
@ Kaki Bukit S(417883)
Singapore 417883

Contact Person: Tel: 6844 1555 (Ms Shirley)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

SLB 1371U – By Email: yap_lee_motor@singnet.com.sg

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed Surveyor :
(Name & Signature) :

Date & Time of Inspection:

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)




Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Renewal Coe Toyota Altis 1.6A



3.08% p.a. \$0 Down, Monthly Pm \$466, 2 Year Warranty, S2a Grade B No Major Damage (V Credit Fin Ltd) StarAd



ABWIN ONE-STOP



Browse by Category Save Search Print = Back (1 2) Next = Sort by Date Posted 20 results/page

24 vehicles | **Search** Toyota Wish [Advanced Search](#) [Search](#) [View All](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Toyota Wish	Any	Any	2010	Any	Any	Any	Available
------------------	-------------	-----	-----	------	-----	-----	-----	-----------



Toyota Wish 2.0A **\$27,700** **\$15,670 /yr** **24-Aug-2010** **1,987 cc** **-** **MPV** **Available**

One And Only Sporty Pear White Wish, Powerful, Fuel Economical, Well Maintained MPV. Spacious And Comfort, Good For Families. Come With Lots Of Gadget Ie Anti Theft System, In House Finance Package Avail For All Your Need. 100% Approval. Act Fast!

[Fetched: 13-Jul-2019](#) [Tags: 2017 Toyota Wish, 2010 Toyota wish, Toyota Wish, Toyota wish, Used Toyota](#)



Toyota Wish 1.6A X **\$27,888** **\$15,700 /yr** **26-Aug-2010** **1,797 cc** **135,069 km** **MPV** **Available**

Price Dropped! Neg Upon Viewing! 1 Owner, Superbly Well Maintained! Major Serviced All Done! Alternator, Suspension, Engine Mountings, Aircon, Cooling Coil, Radiator Etc. Owner Thinking Of Renewing COE For This Car In Dec. Spend A Few Thousand To Do Up...

[Fetched: 17-Jul-2019](#) [Tags: 2018 Toyota Wish, 2010 Toyota wish, Toyota Wish, Toyota wish, Used Toyota](#)



Toyota Wish 2.0A **\$28,500** **\$14,960 /yr** **01-Oct-2010** **1,987 cc** **120,000 km** **MPV** **Available**

Powerful, Fuel Economical, Most Popular Toyota MPV, Spacious And Reliable. Well Maintained And Service. No Further Repairs Needed. Call Now To Arrange For Viewing!

[Fetched: 14-Jul-2019](#) [Tags: 2010 Toyota Wish, 2010 Toyota wish, Toyota Wish, Toyota wish, Used Toyota](#)



Toyota Wish 2.0A **\$27,888** **\$13,790 /yr** **21-Oct-2010** **1,987 cc** **130,969 km** **MPV** **Available**

Powerful, Fuel Economical, Well Maintained MPV. Spacious And Comfort, Good For Families. Bank Loan, In House Loan/High Loan Available. Call Us Now For Viewing.

Creative Auto

[Fetched: 24-Jul-2019](#) [Tags: 2010 Toyota Wish, 2010 Toyota wish, Toyota Wish, Toyota wish, Used Toyota](#)

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads = Back (1 2) Next = 20 results/page

sgCarMart is the number one car classified for possible import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CNG cars & GPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car rentals, compare rates & car insurance. Find buy used Toyota Wish, Toyota Wish Singapore, used Toyota Wish Singapore, used vehicles Singapore or even buy used Toyota Wish Singapore. We have new car dealers competing parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our website also for job openings for Singapore jobs, real estate properties for sale, review, car performance tests, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com shall not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[Download on the App Store](#) [GET IT ON Google play](#)

[Compare](#)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	786Z
Vehicle Details	
Vehicle No.:	SLB1371U
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 2.0 AUTO
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	3ZRA508037
Chassis No.:	JTDGJ20WX05002899
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,003.00
Original Registration Date:	21 Sep 2010
First Registration Date:	21 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$22,003.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Sep 2020
PARF Rebate Amount:	\$12,101.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$44,129.00
COE Rebate Amount:	\$5,025.00
Total Rebate Amount:	\$17,126.00

The information contained herein is correct as at 31 Jul 2019

OK

FORM 1900B02 (FORM Motor Pte Ltd - KAKI BAKI)
 ENTRY DATE & TIME: 29/07/2019 13:39
 SUBMITTED BY: CHIA Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/07/2019 13:39
Date Of Accident	28/07/2019 13:15
Exact Location Of Accident	CTE (AYE) BRADDELL EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB1371U
Insured/Policyholder	
Name Of Registered Owner	KEK CHII CHUAN
NRIC No	S6912786Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96210259
Alternative Phone No	OFFICE-96210259

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP307043
Cover Note Number	

Driver

Name of Driver	KEK CHII CHUAN
NRIC No	S6912786Z
Date Of Birth	22/04/1969
Occupation	INDOOR
Date Of Driving Pass	22/07/1996
Driving Experience	23 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96210259
Fax Number	
Contact Number	OFFICE-96210259
Email Address	NOEMAIL

Address	BLK 62 DAKOTA CRESCENT #06-285
Postcode	390062
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: TAN HENG HEE GENDER: MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MOUNTBATTEN NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 60 DAKOTA CRESCENT #01-213/ 215 , POSTCODE: 390060 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3449999 - FAX NO 64474185
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190728/2098.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW3829E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA HUI RU
NRIC/Passport Number	
Contact Number	97962620
Address	

Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBJ957M
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE C
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJU5619D
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE D
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SLD7000R
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE E
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policeholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/IN No.

YAP LEE

Sketch Plan #2 Pg. 1

SKETCH PLAN



A SLB1371U

B SKW3829E

C GRJA57M

D SJU561AD

E SID700R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

— AS per police report —

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
WPA/CTIS No.

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190728/2098

1 of 5

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

Report No: T/20190728/2098

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 28/07/2019 17:16	Vide Report No: E/20190728/0102	Station Diary No.: 38
---	------------------------------------	--------------------------

Informant's Particulars

Name of Informant: KEK CHII CHUAN		Address: APT BLK 62 DAKOTA CRESCENT #06-285 SINGAPORE 390062	
ID Type / ID No. NRIC NO / S6912786Z		Contact No. Home/Office: Mobile: 96210259	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 22/04/1969	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: SELF-EMPLOYED		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive No	Date/Time of Accident: 28/07/2019 13:15	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY CTE(AYE) Braddell exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBJ957M	Van				Slightly Damaged	0
SJU5619D	Car				Seriously Damaged	2
SKW3829E	Car				Seriously Damaged	2
SLB1371U	Car	TOYOTA	WSH 2.0 AUTO	Brown	Seriously Damaged	1
SLD7000R	Car				Slightly Damaged	0

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190728/2098

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

2 of 5

Report No. T/20190728/2098

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLB1371U	QBE Insurance (Singapore) Pte Ltd	VX020297	01/04/2019	31/03/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Unknown Driver		ID No	NIL
Related Vehicle	GBJ957M (Van)		Contact No	90074847
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	Chua Tuan Kim		ID No.	S7532627J
Related Vehicle	SJU5619D (Car)		Contact No	96313683
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	Chua hui Ru		ID No.	S9115376I
Related Vehicle	SKW3829E (Car)		Contact No	97962520
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190728/2098

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

3 of 5

Report No: T/20190728/2098

CONTINUATION OF REPORT

Driver			
Name	KEK CHII CHUAN	ID No.	S6912786Z
Related Vehicle	SLB1371U (Car)	Contact No.	98210259
Hospital/Clinic	KALLANG MEDICAL CENTRE PTE LTD	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/07/2019	Date Discharge	28/07/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Lim Wei Zhen	ID No.	S9023387D
Related Vehicle	SLD7000R (Car)	Contact No.	98468900
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 28/07/2019 at around 1315hrs I was driving my car bearing plate number SLB1371U along CTE(AYE) near the Braddell exit. at that point of time the traffic on the road was heavy and I was travelling on the 3rd lane of the expressway heading into PIE. there was another car(SLD7000R) that was in front of me. My wife was seated in the front passenger seat of the car with me.

Suddenly the car(SLD7000R) in front of me braked as such to avoid colliding into the car I also applied my brake hard. I managed stop my car about 1 car length distance, however as soon as my car came to a stop immediately there was a sudden and large impact from the rear causing my car to move forward and collided into the rear of the car(SLD7000R) which in turn collided into the car in front of it.

After my car had been rear ended I tried to move my car however it was unable to move as such I then came out of my car to check on the damage as well as my wife. Both myself and my wife were not injured at that point of time. I then saw that it was a chain collision between 4 cars and a van. My car was the 4th vehicle from the front. The car(SKW3829E) that rear ended me was the one that started the chain collision. I then went to speak to the driver of the last car to find out what had happened and was told by him that he was driving on the 3rd lane behind my car when he took a quick look at his side mirror, when he turned back to the front he saw that my car had stopped and also tried to stop his car from colliding into mine however to no avail.

Shortly after the traffic police and ambulance arrived. The car that had rear ended me had about 2 other passenger was taken by the ambulance to the hospital. I do not know who called for ambulance. The traffic police then took our information and I was given a card and told to lodge a traffic police report. I managed to exchanged particulars with all 5 drivers of the 5 vehicles involved. Before leaving the

Sketch Plan #6 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190728/2098

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

4 of 5

Report No. T/20190728/2098

CONTINUATION OF REPORT

accident scene

Only after I had left the scene I then felt soreness in my legs and entire body. I then went to see a doctor and was given 3 days medical leave from 28/07/2019 till 30/07/2019 I wish to state that I do not have any in car camera installed in my car however the car that I had collided into had in car camera footage of the accident.

My car rear and front suffered serious damaged That is all.



**SINGAPORE
POLICE FORCE**



T/20190728/2098

Police Station Of Origin:
Mountbatten NPP
60 Dakota Crescent #01-213 SINGAPORE
390060
Tel No: 1800-3449999

5 of 5


Report No. T/20190728/2098

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 JOSHUA EMMANUEL SHO YI ZHE	Signature Of Informant
Signature Of Interpreter: Not applicable	Date/Time 28/07/2019 17:16
Officer In Charge Of Case: TP / GIT /  Sgt NORAMEERA BINTE MOHAMED HUSSEIN Contact No: 65476236 Authentication Stamp NP100	Classification Of Case:

SLB1371U

Toyota Wish. 1987cc. TP ALG. DEIVE

JTDGJ20WXP5002899.

Front Number Plate Best	30(SN) ✓
Front Number Plate Holder Behind	30(SN) ✓
Front Bumper Distorted	58470 ✓
Front Bumper Clips new	30 ✓
Front Bumper Side Holder x02 1/2	619x2=1238 ✓
Front Bumper Reinforcement. Best	28940 ✓
Front Bumper Sponge. Needed	18210 ✓
Front Bumper Fog Lamp x02 1/2 needed 208x2=416. =208.	
Front Bumper Side Cover x02 Behind 111x2=302 ✓	
Front Bumper Lower Grille Behind	12940 ✓
Headlamp x02 needed	917x2=1834 ✓
Front Grille needed	185 ✓
Front Brace Panel: Best	8910 ✓
Bonnet Distorted	86110 ✓
Bonnet Lock. Distorted	9260 ✓

51792

SLB1371U

Bonnet Hinge x02	new	816 x 2 = 16320	✓
Bonnet Inner Trim	cracked	21130	✓
Bonnet Inner Trim Clips	re	30	✓
Bonnet Logo	re	6890	✓
Front Support Panel	Distorted	809	✓
Front Support Top Cover	Dehd	20510	✓
Front Support Top Cover Clips	re	20	✓
Horn	cracked	125	✓
Air Con Condensers	Distorted	121380	✓
Air Con Discharge Pipe	} New	329	✗
Air Con Suction Pipe		315	✗
Radiator	Distorted	171880	✓
Radiator Top Cover	cracked	9840	✓
Radiator Fan	Coilng. Cracked	28980	✓
Wiper Washer Tank	Dehd	10420	✓
Sleeping Wheel Air Bag	} Activated	248050	✓
Passenger Dashboard Air Bag		278560	✓
Front Seat Belt x 02		8622 x 2 = 172440	✓
Dashboard	to rn	72480	✓

13416.8

SLB1317U

Steering Air Bag Sensor x02 } Activated 323.7 x 2 = 647.40 ✓
Air Bag Control Unit. } 654.90 ✓
Front Fender x02 Buckled 707.4 x 2 = 1414.80 ✓

2717-1

SLB1371U.

Rear Number Plate	Best	30(SW) ✓
Rear Number Plate Holder	Rehd	30(SW) ✓
Rear Number Plate Lamp	x02 ^{NY} _m	75.5 x 2 = 157. ✓
Rear Bumper	Distorted	498.30 ✓
Rear Bumper Clips	m	30 ✓
Rear Bumper Side Holder	x02 m	45.1 x 2 = 90.20 ✓
Rear Bumper Impact Bracket	x02 Dented	65.7 x 2 = 131.40 ✓
Rear Bumper Reflector	x02 RH could	81.70 81.7 x 2 = 163.40 ✓
Reverse Sensor	Dmg	330(SW) 200(SW)
Rear End Panel	Distorted	477.20 ✓
Rear End Panel Sealant	new	60(SW) ✓
Rear End Panel Top Garnish	Rehd	253.60 ✓
Tailtip	x02 could	387.5 x 2 = 775 ✓
Tailgate	Distorted	1248.60 ✓
Tailgate Lock	Jammed	361.10 ✓
Tailgate Weatherstripe	lt	304.70 ✓
Tailgate Outer Chrome Moulding	could	295 ✓

52855

SLB137111.

Tailgate Reflector x 02	Crackd	304.6 x 2 = 609.20
Tailgate Inner Trim Board	Crackd	345.20 ✓
Tailgate Inner Trim Board cups	new	30 ✓
Tailgate Wiper Motor	new	255.30 +
Tailgate Glass Moulding	} new	132.40 ✓
Tailgate Glass Sealant		60 (SN) ✓
Toyota Logo	} new	75.10 ✓
Bornoo Motor Logo		45.20 ✓
Deluxe Logo		44.90 ✓
Rear Fender x 02	RH Buckled	1075 x 2 = 2150 ^{LOTS}
Rear Fender Inner Trim Board x 02	Delhd	589 x 1 = 1178 ✓
Rear Fender Inner Trim Board cups	new	60 ✓
Rear RH Fender Air Vent.	cracked.	104.10 ✓ ^{40(SN)}
Rear Fender Glass Sealant x 02	RH new	40 x 2 = 80 ^(SN)
Floor Panel	Buckled	950.10 ✓
Floor Panel Insulation Pad	new	280 ^(SN) 200 ^(SN)
Floor Panel Top Cover	Delhd	489.50 ✓

SLB1371U.

Spare Tyre ~~Lock~~ Regulator Dwyd 174.90 ✓
 Rear Exhaust Pipe Best 780.20 ✓
 Rear Exhaust Manifold. H/M 3940. X
 Rear Exhaust Heat Shield, crumpled 149.70 ✓

31191.40 S.N: 620
 23393.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Panel Beating

~~3000~~ 2600

Spray Painting

~~2800~~ 2200

Wiring

~~150~~ 60

To undress

~~280~~ 120

To remove reverse sensor

~~100~~ 50

To remove exhaust pipe

~~150~~ 80

To remove tailgate glass

~~180~~ 120

To transfer tailgate fittings. 6270

~~150~~ 80

To remove upholstery.

~~280~~ 180.

To remove rear fender glasses.

~~280~~ 60

To remove condenser, radiator and to ranges

~~180~~ 120

To remove dashboard.

~~380~~ 220

To remove air bags and seat belts.

~~500~~ 380

Total: 30283.55

h/s: 10K

26 Days.

43061.80

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19013437/ATD3N2

Date: 09/09/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994238
Claimant Vehicle No :	SLB1371U	Insured Vehicle No :	SKW3829E
Date of Loss:	28/07/2019	Nature of Claim:	TP
		Claim No:	8075345394SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1371U	Engine No:	3ZRA508037
Make & Model:	TOYOTA WISH, 2.0 (A)	Chassis No:	JTDGJ20WX05002899
Reg. Date:	21/09/2010 (Man. Year: 2010)	Odometer:	165264 km
Colour:	Bronze		
Engine Capacity:	1987 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,631.80	23,951.15	10,680.65	30.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,430.00	6,270.00	2,160.00	25.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,061.80	30,221.15	12,840.65	29.82
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	43,061.80	10,000.00	33,061.80	76.78

INSPECTION

Date of Assignment:	31/07/2019	
Date Inspected:	31/07/2019	Inspected At:
		Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	26.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	584.70 F	*584.70 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*FRONT BUMPER SIDE HOLDER	Necessary	123.80 F	*123.80 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	289.40 F	*289.40 FL
5	1		*FRONT BUMPER SPONGE	Cracked	182.10 F	*182.10 FL
6	1		*FRONT BUMPER FOG LAMP	N/s Cracked	416.00 F	*208.00 FL
7	2		*FRONT BUMPER SIDE COVER	Deformed	302.00 F	*302.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Deformed	129.40 F	*129.40 FL
9	2		*HEADLAMP	Cracked	1,834.00 F	*1,834.00 FL
10	1		*FRONT GRILLE	Cracked	185.00 F	*185.00 FL
11	1		*FRONT BRACE PANEL	Bent	89.10 F	*89.10 FL
12	1		*BONNET	Distorted	861.10 F	*861.10 FL
13	1		*BONNET LOCK	Damaged	92.60 F	*92.60 FL
14	2		*BONNET HINGE	Not Necessary	163.20 F	*-FL
15	1		*BONNET INNER TRIM	Crumpled	211.30 F	*211.30 FL
16	1		*BONNET INNER TRIM CLIPS	Necessary	30.00 F	*30.00 FL
17	1		*BONNET LOGO	Necessary	68.90 F	*68.90 FL
18	1		*FRONT SUPPORT PANEL	Distorted	809.00 F	*809.00 FL
19	1		*FRONT SUPPORT TOP COVER	Deformed	205.10 F	*205.10 FL
20	1		*FRONT SUPPORT TOP COVER CLIPS	Necessary	20.00 F	*20.00 FL
21	1		*HORN	Cracked	125.00 F	*125.00 FL
22	1		*AIR CON CONDENSER	Distorted	1,213.80 F	*1,213.80 FL
23	1		*AIR CON DISCHARGE PIPE	Not Necessary	329.00 F	*-FL
24	1		*AIR CON SUCTION PIPE	Not Necessary	315.00 F	*-FL
25	1		*RADIATOR	Distorted	1,718.80 F	*1,718.80 FL
26	1		*RADIATOR TOP COVER	Cracked	98.40 F	*98.40 FL
27	1		*RADIATOR FAN COWLING	Cracked	289.80 F	*289.80 FL
28	1		*WIPER WASHER TANK	Deformed	104.20 F	*104.20 FL
29	1		*STEERING WHEEL AIR BAG	Activated	2,480.50 F	*2,480.50 FL
30	1		*DASHBOARD AIR BAG	Activated	2,785.60 F	*2,785.60 FL
31	2		*FRONT SEAT BELT	Activated	1,724.40 F	*1,724.40 FL
32	1		*DASHBOARD	Torn	724.80 F	*724.80 FL
33	2		*STEERING AIR BAG SENSOR	Activated	647.40 F	*647.40 FL
34	1		*AIR BAG CONTROL UNIT	Activated	654.90 F	*654.90 FL
35	2		*FRONT FENDER	Buckled	1,414.80 F	*1,414.80 FL
36	2		*REAR NUMBER PLATE LAMP	Not Necessary	157.00 F	*-FL
37	1		*REAR BUMPER	Distorted	498.30 F	*498.30 FL
38	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
39	2		*REAR BUMPER SIDE HOLDER	Necessary	90.20 F	*90.20 FL
40	2		*REAR BUMPER IMPACT BRACKET	Dented	131.40 F	*131.40 FL
41	1		*REAR BUMPER REFLECTOR	O/s Cracked	163.40 F	*81.70 FL
42	1		*REAR END PANEL	Distorted	477.20 F	*477.20 FL
43	1		*REAR END PANEL TOP GARNISH	Deformed	253.60 F	*253.60 FL
44	2		*TAILLAMP	Cracked	775.00 F	*775.00 FL
45	1		*TAILGATE	Distorted	1,248.60 F	*1,248.60 FL
46	1		*TAILGATE LOCK	Jammed	361.10 F	*361.10 FL
47	1		*TAILGATE WEATHERSTRIPE	Cut	304.70 F	*304.70 FL
48	1		*TAILGATE OUTER CHROME MOULDING	Cracked	295.00 F	*295.00 FL
49	2		*TAILGATE REFLECTOR	Cracked	609.20 F	*609.20 FL
50	1		*TAILGATE INNER TRIM BOARD	Cracked	345.20 F	*345.20 FL
51	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
52	1		*TAILGATE WIPER MOTOR	Not Necessary	255.30 F	*-FL
53	1		*TAILGATE GLASS MOULDING	Necessary	132.40 F	*132.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*TOYOTA LOGO	Necessary	75.10 F	*75.10 FL
55	1		*BORNEO MOTOR LOGO	Necessary	45.20 F	*45.20 FL
56	1		*DELUXE LOGO	Necessary	44.90 F	*44.90 FL
57	1		*REAR FENDER	O/s Buckled	2,150.00 F	*1,075.00 FL
58	2		*REAR FENDER INNER TRIM BOARD	Deformed	1,178.00 F	*1,178.00 FL
59	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 F	*60.00 FL
60	1		*REAR RH FENDER AIR VENT	Cracked	104.10 F	*104.10 FL
61	1		*FLOOR PANEL	Buckled	950.10 F	*950.10 FL
62	1		*FLOOR PANEL TOP COVER	Deformed	489.50 F	*489.50 FL
63	1		*SPARE TYRE LOCK REGULATOR	Damaged	174.90 F	*174.90 FL
64	1		*REAR EXHAUST PIPE	Bent	780.20 F	*780.20 FL
65	1		*REAR EXHAUST MOUNTING	Not Necessary	39.40 F	*- FL
66	1		*REAR EXHAUST HEAT SHIELD	Crumpled	149.70 F	*149.70 FL
67	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
68	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
69	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
70	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
71	1		*REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
72	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
73	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
74	1		*REAR FENDER GLASS SEALANT	O/s Necessary	80.00 FS	*40.00 FS
75	1		*FLOOR PANEL INSULATION PAD	Necessary	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	34,631.80	31,708.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	7,757.05
Total Parts (S\$)	34,631.80	23,951.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,000.00	2,600.00
2	SPRAY PAINTING	New	2,800.00	2,200.00
3	WIRING	New	150.00	60.00
4	TO UNDERSEAL	New	280.00	120.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE EXHAUST PIPE	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE UPHOLSTERY	New	280.00	180.00
10	TO REMOVE REAR FENDER GLASSES	New	280.00	60.00
11	TO REMOVE CONDENSER,RADIATOR AND TO RE-GAS	New	180.00	120.00
12	TO REMOVE DASHBOARD	New	380.00	220.00
13	TO REMOVE AIR BAG AND SEAT BELTS	New	500.00	380.00
Gross Labour Cost (S\$)			8,430.00	6,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >