

ASS. REC. BY:

Tampin

REF:


CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: *Michael* Vehicle: IN / OUT

Veh No: *FBG 8140 R.* Yr Regn: *2012 / Nov*
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: *Honda Tiger GL200* c.c. *197.*
 Colour: *Black* A/C: Insured / Std / NI / NA
 Sp. Reading: *54325.* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *MH1M02212BK 079473*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Oil / S/Rim / STD A/Rim or
 Tyre Size: F: *80/80 R18*
 R: *90/90 R18*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. *5* mm R/Bal. *5* mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. *1/8/19 @ 430pm*
 Survey held at *Pany Scooter*
 Des. of Damages Fr / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4/5 @ 2400, 5 days, confirm with Michael. Rebate: \$562
(Red: 100%, 31%)

RECEIVED 12 NOV 2019

Date/Time, File Pass to? : Preli. Report

Mu Typist : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	<i>270</i>
Transportation:	
3 + PS, SI	
Photos	
Others	
TOTAL	<i>270</i>

Report Format: *TP*
 Lump Sum / F.P.T.: *24007*

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 1 August 2019 11:40 AM
To: pang_s_s_m@singnet.com.sg
Cc: assignments
Subject: RE: OUR REF: SNM19D202752-SGU6822L-CBS - FW: Pre Repair Survey FBG8140R

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Pang Scooter [mailto:pang_s_s_m@singnet.com.sg]
Sent: Thursday, 1 August, 2019 9:26 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202752-SGU6822L-CBS - FW: Pre Repair Survey FBG8140R

Hi,

I would like to appoint Taufikh from LKK Auto Consultants Pte Ltd as our surveyor.

Thanks & Best Regards:
Izah from PANG SCOOTER SERVICE

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Wednesday, 31 July 2019 4:51 PM
To: pang_s_s_m@singnet.com.sg
Subject: RE: OUR REF: SNM19D202752-SGU6822L-CBS - FW: Pre Repair Survey FBG8140R

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Wednesday, 31 July, 2019 3:49 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; pang_s_s_m@singnet.com.sg

Subject: OUR REF: SNM19D202752-SGU6822L-CBS - FW: Pre Repair Survey FBG8140R

Dear Boon Sen,

Please conduct PRS for FBG8140R.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Pang Scooter [mailto:pang_s_s_m@singnet.com.sg]

Sent: Tuesday, 30 July, 2019 1:02 PM

To: Claims Dept of China Taiping Insurance <e-claims@sg.cntaiping.com>

Subject: Pre Repair Survey

Hi,

SAVE AS TO COSTS

I would like to request for Pre Repair survey at my workshop.

Here I attach the Estimate Repair.

Third Party Vehicle: FBG 8140R

Insured Vehicle: SGU 6822L

Date Of Accident: 07.06.2019

Thanks & Best Regards:

Izah from PANG SCOOTER SERVICE

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available foresaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2019 16:33
Date Of Accident	07/06/2019 08:30
Exact Location Of Accident	TPE TOWARDS CHANGI NEAR ELIAS ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG8140R
Insured/Policyholder	
Name Of Registered Owner	KULDEEP SINGH S/O DHARAM SINGH
NRIC No	S7183804H
Email Address	KSDEEP1971@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90556080
Alternative Phone No	OTHERS-90556080

Vehicle Particulars

Manufacturer	HONDA
Model	TIGER-197CC GL 200R
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	72136800

Driver

Name of Driver	KULDEEP SINGH S/O DHARAM SINGH
NRIC No	S7183804H
Date Of Birth	31/08/1971
Occupation	INDOOR
Date Of Driving Pass	07/11/2012
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90556080
Fax Number	
Contact Number	OTHERS-90556080
EMail Address	KSDEEP1971@GMAIL.COM

Address	34 JALAN TASEK 1 TAMAN TASEK 80200
Postcode	JOHORBAHR
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS WEST N.P.C
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20190610/2040

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGU6822L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	KULDEEP SINGH S/O DHARAM SINGH
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	FBG8140R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
NRIC/PIN No.

Accident Sketch Plan

SKETCH PLAN



A) FEG 8140R
B) SGM 6822L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Handwritten text in a lined box: "PLS REFER TO POLICE REPORT 1/20190610/2040"

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time


Reporting Centre Person's Signature
Name
NIC/FIN No

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190610/2040

Police Station Of Origin:
Woodlands West N P C
1 Woodlands Street 12 SINGAPORE 738622
Tel No. 1800-363 9999

1 of 3
Report No. T/20190610/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 10/06/2019 10:19	Video Report No	Station Diary No. 134
---	-----------------	--------------------------

Informant's Particulars

Name of Informant KULDEEP SINGH S/O DHARAM SINGH		Address 34 JLN TASEK 1, TAMAN TASEK, 80200 JOHOR BAHRU JOHOR	
ID Type / ID No. NRIC NO / S7183804H		Contact No. Home/Office: 01111403642 Mobile: 90556080	
Nationality MALAYSIAN		Email	
Sex Male	Age 47	Date of Birth 31/08/1971	Type of Informant Rider
Race Punjabi		Language	Institution / School Name
Occupation PRODUCTION SUPERVISOR		Driving Licence Information Class 2B.3	Date of Expiry

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive No	Date/Time of Accident 07/06/2019 08:30	Type of Location Straight Road
Location: Along Road 1 TAMPINES EXPRESSWAY TPE towards Changi Near to Elias Road Exit				
Weather: Clear		Road Surface Wet	Road Speed Limit	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Others			Anyone conveyed by ambulance Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG8140R	Motorcycle	HONDA	TIGER GL200R M	Black	Seriously Damaged	0
SGU6822L	Car				No Damage	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBG8140R	MSIG INSURANCE (SINGAPORE) PTE. LTD	72136800	30/11/2018	29/11/2019

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190610/2040

Police Station Of Origin:
Woodlands West N.P.C.
1 Woodlands Street 12 SINGAPORE 738622
Tel No 1800-363 9999

2 of 3

Report No. T/20190610/2040

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KULDEEP SINGH S/O DHARAM SINGH	ID No	S7183804H
Related Vehicle	FBG8140R (Motorcycle)	Contact No	01111403642
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class 2B.3 Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 07/06/2019 at around 0830hrs, I was travelling along TPE on the second lane. A car (SGU6822L) from the first lane give signal and moved into the second lane without noticing me. Therefore, to avoid collision with the car, I engaged my brake however I skidded and causes me to fall onto the ground along the expressway. I did notice that the car signal to change lane however he did not check if there are any incoming vehicle. At that point of time, I am driving about 40km/h as it is after rain and the floor is slippery. There is another motorbike(VF930) which skidded after me due to the same car.

After the accident happened, the car stopped and came down of their car. The passenger that was inside the car provided me with her contact number and mentioned that is their fault that causes the accident to happen. Subsequently, I was conveyed by the ambulance to Changi General Hospital and was given 3 days MC.

The damages on my motorbike was seriously damaged and there is no damage on the other party car.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190610/2040

Police Station Of Origin
Woodlands West N P.C
1 Woodlands Street 12 SINGAPORE 738622
Tel No: 1800-363 9999

3 of 3

Report No: T/20190610/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report L / Sgt 1 TEO KAI XUN	Signature Of Informant
Signature Of Interpreter Not applicable	Date/Time 10/06/2019 10:19
Officer In Charge Of Case TP / GIT / SI MOHAMMAD ABDILLAH BIN PALIL Contact No: 65476246	Classification Of Case

Authentication Stamp
NP168

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2019		02 Aug 2019 11:41 Edit Adj Rpt	\$2,400.00 Edit Estimates	\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	KULDEEP SINGH S/O DHARAM SINGH , ID: S7183804H								
Vehicle Reg. No.:	FBG8140R	Date of Loss:	07/06/2019 08:00 - :59 [78 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202752C02	Policy/Cover Note No.:	DMPCSN30390719022						
Vehicle Reg. No. (Insured):	SGU6822L	Policy No. (Claimant):	72136800						
		Excess:	\$0.00						
Repairer:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06, 159762 Bukit Merah - Tel: 62714618								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBG8140R (SNM19D202752C02)**
[SGU6822L]

TP
KULDEEP SINGH S/O DHARAM SINGH
Jun 7 2019 8:00AM
[-]
Pang Scooter Service

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:07	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
16	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
17	21/06/19 17:05	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
18	21/06/19 17:05	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/11/19 16:25	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
16	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
17	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
18	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
19	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
20	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
21	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
22	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
23	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
24	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
25	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
26	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
27	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
28	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
29	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
30	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
31	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
32	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
33	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
34	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
35	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
36	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
37	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
38	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
40	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
41	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
42	12/11/19 16:25	General View	Load JPG	<input checked="" type="checkbox"/>
43	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
44	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
45	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
46	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
47	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
48	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
49	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
50	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
51	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
52	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
53	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
54	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
55	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
56	12/11/19 16:26	General View	Load JPG	<input checked="" type="checkbox"/>
57	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	12/11/19 16:26	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
71	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	12/11/19 16:26	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:06	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 17:06	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 17:06	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 17:06	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 17:06	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:07	Accident Statement	Load HTM	<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	21/06/19 17:05	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
18	21/06/19 17:05	Identification Card	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	21/06/19 17:06	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	21/06/19 17:06	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
3	21/06/19 17:06	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
4	21/06/19 17:06	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>
5	21/06/19 17:06	POLICE REPORT	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013482/T1TF3E2

Date: 22/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30390719022
Claimant Vehicle No :	FBG8140R	Insured Vehicle No :	SGU6822L
Date of Loss:	07/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202752C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBG8140R	Engine No:	MC22E1077497
Make & Model:	HONDA TIGER, 197cc GL 200R	Chassis No:	MH1MC2212BK079473
Reg. Date:	30/11/2012 (Man. Year: 2011)	Odometer:	54325 km
Colour:	Black		
Engine Capacity:	197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/80 R18	Rear Tyre Size:	90/90 R18
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,067.00	2,615.40	451.60	14.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	490.00	370.00	120.00	24.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,557.00	2,985.40	571.60	16.07
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	3,557.00	2,400.00	1,157.00	32.53

INSPECTION

Date of Assignment:	02/08/2019	
Date Inspected:	01/08/2019 Inspected At:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06 Singapore 159762
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Nov 2019)	
Parts:	N/A	HONDA TIGER 197cc GL 200R (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG8140R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBE	Bent	135.00 F	*135.00 FL
2	1		*UNDER BRACKET	Bent	195.00 F	*195.00 FL
3	1		*STEERING CON	Necessary	100.00 F	*100.00 FL
4	1		*FRONT FENDER	Cut	135.00 F	*135.00 FL
5	1		*FRONT BRAKE DISC	Bent	185.00 F	*185.00 FL
6	1		*FRONT WHEEL RIM	Dented	398.00 F	*398.00 FL
7	1		*FRONT WHEEL SHAFT	Not Necessary	38.00 F	*- FL
8	1		*FRONT (N) PLATE	Bent	15.00 F	*15.00 FL
9	1		*FRONT COWLING	Cracked	298.00 F	*298.00 FL
10	1		*HEADLIGHT	Cut	185.00 F	*185.00 FL
11	1		*SIGNAL LIGHT	Broken	70.00 F	*70.00 FL
12	1		*HANDLE BAR	Bent	85.00 F	*85.00 FL
13	1		*CLUTCH LEVER	Bent	35.00 F	*35.00 FL
14	1		*MIRROR	Cut	45.00 F	*45.00 FL
15	1		*GEAR PEDAL	Bent	85.00 F	*85.00 FL
16	1		*GEAR SHAFT	Not Necessary	65.00 F	*- FL
17	1		*CLUTCH GASKET	Not Necessary	28.00 F	*- FL
18	1		*L/H FRONT FOOTREST	Bent	65.00 F	*65.00 FL
19	1		*4T	Not Necessary	30.00 F	*- FL
20	2		*FORK OIL SEAL	Necessary	70.00 F	*70.00 FL
21	1		*REAR BOX	Cut	285.00 F	*285.00 FL
22	1		*HEADLIGHT BRACKET	Bent	190.00 F	*190.00 FL
23	1		*L/H FOOTREST BRACKET	Bent	165.00 F	*165.00 FL
24	1		*IU UNIT	Cut	165.00 F	*165.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,067.00	2,906.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	290.60
Total Parts (\$\$)	3,067.00	2,615.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	80.00	60.00
2	LABOUR	New	350.00	250.00
3	WIRING	New	30.00	30.00
4	RIM BALANCING	New	30.00	30.00
Gross Labour Cost (S\$)			490.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >