

ASS. REC. BY: *Maria*

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: *SKH 3049Z*
at Workshop mis *R.*
of *sim C1762H*
Insured:
Policy No. *29114756*
Claims No. *601732*
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: *42500*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *5* days Res.: Yes or No
Lum Sum: *20* % 3 Val: Yes or No
CA / REV / REP. / 24 HRS *271A 38387*

Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: *SKH 3049Z* Yr Regn: *8.112*
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA 7*
Make: *Volkswagen New Golf cc 1390*
Colour: *Grey* A/C: ☒ Insured / Std / NI / NA
Sp. Reading: *132497* T/Radio: ☒ Insured / Std / NI / NA
Eng/No: *WVWZZZTKZCW 336232*
C/No: _____
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or *off*
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: *225/40 ZR18*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MICT / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: *6* mm Rear: *6* mm
R/Bal: *6* mm L/Bal: *6* mm
D.O.A. *31/7/19* D.O.I. *11/8/19*
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s of 2
The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3ys. Rep 9500 left 7149

RECEIVED 20 AUG 2019

2/8/19 Email GIA to MS16
16/8/19 L/S 6500 confid with Alan. (Red 12,332.00, 65%)
20/8/19 Send preli revised via merimen

19/8/2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) *20/8 - typist*

Days Of Repair: *5*

Resurvey No. of Trip: *3*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS \$ _____
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Others
☐ : Weekend (\$ _____)

Report Format : *merimen*

Lump Sum / I.B.I: (\$ *6500/2*)

TOTAL

200
11
211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 20 Aug 2019

Preliminary Advice

Insured Vehicle No	: SMC1762H	Accident Date	: 31/07/2019
TP Vehicle No	: SKG3049Z	Assignment Date	: 20/08/2019
Make	: VOLKSWAGEN NEW GOLF	Est. Duration of Repair	: 5
Date of Inspection	: 1/8/2019		
Inspection At	: FASTECH AUTO PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,832.02
Revised Amount	:S\$	6,500.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Aug 2019		20 Aug 2019 10:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	TAN ZHI HAO, ID: S9123062C		
Vehicle Reg. No.:	SKG3049Z	Date of Loss:	31/07/2019 17:00 - :59 [83 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 601732	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SMC1762H	Policy No. (Claimant):	
		Excess:	
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 5, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 21/08/2019]		
Driver/Custodian (Insured):	MUHAMAD ZAINI BIN RASIB (), NRIC: S7348451J, Tel: +6581959662 Email:		
Adj Asg. Remarks:	Direct Survey by LKK Auto Consultants on 01/08/2019.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 2 August 2019 9:27 AM
To: motorsurvey@sg.msig-asia.com
Cc: KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 31/7/2019, SKG 3049Z (TP VEHICLE), SMC 1762H (OI VEHICLE)
Attachments: GIA.pdf, POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SKG 3049Z at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 1/8/2019

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Golf

Price Range

Depreciation

2012

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Inchcape Pre-Owned > Volkswagen Golf 1.4A TSI

Volkswagen Golf 1.4A TSI

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos

Map

PREMIUM AD



Price	\$39,000		
Depreciation	\$9,930 /yr <small>View models with similar depre</small>	Reg Date	15-May-2012 (2yrs 9mths 13days COE left)
Mileage	155,680 km (21.6k /yr)	Manufactured	2012
Road Tax	\$620 /yr	Transmission	Auto
Dereg Value	\$29,356 as of today (change)	OMV	\$22,665
COE	\$56,551	ARF	\$22,665
Engine Cap	1,390 cc	Power	90.0 kW (120 bhp)
Curb Weight	1,241 kg	No. of Owners	2
Type of Vehicle	Hatchback		

Features

Punchy 1.4L TSI Turbocharged Engine Producing 120Bhp And 200Nm Torque, Coupled With 7 Speed DSG Gearbox, Paddle Shifter, Multi-Function Steering. View specs of the Volkswagen Golf GTI (2003-2009)

Accessories

Original Factory Audio Sound System, Sports Rims, Reverse Sensors, Auto Headlights, Auto Side Mirrors, Fog Lamps.

Description

Experience The Agility, Comfort And Frugal Running Cost Of This Beautiful Hatchback, This Is A Versatile Car For Any Driving Needs. Call Our Sales Consultants For A Viewing Today!

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare Car Valuation - Free



Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Inchcape Pre-Owned

- dealer's pricelist
- 67 vehs sold | 75 vehs available

Address

2 Pandan Crescent Level 1
Search cars nearby this location

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 062C

Vehicle Details

Vehicle No.: SKG3049Z
Vehicle to be Exported: No
Intended Deregistration Date: 01 Aug 2019
Vehicle Make: VOLKSWAGEN
Vehicle Model: NEW GOLF 1.4 TSI AT 5K14Q5
Primary Colour: Blue
Manufacturing Year: 2012
Engine No.: CAV418443
Chassis No.: WVVZZZ1KZCW336232
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$27,867.00
Original Registration Date: 21 Aug 2012
First Registration Date: 21 Aug 2012
Transfer Count: 1
Actual ARF Paid: \$27,867.00 13933

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Aug 2022
PARF Rebate Amount: \$18,113.00

Intended COE Rebate Details

COE Expiry Date: 20 Aug 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$56,501.00
COE Rebate Amount: \$17,238.00
Total Rebate Amount: \$35,351.00

The information contained herein is correct as at 01 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/08/2019 16:47
Date Of Accident	31/07/2019 17:00
Exact Location Of Accident	ALONG RD 1 TELOK BLANGAH ST 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG3049Z
Insured/Policyholder	
Name Of Registered Owner	TAN ZHI HAO
NRIC No	S9123062C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91915214
Alternative Phone No	OTHERS-91915214

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	NEW GOLF 1.4 TSI AT 5K14Q5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5096117917-01
Cover Note Number	

Driver

Name of Driver	TAN ZHI HAO
NRIC No	S9123062C
Date Of Birth	23/06/1991
Occupation	INDOOR
Date Of Driving Pass	24/09/2010
Driving Experience	8 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91915214
Fax Number	
Contact Number	OTHERS-91915214
EMail Address	NOEMAIL

Address	BLK 116 #07-15 HO CHING ROAD
Postcode	610116
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ORCHARD
Police Station Address	ROAD: 51 KILLINEY ROAD , POSTCODE: 239572 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20190801/2044;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC1762H
Vehicle Make/Model/Colour	TOYOTA / PRIUS PLUS (AUTO)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TAN ZHI HAO
Approximate Age	28
Injuries Sustain	
Injured person in which vehicle?	SKG3048Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 116 #07-15 HO CHING ROAD
Postcode	102092

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

EDAC KAKI BUKIT (VAC)
21 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature:
Name: _____
MUC/FIN No.: _____
Tel: 6740 1667
Fax: 6740 1114
Email: vac1@edac.com.sg

* Refer to the attached Police Report No: T/20190801/1094.

I/We declare the foregoing particulars are true in every respect.

[illegible]

Name: P. S. SINGH
NRIC/FIN No: 92305
Email: vocids@singnet.com.sg

Date of Accident : 31-07-2019 Accident Time: 17.00 (24-HR-Format)
 Accident Place : Along Road 1 Telok Blangah street 31
 Vehicle. No. (Car Plate No.) : SKG 3049Z Make/Model: Volkswagen Golf.
 Insurance Company : NTUC Policy No: 5096117917-01.
 Owner or Company Name /IC No. : Tan zhi Hao (S 9123062C)
 Owner or Company Contact No. : 9191 5214 Owner's Hp _____ Company Tel _____
 DRIVER'S Name / IC No. : as above
 DRIVER'S Date Of Birth : 23-06-1991 DRIVER'S License Pass Date 24-09-2010
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner
 DRIVER'S Address : Blk 92B Telok Blangah st 31 #19-193
 DRIVER'S Contact No./ Alt No. : 1) _____ 2) 5102092
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address : _____
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 1 person (Driver)
 Was there any video Captured by car camera: YES (NO)
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): Yes.

Other Party Driver's Particular (if any)

Vehicle. No: <u>SMC 1762H (MS16)</u>	Vehicle. No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

*** NEW - Passenger's name & gender:**

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Refer to the Police Report attachment

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* Refer to the attached Police Report NO: T/20190801/2044.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/08/2019 10:33		Vide Report No.:		Station Diary No.: 27	
Informant's Particulars					
Name of Informant: TAN ZHI HAO			Address: APT BLK 92B TELOK BLANGAH STREET 31 #19-193 SINGAPORE 102092		
ID Type / ID No.: NRIC NO / S9123062C			Contact No.: Home/Office: Mobile: 91915214		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 28	Date of Birth: 23/06/1991	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: UNEMPLOYED		Driving Licence Information: Class: 3,4,5 Date of Expiry:			

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/07/2019 17:00	Type of Location: Straight Road
Location: Along Road 1 TELOK BLANGAH STREET 31 Near to the yellow box Lamp Post Number: 11				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKG3049Z	Car	VOLKSWAGO N	NEW GOLF 1.4 TSI AT 5K14Q5	Blue	Seriously Damaged	0
SMC1762H	Car				Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20190801/2044

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKG3049Z	NTUC Income Insurance Co-Operative Limited	5096117917-01	21/02/2019	20/02/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TAN ZHI HAO		ID No.	S9123062C
Related Vehicle	SKG3049Z (Car)		Contact No.	91915214
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	31/07/2019		Date Discharge	31/07/2019
No. of Days granted Medical Leave		05	Degree of Injury	Slight
Driver				
Name	MUHAMAD ZAINI BIN RASIB		ID No.	S7348451J
Related Vehicle	SMC1762H (Car)		Contact No.	81959662
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4A Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On the 31/7/2019 at about 1700hrs, I was driving my vehicle(SKG3049Z) along Telok Blangah Street 31(Near to the T junction). I wish to state that there are only two lanes along the said road, and my vehicle was on the left lane while the other vehicle(S1)-(SMC1762H) was on my right. At the point in time, the traffic was heavy. Subsequently, when I was about to exit the said street turning into West Coast highway, S1 drove into my lane and his front left side of his vehicle bumped into the front of my vehicle. As a result, my vehicle front bumper dropped down. Even though S1 had bumped into my vehicle, he did not stopped his vehicle but had continued to drive. Consequently, his left side of his vehicle was scratched. S1 then stopped his vehicle after I have horned him. Both parties alighted the vehicle and exchanged particulars. the driver of S1 had also admitted that his fault. At that point in time, my vehicle camera is not working but I believed his vehicle camera is working. S1 is also a grab driver. After the accident, I went to Mount Elizabeth hospital at NOVENA, and the doctor said that I had strained my neck due to the accident and had given me 5 days of MC.



**SINGAPORE
POLICE FORCE**



T/20190801/2044

4 of 4


Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

Report No. T/20190801/2044

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan



IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 LEE CHEE GUAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 3 KOH CHEE SENG, KEVIN ✓

Contact No.: 65472073

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

01/08/2019 10:33

Classification Of Case:

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: FASTECH AUTO PTE LTD
IN: SKG 3049 Z
Date: 1.8.19 14:24



SKG 3049 Z

Volkswagen : Golf V/VI Variant 2008-13 : Sport Suspension (2UC, G02, G05, G07, G25, G33, G58, G80) : 18" Wheel

Front : Left

Actual	Before	Specified Range
-0°53'	-0°53'	-1°11' -0°11'
7°52'	7°52'	7°17' 8°17'
0°16'	0°16'	0°00' 0°10'
12°16'	12°16'	
11°23'	11°23'	
		-2°00' -1°20'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-1°27'	-1°27'	-1°11' -0°11'
8°05'	8°05'	7°17' 8°17'
0°16'	0°16'	0°00' 0°10'
13°50'	13°50'	
12°24'	12°24'	
		-2°00' -1°20'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°34'	0°34'	-0°30' 0°30'
-0°13'	-0°13'	-0°30' 0°30'
-1°35'	-1°35'	
0°32'	0°32'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°52'	-1°52'	-2°15' -1°15'
0°00'	0°00'	-0°01' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°28'	-1°28'	-2°15' -1°15'
0°09'	0°09'	-0°01' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°24'	-0°24'	-0°30' 0°30'
0°08'	0°09'	-0°02' 0°23'
-0°05'	-0°04'	-0°20' 0°20'

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
LKK
1/8/19
1/5 = 6500
5-17

VEHICLE NO: SKG 3049Z

QTY	PARTICULAR			
1 PCS	BONNET		R	\$1,055.00 X
1 PCS	FRONT BUMPER	1072.00	D/S/B.N	\$1,185.32 X
1 PCS	FRONT BUMPER SIDE RETAINER O/S	35.50	one	\$68.50
1 PCS	FRONT BUMPER REINFORCEMENT	505.10	Ref	\$641.20
1 PCS	FRONT BUMPER FOG LAMP GARNISH O/S	145.00	garn	\$195.00
1 PCS	FRONT BUMPER FOG LAMP O/S		11	\$355.00 X
1 PCS	FRONT BUMPER LOWER SPOILER	620.00	Tom	\$820.00
1 PCS	FRONT BUMPER LOWER GARNISH	311.15	Top	\$365.00
1 PCS	FRONT BUMPER PDC SENSOR N/S	195.00	Shield	\$245.00
1 SET	FRONT BUMPER CLIPS		RM	\$50.00
1 PCS	HEADLAMP O/S	1065.00	one	\$1,220.00
1 PCS	FRONT SUPPORT PANEL		R	\$866.00 X
1 PCS	AIR CON CONDENSER		11	\$981.00 X
1 PCS	FRONT FENDER O/S	545.60	Bul	\$645.00
1 PCS	FRONT FENDER INNERSHIELD O/S	165.20	Tom	\$212.00
1 SET	FRONT FENDER INNERSHIELD CLIPS O/S		RM	\$60.00
1 PCS	FRONT DOOR O/S		R	\$1,265.00 X
1 PCS	FRONT SHOCK ABSORBER O/S		RM	\$1,050.00 X
1 PCS	FRONT KNUCKLE ARM O/S		Ref	\$655.00
1 PCS	FRONT KNUCKLE ARM BEARING O/S		Dye	\$250.00
1 PCS	FRONT LOWER ARM O/S		RM	\$485.00 X
1 PCS	FRONT GRILLE		11	\$455.00 X
1 PCS	FRONT GRILLE LOGO		11	\$85.00 X
1 PCS	WIPER WASHER TANK	185.00	RM	\$205.00
				\$13,412.02
	S.NETT			
1 PCS	FRONT SPORT RIM O/S '18 inch'		20/set	\$1,000.00 680 54
1 set	FRONT Door sticker o/s		RM	\$250.00 200
1 PCS	FRONT HEADLAMP BLACK FILM O/S		RM	\$80.00 30
1 SET	FRONT BUMPER STICKER		RM	\$220.00 180
1 SET	FRONT FENDER STICKER O/S		RM	\$200.00 180
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 20
	TO SPRAY RUST PROOFING			\$80.00 30
	TO REFILL AIR CON GAS		11	\$120.00 X
	TO DISMANTLE & REPLACING PDC SENSOR			\$80.00 40
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE			\$280.00 120
	TO CONDUCT WHEEL ALIGNMENT			\$150.00 80
	TO RESET & REPROGRAMME SYSTEM		11	\$300.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,080.00 520
	TO PUTTY & SPRAY PAINTING			\$1,500.00 800
			TOTAL	\$18,832.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "no dispute" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature: 5273.59
Date: 8/5/19

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19013490/UVF3N2

Date: 23/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SKG3049Z	Insured Vehicle No :	SMC1762H
Date of Loss:	31/07/2019	Nature of Claim:	TP
		Claim No:	601732

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3049Z	Engine No:	CAV418443
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 TSI 5K14Q5 (A)	Chassis No:	WVWZZZ1KZCW336232
Reg. Date:	21/08/2012 (Man. Year: 2012)	Odometer:	132497 km
Colour:	Grey		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,162.02	6,543.59	8,618.43	56.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,610.00	2,060.00	56.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,832.02	8,153.59	10,678.43	56.70
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	18,832.02	6,500.00	12,332.02	65.48
+ GST 7.00/7.00% (S\$)	1,318.24	455.00	863.24	65.48
Nett Amount (S\$)	20,150.26	6,955.00	13,195.26	65.48

INSPECTION

Date of Assignment:	20/08/2019	
Date Inspected:	01/08/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2019)
Parts:	144	VOLKSWAGEN NEW GOLF 1.4 TSI 5K14Q5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG3049Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,055.00 F	*- FL
2	1		*FRONT BUMPER	Distorted/Torn	1,185.32 F	*1,072.00 FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	66.50 F	*35.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	641.20 F	*505.10 FL
5	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Grazed	195.00 F	*145.00 FL
6	1		*FRONT BUMPER FOG LAMP O/S	Not Necessary	355.00 F	*- FL
7	1		*FRONT BUMPER LOWER SPOILER	Torn	820.00 F	*620.00 FL
8	1		*FRONT BUMPER LOWER GARNISH	Torn	365.00 F	*311.15 FL
9	1		*FRONT BUMPER PDC SENSOR N/S	Shorted	245.00 F	*195.00 FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*HEADLAMP O/S	Cracked	1,220.00 F	*1,065.00 FL
12	1		*FRONT SUPPORT PANEL	Repair	866.00 F	*- FL
13	1		*AIR CON CONDENSER	Not Necessary	981.00 F	*- FL
14	1		*FRONT FENDER O/S	Buckled	645.00 F	*545.60 FL
15	1		*FRONT FENDER INNERSHIELD O/S	Torn	212.00 F	*165.20 FL
16	1		*SET FRONT FENDER INNERSHIELD CLIPS O/S	Necessary	60.00 F	*60.00 FL
17	1		*FRONT DOOR O/S	Repair	1,265.00 F	*- FL
18	1		*FRONT SHOCK ABSORBER O/S	Serviceable	1,050.00 F	*- FL
19	1		*FRONT KNUCKLE ARM O/S	Bent	655.00 F	*655.00 FL
20	1		*FRONT KNUCKLE ARM BEARING O/S	Damaged	250.00 F	*250.00 FL
21	1		*FRONT LOWER ARM O/S	Serviceable	485.00 F	*- FL
22	1		*FRONT GRILLE	Not Necessary	455.00 F	*- FL
23	1		*FRONT GRILLE LOGO	Not Necessary	85.00 F	*- FL
24	1		*WIPER WASHER TANK	Deformed	205.00 F	*185.00 FL
25	1		*FRONT SPORT RIM O/S 18 INCH	Dented/Bent	1,000.00 FS	*680.00 FS
26	1		*SET FRONT DOOR STICKER O/S	Necessary	250.00 FS	*200.00 FS
27	1		*FRONT HEADLAMP BLACK FILM O/S	Necessary	80.00 FS	*30.00 FS
28	1		*SET FRONT BUMPER STICKER	Necessary	220.00 FS	*180.00 FS
29	1		*SET FRONT FENDER STICKER O/S	Necessary	200.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,162.02	7,129.55
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	585.96
Total Parts (\$\$)	15,162.02	6,543.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	TO DISMANTLE & REPLACING PDC SENSOR	New	80.00	40.00
5	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	280.00	120.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
7	TO RESET & REPROGRAMME SYSTEM	New	300.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	520.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			3,670.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >