

REF:

REF: CS3/MSG19009911/Nsd3-1

Keywords: child sexual abuse; disclosure; self-blame

HS: \$ 19,450.00

Third Parties:

Claimant:

Surveyor: Constant Appraiser

Workshop: Toh painting

From (Person): Monica chung of MSIG Date/Time: 3/17/19
Estimated Cost: _____ Bill to: _____

OD/TP Re-inspection / Evaluation

To inspect Vehicle No: SME 5783K Insured: SLG 4278K

at Workshop m/s Toh painting & services Tel: 6763 1055

of Blk 3, woodlands Rd Unit 341C & G Yew Tee Ind. Est

Policy No: A29014701MCX Claim No: 595467

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30/05/

(Client's Record) 27/09/2019 @ 2pm (6763 1055)

H.O.D. Enforcement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 06/19 Confirmed with 1 Final Fig 1, 1 days (Red S 1 / 1 %; Original 5 days)

Date/Time: 01/10/19 Submit Final Fig 46 p13K, 5 days (Red 6.42/7 33%; Original 5 days)

Date/Time	Action/Instruction
	SME 5753K - CS3/MSA/19009911 / Ncd302 Don: 30/5/2019
22/6/19 -	SLG 4078K - CS3/MSA/19009911 / Ncd302 Don: 30/5/2019 Sally called and said owner can't make it tomorrow, so she will reschedule.

1/10/23

Do Not Finalise

Para(i) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i>)
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

RECEIVED 02 OCT 2019

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by: _____	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	300-120
Nett Value : _____		Transport	
		Photos	
		Others	
		Total	180

1) Date/Time _____ File Pass to _____

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to

ISSUE:

XSS. REC. BY:

REF: CS3/MS619009911 / Ned3e2

...al Instruction:

Surveyor: NAZ

ASSIGNMENT (Office)

From (Person): Monica chung of MS19

Date/Time: 4/6/2019 @ 4:24pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SNE 5723K

Insured: SLG 4278K

at Workshop m/s Toh Painting & Service

Tel: 67607541

of Blk 3 Woodland Road unit 291 C of Joo Tee

Policy No: 29014701 MCX

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 30/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.6.19 5:00pm

Person Contacted: Xiu Hui

Vehicle IN / OUT

Date/Time	Action/Instruction Estimate (X)
	SNE 5723K - X
	SLG 4278K - X

Do Not Finalise

ASSIGNMENT

From: Date: 6-6-2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SNE5783K

at Workshop m/s TOH Painting & Service

of B1K 3 woodland road unit 391C & G Low Tee Industrial

Insured: state

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh: Morning

Contact Xiu Wei: 67631055

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SNE 5783K Yr Regn: 5 OCT, 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES E20 cc 1,991

Colour: BLUE AC: Insured / Std / NI / NA

Sp. Reading: 3000 JAM T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130452A318571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 1 mm

L/Bal. 6 mm

D.O.A. 30/5/19

Survey held at TOH PAINTING

Des. of Damages: Frt / Rear / O/S / N/S / W/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 6/6/19

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range \$85-\$95

[Signature]

18/6/2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RTK, 24

Photos

Others

TOTAL

120

11

131

Report Format: PRE

Lump Sum / L.D.I. (\$

Nivitha (LKK Auto)

From: Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Sent: Wednesday, 31 July 2019 2:18 PM
To: Monica Chung; assignments
Cc: SUR
Subject: RE: Your Ref: AM-jt-Ins-T22-110637-19 (sj) Our Ref: 595467 [accident involving SME 5783 K & SLG 4278 K on 30-5-2019]

Dear Monica,

Appointment confirmed.

Dear Assignment Team,

Please take note on the arrangement.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Monica Chung <Monica_Chung@sg.msig-asia.com>

Sent: Wednesday, 31 July 2019 1:33 PM

To: Celine Fong (LKKAuto) <celinefong@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: FW: Your Ref: AM-jt-Ins-T22-110637-19 (sj) Our Ref: 595467 [accident involving SME 5783 K & SLG 4278 K on 30-5-2019]

Dear Celine,

Please confirm if our surveyor can attend the physical re-inspection.

Thanks.

Regards,

Monica Chung

Executive, Claims Services

D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Jacqueline Tan [mailto:jactan@visionlawllc.com]

Sent: Wednesday, July 31, 2019 12:53 PM

To: Monica Chung <Monica_Chung@sg.msig-asia.com>

Subject: RE: Your Ref: AM-jt-Ins-T22-110637-19 (sj) Our Ref: 595467 [accident involving SME 5783 K & SLG 4278 K on 30-5-2019]

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

WITHOUT PREJUDICE

SAVE AS TO COSTS

CLAIMANT: TAN KAI CHAH CASESARIAN

Dear Monica,

Refer to your email and your request for a reinspection to our client's vehicle SME 5783 K. Please be informed that we have make arrangement as follows:-

Date: 23 August 2019
Time: 2 pm
Place: Toh Painting & Services Pte Ltd
Blk 3 Woodlands Road
391-C & 391-G Yew Tee Industrial Estate
Singapore 677966
Contact: Jennifer/XiuHui (6763-1055)

Please ensure that your appointed surveyor attends to the said appointment and let us have copy of the report upon completion.

Kindly revert with your confirmation on the aforesaid.

Regards

Jacqueline Tan
Secretary
Vision Law LLC
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Tel: 6534-2811, Fax: 6535-6802

From: Monica Chung [mailto:Monica_Chung@sg.msig-asia.com]

Sent: Monday, 22 July, 2019 9:46 AM

To: Jacqueline Tan

Subject: RE: Your Ref: AM-jt-Ins-T22-110637-19 (sj) Our Ref: 595467

WITHOUT PREJUDICE

Dear Jacqueline,

We would like to conduct a physical re-inspection on your client's vehicle.

Please inform us at least 10 working days in advance for us to make the arrangements.

Thank you.

Regards,

Monica Chung
Executive, Claims Services
D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Monica Chung
Sent: Friday, July 12, 2019 9:29 AM
To: Jacqueline Tan <jactan@visionlawllc.com>
Subject: Your Ref: AM-jt-Ins-T22-110637-19 (sj) Our Ref: 595467

WITHOUT PREJUDICE

Dear Jacqueline,

We acknowledge receipt of your letter dated 10 Jul 2019 with enclosures and will reply you soon.

Thank you.

Regards,

Monica Chung
Executive, Claims Services
D: +65 6594 2552 | F: +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

TOH PAINTING & SERVICES PTE LTD
Block 3 Woodlands Road Unit 391C&G
Yew Tee Industrial Estate
Singapore (677966)

Phone 67631055
Fax 67636151
GST Number 20-0311427-D

TAX INVOICE

CAESARIAN TAN KAI CHAH
1 NEWTON ROAD
#28-01
SINGAPORE 307943

Phone: 9187 0188

Fax:

Invoice Number: 101662

Date	Delivery	Customer	Order Number	Packing Slip	Internal Reference	Sales Person	Page
30-Jun-19	30-May-19	SME5783K	M / BENZ E250		SME5783K	0000	1

Code	Description	Quantity	Unit	Price	Discount	Amount
	LUMP SUM REPAIRS					
	TO SUPPLY SPARE PARTS. REPAIR / PANEL BEATING, WELDING, WIRING CHECKING, PUTTY AND SPRAY PAINTING & OTHER CHARGES.	1		\$19,450.00		\$19,450.00
	CONTRACT REPAIR AS RECOMMENDED.					

SGD: TWENTY THOUSAND EIGHT HUNDRED ELEVEN & CENTS FIFTY ONLY



Authorised Signature for TOH PAINTING & SERVICES PTE LTD

Total Net	\$19,450.00
GST	\$1,361.50
Invoice Total Including GST	\$20,811.50

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: Caesarian Tan Kai Chah
1 Newton Road
#28-01
Singapore 307943

Date : 24/06/2019
Invoice No : IV19-06042/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SME 5783K (Inclusive Of Photographs And Transport Charges) Our reference : CAS/19-06/042	\$908.00
Total	\$908.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Caesarian Tan Kai Chah
1 Newton Road
#28-01
Singapore 307943

Date : 24/06/2019

Reference No : CAS/19-06/042

General Information

Registration No. : SME 5783K
Accident Date : 30/05/2019

Particulars of Damaged Vehicle

Colour	: Blue	Make & Model	: Mercedes Benz E250 AMG
Engine Capacity	: 1991 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 2134.5	Engine No.	: 27492031180557
Chassis No.	: WDD2130452A318571	Steering	: In Order
Registration Date	: 05/10/2018	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	245/40R19	PIRELLI	90%
L/H Front Tyre	245/40R19	PIRELLI	90%
R/H Rear Tyre	275/35R19	PIRELLI	90%
L/H Rear Tyre	275/35R19	PIRELLI	90%

Inspection

Repairer : Toh Painting & Services Pte Ltd
Blk 3C Woodlands Road, 391C/G Yew Tee Industrial Estate, Singapore 677966

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$23,155.70
Revised Amount : \$19,450.00
Less Excess : -
Nett Total : \$19,450.00

Remarks

- (A) Survey was done on 06/06/2019
(B) The survey was conducted entirely on WITHOUT PREJUDICE basis.
(C) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Trim bumper	Dented/Broken / CRK	1,889.61	1,889.61 1.5
2	1pc	Front bumper lower grille	Broken / BR	171.64	171.64
3	1pc	Front bumper lower ornamental molding	Grazed / SCR	553.02	553.02 30
4	1pc	Front licence plate molding	Dented/Deformed / DEF	145.02	145.02
5	1pc	Front bumper chrome ring	Serviceable X SVL	324.20	-
6	1pc	Front bumper side grille RH	Grazed / SCR	108.24	108.24
7	1pc	(Str) radar sensor	Dented/Damaged X NN	1,804.94	1,804.94 1.5
8	1pc	Radar mounting bracket	Bent / BT	11.42	11.42
9	1pc	Front lower basic mounting for bumper	Broken / BR	143.96	143.96
10	1pc	Impact absorber	Broken X NN	209.78	209.78 1.5
11	2pcs	Side basic mounting for bumper @ \$92.95	Broken X RH / CRK LH X SVL 92.95	185.90	185.90
12	2pcs	Side mounting rail @ \$9.94	Necessary / NEC	19.88	19.88
13	6pcs	Distance sensor @ \$202.53	3pcs Damaged X SVL	1,215.16	607.59
14	6pcs	Spacer ring @ \$7.30	Necessary X NN	43.82	43.82
15	1pc	Bonnet	Dented/Buckled / BUC	2,654.80	2,654.80 2.3
16	1pc	Radiator grille air duct segment	Broken / BR	152.56	152.56
17	1pc	MB star holder	Necessary X NN	87.75	87.75 1.5
18	1pc	Front Mercedes star	Necessary / NEC	161.59	161.59
19	1pc	Rad grille ornamental molding	Necessary / NEC	77.02	77.02
20	1pc	Rad grille garnish	Broken / BR	771.68	771.68 5
21	1pc	Rad grille	Broken / BR	514.48	514.48
22	1pc	Rad grille frame	Broken / CRK	395.73	395.73 30
23	2pcs	Headlamp unit @ \$3,907.08	Broken / CRK	7,814.16	7,814.16 70
24	1pc	Cross member	Dented/Bent / DD	607.28	607.28
25	1pc	Support panel	Dented/Twisted / DD	607.28	607.28 40
26	1pc	Support panel console mounting	Serviceable X SVL	244.32	-
27	1pc	Bonnet retaining hook	Bent X SVL	81.03	81.03
28	1pc	Right front support panel console	Broken / BR	119.00	119.00
29	1pc	Front fender RH	Dented/Buckled / DD	998.78	998.78
30	1pc	Front fender cowling RH	Distorted/Torn / TN	118.53	118.53
31	1pc	Front intermediate layer RH	Necessary / NEC	11.53	11.53
				22,244.11	21,068.02

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>			
		Less 10%		(2,224.41)	(2,106.80)
			Sub total	20,019.70	18,961.22
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Front bumper clip	Necessary <i>NEC</i>	58.00	58.00
2	1set	Front fender cowl clip RH	Necessary <i>XNN</i>	48.00	48.00
3	1pc	Front licence plate	Dented/Bent <i>DD</i>	50.00	45.00 3
			Sub total	20,175.70	19,112.22
		<u>LABOUR & MISC. CHARGES</u>			
1		Repair & replace front damaged parts		1,200.00	1,000.00 80
2		Spray paint affected area		1,200.00	1,000.00 80
3		Check wiring & refocus headlamp		60.00	40.00
4		Diagnose & reset system after repair		420.00	380.00 25
5		Spray anti rust on affected area		100.00	60.00 50
			Grand total	23,155.70	21,592.22
Recommended cost of lump sum repair (To its pre-accident condition)					19,450.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$19,450.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,
Constant Appraiser Services


Lim Xiong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/06/2019 14:25
Date Of Accident	30/05/2019 19:10
Exact Location Of Accident	JCT OF CHANCERY LANE AND JLN PASIRAN
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SME5783K
Insured/Policyholder	
Name Of Registered Owner	CAESARIAN TAN KAI CHAH
NRIC No	S2656513H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91870188
Alternative Phone No	OTHERS-91870188
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250 AMG LINE AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA403776/1
Cover Note Number	
Driver	
Name of Driver	CAESARIAN TAN KAI CHAH
NRIC No	S2656513H
Date Of Birth	05/10/1953
Occupation	INDOOR
Date Of Driving Pass	16/12/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91870188
Fax Number	
Contact Number	OTHERS-91870188

Address	1 NEWTON ROAD #28-01 SPORE 307943
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG4278K
Vehicle Make/Model/Colour	TOYOTA HARRIER ELEGANCE 2.0 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Branchs Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agent(s) (including their lawyers/law firms), which may be seated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement, and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
(Name & Title)

Driver's Signature
(If different from the Policyholder)
(Name & Title)

Reporting Centre Personnel's Signature
Name: S. Mani
NOC/Title: Branch Manager

Sketch Plan #2

SKETCH PLAN



A - SME 5783K
B - SLH 4278K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 30/5/19 @ ABOUT 1910HR, MY VEHICLE SME 5783K
WAS STATIONARY @ JUNCTION OF JALAN PARISAN &
CHANCERY LANE, PENDING TRAFFIC CLEARANCE.
SUDDENLY VEHICLE SLH 4278K CUT INTO MY LANE
WHILE TURNING IN FROM CHANCERY LANE &
COLLIDED ONTO MY VEHICLE'S FRONT RH PORTION
DESPITE HORNING HER OUT OF PANIC NO INJURIES
NO PASSENGERS

DECLARATION

I/We declare the foregoing particulars are true and correct

31/5/19

Full Name: [Signature]
Date: [Signature]

Officer's Name: [Signature]
Rank: [Signature]
Signature: [Signature]

Reporting Officer's Name: [Signature]
Signature: [Signature]
Signature: [Signature]

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





redefining / insurance

Insurance policy

AXA Insurance Pte Ltd
 1800 888 4888 (Within Singapore)
 (05) 6880 4888 (International)
 (65) 6880 4740
 customers.care@axa.com.sg
 www.axa.com.sg

account number
 03288

Certificate of Insurance

Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia)
 Motor Vehicles (Third Party Risks) Rules, 1955 (Singapore)

Policy details

Policyholder name	TAN KAI DHAN CAESARIAN	Certificate number	6A483776 / 1
Cover	Comprehensive	Chassis number	WDD2130452A338571
Plan name	Flexi	Engine number	27492031180557
NCD applicable	50%		
Vehicle registration number	Kindly submit your Vehicle Registration number as soon as you have it		
Period of insurance	from 05/10/2018 to 04/10/2019 (both dates inclusive)		
Finance lease company	GING INVESTMENTS & FINANCE LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
 (b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation to that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor traffic or when the Motor Car, whether stationary, in use or otherwise, is in or on a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations imposed in accordance with Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), and not to be included under these headings.

EXCESS	Windscreen Excess	Not Applicable
--------	-------------------	----------------

An Additional Excess is applicable as follows:

1. \$8500 for unnamed Authorized Driver
2. \$8500 for declared Young and Inexperienced Driver
3. \$85,000 for undetected Young and Inexperienced Drivers. This additional excess is reduced to \$12,500 if You have chosen AXA Premium Workshop.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorized signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189).
 The Premium Warranty Clause requires the premium to be paid in full within a specific period (varying which there must be no delay) under the policy, renewal certificate, endorsement, etc.

Driving License

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

5266513H

CAESARIAN TAN KAI CHAN

Birth Date: 05 Oct 1953
Issue Date: 07 Jan 2003

10000940568




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Dec 1994

NP 428A

Licence No: 5266513H



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	31/05/2019 17:43
Date Of Accident	30/05/2019 19:20
Exact Location Of Accident	CHANCERY LANE TURNING INTO JLN PARISAN RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG4278K
Insured/Policyholder	
Name Of Registered Owner	33 AUCTION ASIA PTE. LTD.
Co Reg No	201321468H
Email Address	DAVID.FU@33AUCTION.COM
Mobile Phone No	(LOCAL) +65-93867233
Alternative Phone No	OFFICE-67474555
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER-2.0 ELEGANCE (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29014701MCX
Cover Note Number	
Driver	
Name of Driver	LINDA HARDI LIM
Passport No/FIN	X335027
Date Of Birth	22/06/1963
Occupation	INDOOR
Date Of Driving Pass	06/09/2017
Driving Experience	1 YEAR AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98213030
Fax Number	
Contact Number	

Address	29 GENTLE RD
Postcode	309149
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - CUSTOMER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (Including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME5783K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

31 MAY 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Melody Teoh
Customer Service Advisor
Accident & Bodyshop

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 30 May 2019 @ about 7.17pm, I was travelling along Chancery Lane, heading home in Vehicle A (SLG 4278K).

I made a right turn into Jalan Pasiran Road. The roads were dark. Whilst turning into Jalan Pasiran Road, I suddenly collided into Vehicle B (SME 5783K) which was waiting to turn out from Jalan Pasiran Road. No one was injured in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

31 MAY 2019

(SARMC SketchPlanForm_v3)

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name:

NRIC/PIR No.:

Melody Teoh

Customer Service Advisor



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, #21-01, SGT Centre 2, Singapore 06887
 Tel: +65 6807 7888 Fax: +65 6807 7899
 Ex. Reg. No. 2004122175, 1217 Reg. No. 2004122175

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 186 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1986 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form M.E.4
 Singapore (Continued)

MOTORMAX COMMERCIAL
 Comprehensive

Certificate No. A 28014101 MCE

Excess: S\$2500

Windscreen Excess: S\$2100

1. Index Mark and Registration Number of Vehicle
 81042788

2. Name of Policyholder
 33 Auction Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 29/09/2018

4. Date of Expiry of Insurance
 28/09/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
 The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORIZED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of its termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 186) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HUA LIAN AGENCIES PTE LTD
 3 JURONG EAST ST 21
 #03-110 HLM BUILDING
 SINGAPORE 60021
 TEL: +65 6351 2721 FAX: +65 6351 8705

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurer


 For Chief Executive Officer

Company Reg

Home > [Buy Information](#) > [Buy Business Profile and Other Information](#)

Type of Business Information

Instant Information

Business Profile

Business Profile with Certificate of production

Corporate Compliance and Financial Profile

People Profile

Extracts

Certificates

Register

Product Bundle

Package Information

Standard Package

Price and Choice

Other Services

[Transaction Status Enquiry](#)

[Product Authentication](#)

[Refund Application](#)

[Refund Enquiry](#)

Enter Entity Name or Unique Entity Number (UEN)

33 AUCTION

Search Criteria

Entity Name Starting With



Capitula (Enter the above 3 characters)*

Search

Entity

Pa

Filter by

Reset

Showing 1 - 2 of 2 items

View 2

Back Next

Name : 33 AUCTION ASIA PTE. LTD.

UEN : 201321468H

Status : LIVE COMPANY

Address : 27A LOEWEN ROAD SINGAPORE 248636

Industry : ACTIVITIES OF AUCTION HOUSES

Annual Return : N.A.

Annual General Meeting : N.A.

Financial Statements Filed : NOT APPLICABLE

Buy Information

Name : 33 AUCTION PTE. LTD.(Pte.)

WALINDA INVESTMENT PTE LTD(Pte.)

UEN : 19906746M

Status : LIVE COMPANY

Address : 27A LOEWEN ROAD SINGAPORE 248636

Industry : ACTIVITIES OF AUCTION HOUSES

Buy Information

Annual Return : Last Filed on 11/10/2014 for Financial Year ending 31/12/2013

Annual General Meeting : Last Held on 15/09/2014

Financial Statements Filed : 31 Dec 2005 31 Dec 2006

Driving License

KHIRANDAH KEMUDIA PENGUMUD

Urut Keluarga (Pilih Urutan) 1

Urutan 2

Urutan 3

Urutan 4

Urutan 5

KETERANGAN KEMUDIA YANG BERLAKU UNTUK URUTAN

Sebelum	A
Sebelum	B
Sebelum	C
Sebelum	D
Sebelum	E

KETERANGAN YANG MENENTUKAN PENGUMUD

1. LINDA HARDE LIP

2.

MEDAN

3.

22-June-1963

4.

JL.BRAWIJAYA 1 C NO.4 JAKARTA SELATAN

5.

A ☐

B ☐

C ☐

D ☐

E ☐

Signature of Linda

DISQUALIFICATIONS

The holder is holder of the right to live in the

territory of _____ and _____

at _____

The holder is, signed on the right to live in the

territory of _____

No. 0008480

INDONESIA

International Motor Traffic

Surat Izin Mengemudi Internasional
INTERNATIONAL DRIVING PERMIT

Konvensi Lalu Lintas Kendaraan Bermotor Tanggal 8 November 1968
(Convention on Road Traffic of 8 November 1968)

06 September 2008

Berkas lengkap dengan:
VAND 4876

Dikurahkan oleh
Issued by

Suburta

06 September 2017

AV

Tanggal
Date

KORPRI LALU LINTAS POLRI

KORPRI LALU LINTAS POLRI
CORPORATE TRAFFIC POLICE
JALAN PUSAT NO. 100
JAYA KARTASARI, JAKARTA, 10110

06 September 2017

KORPRI LALU LINTAS POLRI
CORPORATE TRAFFIC POLICE
JALAN PUSAT NO. 100
JAYA KARTASARI, JAKARTA, 10110

Passport

1. Welche ist die wichtigste Voraussetzung für die Entstehung von Krebs?
 2. Welche sind die wichtigsten Ursachen für die Entstehung von Krebs?
 3. Welche sind die wichtigsten Risikofaktoren für die Entstehung von Krebs?
 4. Welche sind die wichtigsten Symptome für die Entstehung von Krebs?
 5. Welche sind die wichtigsten Diagnoseverfahren für die Entstehung von Krebs?
 6. Welche sind die wichtigsten Therapieoptionen für die Entstehung von Krebs?
 7. Welche sind die wichtigsten Prognosefaktoren für die Entstehung von Krebs?
 8. Welche sind die wichtigsten Präventionsmaßnahmen für die Entstehung von Krebs?
 9. Welche sind die wichtigsten Forschungsergebnisse für die Entstehung von Krebs?
 10. Welche sind die wichtigsten klinischen Studien für die Entstehung von Krebs?

REPUBLIC OF INDONESIA
REPUBLIC OF INDONESIA

NDN

doi:10.1017/S0022292410000533

X335027

LINDA HARDY LIM

INDONESIA

22 JUN 1983

PAF

MEDAN

10 FEB 2017

10 FEB 2022

HKIM 11210000000291A58JB5231FR,5V

JAKARTA BARAT

F<IONLIM<<LINDA<HARDI<<<<<<<<<<<<<<<<<<<<<<
X335027<<9IDN6306221F22021073174076206000776

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo

TOYOTA MOTOR CORPORATION JAPAN
MODEL DBA-ZSU60W-ANXMP
ENGINE 3ZR-FAE 1986 mL
FRAME No. ZSU60-0077774
COLOR TRIM PLANT OPTION
1F7 FA20 A31
TRANS./AXLE K114 -01A 424

Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019 13:53		04 Jun 2019 16:24 Edit Adj Rpt	S\$13,000.00 Edit Estimates	S\$13,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	33 AUCTION ASIA PTE. LTD., Co. Reg. No.: 201321468H								
Main Claimant:	CAESARIAN TAN KAI CHAH, ID: S2656513H								
Vehicle Reg. No.:	SME5783K	Date of Loss:	30/05/2019 19:00 - :59 [7 Months and 25 Days From LTA Reg. Date (Man Yr)]						
Claim Type:	TP / 595467	Policy/Cover Note No.:	A29014701MCX (Comprehensive) Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	SLG4278K	Policy No. (Claimant):							
		Excess:	S\$3,600.00						
Repairer:	Toh Painting & Services Pte Ltd (HQ) BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW TEE INDUSTRIAL ESTATE, 677966 Woodlands - Tel: 67607541								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 11/09/2019]								
Driver/Custodian (Insured):	LINDA HARDI LIM (), NRIC: X335027 Email:								
Adj Asg. Remarks:	on WP, Liab: 100%. TP lawyer disagree on SJE - assign LKK Auto Consultants. Contact: Jennifer/ Xiuhui @ 6763 1055.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (09/09/2019): Report Send Back Alerts - SME5783K (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME5783K (595467)
[SLG4278K]
TP
CAESARIAN TAN KAI CHAH
May 30 2019 7:00PM
[33 AUCTION ASIA PTE. LTD.]
Toh Painting & Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/06/19 11:38	General View		Load JPG	
2	07/06/19 11:38	General View		Load JPG	
3	07/06/19 11:38	General View		Load JPG	
4	07/06/19 11:38	General View		Load JPG	
5	07/06/19 11:38	General View		Load JPG	
6	07/06/19 11:38	General View		Load JPG	
7	07/06/19 11:38	General View		Load JPG	
8	07/06/19 11:38	General View		Load JPG	
9	07/06/19 11:38	General View		Load JPG	
10	07/06/19 11:38	General View		Load JPG	
11	07/06/19 11:38	General View		Load JPG	
12	07/06/19 11:38	General View		Load JPG	
13	07/06/19 11:38	General View		Load JPG	
14	07/06/19 11:38	General View		Load JPG	
15	07/06/19 11:38	General View		Load JPG	
16	07/06/19 11:38	General View		Load JPG	
17	07/06/19 11:38	General View		Load JPG	
18	07/06/19 11:38	General View		Load JPG	
19	07/06/19 11:38	General View		Load JPG	
20	07/06/19 11:38	General View		Load JPG	
21	07/06/19 11:38	General View		Load JPG	
22	07/06/19 11:38	General View		Load JPG	
23	02/10/19 10:19	Reinspection Photo		Load JPG	
24	02/10/19 10:19	Reinspection Photo		Load JPG	
25	02/10/19 10:19	Reinspection Photo		Load JPG	
26	02/10/19 10:19	Reinspection Photo		Load JPG	
27	02/10/19 10:19	Reinspection Photo		Load JPG	
28	02/10/19 10:19	Reinspection Photo		Load JPG	
29	02/10/19 10:19	Reinspection Photo		Load JPG	
30	02/10/19 10:19	Reinspection Photo		Load JPG	
31	02/10/19 10:19	Reinspection Photo		Load JPG	
32	02/10/19 10:19	Reinspection Photo		Load JPG	

Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/06/19 13:54	OI GIA		Load PDF	
2	03/06/19 13:54	TP GIA		Load PDF	
3	04/06/19 10:17	Workshop details		Load PDF	
4	12/07/19 09:24	REPAIR BILL, SURVEY REPORT		Load PDF	
5	12/07/19 09:24	SURVEY PHOTOS1		Load PDF	
6	12/07/19 09:24	SURVEY PHOTOS2		Load PDF	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/19 13:47	Colour Photo		Load PDF	
2	02/10/19 13:48	PRS Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19009911/NSD3E2-1

Date: 02/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29014701MCX

Claimant
Vehicle No : SME5783K

Insured Vehicle No : SLG4278K

Date of Loss: 30/05/2019

Nature of Claim: TP

Claim No: 595467

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5783K

Make & Model: MERCEDES-BENZ E250, 2.0 AMG LINE (R19 LED) (A)

Engine No: 27492031180557

Reg. Date: 05/10/2018 (Man. Year: 2017)

Chassis No: WDD2130452A318571

Colour: Blue

Odometer: 0 km

Engine Capacity: 1991 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size:

245/40 R19

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,175.70	14,266.49	5,909.21	29.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,890.00	1,090.00	36.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,155.70	16,156.49	6,999.21	30.23
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	23,155.70	13,000.00	10,155.70	43.86
+ GST 7.00/7.00% (S\$)	1,620.90	910.00	710.90	43.86
Nett Amount (S\$)	24,776.60	13,910.00	10,866.60	43.86

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 27/09/2019 Inspected At:

Toh Painting & Services Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD, UNIT
391C&G YEW TEE INDUSTRIAL
ESTATE
Singapore 677966

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
Parts: 143	MERCEDES-BENZ E250 2.0 AMG LINE (R19 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5783K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TRIM BUMPER	Cracked	1,889.61 FL	*1,500.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Broken	171.64 FL	*171.64 FL
3	1		*FRONT BUMPER LOWER ORNAMENTAL MOLDING	Scratched	553.02 FL	*300.00 FL
4	1		*FRONT LICENCE PLATE MOLDING	Deformed	145.02 FL	*145.02 FL
5	1		*FRONT BUMPER CHROME RING	Serviceable	324.20 FL	*- FL
6	1		*FRONT BUMPER SIDE GRILLE RH	Scratched	108.24 FL	*108.24 FL
7	1		*(STR) RADAR SENSOR	Not Necessary	1,804.94 FL	*- FL
8	1		*RADAR MOUNTING BRACKET	Bent	11.42 FL	*11.42 FL
9	1		*FRONT LOWER BASIC MOUNTING FOR BUMPER	Broken	143.96 FL	*143.96 FL
10	1		*IMPACT ABSORBER	Not Necessary	209.78 FL	*- FL
11	1		*SIDE BASIC MOUNTING FOR BUMPER	O/S Cracked / N/S Serviceable	185.90 FL	*92.95 FL
12	2		*SIDE MOUNTING RAIL	Necessary	19.88 FL	*19.88 FL
13	6		*DISTANCE SENSOR	Serviceable	1,215.16 FL	*- FL
14	6		*SPACER RING	Not Necessary	43.82 FL	*- FL
15	1		*BONNET	Buckled	2,654.80 FL	*2,300.00 FL
16	1		*RADIATOR GRILLE AIR DUCT SEGMENT	Broken	152.56 FL	*152.56 FL
17	1		*MB STAR HOLDER	Not Necessary	87.75 FL	*- FL
18	1		*FRONT MERCEDES STAR	Necessary	161.59 FL	*161.59 FL
19	1		*RAD GRILLE ORNAMENTAL MOLDING	Necessary	77.02 FL	*77.02 FL
20	1		*RAD GRILLE GARNISH	Broken	771.68 FL	*500.00 FL
21	1		*RAD GRILLE	Broken	514.48 FL	*514.48 FL
22	1		*RAD GRILLE FRAME	Cracked	395.73 FL	*300.00 FL
23	2		*HEADLAMP UNIT	Cracked	7,814.16 FL	*7,000.00 FL
24	1		*CROSS MEMBER	Dented	607.28 FL	*607.28 FL
25	1		*SUPPORT PANEL	Dented	607.28 FL	*400.00 FL
26	1		*SUPPORT PANEL CONSOLE MOUNTING	Serviceable	244.32 FL	*- FL
27	1		*BONNET RETAINING HOOK	Serviceable	81.03 FL	*- FL
28	1		*RIGHT FRONT SUPPORT PANEL CONSOLE	Broken	119.00 FL	*119.00 FL
29	1		*FRONT FENDER RH	Dented	998.78 FL	*998.78 FL
30	1		*FRONT FENDER COWLING RH	Torn	118.53 FL	*118.53 FL
31	1		*FRONT INTERMEDIATE LAYER RH	Necessary	11.53 FL	*11.53 FL
32	1		*SET FRONT BUMPER CLIP	Necessary	58.00 FS	*58.00 FS
33	1		*SET FRONT FENDER COWLING CLIP RH	Not Necessary	48.00 FS	*- FS
34	1		*FRONT LICENCE PLATE	Dented	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 22,400.11 15,841.88
 - List Item Discount on L Items 10.00/10.00% (\$\$) 2,224.41 1,575.39

Total Parts (\$\$) 20,175.70 14,266.49

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR & REPLACE FRONT DAMAGED PARTS	New	1,200.00	800.00
2	SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	CHECK WIRING & REFOCUS HEADLAMP	New	60.00	40.00
4	DIAGNOSE & RESET SYSTEM AFTER REPAIR	New	420.00	200.00
5	SPRAY ANTI RUST ON AFFECTED AREA	New	100.00	50.00
Gross Labour Cost (S\$)			2,980.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >