

000000

INS. CASE OWNER:

CC 4/III1901

3549, Fgh3

LKK

IDAC:

Surveyor:

Ram

DOI:

ASSIGNMENT

2/8/19

Date / Time:

1/8/19

Registered in Merimen:

2/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 2423P

Name of Insured:

CTOL

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

2/8/19

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO. Driver Name / Age: A KAZIM BIN ABONUKAH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

WUOMO 015

LEBANDWI

SINGI AVE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 2423P

FBL 404T

SLN 8705G



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

FBL 404T - M/14/19/21/20/1/24 404T: 2/8/19  
SHC 2423P - x

2/8/19

16/8

2/8/19

2/10

At lost control of veh. Reg. AWP form off.  
Pending liability approval. (Approved)  
Submit WP report. Case can transfer to  
handle as per city instruction.  
File para Admin to close.

STAGE	DATE / PIC
Non-Reporting Itr (1st):	
Non-Reporting Itr (2nd):	
Non-Reporting Itr (Final):	
Notification Itr (if non-pickup):	
Call OI:	
After call Itr to OI:	
Documentation Check List:	Handler Typist
Notification Itr (if non-pickup)	
After call Itr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

S\$ 1600.00

( 5

days)

Reduction:

41600

% 64

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28. Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(5

x

days)

Loss of Income (LOI):

S\$

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search:

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle  
2) Report Format: WP  
3) Survey fee: 4750/-

COPY SENT 4/10/19

CG 01 (lost control) of veh.

Ram

Email

Call

REPORT

ASS. REC. BY:

REP: CS/TH 19013549/F. 13

Special Instructions:

Surveyor: RAIN

ASSIGNMENT (Office)

From (Person): Gabriel wee

of III

Date/Time: 1/8/19 5.28pm

Estimated Cost:

Bill to:

OD/TP WST/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 409T

Insured:

SHC2423P

at Workshop n/s

Bike Dynamic

Tel:

6749 6637

of

Bik 6 Defuncte 10 # 01-554

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/07/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:22am 2/8/19

Person Contacted:

han

Vehicle IN/OUT

Date/Time	Action/Instruction
	Isbawale 1x
	FBL 409T - X
	SHC 2423P - CC4 1 19013549 71 463
	1204 - 24/07/2019
5/8/19	@ 150pm Eileen agree on Direct Settlement

ASS. REC. BY: RAM

REF: III

PRS

# ASSIGNMENT

From: \_\_\_\_\_ Date: 2/8/19

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 409T

at Workshop n/s: Bike Dynamic

of BIK 6 DeFu lane 18 # 01-554

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Look For Eileen

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBL 409T Yr Regn: MAY / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha FZ150 cc 149

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: out on T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: MEIRG16/82001907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100/80 R17

R: 130/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 4 mm R/Bal: 5 mm

L/Bal: - mm L/Bal: - mm

D.O.A. 24/07/2019 D.O.I. 02/08/2019

Survey held at BIKE DYNAMIC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: \$1000 - \$2000
	Repair days: 4 days
	ESTIMATE WILL BE GIVEN LATER!
	MV: \$1500
	PV: \$4278
	NV: 3000

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

3) = + RS. 34

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Long Form / Short Form

# **QUOTATION FOR REPAIR : FBL409T**

Qty	Description
2 pc	MIRROR L&R
1 pc	HANDLE BAR
1 pc	Brake Lever
2 pc	Balancer
1 pc	Fuel Tank Left Hand Cowling
1 pc	Front Mudguard
1 pc	Rear Mudguard
1 set	Box Rack
1 pc	Swingarm
1 set	Fork
1 Set	Exhaust Cover
1 pc	Front Fuel Tank Cover Left Side
1 pc	Left side Middle Cover
2 pc	Front Footrest
2 pc	Rear Footrest
1 pc	Splash Guard

## **Repairer's Estimate**

NNX	88.00
BT	180.00 \$95
Br	95.00 \$20
Cr	95.00 \$20
Cr	151.00 \$80
Cut	80.00
NNX	80.00
Scr	350.00 \$150
NNX	338.00
BT	450.00
Scr	158.00 \$60
Cr	98.00 \$79
Cut	108.00 \$88
NNX	158.00
Scr	158.00 \$68
Br	98.00 \$69

1st Hem: \$1257

2,685.00

gst 10% = \$1131.30

2,685.00

## **Nett items**

1 pc	Fork Oil Shield
1 pc	Fork Dust Cover
2 pc	number plate
1 pc	Box
2 Bottle	Fork Oil
	Total parts

rec	48.00 \$40
rec	48.00 \$40
BT	28.00
Scr	350.00 \$180
rec	40.00 \$30

3,199.00

Nett Item: \$318

Steering Cone  
towing to alignment body frame (2 way)  
Alignment Body Frame  
Towing fees  
Front rim realign  
Workmanship  
Total parts and labour charges

55.00

20.00

380.00

45.00

80.00

600.00

4,449.00

8 days

Labour: \$55

Total: \$2034.30

4/5 20% = \$1600.00

23/8/19  
R/Days: 5days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	6811

**Vehicle Details**

Vehicle No.:	FBL409T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	FZN150
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	G3E3E0034024
Chassis No.:	ME1RG1618G2001907
Maximum Power Output:	-
Open Market Value:	\$2,362.00
Original Registration Date:	20 May 2016
First Registration Date:	20 May 2016
Transfer Count:	1
Actual ARF Paid:	\$355.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	19 May 2026
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,303.00
COE Rebate Amount:	\$4,278.00
<b>Total Rebate Amount:</b>	<b>\$4,278.00</b>

The information contained herein is correct as at 05 Aug 2019

OK

**Cecilia Chong (LKK Auto)**

---

**From:** Sundari Nagarajan - III <sundari@iii.com.sg>  
**Sent:** Wednesday, 2 October 2019 2:09 PM  
**To:** Cecilia Chong (LKK Auto)  
**Cc:** CS A Team; Hsiao Tong (LKKAuto); Olivia Lau (LKKAuto)  
**Subject:** MCT19070647/01/sn; Accdt invg SHC2423P(III) & FBL409T on 24.7.19

**U r g e n t**

Dear Cecila

We refer to the above accident. We understand that you are the handler for this case. We have already written to LKK on 19.9.19 to submit the survey report but till now SR has not been uploaded in merimen.

Please note that we have already received LOD from TP solicitors on 2.9.19 and they are chasing us for settlement.

Regards,

**Sundari Nagarajan**  
Motor Claims Department  
India International Insurance Pte Ltd  
64, Cecil Street, #04/#05 IOB Building  
Singapore 049711  
DID: 63476071  
FAX: 62244174  
[sundari@iii.com.sg](mailto:sundari@iii.com.sg)  
[www.iii.com.sg](http://www.iii.com.sg)  
Regn No.: 198703792K

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Thursday, 1 August 2019 5:28 PM  
**To:** Sally; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Sundari Nagarajan - III  
**Subject:** RE: [Spam-pop3] RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBL409T (Accident involving FBL409T and SHC2423P on 24.07.2019)  
**Attachments:** shc2423p\_20190731144307.pdf; shc2423p\_20190731144307.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FBL409T and let us have your report urgently.

This claim will be handled by Ms Sundari.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Sally [mailto:info@catherinelimllc.com]  
**Sent:** 01 August, 2019 3:00 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** RE: [Spam-pop3] RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBL409T (Accident involving FBL409T and SHC2423P on 24.07.2019)

Dear Sir (Without Prejudice)

We confirm our client's motorcycle is currently in Bike Dynamic.

Regards  
Sally Goh  
Catherine Lim LLC  
20 Havelock Road #03-01  
Central Square  
Singapore 059765  
Email: [info@catherinelimllc.com](mailto:info@catherinelimllc.com)

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Thursday, August 01, 2019 12:19 PM

**To:** Sally

**Subject:** [Spam-pop3] RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBL409T (Accident involving FBL409T and SHC2423P on 24.07.2019)

Dear Sally,

We have already received a Survey request from Teamwork Garage. Kindly confirm that your client has decided to change his workshop bike dynamic.

*Best Regards,*

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

---

**From:** Sally [<mailto:info@catherinelimllc.com>]

**Sent:** 01 August, 2019 11:26 AM

**To:** Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)>

**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FBL409T (Accident involving FBL409T and SHC2423P on 24.07.2019)

Dear Sir (Without Prejudice)

We refer to your email.

Our client is agreeable to LKK. Please arrange.

Regards

Sally Goh

Catherine Lim LLC

20 Havelock Road #03-01

Central Square

Singapore 059765

Email: [info@catherinelimllc.com](mailto:info@catherinelimllc.com)

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Wednesday, July 31, 2019 2:51 PM

**To:** Sally

**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. FBL409T (Accident involving FBL409T and SHC2423P on 24.07.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.



We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

#### DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS  
畢 NOTARY PUBLIC - 公証官  
玲 COMMISSIONER FOR OATHS - 宣誓官  
律師 CATHERINE C.L.LIM  
情 DIRECTOR  
LLB (HONS) SINGAPORE - 法律系-律師  
M.B.A. (BUSINESS LAW) - 商業系-碩士

20 Havelock Road #03-01  
Central Square Singapore 059765  
UEN No. 201310922K

Tel: (65) 6438 5500  
Fax: (65) 6438 0111  
www.catherinelimllc.com  
Email: info@catherinelimllc.com  
CATHERINE LIM LLC is a law corporation  
with limited liability

Your Ref: SHC 2423P  
Our Ref: CL/1907100/T/BD.sg

31 July 2019

To: India International Insurance Pte Ltd  
64 Cecil Street #04-05  
IOB Building  
Singapore 049711  
Attn: Motor Claims Dept

via fax: 6224 4174 & By Hand

Comfort Transportation Pte Ltd  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

CERTIFICATE OF POSTING  
(Please be informed that all supporting documents  
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBL 409T / SHC 2423P ON 24.07.2019 ALONG SIMET AVE**

We are instructed by WILSON TAY to notify you of a road traffic accident involving our client's vehicle No. FBL 409T and vehicle No. SHC 2423P driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Bike Dynamic  
Blk 6 Defu Lane 10  
#01-554  
Singapore 539187

Tel: 6749 6637 for Eileen

Fax: 6749 6120

Yours faithfully

Enc

Cc: client





Bike model  
Yamaha FZn150

Type  
Any

Price From  
Any

Price To  
Any

Class  
Any

MORE SEARCH OPTIONS ▼

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH ▼

Yamaha FZN150i (/listing/usedbike/yamaha-yamaha-fzn150i/13665/)



(/listing/usedbike/yamaha-yamaha-fzn150i/13665/)

SGD \$6999

Reg : 25/08/2017

Type: Street Bikes

149cc

Downpayment \$699 Before Insurance. Viewing At Bike Production Pte Ltd. Please Kindly Call To Confirm Availability Before Viewing. Address: 610, Serangoon Road S(218216) Tel: 63922555. Trade in/...

Posted on : 02/08/2019

★ PAID AD ★ DEALER AD

■ COMPARE

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-FZN150I/13665/)

Yamaha FZN150i (/listing/usedbike/yamaha-yamaha-fzn150i/12497/)



(/listing/usedbike/yamaha-yamaha-fzn150i/12497/)

SGD \$7778

Reg : 17/02/2016

Type: Street Bikes

149cc

Showroom condition. Low fuel consumption.

Est Monthly SGD \$222

Posted on : 29/07/2019

★ PAID AD ★ DEALER AD

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2019 <a href="#">Edit Reg</a>		01 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	WILSON TAY, ID: S83826811								
Vehicle Reg. No.:	FBL409T	Date of Loss:	24/07/2019 17:00 - :59 [38 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19070647	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC2423P	Policy No. (Claimant):	D19MTC01003116						
		Excess:							
Repairer:	Bike Dynamic Centre (HQ) BLK 6 DEFU LANE 10 #01-554, 539187 Defu Lane - Tel: 67496637								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 15/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (30/09/2019): Alert - Adj Mandate Approved (S\$0.00) - FBL409T - Claim Handler: Sundari Nagaraj...</li> <li>III_SG (27/08/2019): Alert - Adj Mandate Approved (S\$0.00) - FBL409T - Claim Handler: Sundari Nagaraj...</li> <li>III_SG (19/08/2019): Alert - Adj Mandate Maintained - FBL409T - Claim Handler: Sundari Nagarajan</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*FBL409T (MCT19070647)  
 [SHC2423P]  
 TP  
 WILSON TAY  
 Jul 24 2019 5:00PM  
 [COMFORT TRANSPORTATION PTE LTD]  
 Bike Dynamic Centre

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images


1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
2	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
3	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
4	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
5	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
6	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
7	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
8	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
9	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
10	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
11	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
12	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
13	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
14	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
15	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
16	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
17	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
18	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
19	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
20	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
21	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
22	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
23	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
24	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
25	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
26	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
27	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
28	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
29	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
30	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
31	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
32	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
33	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
34	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
35	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
36	05/08/19 10:48	General View			<input checked="" type="checkbox"/>
37	05/08/19 10:48	chassis number			<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/08/19 16:15	EMAIL FROM III DD 01082019			
2	07/08/19 09:38	TP GIA REPORT			
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	05/08/19 10:03	Singapore Accident Statement IV SHC2423P			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	19/09/19 15:46	<b>Letter of Demand from Third Party</b> TPD LOD FROM CATHERINE LIM LLC (PBL409T)	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	



# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19013549/FGB3Q2

Date: 10/10/2019

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant FBL409T

Insured Vehicle No: SHC2423P

Vehicle No: FBL409T

Nature of Claim: TP Claim No: MCT19070647

Date of Loss: 24/07/2019

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBL409T

Make &amp; Model: YAMAHA FZ150, 150cc

Engine No: G3E3E0034024

Reg. Date: 20/05/2016 (Man. Year: 2016)

Chassis No: ME1RG1618G2001907

Colour: Red

Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 100/80 R17

Rear Tyre Size: 180/70 R17

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,199.00	1,449.30	1,749.70	54.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	585.00	665.00	53.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,449.00</b>	<b>2,034.30</b>	<b>2,414.70</b>	<b>54.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	<b>4,449.00</b>	<b>1,600.00</b>	<b>2,849.00</b>	<b>64.04</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>311.43</b>	<b>112.00</b>	<b>199.43</b>	<b>64.04</b>
<b>Nett Amount (S\$)</b>	<b>4,760.43</b>	<b>1,712.00</b>	<b>3,048.43</b>	<b>64.04</b>

### INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 02/08/2019 Inspected At:

Bike Dynamic Centre (HQ)  
BLK 6 DEFU LANE 10 #01-554  
Singapore 539187

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 10 Oct 2019)	
<b>Parts:</b>	N/A	YAMAHA FZ150 150cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBL409T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*MIRROR L&R	Not Necessary	88.00 F	*- FL
2	1		*HANDLE BAR	Bent	180.00 F	*95.00 FL
3	1		*BRAKE LEVER	Broken	95.00 F	*20.00 FL
4	2		*BALANCER	Cracked	95.00 F	*20.00 FL
5	1		*FUEL TANK LEFT HAND COWLING	Cracked	151.00 F	*80.00 FL
6	1		*FRONT MUDGUARD	Cut	80.00 F	*80.00 FL
7	1		*REAR MUDGUARD	Not Necessary	80.00 F	*- FL
8	1		*SET BOX RACK	Scratched	350.00 F	*150.00 FL
9	1		*SWINGARM	Not Necessary	338.00 F	*- FL
10	1		*SET FORK	Bent	450.00 F	*450.00 FL
11	1		*SET EXHAUST COVER	Scratched	158.00 F	*60.00 FL
12	1		*FRONT FUEL TANK COVER LEFT SIDE	Cracked	98.00 F	*78.00 FL
13	1		*LEFT SIDE MIDDLE COVER	Cut	108.00 F	*88.00 FL
14	2		*FRONT FOOTREST	Not Necessary	158.00 F	*- FL
15	2		*REAR FOOTREST	Scratched	158.00 F	*68.00 FL
16	1		*SPLASH GUARD	Broken	98.00 F	*68.00 FL
17	1		*FORK OIL SHIELD	Necessary	48.00 FS	*40.00 FS
18	1		*FORK DUST COVER	Necessary	48.00 FS	*40.00 FS
19	2		*NUMBER PLATE	Bent	28.00 FS	*28.00 FS
20	1		*BOX	Scratched	350.00 FS	*180.00 FS
21	2		*BOTTLE FORK OIL	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNeff. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,199.00</b>	<b>1,575.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>125.70</b>
<b>Total Parts (\$\$)</b>	<b>3,199.00</b>	<b>1,449.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STEERING CONE	New	55.00	55.00
2	TOWING TO ALIGNMENT BODY FRAME (2 WAY)	New	90.00	0.00
3	ALIGNMENT BODY FRAME	New	380.00	150.00
4	TOWING FEES	New	45.00	0.00
5	FRONT RIM REALIGN	New	80.00	80.00
6	WORKMANSHIP	New	600.00	300.00
Gross Labour Cost (\$\$)			<b>1,250.00</b>	<b>585.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >