

22/03/2021

ASS. REC. BY:

REF: CS31/TJ 19013550/EC1302

Special Instruction:

Assigner: Steve

ASSIGNMENT (Office)

From (Person): Gabriel wee

of

III

Date/Time: 1/8/19 @ 5.20pm

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 9851M

Insured:

SH 9123C

at Workshop m/s

Legacy Technica

Tel:

8858 8851

of

39 woodlands close # 01-08

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/7/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.21am

Person Contacted:

ERIC

Vehicle: IN/OUT

Date/Time	Action/Instruction
	Initials (X)
	SLW 9851M - X
	SH 9123C - AS/IRC 10014763/HS+K3 Don - 23/7/2010
	Dismantle: 6/8/2019 @ 11.30am.

ASS. REC. BY:

Steve

REF:

III

PRS

## ASSIGNMENT

From:

Date:

2/8/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 9851M

at Workshop m/s

Legacy Technica Motorsports

of 39 woodlands close # 01-08

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mr. ERIC @ 8858 8851

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

cup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLW 9851M

Yr Regn:

13/03/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

C.C

1496

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

5288

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A 8410169.153

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

905/60R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyo

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/7/19

D.O.I.

2/8/19

1234pm

Survey held at

Legacy Technica

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-75K

Repair range 10K - 11K, 8 days

RECEIVED 08 AUG 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

120

Transportation:

3 + PS, SI

Photos

Others

11

TOTAL

131

Report Format:

PRS

Lump Sum / L&amp;L (\$)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		02 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by adjuster]</b>						
Insured:									
Main Claimant: <b>TAN HUI LING VALERIE</b>									
Vehicle Reg. No.: <b>SLW9851M</b>		Date of Loss: 30/07/2019 07:00 - :59							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SH9123C</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Legacy Technica Motorsports (woodlands) (HQ)</b> 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS, 737856 Woodlands - Tel:									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 15/08/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Thursday, 1 August 2019 5:20 PM  
**To:** Accident@kscgp.com; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** jiapei@kscgp.com; Sundari Nagarajan - III  
**Subject:** RE: 2nd Notice to Conduct Pre-repair Survey - Our Ref: SLW 9851M/LT/jp/ps- Your Ref: SH 9123C  
**Attachments:** PRS-III\_20190801125221.pdf; 2nd PRS (reject) - III.PDF

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SLW9851M  
III INSURED VEHICLE NO. : SH9123C  
DATE OF LOSS : 30.07.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Accident@kscgp.com [mailto:Accident@kscgp.com]  
**Sent:** 01 August, 2019 2:12 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** jiapei@kscgp.com  
**Subject:** 2nd Notice to Conduct Pre-repair Survey - Our Ref: SLW 9851M/LT/jp/ps- Your Ref: SH 9123C

Dear Sirs,

We refer to the subject matter.

Please find enclosed 2nd Notice to Conduct Pre-repair Survey herewith for your attention.

Thank you.

Regards,

Sampu

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**To:** [Accident@kscgp.com](mailto:Accident@kscgp.com)

**Cc:** [jiapei@kscgp.com](mailto:jiapei@kscgp.com)

**Sent:** Thu, 1 Aug 2019 05:48:18 +0000

**Subject:**

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711

**From:** Accident@kscgp.com [mailto:Accident@kscgp.com]

**Sent:** 01 August, 2019 1:00 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>

**Cc:** jiapei@kscgp.com

**Subject:** Notice to Conduct Pre-repair Survey - Our Ref: SLW 9851M/LT/jp/ps - Your Ref: SH 9123C

Dear Sirs,

We refer to the subject matter.

Please find enclosed Notice to conduct Pre-repair Survey herewith for your attention.

Thank you.

Regards,

Sampu

for and on behalf of Mr Gurdeep Singh Sekhon

KSCGP Juris LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708

Email: [accident@kscgp.com](mailto:accident@kscgp.com)

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.  
Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.  
Registration No. 198703792-K

Your Ref : SH 9123C  
Our Ref : SLW 9851M  
Date : 1 August 2019

Fax : 6538 3708  
Tel : 3152 0984  
Email : [accident@kscgp.com](mailto:accident@kscgp.com)

India International Insurance Pte Ltd

BY EMAIL ONLY

**DATE OF ACCIDENT: 30 JULY 2019**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS**

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/no.	Name of Surveyor
1	Richard Wong of RW Automotive Appraisers Services

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Legacy Tecnica Motorsports  
39 Woodlands Close  
#01-08, MEGA @ Woodlands  
Singapore 737856

Contact Person/Tel : Mr Eric Wong / 8858 8851

Yours faithfully,

*PS*



Your Ref : SH 9123C  
Our Ref : SLW 9851M  
Date : 1 August 2019

### Acknowledgement

This is to confirm that I \_\_\_\_\_ *[Full Name of Surveyor]* of  
\_\_\_\_\_ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(c) Re-inspection of new replacement part (part by part) on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

(d) Post – Repair Survey/Inspection on \_\_\_\_\_ [Date] at \_\_\_\_\_ [Time].

\_\_\_\_\_  
Name and signature of Appointed Surveyor  
Company Stamp

\_\_\_\_\_  
Witnessed by:  
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	231F
<b>Vehicle Details</b>	
Vehicle No.:	SLW9851M
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520460768
Chassis No.:	JM6BN22A8H0169153
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,299.00
Original Registration Date:	13 Mar 2018
First Registration Date:	13 Mar 2018
Transfer Count:	1
Actual ARF Paid:	\$14,299.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Mar 2028
PARF Rebate Amount:	\$10,724.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$30,997.00
<b>Total Rebate Amount:</b>	<b>\$41,721.00</b>

The information contained herein is correct as at 02 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/07/2019 18:56
Date Of Accident	30/07/2019 07:15
Exact Location Of Accident	CROSS JUNCTION BETWEEN WOODLANDS AVE 6 & 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9851M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN HUI LING VALERIE
NRIC No	S8222231F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96405349
Alternative Phone No	OFFICE-96405349

### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN EU6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107013333
Cover Note Number	

### Driver

Name of Driver	TAN HUI LING VALERIE
NRIC No	S8222231F
Date Of Birth	08/07/1982
Occupation	INDOOR
Date Of Driving Pass	08/01/2019
Driving Experience	0 YEAR AND 6 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96405349
Fax Number	
Contact Number	OFFICE-96405349
EMail Address	NOEMAIL

Address	15 WOODLANDS AVENUE 6 #02-12 TWIN FOUNTAINS
Postcode	738995
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH9123C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJW6836B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name: Lai  
NRIC/FIN No.:

Sketch Plan #2

Woodlands Aves

SKETCH PLAN

Seagate



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date: 30 July 2019, Time: 0715hrs, Location: Cross Junction Traffic Light along Woodlands Ave 6 & S.

On the above mentioned date, time & location, I was driving my car SLW 9851M along Woodlands Ave 6. The car in front was driving off from green light and I signal to turn right after chevron line. A taxi dash through the chevron line and collide onto my car, the impact was so huge that my car collide onto the front car (SJW 6836B). I alighted to check on the damage, but the taxi try to drive off and have no intention to stop & check.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(\* driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Lai  
NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2019 09:11 <a href="#">Edit Reg</a>		01 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>TAN HUI LING VALERIE</b>									
Vehicle Reg. No.: <b>SLW9851M</b>		Date of Loss: 30/07/2019 07:00 - :59 [16 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>SH9123C</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Legacy Technica Motorsports (woodlands) (HQ)</b> 39 WOODLANDS CLOSE, #01-08 MEGA @ WOODLANDS, 737856 Woodlands - Tel:									
Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 15/08/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLW9851M

[SH9123C]






































TP



















































TAN HUI LING VALERIE



















































Jul 30 2019 7:00AM
























[-]

Legacy Technica Motorsports (woodlands)

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	02/08/19 18:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
57	02/08/19 18:24	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
58	02/08/19 18:24	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
59	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
60	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
61	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
62	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
63	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
64	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
65	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
66	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
67	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
68	02/08/19 18:24	General View	 Load JPG	<input checked="" type="checkbox"/>
69	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
131	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
132	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
133	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
134	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
135	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
136	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
137	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
139	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
140	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
141	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
142	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
143	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
144	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
145	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
146	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
147	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
148	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
149	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
150	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
151	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
152	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
153	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
154	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
155	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
156	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
157	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
158	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
159	07/08/19 12:29	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 10:06	Singapore Accident Statement IV SH9123C	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19013550/ECF3E2

Date: 08/08/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SLW9851M

Insured Vehicle No : SH9123C

Date of Loss: 30/07/2019

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLW9851M

Make &amp; Model: MAZDA 3, 1.5 SEDAN EU6 (A)

Engine No: P520460768

Reg. Date: 13/03/2018 (Man. Year: 2017)

Chassis No: JM6BN22A8H0169153

Colour: Grey

Odometer: 5288 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 02/08/2019 Inspected At:

Legacy Technica Motorsports (woodlands)  
(HQ)  
39 WOODLANDS CLOSE, #01-08 MEGA  
@ WOODLANDS  
Singapore 737856

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 08 Aug 2019)

**Parts:** 143      MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLW9851M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >