

ASS. REC. BY:

REF: CS/FCI/19013635/ESD3^{N2}

Special Instruction:

Owner: Steve

ASSIGNMENT (Office)

CWS

From (Person): Sithera

of FCI

Date/Time: 11.16am 5/8/19

Estimated Cost:

Bill to:

OP / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMG 9795P

Insured:

SHC 0752C

at Workshop m/s

Cycle & Carriage Ltd
209 Penden Gardens

Tel:

65684555

Policy No:

Claim No:

D19004939 MFH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 27/07/2019

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time: 12.05pm @ 5/8/19

Person Contacted:

Jon Bong

Vehicle IN

OUT

Date/Time	Action/Instruction	Initials
	SMG 9795P-X	
	SHC 0752C - NBA / MS415017101/el	
		JOA: 9/10/15
14/08/19 @ 13:40 pm	revised RA to sithera v/a email.	

ASS. REC. BY: Star

REF: FCI

ASSIGNMENT

From: _____ Date: 8/8/2019

Veh No: SMG979SP Yr Regn: 8/01/19

Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

To inspect Vehicle No: SMG 979SP
at Workshop m/s Cycle & Carriage Kia
of 209 Penden Gardens

Make: KIA Cerato c.c. 1591
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 15536 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: KNAF3416MKS020857

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____
(Client's Record)

Steering: In order / Jammed / Leaked / Burnt or

Make of Veh: 2pm (writing)

Brake: In order / Jammed / Leaked / Burnt or

(Policy Condition)

Modi: Nil / S/Rim / STD A/Rim or

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	<u>xx</u>

Tyre Size: F: 225/45R17
R: 11

Bal. or Market Value: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kumho

IDAC Accident Rpt: _____ Consistent?: Yes or No

Front R/Bal. 5 mm

GIA / PR Seen: _____ Consistent?: Yes or No

Rear R/Bal. 5 mm

Est. Repairs: _____ days Res.: Yes or No

L/Bal. 5 mm

Lum Sum: _____ % 3 Val.: Yes or No

D.O.A. 27/7/19 D.O.I. 8/8/19

CA / REV / REP. / 24 HRS (DS)

Survey held at CUC (Photos)

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date / Time	Action / Instruction
	<u>MV-74K 11/10/19 Finalize (only \$2194.95 (PIP), 3 days (A/Ting) (\$ 3,869.60 Red - 64%)</u>

RECEIVED 14 OCT 2019

14/10/2019

Date/Time, File Pass to? 14/10/19 : Preli. Report

Days Of Repair: 3

1) Typ 4 : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to? _____

Add Fee: : Site Insp (\$ _____)

Survey Fee:	<u>145</u>
Transportation:	<u>50</u>
S + RS. St	<u>50</u>
Photos	<u>27</u>
Others	
TOTAL	<u>272</u>

Report Format: _____
Lump Sum (L.S.): (\$ 2,194.00 P/P)

: Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004939MFSH

Date: 14 August 2019

Our Ref: CS/FCI19013635/Es3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMG 9795P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/08/2019 at the premises of M/s Cycle & Carriage Kia Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 6,063.60</u>
Revised Estimate Amount	: <u>S\$ 2,013.20</u>
"Check" Items Amount	: <u>S\$ 859.20</u>
Market Value	: <u>S\$</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Chen Tsue Yee
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-07-2019	Our Ref No. D19004939MFSH
Accident Date	27-07-2019	Claim Type. Third Party
Insured Vehicle	SHC0752C	Third Party Vehicle. SMG9795P
Survey Location	209 PANDAN GARDENS	
Contact Person.	DON BONG	
Contact No.	65684555/ 0	Fax No. 65651240
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE KIA PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 14 August 2019 1:40 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19004939MFSH/1
Attachments: SMG 9795P - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SMG 9795P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 5 August 2019 12:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004939MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVTHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 5 August 2019 11:16 AM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004939MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	198H
Vehicle Details	
Vehicle No.:	SMG9795P
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) SX
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4FGJH709907
Chassis No.:	KNAF3416MK5020857
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$18,084.00
Original Registration Date:	08 Jan 2019
First Registration Date:	08 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$18,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2029
PARF Rebate Amount:	\$13,563.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,000.00
COE Rebate Amount:	\$26,321.00
Total Rebate Amount:	\$39,884.00

The information contained herein is correct as at 13 Aug 2019

OK

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Saravanan S/O Shatiannathan
Period of Insurance : 08 Jan 2019 To 07 Jan 2020
Engine No. : G4FGJH709907
Chassis No. : KNAF3416MK5020857

Vehicle No. : SMG9795P
Policy No. : 1900001194
Endorsement No. :
Issued Date : 18 Jan 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Saravanan S/O Shatiannathan - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part (V) of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500710050

C&C FULCO-CORP SALES
22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCZ88

1001865582/AC/4/03/2019



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KIA CERATO 1.6 A SR SX G335.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: LAX00000, Credit, 01/08/2019/ 22:22, QUD, 247 / DonBong, 55018

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various repair items like 'RENEW ACCIDENT DAMAGE ON REAR BUMPER' and 'COVER-RR BUMPER LWR' with handwritten notes and prices.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08000/SARAVANAN S/O SHATIANNATHAN Reg No/Reg Date SMG9795P / 08/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5020857 Engine No G4FGJH709907 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	01/08/2019/ 22:22	QUD	247 / DonBong	55018

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER-RR BUMPER UNDER,RH <i>2 X NAI</i>	1.00	33.00	20.00	26.40
M ULTRASONIC SENSOR ASSY-BWS <i>2 X NAI</i>	1.00	163.00	20.00	130.40
M ULTRASONIC SENSOR ASSY-BWS <i>2 X NAI</i>	1.00	163.00	20.00	130.40
M MUFFLER ASSY-REAR <i>X NAI</i>	1.00	757.00	20.00	605.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Estimate

Amended 15/8/19

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Steve (LKK) 8322 8813*

SURVEYOR SIGNATURE: _____

DATE: *8/8/19, 2:00pm* *3 days*

REMARKS: *PIP, Reg Bef spray*

B4 painting

Confirm & accepted by

6244.40

	Nett	6,063.60
7% GST on	6063.60	424.45
Total Payable		6,488.05

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : STEVE LKK
 Claim : TP MS FIRST CAP
 DOA : 27.07.2019
 Emailed : 10.10.2019, 2.50pm
 Date survey : 08.08.2019

VEHICLE NO : SMG 9795 P
 MODEL : KIA CERATO 1.6 A SR SX
 WIP : 55018

Material	: \$	<u>904.00</u>
Labour	: \$	<u>1,290.00</u>
Sub-Total	: \$	<u>2,194.00</u>
	:	<u>-</u>
Less Excess	: \$	<u>-</u>
Total	: \$	<u>2,194.00</u>
GST 7%	: \$	<u>153.58</u>
Grand Total	: \$	<u>2,347.58</u>
Finalise By/Date	:	<u>LOI / 10/10/2019</u>

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 5


TP claim SHC752C

Claim GIA / LTA fee \$2.00

Claim Loss of Use / Rental

Claim Medical Fee / Others _____

Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 28/09/2019	Cust No/Name	LCV08000/SARAVANAN S/O SHATIANNATHAN
	Reg No/Reg Date	SMG9795P / 08/01/2019
	Date In/Mileage	28/09/2019/ 16468
	Chassis/Package	KNAF3416MK5020857 /KC17P
	Engine No	G4FGJH709907
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	10/10/2019/ 12:36	TLD	260 / Aiting	55018

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 550.00
E PNT98000 RESPRAY ON REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 420.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 40.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 200.00
M SUNDRY SUNDRIES				✓ 20.00
E PNT88000 REMOVE AND INSTALL REAR PARKING SENSORS TO FACILITATE REPAIR				✓ 60.00
X COVER-RR BUMPER LWR	1.00	✓ 197.00	00.00	197.00
X COVER-RR BUMPER	1.00	✓ 688.00	00.00	688.00
X COVER-RR BUMPER FOG LAMP,RH	1.00	✓ 19.00	00.00	19.00
Z TEXT TP CLAIM FIRST CAPITAL SHC752C DOA : 27.07.19 SURVEYOR STEVE (LKK) 08.08.19 REPAIR 03 DAYS				

Cycle & Carriage celebrates 120 years.
Visit www.cyclecarriage.com/120 for more info!

Parts	904.00			
Labour	1,270.00			
Standard Menu	0.00	7% GST on	Nett	2,194.00
Specialist Job	0.00			153.58
Diagnostics Job	0.00			
Sundry/Others	20.00			
Total(w/o GST)	2,194.00		Total Payable	2,347.58

This is not an official tax invoice.
This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013635/Esd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 752C	Veh. Inspected	SMG 9795P
Policy No.		Coverage (\$)	0.00
Claim No.	D19004939MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	05/08/2019
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KNAF3416MK5020857	Colour	BLUE
Odometer	15536	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	KUMHO	5 mm
L/H Front Tyre	225/45 R17	KUMHO	5 mm
R/H Rear Tyre	225/45 R17	KUMHO	5 mm
L/H Rear Tyre	225/45 R17	KUMHO	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/07/2019	Inspection Date	08/08/2019
Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 9795P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER-RR BUMPER LWR (SN)	CUT	197.00	197.00
1	COVER-RR BUMPER (SN)	DENTED	688.00	688.00
1	COVER-RR BUMPER FOG LAMP,RH (SN)	CUT	19.00	19.00
1	LAMP ASSY-SIDE T/SIGNAL,RH (SN)	NOT NECESSARY	144.80	-
1	EXTN WIRING ASSY-BWS (SN)	NOT NECESSARY	165.60	-
1	BRACKET-RR BEAM UPR MTG,LH (SN)	NOT NECESSARY	7.20	-
1	BRACKET-RR BEAM UPR MTG,RH (SN)	NOT NECESSARY	7.20	-
1	BRACKET-RR BEAM LWR,CTR (SN)	NOT NECESSARY	4.80	-
1	BRACKET-RR BEAM LWR MTG (SN)	NOT NECESSARY	4.80	-
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	254.40	-
1	STAY-RR BUMPER LH (SN)	NOT NECESSARY	52.00	-
1	STAY-RR BUMPER RH (SN)	NOT NECESSARY	52.00	-
1	BRACKET ASSY-RR BPR SIDE UPR,L (SN)	NOT NECESSARY	20.00	-
1	BRACKET ASSY-RR BPR SIDE UPR,R (SN)	NOT NECESSARY	24.80	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	COVER-RR BUMPER UNDER,RH (SN)	NOT NECESSARY	26.40	-
1	ULTRASONIC SENSOR ASSY-BWS (SN)	NOT NECESSARY	130.40	-
1	ULTRASONIC SENSOR ASSY-BWS (SN)	NOT NECESSARY	130.40	-
1	MUFFLER ASSY-REAR (SN)	NOT NECESSARY	605.60	-
1	PARKING SENSOR (SN)	NOT NECESSARY	220.00	-
			2,804.40	924.00
LABOUR				
RENEW ACCIDENT DAMAGE ON REAR BUMPER.			1,650.00	550.00
RESPRAY REAR BUMPER AND AFFECTED AREA.			840.00	420.00
CHECK ELECTRICAL SYSTEM.			40.00	40.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
PERFORM RUST PREVENTION.			80.00	-
REMOVE AND INSTALL REAR EXHAUST MUFFLER.			550.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL REAR PARKING SENSORS.		80.00	60.00
			3,440.00	1,270.00
GRAND TOTAL			6,244.40	2,194.00
RECOMMENDED COST OF REPAIRS				2,194.00

Report Ref No. CS/FCI19013635/Esd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.