

22/03/2002

ASS. REC. BY:

REF: CS3/ C1219013638/ 9c f3e2 | Special Instruction:

Supervisor: GA

ASSIGNMENT (Office)From (Person): Chong Boon Sen of C12 Date/Time: 5.8.19 10.48.07

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 5144 B Insured: GT 1164Rat Workshop m/s Teamwork Garage Tel: 6844 2475of 53 ubi ave 1 #01-24Policy No: DMICV/SN30505718033 Claim No: SNM19D203522102

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 27.7.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5.8.19 10.54.9.m Person Contacted: Shu shun H.O.D. Endorsement: \_\_\_\_\_Vehicle IN OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLH 5144B - MA/TMI 19013324/24
	GT 1164R - MA/TMI 19013324/24
	Dismantle: 6/8/2019

ROA - 27/07/2019

ROA - 23/07/2019

Stringer *bal*

REF: CT1

ASSIGNMENT

From: \_\_\_\_\_ Date: 5.8.2019

Estimated Cost: \_\_\_\_\_

OD  TP  WS  / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 5144B

at Workshop m/s Teamwork Garage

of 53 Ubi Ave 1 #01-24

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp"

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLH 5144B Yr Regn: 08 Nov 2016

Type:  M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Honda HRV 1.5 c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 55615 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRU 1830 GX 200598

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD  A/Rim or \_\_\_\_\_

Tyre Size: F: 215/60R16

R: "

BS  / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>05-08-19</u>

Survey held at w/s 3pm

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$ 4000 - \$ 5000</u>

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: PR

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 150

Transportation: \_\_\_\_\_

\_\_\_\_ S + FS, \_\_\_\_\_ SI

Photos \_\_\_\_\_

Others \_\_\_\_\_

ADD Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

TOTAL 150

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019		05 Aug 2019 10:48 Assign				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>MS TOH MUI GEOK (ZHUO MEIYU)</b> , ID: S7539376H									
Vehicle Reg. No.: <b>SLH5144B</b>		Date of Loss: 27/07/2019 14:00 - :59							
Claim Type: <b>TP / SNM19D203522C02</b>		Policy/Cover Note No.: DMCVSN30505718033							
Vehicle Reg. No. (Insured): <b>GT1164R</b>		Policy No. (Claimant): 18-MV009857-R01							
Excess: S\$0.00									
Repairer: <b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 16/08/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Monday, 5 August 2019 10:43 AM  
**To:** claims@teamworkgarage.com; assignments  
**Cc:** Chong Boon Sen  
**Subject:** RE: OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90//YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

### WITHOUT PREJUDICE

Dear Darren,

We refer to your email of 05.08.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

### Tan Kah Leong

Assistant Executive  
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Monday, 5 August, 2019 10:24 AM

**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>;  
Chee So Chow <sochow.chee@sg.cntaiping.com>; claims@teamworkgarage.com

**Cc:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Subject:** FW: OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90//YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

Dear Kah Leong,

Please assist.

Thank you

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Darren [<mailto:claims@teamworkgarage.com>]

**Sent:** Monday, 5 August, 2019 9:55 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** FW: OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90//YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

Dear China Taiping,

Please assists to appoint LKK as Boon Sen is not in

Darren

Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park

Singapore 408934

Tel: 68442475

Fax: 68442474

---

**From:** Darren

**Sent:** Monday, 5 August 2019 9:47 AM

**To:** Chong Boon Sen

**Subject:** RE: OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90//YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

Hi Boon Sen,

Please appoint LKK

Darren

Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park

Singapore 408934

Tel: 68442475

Fax: 68442474

---

**From:** Chong Boon Sen

**Sent:** Tuesday, 30 July 2019 3:05 PM

**To:** [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)

**Subject:** RE: OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90 //YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

**WITHOUT PREJUDICE**

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Tuesday, 30 July, 2019 2:43 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>;  
Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [claims@teamworkgarage.com](mailto:claims@teamworkgarage.com)

**Subject:** OUR REF: SNM19D203522-GT1164R-CBS - FW: OUR REF : 1907-90 // YOUR REF :  
GT1164R ACCIDENT INVOLVING GT1164R AND SLH5144B

Dear Boon Sen,

Please conduct PRS for SLH5144B.

Note: officer in charge – Boon Sen 63896171.

Thanks,  
shumin

---

**From:** TEAMWORK [<mailto:claims@teamworkgarage.com>]

**Sent:** Tuesday, July 30, 2019 9:59 AM

**To:** Claims Dept of CTI

**Cc:** TEAMWORK

**Subject:** OUR REF : 1907-90 // YOUR REF : GT1164R ACCIDENT INVOLVING GT1164R AND  
SLH5144B

WITHOUT PREJUDICE

OUR REF : 1907-90  
YOUR REF : GT1164R

Dear Sir / Madam,  
PRE-REPAIR INSPECTION FOR SLH5144B  
ACCIDENT INVOLVING GT1164R AND SLH5144B ON 27.07.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

*Shu Shan*

Teamwork Garage Pte Ltd  
Blk 53 Ubi Avenue 1  
#01-24  
Paya Ubi Industrial Park  
Singapore 408934  
Tel: 6844 2475  
Fax:6844 2474

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	376H
Vehicle Details	
Vehicle No.:	SLH5144B
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4530599
Chassis No.:	JHMRU1830GX200598
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$23,781.00
Original Registration Date:	08 Nov 2016
First Registration Date:	08 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$20,294.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2026
PARF Rebate Amount:	\$15,220.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,334.00
COE Rebate Amount:	\$38,696.00
<b>Total Rebate Amount:</b>	<b>\$53,916.00</b>

The information contained herein is correct as at 05 Aug 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/07/2019 18:16
Date Of Accident	27/07/2019 14:00
Exact Location Of Accident	15 UBI RD 4
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH5144B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MS TOH MUI GEOK (ZHUO MEIYU)
NRIC No	S7539376H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92963390
Alternative Phone No	OFFICE-92963390

### Vehicle Particulars

Manufacturer	HONDA
Model	HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	18-MV009857-R01
Cover Note Number	

### Driver

Name of Driver	TANG YANG KEN
NRIC No	S7525380Z
Date Of Birth	20/08/1975
Occupation	INDOOR
Date Of Driving Pass	23/12/1994
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97696561
Fax Number	
Contact Number	OFFICE-97696561
Email Address	NOEMAIL

Address	BLK 656 JALAN TENAGA #04-106
Postcode	410656
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT1164R
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PEH KEK YONG
NRIC/Passport Number	S1362471B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
  - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigations the accident and/or my claims;
  - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
  - (i) To all Insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
  - (ii) For complying with requirements under my regulations, laws or court orders.


  
\_\_\_\_\_  
Policy holder's signature  
Date / time:

  
\_\_\_\_\_  
Driver's signature  
(if driver is not policy holder)  
Date / time:

  
\_\_\_\_\_  
reporting centre personnel's Signature  
Date / time:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated time and date, as I was park along the road side stationary. I suddenly felt a impact hitting the rear portion of my vehicle (SLH5144B). I went down to check and realise vehicle B (GT1164R) collided with my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
\_\_\_\_\_  
Policy holder's signature  
Date & time:

  
\_\_\_\_\_  
Driver's signature  
(if driver is not policy holder)  
Date & time:

  
\_\_\_\_\_  
reporting centre personnel's Signature  
NRIC/FIN No.:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2019		05 Aug 2019 10:48 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by insurer]		
Insured:	-, Co. Reg. No.: -			
Main Claimant:	<b>MS TOH MUI GEOK (ZHUO MEIYU)</b> , ID: S7539376H			
Vehicle Reg. No.:	<b>SLH5144B</b>	Date of Loss:	27/07/2019 14:00 - :59 [32 Months and 19 Days From LTA Reg Date (Man Yr)]	
Claim Type:	<b>TP / SNM19D203522C02</b>	Policy/Cover Note No.:	DMCVSN30505718033	
Vehicle Reg. No. (Insured):	<b>GT1164R</b>	Policy No. (Claimant):	18-MV009857-R01	
		Excess:	S\$0.00	
Repairer:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475			
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]			
Claimant's Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111			
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 16/08/2019]			
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.				
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a>
			<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>
				<b>Handler</b>
				<b>Assigned By</b>
				<b>Completed On</b>
				<b>Created On</b>
				<b>Done?</b>
No results.				

## Claim Documents

\*SLH5144B (SNM19D203522C02)  
 [GT1164R]  
 TP  
 MS TOH MUI GEOK (ZHUO MEIYU)  
 Jul 27 2019 2:00PM  
 [-]  
 Teamwork Garage Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Photos/Images</b>										
3 per page <input type="checkbox"/>										
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
2	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
3	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
4	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
5	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
6	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
7	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
8	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
9	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
10	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
11	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
12	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
13	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
14	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
15	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
16	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
17	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
18	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
19	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
20	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
21	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
22	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
23	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
24	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
25	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
26	06/08/19 09:39	General View		Load JPG	<input checked="" type="checkbox"/>					
27	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
28	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
29	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
30	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
31	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
32	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
33	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
34	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
35	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
36	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					
37	06/08/19 09:40	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	06/08/19 09:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	06/08/19 09:40	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
59	06/08/19 09:40	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
60	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	07/08/19 12:18	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	07/08/19 12:19	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
88	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
89	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
90	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
91	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
92	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
93	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
94	07/08/19 12:19	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail Print
1	29/07/19 18:37	Accident Statement		Load HTM <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail Print
1	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	29/07/19 18:25	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail Print
1	29/07/19 18:25	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	29/07/19 18:25	Accident Sketch Plan		Load JPG <input checked="" type="checkbox"/>

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CT19013638/GCF3E2**Date:** 07/08/2019REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30505718033  
**Claimant Vehicle No :** SLH5144B **Insured Vehicle No :** GT1164R  
 Date of Loss: 27/07/2019 Nature of Claim: TP Claim No: SNM19D203522C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH5144B**  
 Make & Model: HONDA HR-V, 1.5 LX CVT (A) Engine No: L15B4530599  
 Reg. Date: 08/11/2016 (Man. Year: 2016) Chassis No: JHMRU1830GX200598  
 Colour: White Odometer: 55615 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 05/08/2019  
 Date Inspected: 05/08/2019 Inspected At: Teamwork Garage Pte Ltd (HQ)  
 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park  
 Singapore 408934  
 Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 07 Aug 2019)	
<b>Parts:</b>	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH5144B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >