

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % - 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

EQ 234T

Yr Regn:

25/2/19

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make:

BMW X1

C.C

1499

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

4560

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WBAJG12503677210

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or _____Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or _____

Tyre Size:

F:

225/55 R17

R:

A

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/7/19

D.O.I.

7/8/19

Survey held at _____

Performance Mot

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-14SK

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B. (\$)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Enquire PARF/COE Rebate for Registered Vehicle	
Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	115C
Vehicle Details	
Vehicle No.:	EQ234T
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I LED NAV
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	38885542B38B15A
Chassis No.:	WBAJG120503G77210
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$34,636.00
Original Registration Date:	25 Feb 2019
First Registration Date:	25 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$40,491.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2029
PARF Rebate Amount:	\$30,368.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$32,958.00
Total Rebate Amount:	\$63,326.00

The information contained herein is correct as at 07 Aug 2019

OK