

12/03/2002

ASS. REC. BY:

REF: CS/MSG19013715/UGF3M2

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Zheng Han Yangof MS1GDate/Time: 6.8.19 9.33a.m

Estimated Cost:

Bill to:

OD TP WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: SBY 112EInsured: SLT 2683Tat Workshop m/s Hock wah motorTel: 6441 5655of BIC 3011 Dook Industrial Park E #01-2008Policy No: 29114756Claim No: 600242

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 17.7.19

CA / REV / REP. / REV 24 HRS

my"

H.O.D. Endorsement:

Date/Time: 6.8.19 10.05a.mPerson Contacted: AnysiaVehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SBY 112E *

SLT 2683T - X

07/8/19 @ 10.31am revised to Zheng Han Yang via Merimen.

GLA / PR Seen: 1

Consistent: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

17A 62927

Vehicle: IN/OUT

Date:

Person Contacted:

L/Dat.

D.O.A.

17/7/19

D.O.I.

6/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 1/5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/9/19 Confirmed final R of 3035.20 with Anysia.
Red 3506.80, 54.17

RECEIVED 05 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 05/9 Anysia☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

3035.20)

TOTAL

150
11

161