

PERSONAL

ASS. REC. BY:

REF: 08/CTI19013753/Kvd3

n2

Special Instructions:

Signature: Kenneth

Munnen

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI

Date/Time: 6/8/19 @ 9.04am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GU 9074J

Insured: PA 7197A

at Workshop w/e Comfort delgro

Tel: 63838115

of 205 Brindell Road

Policy No: DMBISN3080028000

Claim No: SNMI9D20364102

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2/8/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Enclosure:

Date/Time: 10.35am @ 6/8/19

Person Contacted: William

Vehicle IN/OUT

Date/Time

Action/Instruction

1st initial /

GU 9074J - C06/AxA/5004401/GH a3y2

D.O.A. 10/3/15

PA 7197A - X

23/8/19

@ 15pm William said pending liability

30/9 11pm @ 2800 max, confirmed (Red 1672.86, 379)



ASS. REC. BY:

REF: 072 /

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 8800

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Soon: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GU9074J Yr Regn: 08, 01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Suz Carry cc 1288Colour: White / R A/C: Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JSAF0432V00128049Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim orTyre Size: F: 155R13X8R: Westlake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front \_\_\_\_\_ Rear \_\_\_\_\_


R/Bal. 4 mm R/Bal. 9 mmL/Bal. 4 mm L/Bal. 9 mmD.O.A. 2/18/19 D.O.I. 6/8/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

0/1/19

The UIC / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

1 File pass to  
Bottom Plot.

RECEIVED 04 OCT 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

4/10 - typist

Report Format :

Lump Sum / I.B.I. (\$) 2800/-merimenDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Fines

) Others

TOTAL

220



## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ret	Adj Submitted	Ins Auth'd	Status
Main	05 Aug 2019		06 Aug 2019 09:04 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SINGAPORE TELECOMMUNICATIONS LIMITED, Co. Reg. No.: 199201624D		
Vehicle Reg. No.:	GU9074J	Date of Loss:	02/08/2019 13:00 - :59
Claim Type:	TP / SNM19D203641C02	Policy/Cover Note No.:	DMB1SN30800218000
Vehicle Reg. No. (Insured):	PA7197A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD, 579701 Braddell - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/08/2019]		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



**Nivitha (LKK Auto)**

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Tuesday, 6 August 2019 8:54 AM  
**To:** CDGE Braddell Private Cars Crash Repair Operation; assignments  
**Cc:** Chong Boon Sen  
**Subject:** RE: OUR REF: SNM19D203641-PA7197A-CBS - FW: GU9074J CLAIMING AGAINST PA7197A DOA02082019 CHECK LIABILITY & ARRANGE SURVEY

WITHOUT PREJUDICE

Dear William,

We refer to your email of 06.08.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell\_operation@sparkcarcare.com]  
**Sent:** Tuesday, 6 August, 2019 7:32 AM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Cc:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D203641-PA7197A-CBS - FW: GU9074J CLAIMING AGAINST PA7197A DOA02082019 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Madam,

Kindly arrange Kenneth Kong to survey the vehicle.

Thanks

William Wang



Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

---

**From:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>

**Sent:** Monday, 5 August 2019 5:42 PM

**To:** CDGE Braddell Private Cars Crash Repair Operation <[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)>

**Cc:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject:** RE: OUR REF: SNM19D203641-PA7197A-CBS - FW: GU9074J CLAIMING AGAINST PA7197A DOA02082019  
CHECK LIABILITY & ARRANGE SURVEY

WARNING: This email originated from an external party outside ComfortDelGro. Sender of this email could not be validated and name in the "From" field may be forged.

---

Without Prejudice

Dear William,

We refer to your email dated 5 August 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

**Tan Kah Leong**

Assistant Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*



**From:** Claims Dept of CTI

**Sent:** Monday, 5 August, 2019 5:15 PM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; braddell\_operation@sparkcarcare.com; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject:** OUR REF: SNM19D203641-PA7197A-CBS - FW: GU9074J CLAIMING AGAINST PA7197A DOA02082019 CHECK LIABILITY & ARRANGE SURVEY

Dear Kah Leong,

Please assist to conduct PRS for GU9074J.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** CDGE Braddell Private Cars Crash Repair Operation [[mailto:braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)]

**Sent:** Monday, 5 August, 2019 3:56 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Cc:** CDGE Braddell Private Cars Crash Repair Counter <[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)>; Patrick Chung Chan Kim <[patrickchung@cdge.com.sg](mailto:patrickchung@cdge.com.sg)>; Denis Teo Chin Chye <[denisteo@sparkcarcare.com](mailto:denisteo@sparkcarcare.com)>

**Subject:** GU9074J CLAIMING AGAINST PA7197A DOA02082019 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir / Madam

Please arrange to survey the car at CDGE, Braddell.

And to advice on the liability of the accident.

Car in workshop ready for survey.

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

624D

**Vehicle Details**

Vehicle No.:

GU9074J

Vehicle to be Exported:

No

Intended Deregistration Date:

07 Aug 2019

Vehicle Make:

SUZUKI

Vehicle Model:

CARRY 1.3

Primary Colour:

Red

Manufacturing Year:

2001

Engine No.:

G13BB707743

Chassis No.:

J5AFDA32V00128049

Maximum Power Output:

-

Open Market Value:

\$9,244.00

Original Registration Date:

16 Aug 2001

First Registration Date:

16 Aug 2001

Transfer Count:

0

Actual ARF Paid:

\$463.00

**Intended PARF Rebate Details**

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

**Intended COE Rebate Details**

COE Expiry Date:

31 Dec 2020

COE Category:

C - Goods Vehicle &amp; Bus

COE Period(Years):

5

PQP Paid:

\$22,416.00

COE Rebate Amount:

\$6,266.00

Total Rebate Amount:

\$6,266.00

**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 07 Aug 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/08/2019 16:15
Date Of Accident	02/08/2019 13:30
Exact Location Of Accident	BLK 126 PENDING ROAD OPENSOURCE CARPARK LOT 995
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GU9074J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SINGAPORE TELECOMMUNICATIONS LIMITED
Co Reg No	199201624D
Email Address	CHOWPENG@SINGTEL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63463809

### Vehicle Particulars

Manufacturer	SUZUKI
Model	CARRY 1.3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	
Cover Note Number	

### Driver

Name of Driver	TAN HER BUAY
NRIC No	S1327419C
Date Of Birth	07/11/1958
Occupation	INDOOR
Date Of Driving Pass	30/05/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98257627
Fax Number	
Contact Number	
Email Address	THBUAY@SINGTEL.COM



Address	BLK 506 JELAPANG ROAD #16-22
Postcode	670506
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	BUKIT PANJANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA7197A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	PATRICK AW SOON KEONG
NRIC/Passport Number	S1666615G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2



Vehicle Registration Number	SJL9013Y
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YEONG MOOI YOE
NRIC/Passport Number	S8374078G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	YEONG MOOI YOE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJL9013Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false recording may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### SKETCH PLAN

V1: Cu907f5  
V2: 3JL 9013Y  
V3: PA 7197A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report No: T/20190802/2150

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature:  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature:  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_





**SINGAPORE  
POLICE FORCE**



T/20190802/2150

1 of 4

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190802/2150

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/08/2019 18:22		Vide Report No.: J/20190802/0083		Station Diary No.: 106	
<b>Informant's Particulars</b>					
Name of Informant: TAN HER BUAY			Address: APT BLK 506 JELAPANG ROAD #16-22 SINGAPORE 670506		
ID Type / ID No.: NRIC NO / S1327419C			Contact No.: Home/Office: Mobile: 98257627		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 07/11/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/08/2019 13:35	Type of Location: Car Park
Location: Along Road 1 PENDING ROAD  open space carpark of BLK 126 Pending Road Lot 995				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GU9074J	Van				Seriously Damaged	0
PA7197A	Van					0
SJL9013Y	Car					0

**Details of Person Involved**

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA





**SINGAPORE  
POLICE FORCE**



T/20190802/2150

2 of 4

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190802/2150

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	TAN HER BUAY		ID No. S1327419C
Related Vehicle	GU9074J (Van)		Contact No. 98257627
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	PATRICK AW SOON KEONG		ID No. S1666615G
Related Vehicle	PA7197A (Van)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	YEONG MOOI YEE		ID No. S8374078G
Related Vehicle	SJL9013Y (Car)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 02/08/2019 at about 1245hrs, I had parked my vehicle, V1) GU 9074J at open space carpark of Blk 126 Pending Road lot number 995. Everything was intact. I went to the nearby coffee shop after I had park my vehicle. Subsequently, at about 1335hrs, I discovered that my vehicle was involved in an accident. My van was stationary and park at lot 995. V2) SJL 9013Y and V3) PA7197A had an accident and subsequently V3) had bang onto my vehicle. My van was dragged from lot number 995 to 997 and it went up the curb. Traffic police was at scene and I was advised to lodge a traffic accident report vide J/20190802/008. the traffic police had also took the cctv footage from V3.





**SINGAPORE  
POLICE FORCE**



T/20190802/2150

3 of 4

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190802/2150

CONTINUATION OF REPORT





**SINGAPORE  
POLICE FORCE**



T/20190802/2150

4 of 4

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190802/2150

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 3 MUHAMMAD FADZIL BIN ROHAIZAD	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 02/08/2019 18:22
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMED FEROUZ BIN HUSSEIN Contact No.: 65476206	Classification Of Case:
Authentication Stamp NP168	





ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : GU9074JMake & Model : SUZUKI CARRY 1.3Year of Manufacture : 2001Chassis No. : JSAFDA32V00128049Ins Company : GEGI VS CHINA TAIPINGEngine No. : G13BB707743Excess : -Policy No. : -Date of Accident : 02.08.2019Time of Accident : 13:30

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 2,256.30Plus/Less 15% \$ 338.45Total of Cost / List \$ 1,917.86(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ 185.00Total Parts Cost (Appendix A) \$ 2,102.86Labour (Appendix B) \$ 2,370.00Total Repair Cost \$ 4,472.86

Contact No

**Frt Counter Operation**

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell\_cr@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell\_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Not Authorized  
 6/8/19  
 Presony After Repair

Name of Surveyor : KennethCompany : CKICSurvey conducted on : 6/8/19 at \_\_\_\_\_**Remarks By Surveyor**(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 6/8/19



Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Vehicle No. :	<b>GU9074J</b>	Case Owner :	<b>0</b>
Make & Model :	<b>SUZUKI CARRY 1.3</b>	Year of Manufacture :	<b>2001</b>

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



# Spark Car Care

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : GU9074J Case Owner : 0

Make & Model : SUZUKI CARRY 1.3 Year Manufacture : 2001

Chassis No : JSAFDA32V00128049 Engine No : G13BB707743

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate	1			<i>B<sub>1</sub></i>	\$ 35.00	<i>25/11</i>
2	Front bumper	1	<i>B<sub>1</sub></i>	\$ 397.85	✓		✓
3	Front bumper retainer LH	1	<i>1/2</i>	\$ 35.50			X
4	Front bumper retainer RH	1	<i>D=1</i>	\$ 35.50	✓		✓
5	Front bumper side seal RH	1	<i>NH</i>	TBA			
6	Bonnet	1	<i>B<sub>1</sub></i>	\$ 450.20	✓		✓
7	Bonnet sticker - Singtel	1			✓ <i>1/2</i>	\$ 150.00	✓
8	Headlamp assy RH	1	<i>my An</i>	\$ 360.50	✓		✓
9	RH front fender	1	<i>B<sub>1</sub></i>	\$ 212.55	✓		✓
10	RH front fender inner shield	1	<i>T<sub>1</sub></i>	\$ 37.50	✓		✓
11	RH front fender inner shield clips	8	<i>1/2</i>	\$ 20.00	✓		✓
12	Radiator grille	1	<i>CM</i>	\$ 259.15	✓		✓
13	Front support panel	1	<i>B<sub>1</sub></i>	\$ 447.55	✓		✓
14	0	0					
15	0	0					
16	0	0	<i>158</i>				
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Let's Auto Consultants hence notify the Receiver of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey may be required and is subject to final approval from Insurance Company

Authorised by Receiver  
Signature:  
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**Spark Car Care**  
**ComfortDelgro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

**Bill To** : CHINA TAIPING      **Vehicle Number** : GU9074J  
**Attn to** : LKK - KENNETH      **Type Of Claim** : TP

<b>A. Spare parts</b> \$ <u>2,220.80</u>  <b>B. Supplementary</b> \$ <u>-</u>  <b>C. Nett Price</b> \$ <u>-</u>  <b>D. Supp Nett Price</b> \$ <u>-</u>  <b>E. S/Nett</b> \$ <u>175.00</u>	<b>F. Total Parts</b> \$ <u>2,062.68</u>  <b>G. Total Labour</b> \$ <u>1,690.00</u>  <b>H. Total Repair</b> \$ <u>3,752.68</u>  <b>I. Excess</b> _____ <b>P/P Total</b> <u>3,752.68</u>
---	--

Total Spare Parts Price	\$	2,220.80
Cost plus / List Down      15%		333.12
<b>Total</b>		<b>1,887.68</b>

Total Nett Price	\$	-
Nett Price Less	\$	-
<b>Total</b>		<b>-</b>

Lump Sum Less      20%      \$ 750.54  
\$ 3,002.14  
 Lump Sum Rounding      \$ 3,000.00  
**Total Finalized**      \$ 3,000.00

*N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.*

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day : _____	
Date Survey : _____	LOU/ Day : _____	
Date Out : _____	Total LOU : _____	
Sat/Sun/Ph. : _____	Rental/Day : _____	
Authorized Repair Day <u>5</u>	Total Rental : _____	
Submitted By / Date : WILLIAM WANG 28.09.2019		Confirmed By / Date : _____



# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : GU9074J Case Owner : 0

Make & Model : SUZUKI CARRY 1.3 Year Manufacture : 2001

Chassis No : JSAFDA32V00128049 Engine No : G13BB707743

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front number plate	1				\$ 25.00	
2	Front bumper	1		\$ 397.85			
3	Front bumper retainer LH	1					
4	Front bumper retainer RH	1		\$ 35.50			
5	Front bumper side seal RH	1		TBA			
6	Bonnet	1		\$ 450.20			
7	Bonnet sticker - Singtel	1				\$ 150.00	
8	Headlamp assy RH	1		\$ 360.50			
9	RH front fender	1		\$ 212.55			
10	RH front fender inner shield	1		\$ 37.50			
11	RH front fender inner shield clips	8		\$ 20.00			
12	Radiator grille	1		\$ 259.15			
13	Front support panel	1		\$ 447.55			
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Tel: 63837168 / 63837466 Fax: 62844284, 62815767

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119013753/KVD3N2

Date: 07/10/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30800218000
Claimant Vehicle No :	GU9074J	Insured Vehicle No :	PA7197A
Date of Loss:	02/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203641C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GU9074J	Engine No:	G13BB707743
Make & Model:	SUZUKI CARRY, 1.3 D (M)	Chassis No:	JSAFDA32V00128049
Reg. Date:	16/08/2001 (Man. Year: 2001)	Odometer:	0 km
Colour:	White/Red		
Engine Capacity:	1298 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	155 R13X8	Rear Tyre Size:	155 R13X8
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 9 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 9 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,102.85	2,062.68	40.17	1.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,670.00	700.00	29.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,472.85</b>	<b>3,732.68</b>	<b>740.17</b>	<b>16.55</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>(\$\$)</b>	4,472.85	2,800.00	1,672.85	37.40
<b>+ GST 7.00/7.00% (\$\$)</b>	313.10	196.00	117.10	37.40
<b>Nett Amount (\$\$)</b>	<b>4,785.95</b>	<b>2,996.00</b>	<b>1,789.95</b>	<b>37.40</b>

## INSPECTION

Date of Assignment:	06/08/2019	
Date Inspected:	06/08/2019	Inspected At: Comfortdelgro Engineering Pte Ltd (HQ) 205 BRADDELL ROAD Singapore 579701
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our



*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 04 Oct 2019)	
<b>Parts:</b>	N/A	SUZUKI CARRY 1.3 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GU9074J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	397.85 FL	*397.85 FL
2	1		*FRONT BUMPER RETAINER LH	Serviceable	35.50 FL	*- FL
3	1		*FRONT BUMPER RETAINER RH	Distorted	35.50 FL	*35.50 FL
4	1		*FRONT BUMPER SIDE SEAL RH (NPA)	Not Necessary	0.00 FL	*- FL
5	1		*BONNET	Bent	450.20 FL	*450.20 FL
6	1		*HEADLAMP ASSY RH	Mtg Broken	360.50 FL	*360.50 FL
7	1		*RH FRONT FENDER	Bent	212.55 FL	*212.55 FL
8	1		*RH FRONT FENDER INNER SHIELD	Torn	37.50 FL	*37.50 FL
9	8		*RH FRONT FENDER INNER SHIELD CLIPS	Necessary	20.00 FL	*20.00 FL
10	1		*RADIATOR GRILLE	Cracked	259.15 FL	*259.15 FL
11	1		*FRONT SUPPORT PANEL	Bent	447.55 FL	*447.55 FL
12	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*25.00 FS
13	1		*BONNET STICKER-SINGTEL	Necessary	150.00 FS	*150.00 FS
					<b>Sub Total (S\$)</b>	<b>2,441.30 2,395.80</b>
					<b>- List Item Discount on L Items 15.00/15.00% (S\$)</b>	<b>338.45 333.12</b>
					<b>Total Parts (S\$)</b>	<b>2,102.85 2,062.68</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE/REFIT AIRCOND PARTS,VACUUM & RECHARGE GAS	New	120.00	100.00
2	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE RH FRONT FENDER INNER PANEL,CUTTING/WELDING AND REPLACE DAMAGED PARTS	New	840.00	720.00
3	TO CHECK WIRING FUNCTIONS AND FOCUS HEADLAMPS	New	40.00	20.00
4	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE BONNET,RADIATOR GRILLE,RH FRONT FENDER,RH FRONT FENDER INNER PANEL,FRT SUPPORT PANEL AND AFFECTED AREAS	New	1,250.00	750.00
5	TO CHECK/RE-SET STEERING GEOMETRY AND WHEEL ALIGNMENT	New	120.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,370.00</b>	<b>1,670.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >