



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

|                  |                                                        |
|------------------|--------------------------------------------------------|
| Involving        | 1 2016 LAMBORGHINI HURACAN LP580-2<br>XXXXXX (SMA227D) |
| Date of Loss     | 27 July 2019                                           |
| Time of Loss     | 10.35                                                  |
| Loss Description | SMA227D (INS) C/W WC6919X (MOTORCYCLE)                 |
| Comment          | <input type="text"/>                                   |

### Workshop Details

|                           |                                     |
|---------------------------|-------------------------------------|
| Total Rebate Amount       | <input type="text" value="281740"/> |
| Nett Loss Amount          | \$466,260.00                        |
| Assigned Workshop         | LKK AUTO CONSULTANTS PTE LTD (OD)   |
| Days of work completion * | <input type="text" value="20"/>     |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Vehicle &amp; Driver Details

Vehicle Registration# SMA227D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

27/06/2018



Mileage

17777

Age of Vehicle

1

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATIONManufacturing  
Year

2016

2016

Make

LAMBORGHINI  
HURACAN LP580-2

LAMBORGHINI

Model

XXXXXX

HURACAN LP58C

## Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name

PAN JINGCHENG DONALD

Date of Birth

1 October 1984

dd/mm/yyyy



Age

34

| CATEGORY        | POLICY INFORMATION | ASSESSMENT INFORMATION                    |
|-----------------|--------------------|-------------------------------------------|
| Type            |                    | <input type="text" value=""/>             |
| Type of Paint   |                    | <input type="text" value=""/>             |
| Chassis No      | ZHWEC2ZF9HLA06013  | <input type="text" value="ZHWEC2ZF9HLA"/> |
| Engine No       | CSJ007031          | <input type="text" value="CSJ007031"/>    |
| Engine Capacity |                    | <input type="text" value="5204"/>         |
| Sum Insured     | 765000             | <input type="text" value="0"/>            |
| Market Value    | 0                  | <input type="text" value="748000"/>       |

| CATEGORY                | FNOL INFORMATION                         | POST SURVEY INFORMATION                                                                                                       |
|-------------------------|------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|
| Occupation              | Unknown                                  | <input type="text" value=""/>                                                                                                 |
| Education Qualification | Other                                    | <input type="text" value=""/>                                                                                                 |
| Driving Experience      | 13                                       |                                                                                                                               |
| Driver License #        |                                          | <input type="text" value=""/>                                                                                                 |
| License Type            |                                          | <input type="text" value=""/>                                                                                                 |
| License Issue Date      |                                          | <input type="text" value="dd/mm/yyyy"/>    |
| License Expiration Date |                                          | <input type="text" value="dd/mm/yyyy"/>  |
| Address                 | 38B BRIGHTON CRESCENT, 559222, Singapore | <input type="text" value=""/>                                                                                                 |
| Address type            | Residential                              | <input type="text" value=""/>                                                                                                 |

| CATEGORY         | FNOL INFORMATION | POST SURVEY INFORMATION |
|------------------|------------------|-------------------------|
| Gender           | Male             | <input type="text"/>    |
| Marital status   | Married          | <input type="text"/>    |
| Identification # | S8429112I        | <input type="text"/>    |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

06/08/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

20000

Young/Inexperienced/  
Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

## Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/35ZR19

Rear Tyre Size

245/35ZR19

Front left side

PIRELLI6mm

Rear left side

PIRELLI6mm

Front right side

PIRELLI6mm

Rear right side

PIRELLI6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

Parts

Add   Approve   Deny   Submit All

|  | EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME                                              | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMO |
|--|------|-------|-----------|----------|--------------------------------------------------------|-----------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|----------------|------|
|  |      | 0     | 1         |          | UNDERBODY TRIM                                         | Damaged   | 0                     | 885                   | No                  |              |            |           |                  | 885             | Reviewing      |      |
|  |      | 0     | 1         |          | UNDERBODY TRIM                                         | Damaged   | 0                     | 1052                  | No                  |              |            |           |                  | 1052            | Reviewing      |      |
|  |      | 0     | 2         |          | A/C CONDENSER                                          | Bent      | 0                     | 830                   | No                  |              |            |           |                  | 1660            | Reviewing      |      |
|  |      | 0     | 1         |          | COOLER FOR COOLANT (CENTRE)                            | Bent      | 0                     | 718                   | No                  |              |            |           |                  | 718             | Reviewing      |      |
|  |      | 0     | 1         |          | AIR GUIDE (CENTRE)                                     | Cracked   | 0                     | 128                   | No                  |              |            |           |                  | 128             | Reviewing      |      |
|  |      | 0     | 1         |          | AIR GUIDE (REAR CENTRE)                                | Cracked   | 0                     | 191                   | No                  |              |            |           |                  | 191             | Reviewing      |      |
|  |      | 0     | 1         |          | CONTROL UNIT FOR ACTIVE STEERING (*CHECK) (\$1,147.00) |           | 0                     | 0                     | No                  |              |            |           |                  | 0               | Reviewing      |      |
|  |      | 0     | 2         |          | ADDITIONAL COOLER FOR COOLANT                          | Bent      | 0                     | 649                   | No                  |              |            |           |                  | 1298            | Reviewing      |      |



|  | EDIT | SR NO | QUANTITY | MATERIAL | PART NAME                                         | CONDITION   | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR/ BTTR% | DISCOUNT% | SALVAGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMOVE |
|--|------|-------|----------|----------|---------------------------------------------------|-------------|-----------------------|-----------------------|---------------------|-------------|-----------|----------|------------------|-----------------|----------------|--------|
|  |      | 0     | 1        |          | AIR GUIDE (LEFT)                                  | Cracked     | 0                     | 133                   | No                  |             |           |          |                  | 133             | Reviewing      |        |
|  |      | 0     | 1        |          | AIR GUIDE (RIGHT)                                 | Cracked     | 0                     | 121                   | No                  |             |           |          |                  | 121             | Reviewing      |        |
|  |      | 0     | 1        |          | WISHBONE                                          | Serviceable | 0                     | 0                     | No                  |             |           |          |                  | 0               | Deny           |        |
|  |      | 0     | 1        |          | WISHBONE                                          | Cut         | 0                     | 1715                  | No                  |             |           |          |                  | 1715            | Reviewing      |        |
|  |      | 0     | 1        |          | STEERING GEAR                                     | Damaged     | 0                     | 16820                 | No                  |             |           |          |                  | 16820           | Reviewing      |        |
|  |      | 0     | 1        |          | LED HEADLIGHT (LEFT FRONT) (*CHECK) (\$9,997.00)  |             | 0                     | 0                     | No                  |             |           |          |                  | 0               | Reviewing      |        |
|  |      | 0     | 1        |          | LED HEADLIGHT (RIGHT FRONT) (*CHECK) (\$9,997.00) |             | 0                     | 0                     | No                  |             |           |          |                  | 0               | Reviewing      |        |
|  |      | 0     | 1        |          | TURN SIGNAL INDICATOR                             | Cracked     | 0                     | 286                   | No                  |             |           |          |                  | 286             | Reviewing      |        |
|  |      | 0     | 1        |          | TURN SIGNAL INDICATOR                             | Serviceable | 0                     | 0                     | No                  |             |           |          |                  | 0               | Deny           |        |
|  |      | 0     | 1        |          | BUMPER (WITH PARKING SENSOR)                      | Cracked     | 0                     | 10626                 | No                  |             |           |          |                  | 10626           | Reviewing      |        |
|  |      | 0     | 1        |          | FRONT SPOILER (LEFT)                              | Cracked     | 0                     | 605                   | No                  |             |           |          |                  | 605             | Reviewing      |        |
|  |      | 0     | 1        |          | FRONT SPOILER (RIGHT)                             | Cracked     | 0                     | 605                   | No                  |             |           |          |                  | 605             | Reviewing      |        |

|  | EDIT | SR NO | QUANTITY | MATERIAL | PART NAME                                        | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR/ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMO |
|--|------|-------|----------|----------|--------------------------------------------------|-----------|-----------------------|-----------------------|---------------------|-------------|------------|-----------|------------------|-----------------|----------------|------|
|  |      | 0     | 1        |          | CAP CLOSURE (LEFT)                               | Cut       | 0                     | 213                   | No                  |             |            |           |                  | 213             | Reviewing      |      |
|  |      | 0     | 1        |          | CAP CLOSURE (*CHECK) (\$213.00)                  |           | 0                     | 0                     | No                  |             |            |           |                  | 0               | Reviewing      |      |
|  |      | 0     | 1        |          | LAMBORGHINI EMBLEM                               | Necessary | 0                     | 742                   | No                  |             |            |           |                  | 742             | Reviewing      |      |
|  |      | 0     | 1        |          | BRACKET (LEFT)                                   | Necessary | 0                     | 16                    | No                  |             |            |           |                  | 16              | Reviewing      |      |
|  |      | 0     | 1        |          | BRACKET (RIGHT)                                  | Necessary | 0                     | 16                    | No                  |             |            |           |                  | 16              | Reviewing      |      |
|  |      | 0     | 1        |          | WING                                             | Bent      | 0                     | 6643                  | No                  |             |            |           |                  | 6643            | Reviewing      |      |
|  |      | 0     | 1        |          | WING                                             | Bent      | 0                     | 6643                  | No                  |             |            |           |                  | 6643            | Reviewing      |      |
|  |      | 0     | 2        |          | ALUMINIUM RIM                                    | Cut       | 0                     | 2640                  | No                  |             |            |           |                  | 5280            | Reviewing      |      |
|  |      | 0     | 1        |          | WHEEL HOUSING LINER (LEFT) (*CHECK) (\$510.00)   |           | 0                     | 0                     | No                  |             |            |           |                  | 0               | Reviewing      |      |
|  |      | 0     | 1        |          | WHEEL HOUSING LINER (RIGHT) (*CHECK) (\$510.00)  |           | 0                     | 0                     | No                  |             |            |           |                  | 0               | Reviewing      |      |
|  |      | 0     | 1        |          | FRONT TYRE SET 19" 2WD CPL                       | Cut       | 0                     | 1376                  | No                  |             |            |           |                  | 1376            | Reviewing      |      |
|  |      | 0     | 1        |          | RADIATOR FAN WITH FAN RING (*CHECK) (\$1,430.00) |           | 0                     | 0                     | No                  |             |            |           |                  | 0               | Reviewing      |      |

|                                                                                     | EDIT                                                                                | SR NO | QUANTITY | MATERIAL | PART NAME                         | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR/ BTTR% | DISCOUNT% | SALVAGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) | REMOVE                                                                                |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------|----------|----------|-----------------------------------|-----------|-----------------------|-----------------------|---------------------|-------------|-----------|----------|------------------|-----------------|----------------|---------------------------------------------------------------------------------------|
|    |    | 0     | 1        |          | AIR GUIDE (LEFT)                  | Cracked   | 0                     | 48                    | No                  |             |           |          |                  | 48              | Reviewing      |    |
|    |    | 0     | 1        |          | AIR GUIDE (RIGHT)                 | Cracked   | 0                     | 48                    | No                  |             |           |          |                  | 48              | Reviewing      |    |
|    |    | 0     | 1        |          | SET WIRE (PARKING SENSOR - FRONT) | Cut       | 0                     | 257                   | No                  |             |           |          |                  | 257             | Reviewing      |    |
|    |    | 0     | 1        |          | MOUNTING BAR (LEFT)               | Bent      | 0                     | 123                   | No                  |             |           |          |                  | 123             | Reviewing      |    |
|    |    | 0     | 1        |          | MOUNTING BAR (RIGHT)              | Bent      | 0                     | 123                   | No                  |             |           |          |                  | 123             | Reviewing      |    |
|    |    | 0     | 1        |          | BRACE (RIGHT)                     | Bent      | 0                     | 549                   | No                  |             |           |          |                  | 549             | Reviewing      |    |
|    |    | 0     | 1        |          | ARM (RIGHT FRONT)                 | Bent      | 0                     | 97                    | No                  |             |           |          |                  | 97              | Reviewing      |    |
|    |    | 0     | 1        |          | ARM (RIGHT FRONT)                 | Bent      | 0                     | 93                    | No                  |             |           |          |                  | 93              | Reviewing      |    |
|    |    | 0     | 2        |          | ARM (LEFT & RIGHT)                | Bent      | 0                     | 75                    | No                  |             |           |          |                  | 150             | Reviewing      |    |
|  |  | 0     | 10       |          | CLIP                              | Necessary | 0                     | 2.2                   | No                  |             |           |          |                  | 22              | Reviewing      |  |
|  |  | 0     | 10       |          | SPREADER RIVET                    | Necessary | 0                     | 2.8                   | No                  |             |           |          |                  | 28              | Reviewing      |  |
|  |  | 0     | 10       |          | SECURING ELEMENT                  | Necessary | 0                     | 2.4                   | No                  |             |           |          |                  | 24              | Reviewing      |  |
|  |  | 0     | 10       |          | SPREADER RIVET                    | Necessary | 0                     | 2.3                   | No                  |             |           |          |                  | 23              | Reviewing      |  |
|  |  | 0     | 10       |          | HEXAGON SOCKET HEAD BOLT          |           | 0                     | 1.6                   | No                  |             |           |          |                  | 16              | Reviewing      |  |

Labour

|     |         |       |                         |                                             |                        |                        |                       |                       |                 |         |        |
|-----|---------|-------|-------------------------|---------------------------------------------|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|--------|
| Add | Approve | Deny  | Submit All              |                                             |                        |                        |                       |                       |                 |         |        |
|     | EDIT    | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                   | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | REMOVE |
|     |         | 0     |                         | DISMANTLE, RE FITTING AND REPAIR / KNOCKING | 0                      | 17600                  | 0                     | 0                     | Reviewing       |         |        |
|     |         | 0     |                         | PAINT WORK                                  | 0                      | 2500                   | 0                     | 0                     | Reviewing       |         |        |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary

Add    Approve    Deny    Submit All

| EDIT | SR NO | NAME | ACTION                                                                      | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|------|-------|------|-----------------------------------------------------------------------------|------------------|-----------------|---------|--------|
|      |       | 0    | DAYS OF REPAIR : 12 DAYS                                                    | Reviewing        |                 | 0       |        |
|      |       | 0    | (REPAIR COST NOT CONCLUDE)<br>(EXCLUDE CHECK ITEMS<br>S\$23,804.00<br>NETT) | Reviewing        |                 | 0       |        |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

Estimated Claim  
Amount

\$0.00

Adjusted Claim Amount

\$59,473.00

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$59,373.00

Labour

\$0.00

\$20,100.00

Excess

-\$20,000.00

[Submit for Review](#)