



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/ASM19013759/Kpa3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 07-08-2020



ATTN: YVONNE ANG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |           |                       |            |
|---------------------|-----------|-----------------------|------------|
| <b>Insured Veh.</b> | FBL 6846A | <b>Veh. Inspected</b> | SHD 9848X  |
| <b>Policy No.</b>   | AN3162248 | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | S9M01WC0  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  |           | <b>Assign Date</b>    | 05/08/2019 |

### 2. Vehicle Particulars & Condition

|                         |                      |                     |                      |
|-------------------------|----------------------|---------------------|----------------------|
| <b>Make &amp; Model</b> | RENAULT LATITUDE (A) | <b>c.c</b>          | 1995                 |
| <b>Engine No.</b>       | HIDDEN               | <b>Year of Reg.</b> | 2014                 |
| <b>Chassis No.</b>      | VF1ABL15AUC277392    | <b>Colour</b>       | METALLIC WHITE / RED |
| <b>Odometer</b>         | 421633               | <b>Steering</b>     | IN ORDER             |
| <b>Brakes</b>           | IN ORDER             | <b>Modification</b> | NIL                  |
| <b>General</b>          | GOOD                 |                     |                      |

### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 215/60 R16  | TOURING     | 8 mm           |
| <b>L/H Front Tyre</b> | 215/60 R16  | TOURING     | 8 mm           |
| <b>R/H Rear Tyre</b>  | 215/60 R16  | GITI        | 8 mm           |
| <b>L/H Rear Tyre</b>  | 215/60 R16  | GITI        | 8 mm           |

### 4. Description of Damages

|                                                                             |
|-----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.<br>DAMAGES SEE DETAILS. |
|-----------------------------------------------------------------------------|

### 5. General Information

|                       |                                                                              |                        |            |
|-----------------------|------------------------------------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 01/08/2019                                                                   | <b>Inspection Date</b> | 05/08/2019 |
| <b>Survey held at</b> | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                        |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>3 Working Days</b> |
|-------------------------------------|-----------------------|