

22/03/2012

AKS. REC. BY:

REF: QS/FCI/9013773/Uvd30

Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): cws Serene Ter

of FCI

Date/Time: 12.51pm @ 6/8/19

Estimated Cost: _____

Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBG 6178 X

Insured: SHB 6299K

at Workshop m/s Bun Hock Hin

Tel: 6281 6520

of No. 6 Defriene 4

Policy No: _____

Claim No: D1900 5068 MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 26/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 2.40pm @ 6/8/19

Person Contacted: Raymond

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	(✓)
	FBG 6178 X - X		
	SHB 6299K - NA / INC 08025686/r		
7/8/19	Email preli revised to FCI		

DOA: 26/7/2008

08/11/13) wef

REF:

Fail

ASS. REC. BY: Marcus

ASSIGNMENT

9, 12

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: F8G 6178X
 at Workshop m/s: ASHH
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: F8G 6178X Yr Regn: 9, 12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yanhe YBR125 c.c. 124
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 31311 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: L3PK61783D0009023
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or ok
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 2.75-18
 R: 90-90-18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: 6
 R/Bal. 6 mm R/Bal. _____ mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 26/7/19 D.O.I. 6/8/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Del, o/s body.
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: 3500
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction
LTA 633 3y3 rule.
21/8/19 confirmed 1/5 @ 1000. w/c Raymond. (Recd 884, 479)

RECEIVED 22 AUG 2019

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) 22/8 - typist
 Report Format : CWS
 Lump Sum / I.B.I: (\$) 1000 : _____)
 Days Of Repair: 3
 Resurvey No. of Trip: 1 Survey Fee: 100
 Transportation: 50
 Add Fee: : Site Insp (\$ _____) S+RS, SI
 : Interview (\$ _____) Photos 50
 : Tech. Invs (\$ _____) Others
 : Weekend (\$ _____)
 TOTAL 250

MOTOR SURVEY ASSIGNMENT

Date	05-08-2019	Our Ref No. D19005068MFSH
Accident Date	26-07-2019	Claim Type. Third Party
Insured Vehicle	SHB6299K	Third Party Vehicle. FBG6178X
Survey Location	NO. 6 DEFU LANE 4	
Contact Person.	RAYMOND	
Contact No.	62816520/ 0	Fax No. 62842969
Survey Type	WITHOUT PREJUDICE: EST. COR - \$1,973.08 (SJE)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BAN HOCK HIN CO. PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 7 August 2019 11:17 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005068MFSH/1-FBG 6178X
Attachments: FBG 6178X PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle FBG 6178X
Date of survey: 6/8/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 6 August 2019 4:14 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005068MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 August 2019 12:51 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005068MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.

www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005068MFSH

Our ref: CS/FCI19013773/Uvd3

DATE: 7/8/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO FBG 6178X


We thank for your instruction on 6/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 6/8/2019 at the premises of M/s BAN HOCK HIN CO PTE LTD

Workshop Estimate Amount	: S\$1,844.00
Revised Estimate Amount	: S\$1,059.10
"Check" Items Amount	: S\$399.60
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion and o/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBG6178X
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	E3J2E005402
Chassis No.:	LBPKE1783D0009023
Maximum Power Output:	-
Open Market Value:	\$1,276.00
Original Registration Date:	27 Sep 2012
First Registration Date:	27 Sep 2012
Transfer Count:	5
Actual ARF Paid:	\$192.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,852.00
COE Rebate Amount:	\$633.00
Total Rebate Amount:	\$633.00

The information contained herein is correct as at 07 Aug 2019

OK

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FBG6178X
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	YAMAHA
Vehicle Model:	YBR 125 MANUAL
Chassis No.:	LBPKE1783D0009023
Propellant:	Petrol
Engine No.:	E3J2E005402
Engine Capacity:	124 cc
Maximum Power Output:	-
Maximum Laden Weight:	285 kg
Unladen Weight:	124 kg
Year Of Manufacture:	2012
Original Registration Date:	27 Sep 2012
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
Quota Premium:	\$1,852.00
COE Expiry Date:	26 Sep 2022
Road Tax Expiry Date:	26 May 2020
Inspection Due Date:	26 May 2020
Intended Transfer Date:	31 Aug 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay-up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

[REPORT ERROR > \(/LISTING/LISTING/ERROR/USEDBIKE/13284/\)](#)[+ ADD TO SHORTLIST](#)[Like 0](#)[Share](#)[© SHARE \(WHATSAPP://SEND?TEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/YAMAHA-YAMAHA-YBR125/13284/\)](#)

Yamaha YBR125

Listing Type	Paid Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha YBR125 (/listing/usedbike/model/yamaha-ybr125/)
Engine Capacity	124cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	22/06/2012
COE Expiry Date	21/06/2022 (2 years 10 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: ^{SGD}\$3500

Minimum Down Payment: ^{SGD}\$500

Est Monthly ^{SGD}\$142 for 2 years

DETAILS

Good Fuel Consumption. Showroom Condition.

[SIMILAR BIKES](#)

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/07/2019 13:38
Date Of Accident	26/07/2019 13:00
Exact Location Of Accident	ALONG KRETA AYER ROAD AND KEONG SAIK ROAD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBG6178X
Insured/Policyholder	
Name Of Registered Owner	BAN HOCK HIN COMPANY PRIVATE LIMITED
Co Reg No	197000288K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62816520

Vehicle Particulars

Manufacturer	YAMAHA
Model	YBR 125 MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	AVFMSB0000611902
Cover Note Number	NA

Driver

Name of Driver	SUN XIAOFENG
NRIC No	G2958531N
Date Of Birth	24/10/1995
Occupation	OUTDOOR
Date Of Driving Pass	17/04/2017
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83458107
Fax Number	
Contact Number	
Email Address	PP@SG.MCD.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was riding my bike along Kreta Ayer Road and Keong Saik Road junction. I was stop at the yellow box to checked my traffic, when I started moving my bike. Suddenly SHB6299K was came from my right side, and I cannot stop on and collided onto his car front left side position. My right leg and my neck was painful.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB6299K
Vehicle Make/Model/Colour	MERCEDES BENZ / E 220 CDI BLUEEFFICIENCY
Details Of Properties	NA
Vehicle Category	TAXI
Name of Driver	LIM KIAN SENG
NRIC/Passport Number	S1494416H
Contact Number	98538402
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SUN XIAOFENG
Approximate Age	
Injuries Sustain	PAIN ON RIGHT LEG AND NECK
Injured person in which vehicle?	FBG6178X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

IMPORTANT NOTICE


- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**
 I understand, acknowledge, agree and consent that:
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers who have insured vehicles) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 (ii) investigating the accident and/or my claims.
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 (b) all insurers who have insured vehicles involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAK MARS
 REPORTING OFFICER
 JOHNNY VOO

陈晓峰

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was riding my bike along Kreta Ayer Road and Keong Saik Road junction. I was stop at the yellow box to checked my traffic, when I started moving my bike. Suddenly SHB6299K was came from my right side, and I cannot stop on and collided onto his car front left side position. My right leg and my neck was painful.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

27 July 2019 at 2:12 PM

Date/Time:

27 July 2019 at 2:12 PM



QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

FIRST CAPITAL INSURANCE LTD

VEHICLE NO. : FBG6178X
MAKE/MODEL : YAM / YBR125ESD

*not Alud
slur
2/5 + 1000
32.
6/8/18
the 16.000*

NO. : 34539 - Rev. 1
DATE : 02/08/2019
CLAIM NO. : 11400
POLICY NO. : AVFMSB0000611902
FROM : SHIWEI

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	✓	1.00	\$196.00	180 196.00
2	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180 180.00
3	CABLE SPEEDOMETER P/N: 50366	REPLACE	1.00	\$14.00	14 14.00
4	CRASH BAR P/N: 35878	REPLACE	1.00	\$194.00	12 194.00 X
5	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$78.00	78 78.00
6	TRANSPORT CHARGES P/N: 07169	✓	1.00	\$49.00	35 49.00
7	SPRAY PAINT FRONT COWLING	✓	1.00	\$63.00	50 63.00
8	FORK FRONT ASSY LH P/N: 45155	REPLACE	1.00	\$224.00	224 224.00
9	FORK FRONT ASSY RH P/N: 45154	REPLACE	1.00	\$224.00	224 224.00
10	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$157.00	157 157.00
11	LAMP SIGNAL FRONT LH P/N: 43433	REPLACE	1.00	\$16.00	16 16.00
12	METER ASSY P/N: 42063	REPLACE	1.00	\$264.00	264 264.00 X
13	PLATE FRONT COWLING P/N: 46220	REPLACE	1.00	\$26.00	26 26.00

*34539 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
14	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00
15	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00
16	VISOR P/N: 43130	REPLACE	1.00	\$30.00	30.00
17	SPRAY PAINT FRONT FENDER	✓	1.00	\$49.00	49.00
SUB TOTAL				1884	\$1,844.00
GST @ 7 %					\$129.08
GRAND TOTAL					\$1,973.08

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



SHIWEI

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*34539 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

NO. : 34615

Supplementary 1 To QTN: 34539

DATE : 21/08/2019
CLAIM NO. : 11400
POLICY NO. : AVFMSB0000611902
FROM : RAYMOND

VEHICLE NO. : FBG6178X
MAKE/MODEL : YAM / YBR125ESD

S/N	Description	Action	Qty	Unit Price	Amount
<i>bracket</i>	BRAKCE METER P/N: 63729	Replace	1.00	\$28.00	28.00 ✓
2	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	Replace ✕	1.00	\$12.00	12.00 S.N ✓

SUB TOTAL	\$40.00
GST @ 7 %	\$2.80
GRAND TOTAL	\$42.80

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



*bizSAFE*₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0583
ISO 9001:2015



QUOTATION

Customer :

NO. : 34539 - Rev. 4

FIRST CAPITAL INSURANCE LTD
06 RAFFLES QUAY #21-00
SINGAPORE 048580

DATE : 02/08/2019
CLAIM NO. : 11400
POLICY NO. : AVFMSB0000611902

MOTOR CLAIMS DEPT

FROM : SHIWEI

VEHICLE NO. : FBG6178X
MAKE/MODEL : YAM / YBR125ESD

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00 Disc %: 10.00	162.00
2	CABLE SPEEDOMETER P/N: 50366	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
3	FOOTREST FRONT P/N: 42064	REPLACE	1.00	\$78.00 Disc %: 10.00	70.20
4	FORK FRONT ASSY LH P/N: 45155	REPLACE	1.00	\$224.00 Disc %: 10.00	201.60
5	FORK FRONT ASSY RH P/N: 45154	REPLACE	1.00	\$224.00 Disc %: 10.00	201.60
6	HEADLAMP ASSY P/N: 43129	REPLACE	1.00	\$157.00 Disc %: 10.00	141.30
7	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED		1.00	\$180.00	180.00
8	LAMP SIGNAL FRONT LH	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
9	PLATE FRONT COWLING P/N: 46220	REPLACE	1.00	\$26.00 Disc %: 10.00	23.40
10	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00 Disc %: 10.00	12.60
11	SPRAY PAINT FRONT COWLING		1.00	\$50.00	50.00
12	SPRAY PAINT FRONT FENDER		1.00	\$30.00	30.00
13	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00 Disc %: 10.00	59.40



bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
15	VISOR P/N: 43130	REPLACE	1.00	\$30.00 Disc %: 10.00	27.00
16	BRACKET METER P/N: 63729	Replace	1.00	\$28.00 Disc %: 10.00	25.20
17	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	Replace	1.00	\$12.00	12.00
SUB TOTAL					\$1,258.30
GST @ 7 %					\$88.08
GRAND TOTAL					\$1,346.38

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



bizSAFE₃





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19013773/Uvd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6299K	Veh. Inspected	FBG 6178X
Policy No.		Coverage (\$)	0.00
Claim No.	D19005068MFSH	Excess (\$)	0.00
Assign From	SERENE LER	Assign Date	06/08/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA YBR 125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	LBPKE1783D0009023	Colour	WHITE
Odometer	31311	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	2.75-18	MICHELIN	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	90-90-18	MICHELIN	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/07/2019	Inspection Date	06/08/2019
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 6178X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BRACKET UNDER FORK	BENT	180.00	180.00
1	CABLE SPEEDOMETER	TORN	14.00	14.00
1	CRASH BAR	TO REPAIR SEE LABOUR	194.00	-
1	FOOTREST FRONT	BENT	78.00	78.00
1	FORK FRONT ASSY LH	BENT / TWISTED	224.00	224.00
1	FORK FRONT ASSY RH	BENT / TWISTED	224.00	224.00
1	HEADLAMP ASSY	BROKEN	157.00	157.00
1	LAMP SIGNAL FRONT LH	CRACKED	16.00	16.00
1	METER ASSY	SERVICEABLE	264.00	-
1	PLATE FRONT COWLING	BROKEN	26.00	26.00
1	RUBBER FOOTREST FRONT	TORN	14.00	14.00
1	SET STEERING CONE	NECESSARY	66.00	66.00
1	VISOR	BROKEN	30.00	30.00
1	BRACKET METER (ADDITIONAL)	BENT	28.00	28.00
	LESS 10% DISCOUNT		-	-105.70
			1,515.00	951.30
<u>SPECIAL NETT ITEMS</u>				
1	STICKER NUMBER PLATE FRONT (BLACK) (SN) (ADDITIONAL)	NECESSARY	12.00	12.00
			12.00	12.00
<u>LABOUR</u>				
	LABOUR - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED. INCLUSIVE OF THE REPAIR OF CRASH BAR.		196.00	180.00
	TRANSPORT CHARGES.		49.00	35.00
	SPRAY PAINT FRONT COWLING.		63.00	50.00
	SPRAY PAINT FRONT FENDER.		49.00	30.00
			357.00	295.00
GRAND TOTAL			1,884.00	1,258.30



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00
---	--	--	----------

Report Ref No. CS/FCI19013773/Uvd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.