

ASS. REC. BY:

REF:

CS1MSG190138201 R/cf352

Special Instruction:

Supervisor: Rasul

ASSIGNMENT (Office)

minim

From (Person): Irene Tan Gek Ing of MSG Date/Time: 6.8.1911.50p.m

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJZ 4998P Insured: SMG 1292B

at Workshop m/s MTM Performanca Tel: 9221 0404

of 4B Toh Guan Road East #01-115

Policy No: 29130850 APO Claim No: 601607

Sum Insured: Excess:

Make of Veh: D.O.A. 1-8-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 7.8.19 9.20a.m Person Contacted: Erwin

Vehicle IN (OUT)

Date/Time	Action/Instruction ( X ) Estimate.
	SJZ 4998P - X
	SMG 1292B - X
29/8/19	@ 1135am Erwin said call for independant no estimate
	Dismantle: 29/8/2019
	Dismantle: 29/8/2019
	After repair: 12/9/2019

Runul  
PRS

REF: MSG

823 I

ASSIGNMENT

From: Date: 28.8.2019

Veh No: SJZ 4998P Yr Bogn: 2012 / MAY

Estimated Cost:

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

OD:  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

Make: B.M.W 320 I AT C.C. 1997

To Inspect Vehicle No: SJZ 4998P  
at Workshop n/s: MTM Performance  
of 4870h Guan Road East #01-115

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 152126 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: WBA 3B120 70E 98 35 30

Claims No.

Gen. Cond: Good /  Fair / Poor / Burnt

Sum Insured:

Excess:

Steering:  Normal / Jammed / Leaked / Burnt or

(Client's Record)

Brake:  Normal / Jammed / Leaked / Burnt or


Make of Veh: After 2.00 p.m

Modi: Nil /  SRim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 235/40R18  
R: "

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO /  YOKO or

Bal. or Market Value: 63K

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm

IDAC Accident Rport: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

D.O.A. 01/08/19 D.O.I. 28/08/19

Lum Sum: % 3 Val.: Yes or No

Survey held at: MTM PERFORMANCE

CA / REV / REP. / 24 HRS

msy

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range - 7K - 8K

Repair Day - 6 days

*[Signature]*  
11/9/2019

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 6

1)

: Final Report

Resurvey No. of Trip: 3

Date/Time, File Return to?

Survey Fee:

2)

Add Fee:  Site Insp (\$

Transportation:

Report Format: PRS

Interview (\$

\_\_\_ \$ + RS \_\_\_ \$

Lump Sum / I.B.I. (\$

Tech. Invs (\$

) Photos

Weekend (\$

) Offits

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Aug 2019		06 Aug 2019 16:55 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ABDUL RANI BIN IDRIS, ID: S6947115C, Tel: +6596183070, Email: ABDUL_RANI_IDRIS@SCHOOLS.GOV.SG								
Main Claimant:	SEOW CHEE LOONG JIMMY(XIAO ZHILONG JIMMY), ID: S8429823I								
Vehicle Reg. No.:	SJZ4998P	Date of Loss: 01/08/2019 08:00 - :59 [86 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 601607	Policy/Cover Note No.: 29130850APO (Comprehensive) Coverage: 28/06/2019 - 27/06/2020							
Vehicle Reg. No. (Insured):	SMG1292B	Policy No. (Claimant): Excess: S\$500.00							
Repairer:	Mtm Performance Auto Pte Ltd ( ) 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/08/2019]								
Driver/Custodian (Insured):	ABDUL RANI BIN IDRIS (49 / Male) , NRIC: S6947115C, Tel: +6596183070 Email: ABDUL_RANI_IDRIS@SCHOOLS.GOV.SG								
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Erwin @ 9221 0404.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/08/2019 13:05
Date Of Accident	01/08/2019 08:40
Exact Location Of Accident	WHAMPOA SOUTH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ4998P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SEOW CHEE LOONG, JIMMY (XIAO ZHILONG, JIMMY)
NRIC No	S8429823I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96944533
Alternative Phone No	OFFICE-96944533

### Vehicle Particulars

Manufacturer	BMW
Model	320I
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109205562(CLASSIC)
Cover Note Number	

### Driver

Name of Driver	SEOW CHEE LOONG, JIMMY (XIAO ZHILONG, JIMMY)
NRIC No	S8429823I
Date Of Birth	24/09/1984
Occupation	INDOOR
Date Of Driving Pass	04/11/2008
Driving Experience	10 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96944533
Fax Number	
Contact Number	OFFICE-96944533
Email Address	NOEMAIL

Address 8 WHAMPOA EAST #20-19  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : ---  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] BEDOK SOUTH NPC  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20190801/2060

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SMG1292B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	DRIVER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJZ4998P
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 1/8/19 1:00 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

(DAC) REPORTER (VAC)

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20190801/2060

1 of 4

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

Report No T/20190801/2060

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 01/08/2019 11:54	Vide Report No.:	Station Diary No.: 33
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: SEOW CHEE LOONG, JIMMY		Address: 8 WHAMPOA EAST #20-19 SINGAPORE 338520	
ID Type / ID No.: NRIC NO / S84298231		Contact No.: Home/Office: Mobile: 96944533	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 34	Date of Birth: 24/09/1984	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: OPERATIONS MANAGER		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/08/2019 08:40	Type of Location: merging lane
Location: Along Road 1 Traveling Toward Road 2 WHAMPOA SOUTH BENDEMEER ROAD Road 1 merging to road 2				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJZ4998P	Car	BMW	320I AT D/AB 4DR ABS HID NAV	White	Slightly Damaged	1
SMG1292B	Car	BMW		Black	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20190801/2060

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

2 of 4

Report No. T/20190801/2060

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJZ4998P	NTUC Income Insurance Co-Operative Limited	5109205562	15/05/2019	14/05/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	SEOW CHEE LOONG, JIMMY		ID No.	S8429823I
Related Vehicle	SJZ4998P (Car)		Contact No.	96944533
Hospital/Clinic	SHENTON FAMILY MEDICAL CLINIC		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	01/08/2019		Date Discharge	01/08/2019
No. of Days granted Medical Leave	03		Degree of Injury	Slight
Driver				
Name	Abdul Rani Bin Idris		ID No.	S6947115C
Related Vehicle	NIL		Contact No.	96183070
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On the 01/08/2019 at about 0840hrs, I was driving my vehicle bearing SJZ4998P along Whampoa South. At the point of time, my wife was in the vehicle.

While I was driving my vehicle merging into Bendemeer Road. I stopped my vehicle before the merging lane as the traffic was very heavy at the point of time. As my view was blocked by the pillar, I inched my vehicle forward.

After I was inch forward I stopped my vehicle and felt an impact from the rear of my vehicle and realised that the vehicle at the rear(SMG1292B) had collided onto my vehicle. I stopped my vehicle and went down to make a check and observed that my rear bumper was cracked, both rear tail light was cracked and my car boot was unable to close properly.

We exchanged particulars and took some photos and left.



**SINGAPORE  
POLICE FORCE**



T/20190801/2060

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999

3 of 4

Report No. T/20190801/2060

CONTINUATION OF REPORT

As both my wife and myself felt some discomfort after the accident, we went for consultation. I was given 3 days of MC.

I have an in car camera in my vehicle, I am not sure if the vehicle at the rear had an in car camera.



**SINGAPORE  
POLICE FORCE**



T/20190801/2060

Police Station Of Origin:  
Bedok South N.P.C  
20 Chai Chee Drive SINGAPORE 469045  
Tel No: 1800-2448999


4 of 4  
Report No. T/20190801/2060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 WANG JUNJIE	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/08/2019 11:54
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LU Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168	 SINGAPORE POLICE FORCE SIGNATURE

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	823I
Vehicle Details	
Vehicle No.:	SJZ4998P
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2019
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT D/AB 4DR ABS HID NAV
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	A1930177N20B20B
Chassis No.:	WBA3B12070E983530
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$38,950.00
Original Registration Date:	15 May 2012
First Registration Date:	15 May 2012
Transfer Count:	1
Actual ARF Paid:	\$38,950.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2022
PARF Rebate Amount:	\$23,370.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$92,050.00
COE Rebate Amount:	\$24,918.00
<b>Total Rebate Amount:</b>	<b>\$48,288.00</b>

The information contained herein is correct as at 29 Aug 2019

OK

63,000  
48,288  
-----  
14,712

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2019		06 Aug 2019 16:55 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ABDUL RANI BIN IDRIS, ID: S6947115C, Tel: +6596183070, Email: ABDUL_RANI_IDRIS@SCHOOLS.GOV.SG								
Main Claimant:	SEOW CHEE LOONG JIMMY(XIAO ZHILONG JIMMY), ID: S8429823I								
Vehicle Reg. No.:	SJZ4998P	Date of Loss: 01/08/2019 08:00 - :59 [86 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 601607	Policy/Cover Note No.: 29130850APO (Comprehensive) Coverage: 28/06/2019 - 27/06/2020							
Vehicle Reg. No. (Insured):	SMG1292B	Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer:	Mtm Performance Auto Pte Ltd ( ) 48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB, 608586 Jurong East - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 07/08/2019]								
Driver/Custodian (Insured):	ABDUL RANI BIN IDRIS (49 / Male), NRIC: S6947115C, Tel: +6596183070 Email: ABDUL_RANI_IDRIS@SCHOOLS.GOV.SG								
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Erwin @ 9221 0404.								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SJZ4998P (601607)  
[SMG1292B]

TP

**SEOW CHEE LOONG JIMMY(XIAO ZHILONG JIMMY)**

Aug 1 2019 8:00AM

[ABDUL RANI BIN IDRIS]

Mtm Performance Auto Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser ▾	
<b>Assessment Reports</b>			1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/08/19 11:36	<b>Accident Statement</b> From:OD - Reg. No: SMG1292B, Claimant: ABDUL RANI BIN IDRIS		Load HTM	
<b>Photos/Images</b>			3 per page ▾	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
22	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
23	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
24	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
25	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
26	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
27	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
28	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
29	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
30	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
31	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
32	02/09/19 16:56	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
33	02/09/19 16:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
34	02/09/19 16:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
35	02/09/19 16:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
36	02/09/19 16:57	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
37	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
38	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
39	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
40	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
41	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
42	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
43	02/09/19 16:57	General View	Load JPG	<input checked="" type="checkbox"/>
44	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
80	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
81	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
82	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
83	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
84	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
85	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
86	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
87	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
88	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
89	02/09/19 16:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
90	02/09/19 16:58	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	02/09/19 16:58	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	12/09/19 12:24	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
116	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
117	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
118	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
119	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
120	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>
121	12/09/19 12:25	Photo After Spray		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/08/19 11:36	PRI		<input type="checkbox"/>
2	02/08/19 11:36	TP GIA		<input type="checkbox"/>
3	06/08/19 15:32	Agree on SJE		<input type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  <div style="border: 1px solid gray; height: 100px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19013820/R1CF3S2  
**Date:** 12/09/2019

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29130850APO
<b>Claimant Vehicle No :</b>	SJZ4998P	<b>Insured Vehicle No :</b>	SMG1292B
Date of Loss:	01/08/2019	Nature of Claim:	TP
		Claim No:	601607

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJZ4998P</b>	Engine No:	A1930177N20B20B
Make & Model:	BMW 320I, 2.0 AT D/AB 4DR ABS HID NAV (A)	Chassis No:	WBA3B12070E983530
Reg. Date:	15/05/2012 (Man. Year: 2012)	Odometer:	152126 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	06/08/2019	Mtm Performance Auto Pte Ltd
Date Inspected:	28/08/2019 Inspected At:	48 TOH GUAN ROAD EAST #01-115
		ENTERPRISE HUB
		Singapore 608586
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 12 Sep 2019)

**Parts:**      143      BMW 320I 2.0 AT D/AB 4DR ABS HID NAV (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**      Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJZ4998P)

**Validity:**      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >