

22/03/2009

ASS. REC. BY:

REF:

CS3/III19013860/Rld3<sup>5</sup>

Special Instructions:

Owner: Rasul

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of

III

Date/Time:

6/8/19 @ 5:29pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 2954E

Insured:

SHB 6712J

at Workshop in/s:

Fix Auto

Tel:

6710 40775

of

5500n Lee Street # 01-61 pioneer

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/8/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:03am @ 9/8/19

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time:

Action/Instruction

Johny? X

SJM 2954E - X

SHB 6712J - CS3/III/8014861/Kfa 3y 2

200. 11/8/18

Dismantle: 8/8/2019 @ 11:10am

After repair: 15/8/2019 @ 12:55pm



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		07 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:			
Main Claimant:	ZHANG YAN, ID: S6960279G		
Vehicle Reg. No.:	SJU2954E	Date of Loss:	04/08/2019 13:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHB6712J	Policy No. (Claimant):	
		Excess:	
Repairer:	Fix Auto Pte Ltd (HQ) 5 SOON LEE STREET, #01-61 PIONEER POINT, 627607 Pioneer - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/08/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 6 August 2019 5:29 PM  
**To:** Lua Siew Hui; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Wendy Jiang; Sherini Pillai  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJU2954E (Accident involving SJU2954E and SHB6712J on 04.08.2019)[1908-7402(FIX)(PD)]  
**Attachments:** shb6712j\_20190806140729.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SJU2954E  
III INSURED VEHICLE NO. : SHB6712J  
DATE OF LOSS : 04.08.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by Sherini.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Lua Siew Hui [mailto:lua\_siewhui@rssolomon.com]  
**Sent:** 06 August, 2019 2:35 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** Wendy Jiang <wendy\_jiang@rssolomon.com>  
**Subject:** Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJU2954E (Accident involving SJU2954E and SHB6712J on 04.08.2019)[1908-7402(FIX)(PD)]

Dear Gabriel,

We thank you for your email of even date.

We write to inform that our client will be appointing her own Surveyors.

In this regard, please arrange your surveyors to contact Ms Irene Lee of Fix Auto Pte Ltd at tel no.: 671040775 for a pre-repair survey of our client's vehicle located at 5 Soon Lee Street #01-61 Pioneer Point Singapore 627607.

Yours sincerely

Lua Siew Hui | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

**Advocates & Solicitors**

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e [lua\\_siewhui@rssolomon.com](mailto:lua_siewhui@rssolomon.com) | w [www.rssolomon.com](http://www.rssolomon.com)

---

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system. Thank you.

On Tue, Aug 6, 2019 at 2:12 PM Motor Claim - III <[motorclaim@iii.com.sg](mailto:motorclaim@iii.com.sg)> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Our Ref. : RSS/1908-7402 (FIX)(PD)  
Your Ref. :

W : Lua Siew Hui/ Wendy Jiang  
E : lua\_siewhui@rssolomon.com/ wendy\_jiang@rssolomon.com

6 August 2019

**India International Insurance Pte Ltd**  
64 Cecil Street  
#04-05 IOB Building  
Singapore 049711  
Kind Attn: Motor Claim Dept



R. S. SOLOMON LLC  
ADVOCATES & SOLICITORS

By Fax: [6224 4174]  
& PDX: [8172]

Dear Sirs,

**PRE-REPAIR SURVEY**

**ACCIDENT INVOLVING SJU2954E & SHB6712J ON 4<sup>TH</sup> AUGUST 2019 AT ABOUT 1300 HRS**

We act for the owner ("our Client") of vehicle no. SJU2954E.

2. We hereby notify you of a road traffic accident on **4<sup>th</sup> August 2019** at about **1300 hours** along Airport Boulevard towards Changi Airport Terminal 2 involving our Client's vehicle and vehicle registration no. SHB6712J driven by your insured's driver. A copy of our Client's Accident Statement is enclosed.

3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceeds to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you intend to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair his vehicle without further reference to you.

Yours faithfully,

**R. S. SOLOMON LLC**  
ADVOCATES & SOLICITORS

ENCL





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/08/2019 15:13
Date Of Accident	04/08/2019 13:00
Exact Location Of Accident	AIRPORT BOULEVARD TOWARDS CHANGI AIRPORT T2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2954E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ZHANG YAN
NRIC No	S6960279G
Email Address	LHZZY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91782895
Alternative Phone No	OFFICE-91782895

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	POLO 1.4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106045635
Cover Note Number	


### Driver

Name of Driver	ZHANG YAN
NRIC No	S6960279G
Date Of Birth	10/11/1969
Occupation	INDOOR
Date Of Driving Pass	26/03/2016
Driving Experience	3 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91782895
Fax Number	
Contact Number	OFFICE-91782895
EEmail Address	LHZZY@HOTMAIL.COM

Details Of Properties	REFER ATTACHED
Vehicle Category	TAXI
Name of Driver	LAM CHENG LEONG (LIN ZHENLIANG)
NRIC/Passport Number	S7909362I
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REFER ATTACHED
No. Of Passenger (Including Driver)	

# Sketch Plan #2

SKETCH PLAN



(A) SJU2954E  
(B) SHB6712J

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was going towards T2 and suddenly I felt & heard a Bang from my vehicle rear. We both stopped and vehicle 'B' taxi driver went further up to talk and saw damages on both vehicles. Only 2 vehicles involved.

(Vehicle 'B' vehicle driver send me a photo of his IC & DL. (SHB6712J))

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Zhang Jun  
Policyholder's Signature  
Date & Time:

Zhang Jun  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	279G
Vehicle Details	
Vehicle No.:	SJU2954E
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 6SP AT
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	BUD472517
Chassis No.:	WVWZZZ9NZ9U034078
Maximum Power Output:	59.0 kW (79 bhp)
Open Market Value:	\$15,021.00
Original Registration Date:	26 Nov 2009
First Registration Date:	26 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$15,021.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2019
PARF Rebate Amount:	\$7,510.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,899.00
COE Rebate Amount:	\$535.00
Total Rebate Amount:	\$8,045.00

The information contained herein is correct as at 13 Aug 2019

OK

10,000  
8,045  
1900  
1.5k  
repair limit

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2019 10:58 <a href="#">Edit Reg</a>		06 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>ZHANG YAN</b> , ID: S6960279G		
Vehicle Reg. No.:	<b>SJU2954E</b>	Date of Loss:	04/08/2019 13:00 - :59 [116 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	<b>SHB6712J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Fix Auto Pte Ltd (HQ)</b> 5 SOON LEE STREET, #01-61 PIONEER POINT, 627607 Pioneer - Tel:		
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sherini Pillai</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 20/08/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































## Claim Documents

\*SJU2954E  
[SHB6712J]  
TP  
ZHANG YAN  
Aug 4 2019 1:00PM  
[-]  
Fix Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/08/19 09:01	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	19/08/19 09:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
37	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
38	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
39	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
40	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
41	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
42	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
43	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
44	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
45	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
46	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
47	19/08/19 09:03	Photographs of Damaged Parts	1 Load JPG	✓
48	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
49	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
50	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
51	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
52	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
53	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
54	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
55	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
56	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
57	19/08/19 09:03	Photo After Spray	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	08/08/19 08:18	Singapore Accident Statement	1 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19013860/R1CD3S2

Date: 22/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJU2954E

Insured Vehicle No : SHB6712J

Date of Loss: 04/08/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJU2954E**

Make &amp; Model: VOLKSWAGEN POLO, 1.4 (A)

Engine No: BUD472517

Reg. Date: 26/11/2009 (Man. Year: 2009)

Chassis No: WVVZZZ9NZ9U034078

Colour: Grey

Odometer: 78772 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 175/65 R14

Rear Tyre Size: 175/65 R14

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 06/08/2019

Date Inspected: 07/08/2019 Inspected At:

 Fix Auto Pte Ltd (HQ)  
 5 SOON LEE STREET, #01-61 PIONEER POINT  
 Singapore 627607

Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 Aug 2019)

**Parts:** 144      VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJU2954E)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >