



Your Ref: C0471112

Date: 04th Sep 2019

Our Ref: CS3/AXA18003746/T1sd3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Tan Wan Cong

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJK 2695E
INSURED VEHICLE: SHD 9797J
ACCIDENT DATE: 16/02/2018**

We thank you for your instruction on 06/08/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJK 2695E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SJK 2695E and SHD 9797J.
- c) Final Repair Bill of SJK 2695E from M/s TeamWork Garage Pte Ltd.
- d) Colour damaged vehicle photographs of SJK 2695E.

Pre-Repair Inspection Date : 28/02/2019 at M/s TeamWork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Paya Ubi Industrial Park, Singapore 408934 .

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

| | |
|----------------------|--|
| Registration Number | : SJK 2695E |
| Make & Model | : Nissan Teana 2.0L CVT ABS D/Airbag 2WD |
| Year of Registration | : 2008 |
| Chassis Number | : JN1BDUJ32Z0000442 |
| Engine Capacity | : 1997 cc |

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.