

22/03/2002

ASS. REC. BY:

REF: 33/CT119013903/Gcf3

Special Instruction:

Surveyor: GQ

## ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 7.8.19 16.41P<sup>h</sup>

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 586C

Insured: GBG 4723K

at Workshop m/s N10 Automotive

Tel: 90914853

of 53 UB Max 1 #05-42

Policy No: DMCVSN30491418000

Claim No: SNM 1911203696102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.8.2019

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time: 7.8.19 5.10p.m

Person Contacted: Mrs N10

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF 586C - NA/INC 19013736/64
	GBG 4723K - NA/INC 19013736/64
	Dismantle: 14/8/2019.

DOA - 05/08/2019

DOA - 05/08/2019

(08/11/14)

Surveyor

PRS  
GRL

REF:

C71

## ASSIGNMENT

From: \_\_\_\_\_ Date: 8.8.2017

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLF 586C

at Workshop m/s N10 Auto motive

of 53 ub Ave 1 #05-44

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLF 586C Yr Regn: 11 Aug 2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 109998 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MM6DL2SAA6W23354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 185/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 08-08-19

Survey held at IDAC NAC 11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: PRS

Lump Sum / I.B.I.: (\$ )

Survey Fee: 150

Transportation: S + RS, \$

Photos

Others

TOTAL

150

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2019		07 Aug 2019 16:41 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	EAT & SMILE ASIA PTE LTD, Co. Reg. No.: 201217617Z		
Main Claimant:	NEO AUTO LEASING PTE LTD, Co. Reg. No.: 201814915N		
Vehicle Reg. No.:	SLF586C	Date of Loss:	05/08/2019 15:00 - :59 [35 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D203696C02	Policy/Cover Note No.:	DMCVSN30491418000
Vehicle Reg. No. (Insured):	GBG4723K	Policy No. (Claimant):	5103424803
		Excess:	\$0.00
Reparer:	Neo Automotive (HQ) 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/08/2019]		
Driver/Custodian (Insured):	WONG CHONG SENG (51 / Male) , NRIC: S1828296H Email:		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	915N
Vehicle Details	
Vehicle No.:	SLF586C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	P520367442
Chassis No.:	MM6DL2SAAGW213354
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$15,224.00
Original Registration Date:	11 Aug 2016
First Registration Date:	11 Aug 2016
Transfer Count:	2
Actual ARF Paid:	\$10,224.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Aug 2026
PARF Rebate Amount:	\$7,668.00
Intended COE Rebate Details	
COE Expiry Date:	10 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$37,043.00
<b>Total Rebate Amount:</b>	<b>\$44,711.00</b>

The information contained herein is correct as at 14 Aug 2019

OK

## Mazda 2 Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
<b>Mazda 2 1.5A Deluxe</b>	<b>\$57,800</b>	\$6,990 /yr	30-Nov-2016	1,496 cc	30,700 km	Autolink Holdings Pte Ltd	<b>Available</b>

Low Mileage, Done 30700KM Only. Serviced And Warranty Under Agent Till 30/11/19. Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan At Interest Rate And Compe...

Office No. - 63463383

Lee - 98468156 | Erik Tan - 94500673

<b>Mazda 2 1.5A Deluxe</b>	<b>\$60,800</b>	\$7,590 /yr	27-Sep-2016	1,496 cc	51,000 km	Regal Motoring Pte Ltd	<b>Available</b>
----------------------------	-----------------	-------------	-------------	----------	-----------	------------------------	------------------

Under Agent Warranty! Full Agent Serviced To Date! Accident Free! Very Well Maintained Interior & Exterior! Flexible Loan Packages Available! Trade In Welcome! Don't Miss! View With No Obligations! Ca...

Office No. - -

Kenny - 96263621 | Kelvin - 91900890

<b>Mazda 2 1.5A</b>	<b>\$60,800</b>	\$7,920 /yr	29-Aug-2016	1,496 cc	98,000 km	Hui Hua Credit Pte Ltd	<b>Available</b>
---------------------	-----------------	-------------	-------------	----------	-----------	------------------------	------------------

Comes With Free 6 Months In House Warranty And 1 Free Servicing! Supreme Condition! Excellent Fuel Consumption! Monthly As Low As \$600+! Flexible In House Financing And High Trade In Given! Call Now T...

Office No. - 64696611 / 64646611

Weisley - 84888000 | Jian Rong - 91830337 | Jevon - 88588388 | Jarryl Ng - 85888000

<b>Mazda 2 1.5A</b>	<b>\$57,800</b>	\$7,500 /yr	29-Aug-2016	1,496 cc	56,350 km	Motor-East Pte Ltd	<b>Available</b>
---------------------	-----------------	-------------	-------------	----------	-----------	--------------------	------------------

Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! Keyless Start, Sport Rims, Leather Seats, Grey In Colour, Maintained And Serviced Reg...

Office No. - 67772200

Alvin Neo - 81886100 | John Toh - 92717577 | Bernard Teng - 96818152 | Jing Jing - 98467878

<b>Mazda 2 1.5A Deluxe</b>	<b>\$57,800</b>	\$7,270 /yr	22-Aug-2016	1,496 cc	63,339 km	Cosmo Automobiles	<b>Available</b>
----------------------------	-----------------	-------------	-------------	----------	-----------	-------------------	------------------

Promo 1.98% Interest Rate! Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident-Free Quality Pre Owned With Low Mileage And Agent Service History ...

Office No. - 64651090

Sam - 97926962 | Alan - 92325665 | Dennis - 92234854 | Leonard - 83337808

<b>Mazda 2 1.5A Deluxe</b>	<b>\$58,000</b>	\$7,320 /yr	16-Aug-2016	1,496 cc	48,500 km	Munich Alpina Pte Ltd	<b>Available</b>
----------------------------	-----------------	-------------	-------------	----------	-----------	-----------------------	------------------

Loan Interest At 2.28%. Extremely Well Maintained And Fully Agent Maintained. This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe! Up To 80% Financing Possible! Trade In ...

Office No. - -

Ben - 91849182 | Dave - 94559794

<b>Mazda 2 1.5A</b>	<b>\$57,800</b>	\$7,550 /yr	11-Aug-2016	1,496 cc	87,123 km	Motor-East Pte Ltd	<b>Available</b>
---------------------	-----------------	-------------	-------------	----------	-----------	--------------------	------------------

Vehicle Viewing At 1094 Lower Delta Road. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! Keyless Start, Sport Rims, Leather Seats, G...

Office No. - 67772200

Joyce Wong - 81987778 | Desmond Koh - 92398586 | Rick Hong - 84674440 | J Tang - 83741233

<b>Mazda 2 1.5A</b>	<b>\$60,800</b>	\$7,980 /yr	11-Aug-2016	1,496 cc	70,000 km	Hui Hua Credit Pte Ltd	<b>Available</b>
---------------------	-----------------	-------------	-------------	----------	-----------	------------------------	------------------

Comes With Free 6 Months In House Warranty And 1 Free Servicing! Supreme Condition! Excellent Fuel Consumption! Monthly As Low As \$600 Plus! Flexible In House Financing And High Trade In Given! Call N...

Office No. - 64696611 / 64646611

Weisley Koh - 84888000 | Alex Chng - 86661188 | Max Siah - 93801243 | Jevon Ng - 88588388

<b>Mazda 2 1.5A</b>	<b>\$60,800</b>	\$7,980 /yr	11-Aug-2016	1,496 cc	83,000 km	Hui Hua Credit Pte Ltd	<b>Available</b>
---------------------	-----------------	-------------	-------------	----------	-----------	------------------------	------------------

Comes With Free 6 Months In House Warranty And 1 Free Servicing! Supreme Condition! Excellent Fuel Consumption! Monthly As Low As \$600 Plus! Flexible In House Financing And High Trade In Given! Call N...

Office No. - 64696611 / 64646611

Weisley Koh - 84888000 | Joey Ng - 88110091 | Jevon Ng - 88588388 | Jian Rong - 91830337

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/08/2019 13:18
Date Of Accident	05/08/2019 15:45
Exact Location Of Accident	JUNC OF YUAN CHING RD & YUNG HO RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF586C
-----------------------------	---------

### Insured/Policyholder

Name Of Registered Owner	NEO AUTO LEASING PTE LTD
Co Reg No	201814915N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91449265

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 2
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5103424803
Cover Note Number	-

### Driver

Name of Driver	ARULTHAMBI RAJ S/O MARIASAVARY ROYALSAMY
NRIC No	S0136020E
Date Of Birth	30/03/1953
Occupation	OUTDOOR
Date Of Driving Pass	30/06/2005
Driving Experience	14 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92389815
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 162 YUNG PING RD #08-17
Postcode	610162
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 158 YUNG LOH ROAD , POSTCODE: 610158 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2659999 - FAX NO: 62664987
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG4723K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

ARULTHAMBI RAJ S/O MARIASAVARY ROYALSAMY

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SLF586C

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190805/2151

1 of 3

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

Report No. T/20190805/2151

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/08/2019 21:16	Vide Report No.:	Station Diary No.: 41
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: ARULTHAMBI RAJ S/O MARIASAVARY ROYALSAMY	Address: APT BLK 162 YUNG PING ROAD #08-17 SINGAPORE 610162		
ID Type / ID No.: NRIC NO / S0136020E	Contact No.:	Mobile: 92389815	
Nationality: SINGAPORE CITIZEN	Home/Office:	Email:	
Sex: Male	Age: 66	Date of Birth: 30/03/1953	Type of Informant: Driver
Race: Indian	Language:		Institution / School Name:
Occupation: SELF EMPLOYED	Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 05/08/2019 15:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 YUAN CHING ROAD YUNG HO ROAD At the X-junction.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG4723K						0
SLF586C						0

**Details of Person Involved**

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL		

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190805/2151

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

2 of 3

Report No. T/20190805/2151

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	WONG CHONG SENG FREDERICK		ID No. S1828296H
Related Vehicle	GBG4723K		Contact No. 97489243
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ARULTHAMBI RAJ S/O MARIA SAVARY ROYALSAMY		ID No. S0136020E
Related Vehicle	SLF586C		Contact No. 92389815
Hospital/Clinic	DRS KOO LOH & ASSOCIATES PTE LTD		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	05/08/2019	Date Discharge	05/08/2019
No. of Days granted Medical Leave	04	Degree of Injury	NIL

**Brief Details.**

On 05/08/2019 at about 1545hrs, while I was driving V1) SLF586C along Yuan Ching Road towards Boon Lay Way, I had stopped V1 behind another vehicle at the traffic junction of Yuan Ching Road and Yung Ho Road as the traffic lights was red. Shortly after waiting, the traffic lights had turn green, I had disengaged my brakes and before my vehicle had move off, I felt an impact from the rear. After the collusion, I noticed the lorry behind me bearing registration plate number V2) GBG4723K. we exchange particular as no one was injured at the point of accident and I went home to rest.

On 05/08/2019 at about 1930hrs, I felt backaches was unbearable and was feeling dizzy hence I decided to seek medical assistance from Drs Koo Loh Associates located at Blk 152 Yung Ho Road B1-03 and was given 04 days of medical leave.

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190805/2151

Police Station Of Origin:  
Jurong NPP  
158 Yung Loh Road #01-58 SINGAPORE  
610158  
Tel No: 1800-2659999

3 of 3

Report No. T/20190805/2151

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/  
Sgt 2 NG WEI LIN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Authentication Stamp  
NP158

Signature Of Informant:

Date/Time:  
05/08/2019 21:16

Classification Of Case:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2019		07 Aug 2019 16:41 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>EAT &amp; SMILE ASIA PTE LTD</b> , Co. Reg. No.: 201217617Z								
Main Claimant:	<b>NEO AUTO LEASING PTE LTD</b> , Co. Reg. No.: 201814915N								
Vehicle Reg. No.:	<b>SLF586C</b>	Date of Loss:	05/08/2019 15:00 - :59 [35 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D203696C02</b>	Policy/Cover Note No.:	DMCVSN30491418000						
Vehicle Reg. No. (Insured):	<b>GBG4723K</b>	Policy No. (Claimant):	5103424803						
		Excess:	S\$0.00						
Repairer:	<b>Neo Automotive (HQ)</b> 53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK SINGAPORE, 408934 Ubi - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 20/08/2019]								
Driver/Custodian (Insured):	WONG CHONG SENG (51 / Male) , NRIC: S1828296H Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SLF586C (SNM19D203696C02)**  
**[GBG4723K]**

**TP**

**NEO AUTO LEASING PTE LTD**


















































**Aug 5 2019 3:00PM**

**[EAT & SMILE ASIA PTE LTD]**

**Neo Automotive**

Upload Documents		Upload Photos		Compose New Letter		View		View In Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Ubi)					Thumbnail	Print	
1	06/08/19 13:35	Accident Statement					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
2	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
3	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
4	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
5	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
6	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
7	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
8	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
9	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
10	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
11	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
12	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
13	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
14	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
15	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
16	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
17	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
18	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
19	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
20	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
21	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
22	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
23	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
24	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
25	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
26	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
27	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
28	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
29	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
30	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
31	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
32	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
33	20/08/19 11:34	General View					Load JPG	<input checked="" type="checkbox"/>	
34	20/08/19 11:34	General View					Load JPG		



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	20/08/19 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/08/19 11:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	07/08/19 16:39	PRS		Load PDF	
2	07/08/19 16:39	INSD GBG4723K GIA REPORT		Load PDF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	06/08/19 13:35	Accident Statement		Load HTM	
Photos/Images					
				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	06/08/19 13:35	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	06/08/19 13:29	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	06/08/19 13:29	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	06/08/19 13:30	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
4	06/08/19 13:30	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
5	06/08/19 13:30	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119013903/GCF3E2

Date: 22/08/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30491418000

Claimant Vehicle  
No : SLF586CInsured Vehicle  
No : GBG4723K

Date of Loss: 05/08/2019

Nature of Claim: TP

Claim  
No: SNM19D203696C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF586C**

Make &amp; Model: MAZDA 2, 1.5 HATCHBACK L SP.6EAT (A)

Engine No: P520367442

Reg. Date: 11/08/2016 (Man. Year: 2016)

Chassis No: MM6DL2SAAGW213354

Colour: Silver

Odometer: 109998 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 07/08/2019

Date Inspected: 08/08/2019 Inspected At:

 Neo Automotive (HQ)  
 53 UBI AVE 1 #05-44 PAYA UBI  
 INDUSTRIAL PARK SINGAPORE  
 Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
<b>Parts:</b>	144	MAZDA 2 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF586C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >