

ASS. REC. BY:

REF: CS/A25M013906 / Uy f302 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Hor Yin Ru / of AIG Date/Time: 8.8.19 9.20 a.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 5097A Insured: SLM 3448L

at Workshop m/s Uni Motor Tel: 9798 1616

of 1 kati Bukit Ave 6 #01-94

Policy No: Claim No: TP/7906534642SG

Sum Insured: Excess:

Make of Veh: D.O.A. 1.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8.8.19 10.43 a.m. Person Contacted: A Lin H.O.D. Endorsement:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLD 5097A - X
	SLM 3448L - X
	TP GIA Report Upload in Merimen 22/8/19

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

AIC

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: S4D5097A
at Workshop m/s unimen
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4510

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S4D5097A Yr Regn: 6, 12
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CAI
Make: Toyota c.c. 2494
Colour: silver A/C: Insured / Std / NI / NA
Sp. Reading: 712/2 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MR053CK5004002615
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: 7 mm Rear: 7 mm
R/Bal. 7 mm L/Bal. 7 mm
D.O.A. 1/8/19 D.O.I. 2/8/19
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 37972 netf 70g

21/8/19 1/5 @ 3500 confid with Athin (Red = 3829-93, 52%)

RECEIVED 22 AUG 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

22/8 Typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 3500-00)

TOTAL

250

11

261

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2019 Edit Reg		08 Aug 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	GUNARSO WIBISONO, ID: S6875685E		
Main Claimant:	EXCLUSIVE LIMO, Co. Reg. No.: NA		
Vehicle Reg. No.:	SLD5097A	Date of Loss:	01/08/2019 00:00 - :59
Claim Type:	TP / 7906534642SG	Policy/Cover Note No.:	2100503731 (Comprehensive) Coverage: 28/03/2019 - 27/03/2020
Vehicle Reg. No. (Insured):	SLM3448L	Policy No. (Claimant):	
		Excess:	
Repairer:	Unimotor Co (HQ) NO 1 KAKI BUKIT AVE 6 #01-94, 417883 Kaki Bukit - Tel: 67182795		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/08/2019]		




ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (13/08/2019): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SLD5097A vs SLM3448L (OI) on D.O.A.: 01/08/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A' (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divy
Sent: 8/8/2019 9:26:02 AM
Attachments:  sld5097-pri-3_08072019_053713.pdf  SLD 5097A- PRI_08072019_041408.pdf  SLD 5097A- PRI_08072019_041408.pdf

Hi,

Please refer to the enclosed request from **C Paglar & Co.**

Claim no : 7906534642SG003
Case Owner : Chan Kian Meng

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: PRI Cpaglar [mailto:pri@cpaglar.com.sg]
Sent: Wednesday, August 07, 2019 5:46 PM
To: Hor, Yinrul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3448L AND SLD5097A ON 01/08/2019

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear Sirs,

We enclose herewith our letter dated 7th August 2019 for your attention.

Thanks and Regards,
Linda Md Shah
on behalf of C Paglar & Co
GST Registration No. M90371275E

On Wed, Aug 7, 2019 at 4:32 PM Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-08-14 16:31 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please

immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: pri@cpaglar.com.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Theerthan.Parthiban@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM3448L AND SLD5097A ON 01/08/2019
Date: Wed, 7 Aug 2019 08:31:27 +0000
Without Prejudice

Your Reference : CP/PRI/SLD5097/19/LD
Our Reference : 7906534642SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: PRI Cpaglar [mailto:pri@cpaglar.com.sg]
Sent: Wednesday, August 07, 2019 4:40 PM
To: Lim, Sheng Yang; Abu Kassim, Noor Mariesa; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Md Ishak, Mohd Imran
Cc: Constance Paglar
Subject: [EXTERNAL] OUR REF: CP/PRI/SLD5097/19/LD (SF) YOUR REF: SLM 3448L NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC ACCIDENT ON 1ST AUGUST 2019 INVOLVING MOTOR VEHICLE NO. SLD 5097A AND SLM 3448L ALONG TANGLIN ROAD TOWARDS ORCHARD ROAD AT ABOUT 1800 HOUR...

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

Enclosed is a copy of our letter dated 7th August 2019 for your necessary action.

Regards,

Shu Fong
For and on behalf of
Messrs C Paglar & Co
50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874
Tel: 6536 5456
Fax: 6536 8706

GST Registration Number: M90371275E

CPc

C PAGLAR & CO

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

50 Chin Swee Road

#05-03 Thong Chai Building

Singapore 169874

Telephone: (65) 6536 5456

Facsimile: (65) 6836 2195

Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SLM 3448L
Our Reference: CP/PRI/SLD5097/19.lid

Date : 7th August 2019

BY EMAIL

AIG ASIA PACIFIC INSURANCE PTE LTD

ATTN: MOTOR CLAIMS DEPT

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES

We refer to your email dated 7th August 2019.

We have our client's instructions to agree to use Mr. Marcus Chua from LKK Auto Consultants Pte Ltd as the Single Joint Expert.


Please note that the said vehicle can be inspected at:

→ **UNIMOTOR COMPANY**
1 Kaki Bukit Avenue 6
#01-94 Autobay@KB
Singapore 417883
Contact No.: 9798 1616 (Alvin)

KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,



C PAGLAR & CO

cc. [Client by Fax 6747 2373 Only] – (SLD 5097A)

Please initial here after completion of pre-repair inspection.
Thank you

.....
Appointed Surveyor (Name & Signature)

.....
Date & Time of Inspection

Form 3

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/08/2019 15:11
Date Of Accident 01/08/2019 18:00
Exact Location Of Accident TANGLIN ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD5097A
Insured/Policyholder
Name Of Registered Owner EXCLUSIVE LIMO & CAR RENTALS
Co Reg No -
Email Address JOHNNY@EXCLUSIVELIMO.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-91018983
Vehicle Particulars
Manufacturer TOYOTA
Model CAMRY
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A29090375 MCX
Cover Note Number
Driver
Name of Driver RAJCHEL ANNA MARIA
Work Permit No G5893098P
Date Of Birth 28/03/1974
Occupation INDOOR
Date Of Driving Pass 29/03/1994
Driving Experience 25 YEARS AND 4 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-96902933
Fax Number
Contact Number
EMail Address NOEMAIL

Address	24 KHEAM HOCK ROAD
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM3448L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GUNARSO WIBISONO
NRIC/Passport Number	S6875685E
Contact Number	96894573
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (an insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected (under (d) above) may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for compliance with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/Fin No.:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, LBI Yi Tuck, is making a report on behalf of driver
 Raychel Anna Maana on an accident on 01/8/19
 P/s Find Attached report as requested.
 I have spoken with Catherine of M21G, and she ask me
 to make a report on the driver's behalf who is overseas.

DECLARATION

I/We declare that the above are true in every respect.

Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Lenco Personnel's Signature
 Name
 NR000775702

Individual Statement Pg. 1

Accident involving SLD5097A & SLM3448L on 01-08-2019

The accident took place on Thursday, 1st of August 2019 at around 6pm on Tanglin Road towards Orchard Road.


I was waiting (not moving) for the bus in front of me to drive off, when suddenly the car (SLM 3448L) hit my car on the back.

Attached the copy of my passport and driving license for your records.



Rajchel Anna Maria

(G5893098P)





友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 15/08/2019 OUR REF: UAPL1287
REPAIR ESTIMATE TO THE TOYOTA CAMRY NO: SLD5097A

- (Set 2)
- 1 REAR BUMPER ASSY
 - 1 REAR BUMPER GROMMET
 - 1 REAR BUMPER REINFORCEMENT
 - 1 L/H REAR BUMPER REFLECTOR
 - 2 REAR BUMPER BOIT COVER
 - 2 REAR BUMPER SIDE RETAINER
 - 2 REAR BUMPER SIDE SUPPORT HOLDER CLIPS
 - 2 REAR BUMPER SENSOR
 - 1 REAR BUMPER LOWER COVER
 - 10 REAR BUMPER CLIPS
 - 1 REAR ~~TRAIL~~ END PANEL
 - 1 REAR ~~TRAIL~~ END PANEL INNER LINING
 - 1 REAR PANEL CENTER LOCKING SENSOR
 - 1 L/H REAR TAILLAMPS ASSY 421-30
 - 1 REAR BOOT ASSY
 - 1 L/H REAR BOOT HINGES
 - 1 REAR BOOT LOCK
 - 1 REAR BOOT STRIKER
 - 1 REAR BOOT WEATHERSTRIP
 - 1 REAR CAMRY EMBLEM
 - 1 REAR HYBRID EMBLEM
 - 1 REAR PANEL LINING

DD/α	\$	883.40	✓
ru	\$	16.00	✓
DD	\$	455.60	✓
11	\$	113.40	X
11	\$	44.60	α
11	\$	208.80	α
11	\$	103.20	α
shold	\$	654.40	✓
11	\$	136.20	X
ru	\$	50.00	✓
DD	\$	602.10	✓
twi	\$	221.30	✓
11	\$	355.60	α
11	\$	587.40	✓
11	\$	1,023.40	α
11	\$	156.60	α
11	\$	378.50	α
11	\$	36.40	α
11	\$	138.60	X
ru	\$	54.30	✓
ru	\$	56.80	✓
Repairs	\$	383.30	X
	\$	6,639.90	
	\$	1,659.98	
	\$	4,979.93	

LESS 25%.....

SPECIAL NETT:-

1 REAR NUMBER PLATE

11 \$ 50.00 α

LABOUR CHARGES:-

TO SPARY UNDERCOATING IN REPAIR

\$ 150.00 50

TO PUTTY AND RESPARY REAR DAMAGED PORTION

\$ 1,000.00 800

TO PANEL BEAT DAMAGED PORTION & RENEW PARTS

\$ 1,000.00 900

TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING

\$ 150.00 80
\$ 7,329.93

Not Approved
2/5 3500
8/8/19
Cheong H. Atkinson
Sdy

3415.20
2561.40
4291.4

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	858D
Vehicle Details	
Vehicle No.:	SLD5097A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY HYBRID CVT
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	2AR0687763
Chassis No.:	MR053CK5004002615
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$40,052.00
Original Registration Date:	28 Jun 2012
First Registration Date:	28 Jun 2012
Transfer Count:	1
Actual ARF Paid:	\$24,032.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2022
PARF Rebate Amount:	\$14,419.00 12016
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$82,003.00
COE Rebate Amount:	\$23,553.00
Total Rebate Amount:	\$37,972.00

The information contained herein is correct as at 13 Aug 2019

OK

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)

AVIVA

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**New 5 Years Coe Renewal Toyota Altis 1.6A**

3.08%P.A \$0 Down \$0 Admin.2
Year Warranty Sta Grade B No
Major Dmg Mthly \$468
GV Credit Pte Ltd StarAd

One Stop Ca
Finance, Insurance
New and Used Car

Browse by Category

Sort by Date Posted

2 vehicles

CAMRY

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

Search Selection**CAMRY**

Any

Any

2012

Any

Any

**Toyota Camry 2.0A****\$41,700****\$12,180 /yr****21-Feb-2012****1,998 cc****98,000 km**

Rare 1 Owner Only. Low Mileage Of 98,000km. Beautiful Silver Paintwork. Well Kept By Previous Owner. Phone Bluetooth Connectivity With Navigation, Reverse Camera. 3M Solar Film. Call Now Before It's Gone.

Posted: 03-Aug-2019

Tags: 2012 Toyota Camry, 2012 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

**Toyota Camry 2.0A****\$43,800****\$12,380 /yr****09-Apr-2012****1,998 cc****100,000 km**

Rare 1 Owner! Very Low Mileage! Pristine Condition! Car Is As Good As New, No Repair Needed, Very Economical Luxury Drive! No Gimmicks! Trade In Welcome! Call Us For An Appointment Now!

Posted: 20-Jul-2019

Tags: 2012 Toyota Camry, 2012 toyota camry, Toyota Camry, toyota camry, Toyota, Camry, camry, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
------	-------	-------	--------------	----------	---------	---------	---

For old advertisements, view [Expired ads](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resour](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars insurance. Find buy used CAMRY, CAMRY Singapore, used CAMRY Singapore, used CAMRY, used vehicles Singapore or even buy used CAMRY Singapore. We have parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our parallel importers, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & more.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information is accurate, complete or current.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Aug 2019 Edit Reg		08 Aug 2019 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GUNARSO WIBISONO , ID: S6875685E								
Main Claimant:	EXCLUSIVE LIMO , Co. Reg. No.: NA								
Vehicle Reg. No.:	SLD5097A	Date of Loss:	01/08/2019 00:00 - :59 [85 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7906534642SG	Policy/Cover Note No.:	2100503731 (Comprehensive) Coverage: 28/03/2019 - 27/03/2020						
Vehicle Reg. No. (Insured):	SLM3448L	Policy No. (Claimant):							
		Excess:							
Repairer:	Unimotor Co (HQ) NO 1 KAKI BUKIT AVE 6 #01-94, 417883 Kaki Bukit - Tel: 67182795								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (13/08/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLD5097A (7906534642SG)**
[SLM3448L]
TP
EXCLUSIVE LIMO
Aug 1 2019 12:00AM
[GUNARSO WIBISONO]
Unimotor Co

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Assessment Reports											1 per page		<input checked="" type="checkbox"/>	
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail		Print	
1	13/08/19 12:24		Accident Statement From:OD - Reg. No: SLM3448L, Claimant: GUNARSO WIBISONO										Load HTM	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)								Thumbnail		Print	
1	10/08/19 14:31		Chassis Number										Load JPG <input checked="" type="checkbox"/>	
2	10/08/19 14:32		Odometer Reading										Load JPG <input checked="" type="checkbox"/>	
3	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
4	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
5	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
6	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
7	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
8	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
9	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
10	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
11	10/08/19 14:32		General View										Load JPG <input checked="" type="checkbox"/>	
12	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
13	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
14	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
15	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
16	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
17	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
18	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
19	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
20	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
21	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
22	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
23	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
24	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
25	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
26	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
27	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
28	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
29	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
30	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
31	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
32	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	
33	10/08/19 14:33		General View										Load JPG <input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
34	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
35	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
36	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
37	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
38	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
39	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
40	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
41	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
42	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
43	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
44	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
45	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
46	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
47	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
48	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
49	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
50	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
51	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
52	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
53	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
54	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
55	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
56	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
57	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
58	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
59	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
60	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
61	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
62	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
63	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
64	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
65	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
66	10/08/19 14:33	General View		Load JPG <input checked="" type="checkbox"/>
67	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
68	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
69	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
70	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
71	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
72	13/08/19 18:17	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	22/08/19 11:43	Singapore Accident Statement TP		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19013906/UYF3E2

Date: 26/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100503731
Claimant Vehicle No : SLD5097A **Insured Vehicle No :** SLM3448L
 Date of Loss: 01/08/2019 Nature of Claim: TP Claim No: 7906534642SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD5097A**
 Make & Model: TOYOTA CAMRY, 2.5 (A) Engine No: 2AR0687763
 Reg. Date: 28/06/2012 (Man. Year: 2012) Chassis No: MR053CK5004002615
 Colour: Silver Odometer: 71212 km
 Engine Capacity: 2494 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,029.92	2,561.40	2,468.52	49.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,830.00	470.00	20.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,329.92	4,391.40	2,938.52	40.09
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	7,329.92	3,500.00	3,829.92	52.25

INSPECTION

Date of Assignment: 08/08/2019
 Date Inspected: 08/08/2019 Inspected At: Unimotor Co (HQ)
 NO 1 KAKI BUKIT AVE 6 #01-94
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented / Deformed	883.40 FL	*883.40 FL
2	1		*SET REAR BUMPER GROMMET	Necessary	16.00 FL	*16.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	455.60 FL	*455.60 FL
4	1		*L/H REAR BUMPER REFLECTOR	Not Necessary	113.40 FL	*- FL
5	2		*REAR BUMPER BOIT COVER	Not Necessary	44.60 FL	*- FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	208.80 FL	*- FL
7	2		*REAR BUMPER SIDE SUPPORT HOLDER CLIPS	Not Necessary	103.20 FL	*- FL
8	2		*REAR BUMPER SENSOR	Shorted	654.40 FL	*654.40 FL
9	1		*REAR BUMPER LOWER COVER	Not Necessary	136.20 FL	*- FL
10	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	1		*REAR END PANEL	Dented	602.10 FL	*602.10 FL
12	1		*REAR END PANEL INNER LINING	Twisted	221.30 FL	*221.30 FL
13	1		*REAR PANEL CENTER LOCKING SENSOR	Not Necessary	355.60 FL	*- FL
14	1		*L/H REAR TAILLAMPS ASSY	Cracked	567.40 FL	*421.30 FL
15	1		*REAR BOOT ASSY	Repair	1,023.40 FL	*- FL
16	1		*L/H REAR BOOT HINGES	Not Necessary	156.60 FL	*- FL
17	1		*REAR BOOT LOCK	Not Necessary	378.50 FL	*- FL
18	1		*REAR BOOT STRIKER	Not Necessary	36.40 FL	*- FL
19	1		*REAR BOOT WEATHERSTRIP	Not Necessary	138.60 FL	*- FL
20	1		*REAR CAMRY EMBLEM	Necessary	54.30 FL	*54.30 FL
21	1		*REAR HYBRID EMBLEM	Necessary	56.80 FL	*56.80 FL
22	1		*REAR PANEL LINING	Repeated	383.30 FL	*- FL
23	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,689.90	3,415.20
- List Item Discount on L Items 25.00/25.00% (S\$)	1,659.98	853.80
Total Parts (S\$)	5,029.92	2,561.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPARY UNDERCOATING IN REPAIR	New	150.00	50.00
2	TO PUTTY AND RESPRAY REAR DAMAGED PORTION	New	1,000.00	800.00
3	TO PANEL BEAT DAMAGED PORTION & RENEW PARTS	New	1,000.00	900.00
4	TO DISM / REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING	New	150.00	80.00
Gross Labour Cost (\$\$)			2,300.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >