

Signature

PRS
Xnl.

REF: SMO


C 4923 R /

ASSIGNMENT

From: _____ Date: 18/10/18
Estimated Cost: _____
ODI TP WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No. PC 2277A
at Workshop m/s Gspeed Autowerkz
of 68 kaki Bkt Ave 6# 02-05
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: Sun sun @ 85332934

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1up
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: PC 2277A Yr Regn: 25 Mar 2014
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Hiace C.C. 2982
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 331603 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ITTST22P700019125
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 155 R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. _____ D.O.I. 18-10-18
Survey held at w/s rpm
Des. of Damages: Frt / Rear / O/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
\$1500 - \$2500

RECEIVED 1 9 OCT 2018

Date/Time: File Pass to? ☐ : Preli. Report
☐ : Final Report

1) _____

Date/Time: File Return to? _____

Report Format: PR2

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$ _____) ☐ S - RS _____
☐ Interview (\$ _____) ☐ Photos
☐ Tech Invs (\$ _____) ☐ Others
☐ Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS _____

Photos

Others

TOTAL

100
10
110

Nivitha (LKK Auto)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Sent: Wednesday, 7 August 2019 12:43 PM
To: Catherine Lim LLC; Sarjeet Singh
Cc: sur@lkkauto.com; admin-d@lkkauto.com
Subject: MC Suit: 9903/2019 ; RE: Your ref : CL/181037/T/SAW.sg DOA: 27.09.2018
Our Ref : CMTD1804237
Attachments: WOS.pdf; Statement of Claim.pdf; List of Documents.pdf

Without Prejudice

Dear Sir / Madam,

With reference to your email below, we will appoint our solicitor, Mr Sarjeet of M/s KELVIN CHIA PARTNERSHIP to MOA for the enclosed copy of MC Suit : 9903/2019.

Please note that we are verifying with our driver the damage consistency between both vehicles and will be carrying out the paper resurvey for your client's vehicle PC2277A.

We will revert with our proposal once we have the report.

Dear Mr Sarjeet,

Please assist for the enclosed copy of MC Suit : 9903/2019 as we attempt to negotiate settlement, thank you Sir.

By copy to Ms Celine of M/s LKK AUTO,

As just spoken, once we have verified with our driver for the damage consistency, please proceed with the paper resurvey and do forward the soft copy report once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



or



Download now @

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Catherine Lim LLC <info@catherinelimllc.com>

Sent: Wednesday, 7 August, 2019 10:49 AM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: Re: Your ref : CL/181037/T/SAW.sg DOA: 27.09.2018 Our Ref : CMTD1804237

Dear Sir

We have filed a Writ of Summons & List of Documents against your insured / driver. A copy of the Writ of Summons & List of Documents are enclosed for your attention.

Please let us know by **15 August 2019** whether you will be appointing solicitors to accept service of process.

Regards,
Catherine Lim LLC

From: Ye, Yong Kang Melvin

Sent: Friday, October 12, 2018 5:37 PM

To: Sally

Cc: Gnoh, Pau Loong ; Teo, Grace ; Henry, Irene James

Subject: RE: Your ref : CL/181037/T/SAW.sg DOA: 27.09.2018 Our Ref : CMTD1804237

Our Reference: CMTD1804237

Your Reference: CL/181037/T/SAW.sg

Without Prejudice

We refer to your reply dated 12/10/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Melvin Ye
Claims Division
D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Sally [<mailto:info@catherinelimllc.com>]
Sent: Friday, 12 October, 2018 5:10 PM
To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: RE: Your ref : CL/181037/T/SAW.sg DOA: 27.09.2018 Our Ref : CMTD1804237

Dear Sir (Without Prejudice)

We refer to your email.

Our client is not agreeable to your list of surveyor and attached herewith our client's list as single joint expert.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Ye, Yong Kang Melvin [<mailto:melvin.ye@sompo.com.sg>]
Sent: Friday, October 12, 2018 4:12 PM
To: info@catherinelimllc.com

Cc: Gnoh, Pau Loong; Teo, Grace; Gnoh, Pau Loong

Subject: Your ref : CL/181037/T/SAW.sg DOA: 27.09.2018 Our Ref : CMTD1804237

Our Reference: CMTD1804237

Your Reference: CL/181037/T/SAW.sg

Without Prejudice

Date: 12th October 2018

Attention:

M/S CATHERINE LIM LLC

Dear Jacelyn,

ACCIDENT INVOLVING PC2277A & PC126R ON 27.09.2018

We refer to your Notice of Accident dated 12/10/2018.

Please be informed that Mr Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

IN THE STATE COURTS OF THE REPUBLIC OF SINGAPORE

Case No.: MC/MC 9903/2019

Filed: 10-July-2019 04:55 PM

Between

Heavenly Tours Pte Ltd
(Singapore UEN No. 201014923R)

...Plaintiff(s)

And

Hui Leong Transport (2010) Pte Ltd
(Singapore UEN No. 201010850C)

...Defendant(s)



WRIT OF SUMMONS

To:

Hui Leong Transport (2010) Pte Ltd
39 Woodlands Close #03-20 Singapore 737856

THIS WRIT OF SUMMONS has been issued against you in respect of the claim endorsed herein.

You must:

1. satisfy the claim; or
2. enter an appearance,

within 8 days after the service of this Writ, failing which, the Plaintiff(s) may proceed with the action and enter judgment against you without further notice.

THIS WRIT OF SUMMONS is issued by the solicitors for the Plaintiff(s) whose particulars are as below.
The address(es) of the Plaintiff(s) is/are 64 Rangoon Road #01-22 Singapore 218354.

Solicitor(s) for the Plaintiff(s)

CATHERINE LIM LLC
20 HAVELOCK ROAD # 03 - 01 CENTRAL SQUARE Singapore 059765
Tel No.: 64385500
Fax No.: 64380111
Email: info@catherinelimllc.com
File Ref No.: CL/181037/T/SAW
Solicitor in charge: LIM CHUI LING CATHERINE



JENNIFER MARIE
REGISTRAR
STATE COURTS
SINGAPORE

STATEMENT OF CLAIM

Please see attached Statement of Claim.

Note:

1. This writ may not be served more than 6 calendar months after the above date unless renewed by order of the Court.
2. To defend the claim, the Defendant(s) must enter an appearance(s) using the electronic filing service either personally or by a solicitor at the Registry of the STATE COURTS and notify the (Plaintiff(s) / Plaintiff's solicitors) accordingly within 8 days after service hereof, otherwise judgment may be entered against him without further notice.
3. Where the Defendant enters an appearance, he must also serve a defence on the solicitor for the Plaintiff within 14 days after the last day of the time limited for entering an appearance; otherwise judgment may be entered against him without further notice.

STATEMENT OF CLAIM

1. The Plaintiff is and was at all material times the owner of motor vehicle No. PC 2277A.
2. On or about the 27th day of September 2018 at about 1.15 p.m., the Plaintiff's authorised driver, one Muhammad Shafiq Bin Mohamed Zarufulla ('the Plaintiff's Driver') was driving bus No. PC 2277A and had parked at the Singapore Zoo Coach area. Bus No. PC 126R driven by the Defendant's agent and/or servant and/or authorised driver, one Peter Ting Cherng Jein ('the Defendant's driver') was reversing out from the parking lot when the left side swiped onto the Plaintiff's bus. Further and/or alternatively, the Defendant's driver so drove his bus No. PC 126R in such a way that he caused and/or contributed to the accident between the Plaintiff's bus and the Defendant's bus.
3. The said collision was caused and/or contributed by the negligence of the Defendant's driver in the driving, management and control of his motor vehicle.

PARTICULARS OF NEGLIGENCE OF THE DEFENDANT'S DRIVER

- (a) Failing to keep a proper lookout;
- (b) Failing to maintain a safe braking distance;
- (c) Reversing at an excessive speed in the circumstance;
- (d) Failing to have any or any proper control over bus No. PC 126R;
- (e) Failing to notice the Plaintiff's bus in sufficient time to avoid the said collision or at all;
- (f) Reversing too closely to the Plaintiff's bus;
- (g) Failing to stop, slow down, swerve or in any other way so to manage or control the bus No. PC 126R as to prevent the said collision;

PARTICULARS OF SPECIAL DAMAGES

- | | |
|---------------------|------------|
| (a) Cost of Repairs | \$6,750.00 |
|---------------------|------------|

(b) loss of Rental

[2]

\$2,340.00

\$9,090.00

And the Plaintiff claims:-

(a) the said sum of \$9,090.00 or alternatively damages;

(b) interest;

(c) costs; and

(d) Such other relief as this Honourable Court deem fit

10 JUL 2019
Dated this day of 2019

U

SOLICITORS FOR THE PLAINTIFFS

~~And \$800.00 (or such sum as may be allowed on taxation) for costs, and also, if the Plaintiffs obtain an order for substituted services the further sum of \$300.00 plus disbursements (or such sum as may be allowed on taxation). If the amount claimed and costs be paid to the Plaintiff or his/her/their Solicitors within eight days after service hereof (inclusive of the day of service), further proceedings will be stayed.~~

~~NOTICE OF SERVICE ON MANAGER OF PARTNERSHIP~~

~~Take notice that the Writ of Summons is served on you as the person having the control or management of the partnership business of the abovenamed defendant firm (and also as partner in the said firm (s)).~~

Solicitors for the Plaintiff

If the Defendant(s) enters an appearance, then, unless a summons for judgement is served on him in the meantime, he must also serve a defence on the solicitor for the plaintiff within 14 days after the last day of the time limited for entering an appearance, otherwise judgment may be entered against him without further notice.

This Writ is issued by M/s Catherine Lim LLC, 20 Havelock Road, #03-01 Central

[3]
Square, Singapore 059765, Solicitors for the said Plaintiff whose address is at c/o 474 Jurong
West Street 41 #12-398 Singapore 640474.

ENDORSEMENT OF SERVICE

This Writ was served by _____ by way of personal service (or as may be)
(state manner of service or in accordance with the terms of an order for substituted service) on
the Defendant who is known to me by _____ /who admitted to me that
he/she was at _____ on _____, the _____ day of _____ 2019
at _____ a.m./p.m.

Indorsed the _____ day of _____ 2019 Process Server

Form 8

(To be filed with Writ of Summons)

1. Has the defendant or his insurer acknowledged receipt of the plaintiff's letter of claim?

Ans. ☒ Yes ☐ No.

2. Have attempts been made to settle the matter?

Ans. ☒ Yes ☐ No.

If no, please give reasons.

3. Is the question of liability agreed?

Ans. ☐ Yes ☒ No.

4. Is the question of quantum agreed?

Ans. ☐ Yes ☒ No.

5. Has the defendant indicated that he has a counterclaim?

Ans. ☐ Yes ☒ No.

6. The following documents/information have been exchanged between the plaintiff and the defendant (please tick accordingly):

☒ GIA reports and type-written transcripts of all persons involved in the accident, including a sketch plan.

☒ Repairer's bill and evidence of payment.

☒ Surveyor's report.

☐ Excess bill/receipt.

☐ Vehicle registration card.

☐ COE/PARF certificates.

- ☐ Names and addresses of witnesses.
- ☐ Photographs of damage to all vehicles.
- ☐ Photographs of accident scene.
- ☐ Invoice and receipt for rental of alternative vehicle.
- ☐ Whether the insurer has been notified of the accident and allowed to carry out a pre-repair inspection of the claimant's vehicle.

Remarks (if any)

7(a) Did the accident involve a chain collision or more than 2 vehicles?

Ans. Yes/No.

7(b) If yes, has the defendant indicated that he intends to bring in a third party?

Ans. Yes/No.

7(c) If yes, has the third party indicated that he intends to bring in a fourth party?

Ans. Yes/No.

7(d) Were there any other parties involved in the accident?

Ans. Yes/No.

If yes, please provide details.

IN THE STATE COURTS OF THE REPUBLIC OF SINGAPORE

MC/MC Suit No. 9903/2019

Between

HEAVENLY TOURS PTE LTD
(Singapore UEN No.201014923R)

... Plaintiff

And

HUI LEONG TRANSPORT (2010) PTE LTD
(Singapore UEN No. 201010850C)

... Defendant

LIST OF DOCUMENTS

The following is a list of documents relating to the matters in question in this action which are or have been in the possession, custody or power of the abovenamed Plaintiff and are referred to in the Writ of Summons, which is served in compliance with the Order 108, Rule 2 of the Rules of Court.

1. The Plaintiff has in his possession, custody or power the documents relating to the matters in question in this action set out in Schedule 1 to this list of documents.
2. The Plaintiff had, but does not now have, in his possession, custody or power the documents relating to the matters in question in this action set out in Schedule 2 to this list of documents.
3. Other than the documents set out in Schedules 1 and 2 to this List of Documents, neither the Plaintiff, nor his solicitor nor any other person on his behalf, has now, or at any time in the past ever had, in his possession, custody or power any document of any description whatever relating to any matter in question in this action.

SCHEDULE 1

PART 1

<u>No.</u>	<u>Date</u>	<u>Description</u>
1.	28 September 2018	Singapore Accident lodged by the Plaintiff
2.	28 September 2018	Singapore Accident lodged by the Defendant

3.	21 December 2018	Final repair bill by 6 Speed Autowerkz Pte Ltd
4.	21 November 2018	Survey report ref no: CAS/18-11/031 from Constant Appraiser Services
5.	3 January 2019	Letter of Demand to Sompo Insurance Singapore Pte Ltd

PART 2


Cause papers, notes, instructions to the Plaintiff's solicitors and confidential communication between the Plaintiff and his solicitors with reference to the matters in question in this action for the purpose of obtaining legal advice.

SCHEDULE 2

There are no documents falling under this category.

2 - AUG 2019

Dated this day 2019


 Solicitors for the Plaintiff
 M/s Catherine Lim LLC

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Heavenly Tours Pte Ltd
c/o 68 Kaki Bukit Avenue 6
#02-05 ARK@Kaki Bukit
Singapore 417896

Date : 21/11/2018

Reference No : CAS/18-11/031

General Information

Registration No. : PC 2277A
Accident Date : 27/09/2018

Particulars of Damaged Vehicle

Colour	: White	Make & Model	: Toyota Hiace High Roof Commuter Turbo Auto
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 331603	Engine No.	: 1KD2376002
Chassis No.	: JTFS22P700019125	Steering	: In Order
Registration Date	: 25/03/2014	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	BRIDGESTONE	90%
L/H Front Tyre	195R15	BRIDGESTONE	90%
R/H Rear Tyre	195R15	BRIDGESTONE	90%
L/H Rear Tyre	195R15	BRIDGESTONE	90%

Inspection

Repairer : 6 Speed Autowerks Pte Ltd
68 Kaki Bukit Avenue 6, #02-05 ARK@Kaki Bukit, Singapore 417896

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$9,865.93
Revised Amount : \$6,750.00
Less Excess : -
Nett Total : \$6,750.00

Remarks

- (A) Survey was done on 17/10/2018
- (B) Re-survey after repair was done on 24/10/2018
- (C) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (D) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Constant Appraiser Services

Vehicle No : PC 2277A

Our ref : CAS/18-11/031

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – LIST ITEMS</u>					
1	1pc	Tailgate	Dented	2,405.60	2,405.60
2	1pc	Tailgate glass moulding	Necessary	271.50	271.50
3	1pc	Tailgate inner lock	Serviceable	281.95	-
4	1pc	Tailgate emblem logo	Necessary	71.20	71.20
5	1pc	Tailgate weatherstrip	Distorted	228.45	X 228.45
6	2pcs	Tailgate side stopper @ \$48.80	Serviceable	97.60	-
7	2pcs	Tailgate side stopper striker @ \$45.00	Serviceable	90.00	-
8	1pc	Tailgate emblem Toyota sticker	Necessary	43.00	43.00
9	1pc	Tailgate emblem Hiace sticker	Necessary	52.00	52.00
10	1pc	Taillamp LH	Serviceable	338.50	-
11	1pc	Rear bumper	Dented/Grazed	451.60	/ 451.60
12	2pcs	Rear bumper side retainer @ \$45.50	Serviceable	91.00	-
13	1pc	Rear fender LH	Dented/Warped	2,295.60	X 2,295.60
14	1pc	Rear fender glass moulding LH	Necessary	224.00	X 224.00
15	1pc	Center body panel LH	Dented/Warped	951.40	X 951.40
16	1pc	Center body panel glass moulding LH	Necessary	110.50	X 110.50
				8,003.90	7,104.85
Less 25%				(2,000.97)	(1,776.21)
Sub total				6,002.93	5,328.64
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>					
1	1set	Rear bumper clip	Necessary	45.00	/ 45.00
2	1pc	Tailgate sticker 70km/h	Necessary	12.00	X 12.00
3	1pc	Tailgate sticker Emergency Door Pull To Open	Necessary	48.00	X 48.00
4	1set	Tailgate inner trim board clip	Necessary	28.00	X 28.00
5	1pc	Rear side body panel glass sealant LH	Necessary	200.00	X 160.00
6	1set	Rear windscreen sealant	Necessary	100.00	X 80.00
Sub total				6,435.93	5,701.64
<u>LABOUR & MISC. CHARGES</u>					
1		To remove, refix tailgate glass		140.00	120.00 X
2		To remove, refix tailgate mechanism		100.00	70.00 X

Constant Appraiser Services

Vehicle No : PC 2277A

Our ref : CAS/18-11/031

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>LABOUR & MISC. CHARGES (CONT'D)</u>			
3		To check rear electrical wiring		40.00	20.00 ✓
4		To remove, refix interior trim to assist repair		120.00	80.00 ✓
5		To remove, refix rear seat & carpet		150.00	120.00 ✓
6		To remove, refix reverse sensor		80.00	60.00 ✓
7		To respray undercoating		100.00	60.00 ✓
8		To respray painting & etc		1,200.00	1,000.00 ✓
9		Panel beating, cut, weld, remove & replacing above parts		1,500.00	1,200.00 ✓
		Grand total		9,865.93	8,431.64
Recommended cost of lump sum repair to its pre-accident condition)					6,750.00


1460

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$6,750.00 on a contractual basis. Under normal circumstances, the repair period would be about 7 (Seven) working days.

Yours faithfully,
Constant Appraiser Services


Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA



38 29.06
20% = 3050
5 Days.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2018 16:17
Date Of Accident	27/09/2018 13:15
Exact Location Of Accident	SINGAPORE ZOO (BUS COACH AREA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2277A
Insured/Policyholder	
Name Of Registered Owner	HEAVENLY TOURS PTE LTD
Co Reg No	NA
Email Address	SHAFIQ_MUHD@HOTMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-94461887

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVBPSB0005851800
Cover Note Number	

Driver

Name of Driver	MUHAMMAD SHAFIQ BIN MOHAMED ZAFURULLA
NRIC No	S9018837B
Date Of Birth	27/05/1990
Occupation	OUTDOOR
Date Of Driving Pass	30/05/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94461887
Fax Number	
Contact Number	
Email Address	SHAFIQ_MUHD@HOTMAIL.COM

Address	BLK 474 JURONG WEST STREET 41 #12-398
Postcode	640474
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC126R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	PETER TING CHERNG JEIN
NRIC/Passport Number	S7989536I
Contact Number	84014515
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name:
NRIC / Fin No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29 Sept 2018, at about 13 15HRS my company's vehicle (PC2277A) was parked at Singapore Zoo bus coach area. My vehicle was hit by another vehicle (PC126R) while ^{he was} reversing to move out from his lot.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide **within 21 days** of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC / Fin No.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UTN: 346500306 / GST Reg. No.: M40017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : NSI 118126103 Vehicle Registration No: PC 22774
Name(as shown in NRIC) : Muhammad Shafiq Bin Mohamed Zafuralla NRIC/FIN/Passport No : S9018837D
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Blk 474 Jurong West Street 4, #12-398, Singapore (640474)
Contact (Tel) : - Mobile No. : 94461887
Email Address : Shafiq-Muham C@hotmail.com
Date of Accident : 22/9/2018 Time of Accident : 13:15
Place of Accident : Singapore Zoo (Bus Coach Area)
Insurance Company : Allied World

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

→ Amend from Reporting only to Third Party

[Signature]
Policyholder / Driver's Signature
Date:

[Signature] STA Sin My.
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: 3/10/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/09/2018 15:03
Date Of Accident	27/09/2018 13:25
Exact Location Of Accident	SINGAPORE ZOO CAR PARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC126R
Insured/Policyholder	
Name Of Registered Owner	HUI LEONG TRANSPORT (2010) PTE LTD
Co Reg No	201010850C
Email Address	OPERATIONS@HUILEONGBUS.COM
Mobile Phone No	
Alternative Phone No	Office-63682810
Vehicle Particulars	
Manufacturer	HIGER
Model	KLQ6108GQ-6.7 D ABS TURBO (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D17MTSCBU000036
Cover Note Number	
Driver	
Name of Driver	PETER TING CHERNG JEIN
NRIC No	S7989536I
Date Of Birth	05/09/1979
Occupation	OUTDOOR
Date Of Driving Pass	23/07/2007
Driving Experience	11 YEARS AND 2 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-84014515
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	33 JLN KEMPAS INDAH 1/6 TMN KEMPAS INDAH
Postcode	81300
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 27/09/18 @ 13:25HRS, I WAS REVERSING MY BUS PC126R AT SINGAPORE ZOO CAR PARK. I DID NOT NOTICE A VEHICLE PC2277A WAS PARKED AT CAR PARK LOT. WHEN MY BUS SIDE MIRROR BRUSHED ONTO THE SAID VEHICLE PC2277A WHILE REVERSING. P/S : BUS NO COMING TO REPORTING CENTRE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC2277A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to assist in the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Remedy Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer said Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purposes) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NIC/ID No:



SKETCH PLAN

WATER A = PC126R

Model 6 : PC 237-1A



Singapore 730 018 8888

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/04/20 @ 13:25 hrs, I was receiving my bus PC O&P of Singapore 220 for port. I did not realise it whilst PC 2271A was posted at cor port lot when my bus side mirror brushed into the said wheel PC 2271A while receiving.

Pls: Bus PC moving to loading center.

DECLARATION

Little doubt is the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel
Name:
NRCC/1181 New



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18018656/Gyd3e2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 13-09-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 126R	Veh. Inspected	PC 2277A	
Policy No.	D18MTSCBU000041	Coverage (\$)	0.00	
Claim No.	CMTD1804237	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	07/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTFST22P700019125	Colour	WHITE	
Odometer	331603	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2018	Inspection Date	18/10/2018	
Survey held at	6 SPEED AUTOWERKZ PTE. LTD. 68 KAKI BUKIT AVENUE 6 #02-05 ARK@KB SINGAPORE 417896			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2277A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED	2,405.60	2,405.60
1	TAILGATE GLASS MOULDING	NECESSARY	271.50	110.00
1	TAILGATE INNER LOCK	SERVICEABLE	281.95	-
1	TAILGATE EMBLEM LOGO	NECESSARY	71.20	71.20
1	TAILGATE WEATHERSTRIP	SERVICEABLE	228.45	-
2	TAILGATE SIDE STOPPER @\$48.80	SERVICEABLE	97.60	-
2	TAILGATE SIDE STOPPER STRIKER @\$45.00	SERVICEABLE	90.00	-
1	TAILGATE EMBLEM TOYOTA STICKER }	NECESSARY	43.00	60.35
1	TAILGATE EMBLEM HIACE STICKER }	NECESSARY	52.00	-
1	TAILLAMP LH	SERVICEABLE	338.50	-
1	REAR BUMPER	DENTED / GRAZED	451.60	451.60
2	REAR BUMPER SIDE RETAINER @\$45.50	SERVICEABLE	91.00	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,295.60	-
1	REAR FENDER GLASS MOULDING LH	NOT NECESSARY	224.00	-
1	CENTER BODY PANEL LH	TO REPAIR SEE LABOUR	951.40	-
1	CENTER BODY PANEL GLASS MOULDING LH	NOT NECESSARY	110.50	-
	LESS 25% DISCOUNT		-2,000.98	-774.69
			6,002.92	2,324.06
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	TAILGATE STICKER 70KM/H (SN)	NOT NECESSARY	12.00	-
1	TAILGATE STICKER EMERGENCY DOOR PULL TO OPEN (SN)	NOT NECESSARY	48.00	-
1	SET TAILGATE INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	28.00	-
1	REAR SIDE BODY PANEL GLASS SEALANT LH (SN)	NOT NECESSARY	200.00	-
1	SET REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
			433.00	45.00
LABOUR				
	TO REMOVE, REFIX TAILGATE GLASS	NOT NECESSARY	140.00	-

Report Ref No. CS3/SMO18018656/Gyd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REFIX TAILGATE MECHANISM.	NOT NECESSARY	100.00	-
	TO CHECK REAR ELECTRICAL WIRING.		40.00	20.00
	TO REMOVE, REFIX INTERIOR TRIM TO ASSIST REPAIR.		120.00	80.00
	TO REMOVE, REFIX REAR SEAT & CARPET.		150.00	120.00
	TO REMOVE, REFIX REVERSE SENSOR.		80.00	40.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	100.00	-
	TO RESPRAY PAINTING & ETC.		1,200.00	600.00
	PANEL BEATING, CUT, WELD, REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH AND CENTER BODY PANEL LH.		1,500.00	600.00
			3,430.00	1,460.00
GRAND TOTAL			9,865.92	3,829.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS3/SMO18018656/Gyd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.