

ASS. REC. BY:

REF: CS3/Smo 190139/41 Gcf302 Special Instruction:

Surveyor: GIA ASSIGNMENT (Office)From (Person): Agnes Chan Smu Hui of SMO Date/Time: 8-8-19 12:18p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FS 9881T Insured: GBH 49460at Workshop m/s HUA chin (2000) Trading Tel: 6896 6619 | 6515 5189
of 50 Bukit Batok Street 23 #02-02Policy No: D19MPCV6001705 Claim No: CMTD 1903802

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 8-8-19 1:10pm Person Contacted: MR Lim H.O.D. Endorsement: _____
Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	FS 9881T - AS/IN (16012073) / H1 Gbn2
	GBH 49460 - X
<u>20/8 2:36pm</u>	<u>Ying Ping said they don't have GIA.</u>

Surveyor

PRS
Bal.

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Hua chin
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FS9881T Yr Regn: Jan 01
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda NSR 150SP 149
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 10869 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: NS150SP0010932
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80-17
 R: 110/70-17
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 08-08-19
 Survey held at w/s 5:30pm
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
and.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
\$5000 - \$6000

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation:

- S + RS. - SI

- Photos

- Others

-

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : PRS

Lump Sum / I.B.I: (\$

100
11
111

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2019		08 Aug 2019 12:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	ZAP PILING PTE LTD, Co. Reg. No.: 198900332N		
Main Claimant:	MOHAMED HUSSAIN BIN NAZIR MOHAMED, ID: S9341848D		
Vehicle Reg. No.:	FS9881T	Date of Loss:	02/08/2019 18:00 - :59
Claim Type:	TP / CMTD1903802	Policy/Cover Note No.:	D19MTPCVE001705 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH4946D	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/08/2019]		
Adj Asg. Remarks:	WS: MR LIM W KOON 6896 6619		
ASSOCIATED MAIL RECEIVED			
		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	848D
Vehicle Details	
Vehicle No.:	FS9881T
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	NSR150SP
Primary Colour:	Green
Manufacturing Year:	2000
Engine No.:	NS150SPE0010932
Chassis No.:	NS150SP0010932
Maximum Power Output:	-
Open Market Value:	\$4,100.00
Original Registration Date:	17 Jan 2001
First Registration Date:	17 Jan 2001
Transfer Count:	11
Actual ARF Paid:	\$615.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2020
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,517.00
COE Rebate Amount:	\$206.00
Total Rebate Amount:	\$206.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 20 Aug 2019

OK






































...CLAIM SUBFOLDER...(Pending for Survey Report)

































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Aug 2019		08 Aug 2019 12:18 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ZAP PILING PTE LTD , Co. Reg. No.: 198900332N								
Main Claimant:	MOHAMED HUSSAIN BIN NAZIR MOHAMED , ID: S9341848D								
Vehicle Reg. No.:	FS9881T	Date of Loss:	02/08/2019 18:00 - :59 [222 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903802	Policy/Cover Note No.:	D19MTPCVE001705 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH4946D	Policy No. (Claimant):							
		Excess:							
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/08/2019]								
Adj Asg. Remarks:	WS: MR LIM W KOON 6896 6619								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FS9881T (CMTD1903802)
 [GBH4946D]
 TP
 MOHAMED HUSSAIN BIN NAZIR MOHAMED
 Aug 2 2019 6:00PM
 [ZAP PILING PTE LTD]
 Hua Chin (2000) Trading Motor Service Centre

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
11	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
12	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
13	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
14	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
15	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
16	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
17	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
18	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
19	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
20	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
21	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
22	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
23	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
24	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
25	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
26	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
27	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
28	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
29	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
30	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
31	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/19 10:50	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	08/08/19 11:19	Pre-Repair Survey +GIA	 Load PDF	
2	08/08/19 11:43	Pre-Repair Survey - ASSIGN LKK	 Load PDF	
3	08/08/19 12:17	Pre-Repair Survey - Hua Chin (2000) Trading Motor Service Centre	 Load PDF	
4	08/08/19 12:17	Singapore Accident Statement - GBH4946D	 Load PDF	
5	21/08/19 14:13	PD LOD W ENCLS DT 14.08.19 FR MAHADI ABU BAKAR & PARTNERS - GBH4946D PD LOD W ENCLS DT 14.08.19 FR MAHADI ABU BAKAR & PARTNERS - GBH4946D	 Load PDF	
6	21/08/19 14:51	LTR W ENCLS DTD 19.08.19 FR MAPHILINDO COMPANY - GBH4946D LTR W ENCLS DTD 19.08.19 FR MAPHILINDO COMPANY - GBH4946D	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19013914/GCF3E2

Date: 22/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPCVE001705
Claimant Vehicle No :	FS9881T	Insured Vehicle No :	GBH4946D
Date of Loss:	02/08/2019	Nature of Claim:	TP
		Claim No:	CMTD1903802

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FS9881T	Engine No:	NS150SPE0010932
Make & Model:	HONDA NSR150SP, 149cc (M)	Chassis No:	NS150SP0010932
Reg. Date:	17/01/2001 (Man. Year: 2000)	Odometer:	10869 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	110/70-17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	08/08/2019	
Date Inspected:	08/08/2019 Inspected At:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING Singapore 659578
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 22 Aug 2019)
Parts:	N/A	HONDA NSR150SP 149cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS9881T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >