

**PRECISE AUTO SERVICE**

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

19-08-19

Date Of Accident : 04-08-2019

OUR REF : FBJ 6166P/T/19

HASBARINI BINTE HASAN

Blk 7 Jalan Batu

#09-107

Singapore 431007

*Hck - Mercus*

*Date In/out: 07/08/19 to 19-08-19*

*k*  
*Not Allowed*  
*aka*  
*d/s #2300*  
*H by.*  
*8/8/19*  
*19-08-19*

**ESTIMATE BILL ON VEH. NO. : FBJ 6166P**

**MODEL : KTM 200 DUKE**

**CHASSIS NO. : VBKJUC405EC009978**

**LIST ITEM**

Handle Bar	<i>su</i>	110.00 <i>X</i>
Handle Bar Rubber	<i>cu7</i>	55.00
Clutch Lever - LH	<i>scr</i>	63.00
Clutch Lever Switch - LH	<i>Dye</i>	58.00
Head Lamp Cover Garnish	<i>n</i>	195.00 <i>X</i>
Front Mudguard	<i>cu7</i>	160.00
Front Cover - LH	<i>n</i>	85.00 <i>X</i>
Fuel Tank Garnish Cover - LH	<i>cu7</i>	98.00
Front Suspension Strut - LH	<i>Dye/cu7</i>	450.00
Chain Cover	<i>n</i>	60.00 <i>X</i>
Foot Gear Lever - LH	<i>scr</i>	65.00
Gear Rod	<i>scr</i>	60.00
Foot Rest Bracket	<i>scr</i>	110.00
Foot Rest Rubber - LH	<i>cu7</i>	58.00
Radiator	<i>no/Am</i>	580.00
Radiator Side Cover - LH	<i>To.n</i>	30.00

*1-1787*  
*w7*  
*1628.30*

2,237.00  
Less 10% Discount : 223.70  
2,013.30

S. Neff

**SPECIAL NETT ITEM**

Luggage Box (Hepco & Becker)

SNW 650  
850.00

Luggage Box Bracket

SNW 110.00

Rear Number Plate

SNW 20.00<sup>10</sup>

**LABOUR CHARGE**

Towing

35 100.00

To Replace Recommended Parts.

250 350.00

To Check Wiring System.

12 X 25.00 X

Transport Charges (2 Trips).

Repair 100.00 X

To Respray Ferring.

250.00 ✓

3,818.30

GST 7% : 267.28

**AMOUNT DUE : 4,085.58**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: