

ASS. REC. BY:

REF:

es/FCI/9013923/kq/3/12

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

CWS

From (Person): Serene Lee

of

FCI

Date/Time: 7:08pm 7/8/19

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 3102M

Insured:

SHD 73092

at Workshop m/s

Hui Yung Motor

Tel:

6451 5752

of

Blk 176 Sin Ming Drive # 04-02

Policy No:

Claim No:

D19005141MFS#

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/8/2019

CA / REV / REP. / REV 24 HRS

Imp

H.O.D. Endorsement:

Date/Time: 10:33am 8/8/19

Person Contacted:

Bel

Vehicle IN/OUT

| Date/Time        | Action/Instruction              |
|------------------|---------------------------------|
|                  | Johnnie? ✓                      |
|                  | SMJ 3102M-X                     |
|                  | SHD 73092-X.                    |
| 15/8/19 @ 2.17pm | revised to Serene Lee by email. |
|                  |                                 |
|                  |                                 |

ASS. REC. BY:

REF: FCI

## ASSIGNMENT

From:

Date:

14/8/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMJ 3102M

at Workshop m/s

Hui Yang Motor

of

Blk 176 8-Ming Drive #04-02

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

8100k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMJ 3102M Yr Regn: 02 / 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda <sup>SA</sup> Wagon 14P6

Colour:

M. P. White

A/C: Insured / Std / NI / NA

Sp. Reading

45045

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB7 107P503

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: <sup>Hyphen</sup> 185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

4

mm

L/Bal.

8

mm

L/Bal.

4

mm

D.O.A.

5/8/19

D.O.I.

14/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/8 11:15pm @ 1150k Car Insured (Red 814, 41%)

RECEIVED 23 AUG 2019

Date/Time, File Pass to?



: Preli. Report

1) 25/8 TRISA



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

100

Transportation:

50

S + RS. SI

50

Photos

13

Others

TOTAL

213

Report Format:

TP

Lump Sum / LPS: (%)

1150



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005141MFSH

Date: 15 August 2019

Our Ref: CS/FCI19013923/Kqd3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SMJ 3102M .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 14/08/2019 at the premises of M/s HUI YANG MOTOR, and have the following to report:-

|                          |                         |
|--------------------------|-------------------------|
| Workshop Estimate Amount | : S\$ <u>1,964.00</u> . |
| Revised Estimate Amount  | : S\$ <u>1,459.00</u> . |
| "Check" Items Amount     | : S\$ <u>-</u> .        |
| Market Value             | : S\$ <u>-</u> .        |
| LTA Reimbursement Value  | : S\$ <u>-</u> .        |
| Nett Value               | : S\$ <u>-</u> .        |

**Description of Damage:**

The vehicle sustained damages at the rear n/s door.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                            |                               |
|--------------------|------------------------------------------------------------|-------------------------------|
| Date               | 07-08-2019                                                 | Our Ref No. D19005141MFSH     |
| Accident Date      | 05-08-2019                                                 | Claim Type. Third Party       |
| Insured Vehicle    | SHD7309Z                                                   | Third Party Vehicle. SMJ3102M |
| Survey Location    | BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE            |                               |
| Contact Person.    | BEL                                                        |                               |
| Contact No.        | 64515752/ 0                                                | Fax No. 64514658              |
| Survey Type        | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED (EST. COR \$1964) |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                               |                               |
| Contact Person     | NA                                                         | Fax No. 68416315              |
| Contact Number.    | NA                                                         |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                        |                         |
|-------------------|------------------------|-------------------------|
| Cc : Workshop     | HUI YANG MOTOR SERVICE | Attention. NIL          |
| Cc : TP Solicitor | NA                     | TP Solicitor Fax No. NA |
| Officer Incharge  | SERENE                 |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 15 August 2019 2:17 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Serene Ler'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19005141MFSH/1  
**Attachments:** CSFCI19013923Kqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SMJ 3102M.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Sent:** Thursday, 8 August 2019 10:28 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Serene Ler' <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19005141MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 14/08/2019.

Best Regards

**G.NIVITHA**

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 7 August 2019 7:08 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Serene Ler <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19005141MFSH/1

Dear Sir/Mdm,

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

05/08/2019

Owner: VFM PTE LTD

## ESTIMATE TO REPAIR HONDA FREED - SMJ3102M

1pc rear LH door  
1pc rear LH door frame sticker

*ms Rev 1/9*  
*14/08/19*  
*after 11am*  
*(LKK)*

*As* \$ 1,105.00 —  
*na* \$ 25.00 —

less 20%

\$ 1,130.00  
\$ 226.00  
\$ 904.00

remove & refit rear LH door glass  
wiring  
tuffkote  
spray painting  
labour charges  
Total

\$ 100.00 *60%*  
\$ 80.00 *15%*  
\$ 80.00 *30%*  
\$ 400.00 *25%*  
\$ 400.00 *20%*  
\$ 1,964.00

*Not Withheld*  
*11pm @ 150%*  
*Presum After Paint*  
*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                                    |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                         |                                                                                                    |                 | Ref : CS/FCI19013923/Kqd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                                    |                 | Date : 26-08-2019           |  |
|                                                                                                                                                                                        |                                                                                                    |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                                    |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHD 7309Z                                                                                          | Veh. Inspected  | SMJ 3102M                   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                                    | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D19005141MFSH                                                                                      | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | SERENE LER                                                                                         | Assign Date     | 07/08/2019                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA FREED (A)                                                                                    | c.c             | 1496                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                             | Year of Reg.    | 2019                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | GB71079503                                                                                         | Colour          | METALLIC PEARL WHITE        |                                                                                     |
| Odometer                                                                                                                                                                               | 45045                                                                                              | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                           | Modification    | NIL                         |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                               |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                               | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 185/65 R15                                                                                         | KAPSEN          | 8 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 185/65 R15                                                                                         | KAPSEN          | 8 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 185/65 R15                                                                                         | YOKOHAMA        | 4 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 185/65 R15                                                                                         | YOKOHAMA        | 4 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                                    |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S DOOR.                                                                                                                                    |                                                                                                    |                 |                             |                                                                                     |
| DAMAGES SEE DETAILS.                                                                                                                                                                   |                                                                                                    |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                                    |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 05/08/2019                                                                                         | Inspection Date | 14/08/2019                  |                                                                                     |
| Survey held at                                                                                                                                                                         | HUI YANG MOTOR PTE LTD<br>BLOCK 176 SIN MING DRIVE<br>#04-02 SIN MING AUTOCARE<br>SINGAPORE 575721 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                                    |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                    |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                                    |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                                    |                 | <b>2 Working Days</b>       |                                                                                     |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 3102M**

| Qty                                                                             | Description of Parts               | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---------------------------------------------------------------------------------|------------------------------------|-----------|---------------------------|-------------------|
|                                                                                 | <b><u>REPLACEMENT OF PARTS</u></b> |           |                           |                   |
| 1                                                                               | REAR LH DOOR                       | BENT      | 1,105.00                  | 1,105.00          |
| 1                                                                               | REAR LH DOOR FRAME STICKER         | NECESSARY | 25.00                     | 25.00             |
|                                                                                 | LESS 20% DISCOUNT                  |           | -226.00                   | -226.00           |
|                                                                                 |                                    |           | 904.00                    | 904.00            |
|                                                                                 | <b><u>LABOUR</u></b>               |           |                           |                   |
|                                                                                 | REMOVE & REFIT REAR LH DOOR GLASS. |           | 100.00                    | 60.00             |
|                                                                                 | WIRING.                            |           | 80.00                     | 15.00             |
|                                                                                 | TUFFKOTE.                          |           | 80.00                     | 30.00             |
|                                                                                 | SPRAY PAINTING.                    |           | 400.00                    | 250.00            |
|                                                                                 | LABOUR CHARGES.                    |           | 400.00                    | 200.00            |
|                                                                                 |                                    |           | 1,060.00                  | 555.00            |
|                                                                                 | <b>GRAND TOTAL</b>                 |           | <b>1,964.00</b>           | <b>1,459.00</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |                                    |           |                           | <b>1,150.00</b>   |

Report Ref No. CS/FC19013923/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.