

22/01/2019

ASS. REC. BY:

REF: CS3 / AIG / 9013926 / Fed 3/12

Special Instruction:

Conveyer: Ram

ASSIGNMENT (Office)

From (Person):

Maimmen

Chin Lee Yng

of

AIG

Date/Time:

8/8/19 @ 10:32am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 9697P

Insured:

SKV 5414K

at Workshop m/s

GP Motoring

Tel:

9061 8091

of

282 Macpherson Road

Policy No:

2100429765

Claim No:

6330985650SG

Sum Insured:

Excess:

D.O.A.

29/07/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:30pm @ 8/8/19

Person Contacted:

Mr. Ken

Vehicle

IN/OUT

Date/Time

Action/Instruction

Initials (X)

FBH 9697P - X

SKV 5414K - X

Dismantle: 13/8/2019

After repair: 23/8/2019

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: FBH 9697P

Yr Regn: NOV, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or

Make: Yamaha F216

C.C 153

Colour Black

A/C: Insured / Std / NI / NA

Sp. Reading 89985

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: ME1210099 D2028580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 110/70 R17

R: 150/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

metzeler

Front

Rear

R/Bal. 3 mm

R/Bal. 4 mm

L/Bal. mm

L/Bal. mm

D.O.A. 29/07/2019

D.O.I. 8/8/2019

Survey held at

GP motoring

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~Repair - \$1000 - \$1000~~

Repair days: 4 days.

MV: \$4000

PV: \$729

W: \$3000

RECEIVED 26 AUG 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) 3 + RS, SI

) Photos

) Others

TOTAL

Report Format:

DAR

Lump Sum / I.B.I. (\$

180

11

141

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019 <a href="#">Edit Reg</a>		08 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Telagawathi Roresenglewi, ID: S8483491B								
Main Claimant:	MUHAMMAD DANIAL BI RAHMAT								
Vehicle Reg. No.:	FBH9697P	Date of Loss:	29/07/2019 00:00 - :59						
Claim Type:	TP / 6330985650SG	Policy/Cover Note No.:	2100429765 (Comprehensive) Coverage: 23/09/2018 - 22/09/2019						
Vehicle Reg. No. (Insured):	SKV5414K	Policy No. (Claimant):							
		Excess:							
Repairer:	GP MOTORING PTE LTD (HQ) 282 Macpherson Road, 348607 Macpherson - Tel: 67464240								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 21/08/2019]								
Claimant's Solicitor:	JusEquity Law Corporation - Tel: 65369339								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (13/08/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 8/8/2019 10:32:39 AM  
Attachments:  [PRI FBH9697P.PDF](#)

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** Alfred Ng [mailto:[alfred\\_ng@juseq.com.sg](mailto:alfred_ng@juseq.com.sg)]  
**Sent:** Thursday, August 08, 2019 9:41 AM  
**To:** Hor, Yinrul  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV5414K AND FBH9697P ON 29/07/2019

**This message is from an external sender; be cautious with links and attachments.**

Your ref: 6330985650SG003  
Our ref: JEQ/190785/0819/GP/PI

Dear Yinrul,

We refer to your email dated today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraisal Services Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Oh Appraisal Services;
10. CL Appraisal Pte Ltd.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**GP Motoring Pte Ltd**

**282 Macpherson Road**

**Singapore 348607**

**Tel: 6909-9284    Mobile: 9061-8091.**

**Fax: 6909-9274**

**Person In charge : Mr. Ken Sim**

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng

Executive

On behalf of Mr Michael Yap

M/s JusEquity Law Corporation

No. 171 Chin Swee Road

#02-01/02/06 Singapore 169877

Tel : 6536 9339

Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

----- Original Message -----

**From:** Hor, Yinrul

**To:** alfred\_ng@juseq.com.sg

**Cc:** Fong, Andy-SY ; Chin, Lee-Ying ; Abu Kassim, Noor Mariesa ; Azlan, Syazairdina ; Chan, Yoke Shi ; Lim, Sheng Yang ; Mithoosingh, Aashweenjeetkaur ; Parthiban, Theerthan ; Subramaniam, Divyashni ; Tong, Wahxin

**Sent:** Thursday, August 08, 2019 8:55 AM

**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV5414K AND FBH9697P ON 29/07/2019



This is a secure, encrypted message. To read it, open the attachment.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	270G
<b>Vehicle Details</b>	
Vehicle No.:	FBH9697P
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Aug 2019
Vehicle Make:	YAMAHA
Vehicle Model:	FZ 16
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	21CG028428
Chassis No.:	ME121C0G9D2028580
Maximum Power Output:	-
Open Market Value:	\$2,240.00
Original Registration Date:	25 Nov 2013
First Registration Date:	25 Nov 2013
Transfer Count:	5
Actual ARF Paid:	\$336.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Nov 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,712.00
COE Rebate Amount:	\$729.00
<b>Total Rebate Amount:</b>	<b>\$729.00</b>

The information contained herein is correct as at 21 Aug 2019

OK



(1)

Bike model  
Type  
Any


Price From  
Any

Price To  
Any

Class  
Any

MORE SEARCH OPTIONS

Q SEARCH VIEW ALL (/LISTING/USED/BIKES/LISTING/)



## Yamaha FZ16

Listing Type	Free Ad
Brand	Yamaha (/listing/usedbike/brand/yamaha/)
Model	Yamaha FZ16 (/listing/usedbike/model/yamaha-fz16/)
Engine Capacity	153cc
Classification	Class 2B (/listing/usedbike/model/motorcycle-for-sale/class/class-2b/)
Registration Date	15/03/2013
COE Expiry Date	14/03/2023 (3 years 6 months left)
Mileage	34690km
No. of owners	1

Type of Vehicle  
Street Bikes  
(/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

REPORT ERROR (/LISTING/LISTING/ERROR/USED/BIKE/136147)

ADD TO SHORTLIST

Like 0

Share

SHARE (WHATSAPP//SENDTEXT=HTTPS//WWW.SGBIKEMART.COM.SG/LISTING/USED/BIKE/YAMAHA-YAMAHA-FZ16/136147)

### SELLER INFORMATION

Name  
Chris

Contact  
+65 97348206

### FORMS TO DOWNLOAD

- Agreement Form (/static/forms/agreement.pdf)
- Handing Over Form (/static/forms/handover/handover.pdf)
- Deposit Receipt (/static/forms/deposit\_receipt.pdf)
- LTA Transfer Form (/static/forms/deposit\_receipt.pdf)
- Private Settlement Form (/static/forms/private-settlement-agreement.pdf)



Price: SGD\$4300

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2019 12:19
Date Of Accident	29/07/2019 18:05
Exact Location Of Accident	SLE TOWARDS BKE AFTER UPPER THMSON EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH9697P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUHAMMAD DANIAL BIN RAHMAT
NRIC No	S9535270G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87862675
Alternative Phone No	OFFICE-87862675

### Vehicle Particulars

Manufacturer	YAMAHA
Model	FZ16-153CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	D18MTMC01003357
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD DANIAL BIN RAHMAT
NRIC No	S9535270G
Date Of Birth	08/10/1995
Occupation	INDOOR
Date Of Driving Pass	12/04/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87862675
Fax Number	
Contact Number	OFFICE-87862675
EMail Address	NOEMAIL



Address	BLK 21 JALAN TENTERAM #01-453
Postcode	320021
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS DIVISION HQ
Police Station Address	ROAD: 1 WOODLANDS STREET 12 , POSTCODE: 738622 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT AND SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV5414K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SARBUDEEN S/O ABDUL SALAM
NRIC/Passport Number	S7823649C
Contact Number	97846360
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBH9697P

Were seat belts worn?

NO

Was this injured conveyed to hospital by ambulance?


YES

Address

Postcode

Sketch Plan Pg. 1

### SKETCH PLAN



Road Shoulder

← SLE towards BKE before <sup>upper</sup> ~~thrombosis~~ exit.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

131 87 2015

1273 m

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 13/8/2019  
12pm

Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:



L/20190730/7919

1 of 2

Report No. L/20190730/7010

Date/Time Report Made 30/07/2019 11:16	Vide Report No.	Station Diary No.		
Name Of Informant MUHAMMAD DANIAL BIN RAHMAT	Address APT BLK 717B WOODLANDS DRIVE 70 #05-32 SINGAPORE 732717			
ID Type / ID No. NRIC NO / S9535270G	Contact No. Home/Office:	Mobile: 98235004		
Nationality SINGAPORE CITIZEN	Email Address danielbinrahmat@gmail.com			
Occupation Aircraft Trainee Technician	Sex Male	Age 23	Date of Birth 08/10/1995	Race Malay
Institution/School Name	Language English			
Date/Time Of Incident 29/07/2019 18:05 - 29/07/2019 18:15	Location Of Incident SELETAR EXPRESSWAY			

I was lane splitting and went on to the second lane as there was a jam ahead. The car, plate number SKV5414K, was driving on lane one and jammed brake and swerved out into my lane to avoid a car in front of him. This made me jam brake as well and his side mirror hit me causing me to fly off my bike and roll a couple meters down. He stopped his vehicle after. I was sent to the hospital with deep abrasions on both my arms and legs and was given 3 days of MC. We managed to exchange particulars. This report is an update from previous report number L/20190730/7008 as I entered the wrong location.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 30/07/2019 11:16
Officer In-Charge Of Case:	Classification Of Case:

Page 6 of 22



**SINGAPORE  
POLICE FORCE**



L/20190730/7010

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. L/20190730/7010

<b>Subjects Involved</b>			
<b>Suspect</b>			
Person Name	Sarbudeen S/O Abdul Salam		
ID Type	NRIC NO	ID No	S7823649C
Gender	Male	Age	40-41
Race	Indian	Language	English
Address	701 Woodlands Drive 40 #02-106 SINGAPORE 730701	Mobile No	97846360
Complexion	Dark tan	Build	Slim
Hair Colour	Black		
<b>Victim</b>			
Person Name	MUHAMMAD DANIAL BIN RAHMAT		
ID Type	NRIC NO	ID No	S9535270G
Gender	Male	Age	23
Race	Malay	Language	English
Occupation	Aircraft Trainee Technician	Address Type	
Address	APT BLK 717B WOODLANDS DRIVE 70 #05-32 SINGAPORE 732717	Mobile No	98235004
Is Informant A Victim?	Yes		
<b>Person Name</b> MUHAMMAD DANIAL BIN RAHMAT (Informant)			

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

30/07/2019 11:16

Classification Of Case:



60 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048023  
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg  
Co. Reg. No.: 196905490E | GST Reg. No.: M200903199

### Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

**Car No./Policy No.** : D18MTMC01003357  
**Insured** : MUHAMMAD DANIAL BIN RAHMAT  
**Motor Vehicle (Regn No.)** : FBH9697P  
**Cover** : Third Party, Fire & Theft  
**Policy Commencement Date** : 13 JUNE 2018 18:52  
**Policy Expiry Date** : 24 NOVEMBER 2019 23:59  
**Maximum Liability (Section I)** : Market value at time of loss  
**Excess\*** : \$300 - Section I  
**Named Driver 1** : MUHAMMAD DANIAL BIN RAHMAT  
**Named Driver 2** : SYED FARHAN BIN SYED SAGOFF  
**HIRE PURCHASE OWNER** : GP MOTORING PTE LTD

\* Subject to GST wherever applicable

**Persons or Classes of Persons entitled to drive\***

MUHAMMAD DANIAL BIN RAHMAT, SYED FARHAN BIN SYED SAGOFF

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

**Limitations As To Use**

Use only for social, domestic and pleasure purposes and  
(a) by the Insured in person in connection with his business or profession or  
(b) in connection with the Insured's business or profession

**The Policy does not cover**

- (i) Use for racing pacemaking, reliability trial or speed-testing
- (ii) Use for the carriage of passengers for hire or reward
- (iii) Use for any purpose in connection with the Motor Trade

**Accident Reporting**

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at [www.sompo.com.sg](http://www.sompo.com.sg) or call our Emergency Hotline: (65) 6461 6555.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Transport Act, 1987 (Malaysia); and (2) the policy terms, conditions and exceptions of the Motorcycle Policy (Ref MCY-MTMC-01)

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 13 JUNE 2018 18:52

**IMPORTANT NOTICE**

- o Keep the Certificate in your Motor Vehicle;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Vehicle or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Vehicle has been sold to another person. The Policy is not transferable to the new owner of the Motor Vehicle.

Intermediary Code & Name : 11E07901 & ENSURE PTE. LTD. (MOTORCYCLE) CI Code: MY100 FWDZLW4KKM1MJKAH





## Motorcycle

Vehicle No: FBH 9677P

NAC	INC	Item	CON	AC	Qty
3001	991886	Front Number Plate	scr	/	
3001	995065	Front Tyre		/	
3002	995095	Front Rim	scr	/	
3003	994872	Front Tyre Rim Spoke		/	
3004	991771	Front Fender Wheel Guard	cra	/	
3005	991283	Front Brake Disc		/	
3006	991281	Front Brake Caliper		/	
3007	991785	Front Fork Assy	BT	/	
3008	991787	Front Fork Inner Tube		/	
3009	991789	Front Fork Outer Tube		/	
3010	991167	Front Fork Bracket	PLS	/	
3011	991182	Front Fork Oil Seal	rec	/	
3012	991174	Front Fork Garnish		/	
3013	992376	Front Headlamp Rim		/	
3014	992328	Front Headlamp	scr	/	
3015	992337	Front Headlamp Bracket		/	
3016	992345	Front Headlamp Fairing	cra	/	
3017	992130	Front Windshield		/	
3018	992134	Front Wing Mirror	MIS	/	
3019	995245	Front LH Signal Lamp	scr	/	
3020	995246	Front RH Signal Lamp		/	
3021	992556	Meter Casing		/	
3022	992553	Meter Assy		/	
3023	991019	ERP Bracket		/	
3024	991020	ERP Unit		/	
3025	992446	Ignition Switch		/	
3026	992442	Ignition Key Assy		/	
3027	990706	Cowling Stay		/	
3028	994470	Steering Stem	BT	/	
3029	994427	Steering Cone	BT	/	
3030	992299	Handle Bar		/	
3031	992312	Handle Bar Switch		/	
3032	992310	Handle Bar Grip	REC	/	
3033	995184	Handle Bar Balancer LH	cut	/	
3034	992300	Handle Bar Balancer RH		/	
3035	992179	Fuel Tank	DD R	/	
3036	990438	Brake Reservoir		/	
3037	990621	Clutch Lever	MTS	/	
3038	992293	Hand Brake Lever		/	
3039	991119	Side Fairing		/	
3040	994220	Side Fairing Top Garnish		/	
3041	994219	Side Fairing Inner Garnish		/	
3042	991118	Fairing Shield		/	
3043	992047	Front Top Fairing Inner Garnish		/	
3044	991123	Fairing Top Garnish		/	
3045	990538	Center Fairing		/	
3046	993378	Rear Fairing		/	
3047	991121	Fairing Stopper		/	
3048	991117	Fairing Lower		/	

NAC	INC	Item	CON	AC	Qty
3049	995074	Radiator		/	
3050	992738	Radiator Cowling		/	
3051	994146	Seal Assy		/	
3052	990915	Engine Crash Bar		/	
3053	990928	Engine Guard		/	
3054	990219	Battery		/	
3055	990224	Battery Cover		/	
3056	990223	Battery Bracket		/	
3057	991144	Foot Brake		/	
3058	991154	Front Foot Rest		/	
3059	991779	Front Foot Rest Bracket		/	
3060	994269	Side Stand		/	
3061	992549	Main Stand		/	
3062	990615	Clutch Engine Cover		/	
3063	992478	Kick Starter Rubber		/	
3064	992477	Kick Starter Lever		/	
3065	991145	Foot Gear Shifter		/	
3066	993500	Rear Foot Rest		/	
3067	993501	Rear Foot Rest Bracket		/	
3068	992581	Exhaust Muffler Heat Shield	scr	/	
3069	991058	Exhaust Muffler Assy		/	
3070	993719	Rear LH Shock Absorber		/	
3071	993720	Rear RH Shock Absorber		/	
3072	995065	Rear Tyre		/	
3073	991200	Rear Rim		/	
3074	994872	Rear Tyre Rim Spoke		/	
3075	993474	Rear Fender Wheel Guard		/	
3076	993443	Rear Fender Mudflap		/	
3077	992940	Rear Brake Disc		/	
3078	992936	Rear Brake Caliper		/	
3079	995236	Rear Spocket		/	
3080	990585	Chain		/	
3081	990580	Chain Guard		/	
3082	994530	Swing Arm		/	
3083	993819	Rear Sub frame		/	
3084	995245	Rear LH Signal Lamp		/	
3085	995246	Rear RH Signal Lamp		/	
3086	995251	Rear Taillamp		/	
3087	993626	Rear Number Plate		/	
3088	994192	Side Box		/	
3089	992927	Rear Box	MIS	/	
3090	992928	Rear Box Bracket		/	
3091	991328	Emblem		/	
3092	990247	Sticker		/	
		SNP with balancer (LH)	cra	/	
		FUEL TANK LEFT COWLING	cut	/	
		BOX BASE plate	cut	/	

No of Items:

Assessor:

# ...CLAIM SUBFOLDER...(Pending for Survey Report)




































PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2019 <a href="#">Edit Reg</a>		08 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by adjuster]</span>									
Insured:	Telagawathi Roresenglewi, ID: S8483491B								
Main Claimant:	MUHAMMAD DANIAL BI RAHMAT								
Vehicle Reg. No.:	FBH9697P	Date of Loss:	29/07/2019 00:00 - :59 [68 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6330985650SG	Policy/Cover Note No.:	2100429765 (Comprehensive) Coverage: 23/09/2018 - 22/09/2019						
Vehicle Reg. No. (Insured):	SKV5414K	Policy No. (Claimant):							
		Excess:							
Repairer:	GP MOTORING PTE LTD (HQ) 282 Macpherson Road, 348607 Macpherson - Tel: 67464240								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 21/08/2019]								
Claimant's Solicitor:	JusEquity Law Corporation - Tel: 65369339								
<b>ASSOCIATED MAIL RECEIVED</b> <span>View All</span> <span>Compose Case Mail</span>									
<ul style="list-style-type: none"> <li>AIG_SG (13/08/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span>View All</span> <span>Search Tasks</span> <span>Create New Task</span> <span>Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBH9697P (6330985650SG)  
[SKV5414K]  
TP  
MUHAMMAD DANIAL BI RAHMAT  
Jul 29 2019 12:00AM  
[Telagawathi Roresenglewi]  
GP MOTORING PTE LTD

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
2	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
3	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
4	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
5	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
6	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
7	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
8	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
9	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
10	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
11	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
12	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
13	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
14	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
15	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
16	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
17	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
18	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
19	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
20	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
21	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
22	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
23	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
24	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
25	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
26	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
27	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
28	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
29	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
30	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
31	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
32	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
33	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
34	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
35	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
36	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>
37	15/08/19 09:06	General View											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/08/19 09:06	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/08/19 09:06	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/08/19 09:06	General View	 Load JPG	<input checked="" type="checkbox"/>
41	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/08/19 16:22	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	26/08/19 10:09	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
89	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
90	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
91	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
92	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
96	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
97	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
98	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
99	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
103	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
104	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
105	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
106	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
107	26/08/19 10:09	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div></div> <div> <div></div> <div></div> </div> </div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19013926/FCD3E2

Date: 30/08/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100429765  
**Claimant Vehicle** FBH9697P **Insured Vehicle No :** SKV5414K  
**No :**  
 Date of Loss: 29/07/2019 Nature of Claim: TP Claim No: 6330985650SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FBH9697P**  
 Make & Model: YAMAHA FZ16, 153cc (M) Engine No: 21CG028428  
 Reg. Date: 25/11/2013 (Man. Year: 2013) Chassis No: ME121C0G9D2028580  
 Colour: Black Odometer: 89985 km  
 Engine Capacity: 153 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 150/60 R17  
 Front Left Side: Metzeler 3 mm Rear Left Side: Metzeler 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 08/08/2019  
 Date Inspected: 08/08/2019 Inspected At: GP MOTORING PTE LTD (HQ)  
 282 Macpherson Road  
 Singapore 348607  
 Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRONT RIM	Scratched	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
4	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
5	1		*FRONT FORK BRACKET	Distorted	0.00 F	*- F
6	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
7	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
8	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
9	1		*FRONT WING MIRROR	Missing	0.00 F	*- F
10	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
11	1		*STEERING STEM	Bent	0.00 F	*- F
12	1		*HANDLE BAR	Bent	0.00 F	*- F
13	2		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
14	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
15	1		*FUEL TANK	Repair	0.00 F	*- F
16	1		*CLUTCH LEVER	Cut	0.00 F	*- F
17	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
18	1		*REAR BOX	Missing	0.00 F	*- F
19	1		*GRIP WITH BALANCER (LH)	Cracked	0.00 F	*- F
20	1		*FUEL TANK LEFT COWLING	Cut	0.00 F	*- F
21	1		*BOX BASE PLATE	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >