

ASS. REC. BY

REF:

CS3/III/9013932/Fcd302

Special Instruction:

Surveyor: Ram

## ASSIGNMENT (Office)

From (Person): Muthu Gabriel Wee

of

III

Date/Time: 8/8/19 @ 9.06am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 288A

Insured:

SHD 3123T

at Workshop m/s

Alpha Car Services

Tel:

6509 8258

of

1 Kaki Bukit Ave 6 # 01-59

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/8/2019

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 3.17pm @ 8/8/19

Person Contacted:

Cai Hing

Vehicle: IN/OUT

Date/Time

Action/Instruction

Estimate X

SJM 288A - X

SHD 3123T-CC4/III/9002890/Jpc13

ADA: 12/2/2019

Dismantle: 14/8/2019. @ 4.30pm

Resurvey: 15/8/2019. @ 5pm. (Dismantle)

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SJM 288A

Yr Regn: sep / 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mercedes benz C200

c.c 1991

Colour white

A/C: Insured / Std / NI / NA

Sp. Reading 71730

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: WD2050422 R185979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/35 R17

R: 275/30 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 06/08/2019

D.O.I. 08/08/2019 0412pm

Survey held at

alpha cars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$8000 - \$9000

Repair days: 6 days

MV \$133000

PV \$73333

NV \$859000

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

120

11

131

Report Format :

PRS

Lump Sum / I.B.I. (\$

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRJ

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) <a href="#">Edit Reg</a>		08 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by adjuster]</b>							
Insured:									
Main Claimant:	ANG KWANG PING, ID: S8002090B								
Vehicle Reg. No.:	SJM288A	Date of Loss:	06/08/2019 13:00 - :59						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHD3123T	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 21/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Thursday, 8 August 2019 9:06 AM  
**To:** PRI Cpaglar; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Sundari Nagarajan - III  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJM288A (Accident involving SJM288A and SHD3123T on 06.08.2019)  
**Attachments:** shd3123t\_20190807143805.pdf; shd3123t\_20190808083147.pdf

Dear Sir / Mdm

**This Pre-Repair Survey is on Without Prejudice Basis.**

THIRD PARTY VEHICLE NO. : SJM288A  
III INSURED VEHICLE NO. : SHD3123T  
DATE OF LOSS : 06.08.19

We acknowledge receipt of your email.

**In compliance to Pre-Action Protocol for NIMA cases, we note that**

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

**\*\*We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

**\*\*Surveyor kindly upload this assignment to Merimen.**

Thank You.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

---

**From:** Motor Claim - III  
**Sent:** 07 August, 2019 2:55 PM  
**To:** 'PRI Cpaglar' <pri@cpaglar.com.sg>  
**Subject:** PRE-REPAIR INSPECTION FOR VEHICLE NO. SJM288A (Accident involving SJM288A and SHD3123T on 06.08.2019)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext – 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

**CPc****C PAGLAR & CO**

ADVOCATES &amp; SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

50 Chin Swee Road  
#05-03 Thong Chai Building  
Singapore 169874  
Telephone: (65) 6536 5456  
Facsimile: (65) 6536 8706  
Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE  
WILL NOT BE ACCEPTED

Your Reference: SHD 3123T  
Our Reference: CP/PRI/SJM288/19.sc (sf)

Date: 7<sup>th</sup> August 2019

To: COMFORT TRANSPORTATION PE LTD  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

CERTIFICATE OF POSTING

Dear Sirs,

NOTICE OF ROAD TRAFFIC ACCIDENT ON ROAD TRAFFIC ACCIDENT ON 6<sup>th</sup> August 2019 INVOLVING MOTOR VEHICLE NO. SJM 288A AND SHD 3123T ALONG NEWTON ROAD TOWARDS ORCHARD ROAD AT ABOUT 1315 HOURS. PURSUANT TO PARAGRAPH 2.2 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by Ang Kwang Ping to notify you of a road traffic on 6<sup>th</sup> August 2019 at about 1315 hours along **Newton Road towards Orchard Road** involving our client's vehicle registration number **SJM 288A** and vehicle registration number **SHD 3123T** driver by you/ your authorized driver, servant and/or agent at the material time. A copy of the Singapore accident statement report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

**PLEASE REPLY BY EMAIL ONLY: pri@cpaglar.com.sg**

**DO NOT REPLY BY FAX.**

Yours faithfully,

**C PAGLAR & CO.**

Enc.

cc. India International Insurance Pte Ltd  
ATTN: MOTOR CLAIMS DEPT


Fax No. 6224 - 4174

cc. [Client by Email: AlphaCarServices@hotmail.com] - (SJM 288A)

**CPc****C PAGLAR & CO**

ADVOCATES &amp; SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275E



50 Chin Swee Road  
#05-03 Thong Chai Building  
Singapore 169874  
Telephone: (65) 6536 5456  
Facsimile: (65) 6836 2195  
Email: pri@cpaglar.com.sg  
SERVICE OF COURT DOCUMENTS BY  
FACSIMILE WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SHD 3123T  
Our Reference: CP/PRI/SJM288/19.sc

Date : 7<sup>th</sup> August 2019

To : INDIA INTERNATIONAL INSURANCE PTE LTD BY FAX: 6224 4174  
ATTN: MOTOR CLAIMS DEPT

Dear Sirs,

- CORRESPONDENCE PURSUANT TO PARAGRAPH 2.4 & 2.6 OF THE PRE-ACTION PROTOCOL FOR NIMA CASES.
- ROAD TRAFFIC ACCIDENT ON 6<sup>TH</sup> AUGUST 2019 INVOLVING MOTOR VEHICLE NO. SJM 288A AND SHD 3123T ALONG NEWTON ROAD TOWARDS ORCHARD ROAD AT ABOUT 1315 HOURS.

We refer to your email dated 7<sup>th</sup> August 2019.

Our client does not agree to your list of surveyors.

We are instructed to propose the use of one of the motor surveyors named in the attached list to conduct the pre-repair survey as a single joint expert.

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors.

**PLEASE REPLY BY EMAIL ONLY: pri@cpaglar.com.sg**

Yours faithfully,

**C PAGLAR & CO.**

Enc.

cc. COMFORT TRANSPORTAION PTE LTD  
383 Sin Ming Drive  
GAS Building  
Singapore 575717

CERTIFICATE OF POSTING

Form 2

## **LIST OF SURVEYORS**

Contact Person	: Mr. Dave Chang
Contact Person	: Mr. Sebastian Lim
Contact Person	: Mr. Alan Cheong
Contact Person	: Mr. Yap Teck Chye
Contact Person	: Mr. Andrew How
Contact Person	: Mr. Marc Ananda
Contact Person	: Mr. Dennis Yap
Contact Person	: Mr. Yap Teck Lee
Contact Person	: Mr. Dixon Yeo
Contact Person	: Mr. T.T. Rajan



&gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	090B
<b>Vehicle Details</b>	
Vehicle No.:	SJM288A
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 A/T ABS D/AIRBAG 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	27492030650781
Chassis No.:	WDD2050422R185974
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,075.00
Original Registration Date:	13 Sep 2016
First Registration Date:	13 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$43,105.00 $\times 50\% = \cancel{\$21,552.50}$ <u>\$21,552.50</u>
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	<u>Yes</u>
PARF Eligibility Expiry Date:	12 Sep 2026
PARF Rebate Amount:	\$32,328.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$41,005.00
<b>Total Rebate Amount:</b>	<b>\$73,333.00</b>

The information contained herein is correct as at 13 Aug 2019

DOA: 06/08/2019

OK

Remaining: 7 years 1 month 6 days (85.2 months)

Depri: \$5700 (yearly) \$1308.33 (monthly)

 $\$85.2 \times \$1308.33 = \$111,469.71$  $\$111,469.71 + \$21,552.50 = \$133,022.21$



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/08/2019 19:36
Date Of Accident	06/08/2019 13:15
Exact Location Of Accident	NEWTON RD TOWARDS ORCHARD RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM288A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANG KWANG PING
NRIC No	S8002090B
Email Address	ALPHACARSERVICES@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97936146
Alternative Phone No	OFFICE-97936146

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C200
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29094337QMY
Cover Note Number	

### Driver

Name of Driver	ANG KWANG PING
NRIC No	S8002090B
Date Of Birth	24/01/1980
Occupation	INDOOR
Date Of Driving Pass	15/04/1999
Driving Experience	20 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97936146
Fax Number	
Contact Number	OFFICE-97936146
Email Address	ALPHACARSERVICES@HOTMAIL.COM

Address	BLK 498 JURONG WEST ST 41 #01-474
Postcode	640498
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3123T
Vehicle Make/Model/Colour	HYUNDAI I40
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN SIAK WAH
NRIC/Passport Number	S6925030J
Contact Number	

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	ANG KWANG PING
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJM288A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 498 JURONG WEST ST 41 #01-474
Postcode	640498

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 6/8/19


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 6/8/19

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

## Sketch Plan #2

### SKETCH PLAN

Newton Road  
towards Orchard Road



Vehicle A - SJM 2588A

Vehicle B - SHC 3103T

Evelyn Road

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

06/08/19 at around 1:00pm My car SJM2588A was  
traveling towards Newton Circus to Orchard Road I was going straight  
on the extreme right lane when suddenly Vehicle BYSH0510ST  
decided to make an illegal U-turn and it was too late for  
my car to stop

### DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's signature

Date & Time

6/8/19

Driver's signature

(If driver is not the policyholder)

Date & Time

6/8/19

Reporting Centre Personnel's signature

Name

WRC/2/25/10

POLICE REPORT Pg. 1



SINGAPORE  
POLICE FORCE



T/20190807/2044

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

2 of 3  
Report No. T/20190807/2044

CONTINUATION OF REPORT

Driver			
Name	Tan Siak Wah	ID No.	S6925030J
Related Vehicle	SHD3123T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ANG KWANG PING	ID No.	S8002090B
Related Vehicle	SJM288A (Car)	Contact No.	97936146
Hospital/Clinic	RAFFLES MEDICAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/08/2019	Date Discharge	06/08/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 06/08/2019 at about 1330hrs, I was driving along Newton Rd towards Newton Circus near Hakka Methodist Church on the first lane of the three lane road. Suddenly, a taxi SHD3123T driving on the third lane turned right into the first and second lane, seemingly attempting to make a U-Turn. I could not stop in time and my car collided with the right side of the taxi. The taxi driver did not seem injured. I felt pain on my back and the neck. My car suffered damages at the front where the bumper and bonnet came off. The taxi suffered damages on the right side doors. Neither traffic police nor ambulance came to scene. I saw a doctor at Raffles Medical and was given three days MC for my back and neck.



POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190807/2044

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

3 of 3

Report No. T/20190807/2044

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /  
SCSGT(1) LAI YUEN SHENG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /  
Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED  
MOHD SAID  
Contact No.: 65476172

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:

07/08/2019 11:56

Classification Of Case:

POLICE REPORT Pg. 1



SINGAPORE  
POLICE FORCE



T/20190807/2044

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

1 of 3  
Report No T/20190807/2044

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/08/2019 11:56		Vide Report No.:		Station Diary No.: 75	
Informant's Particulars					
Name of Informant: ANG KWANG PING			Address: APT BLK 498 JURONG WEST STREET 41 #01-474 SINGAPORE 640498		
ID Type / ID No.: NRIC NO / S8002090B			Contact No.: Home/Office:                      Mobile: 97936146		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 39	Date of Birth: 24/01/1980	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: OUTDOOR SALES			Driving Licence Information: Class:                      Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/08/2019 13:30	Type of Location: Straight Road
Location: Along Road 1 NEWTON ROAD  towards Newton Circus outside Hakka Methodist Church				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHD3123T	Car	HYUNDAI		Blue	Seriously Damaged	0
SJM288A	Car	MERCEDES BENZ		White	Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

# Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
 4 Raffles Quay #12-00 Singapore 048580  
 Tel (65) 6724 0010 Fax (65) 6724 2020  
 Operating Hours: Monday to Friday, 09:00 - 17:00  
 UEN: S66500386 / GST Reg. No. S44881778

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No. M47+191054-5 Vehicle Registration No. 3M-881-9  
 Name (as shown on NRIC) ANJ KWANG PING NRIC/FIN/Passport No. J420090906  
 [\*Vehicle Driver / Vehicle Owner] [\*] Please delete as appropriate  
 Address 612 498 Jurong West Street 4 #01-1474 Singapore (Postcode) 630147  
 Contact (Tel) \_\_\_\_\_ Mobile No. 97436146  
 Email Address Alphamur@msia.org.sg  
 Date of Accident 06/03/2019 Time of Accident 10:15 AM  
 Place of Accident Newton Road towards Orchard Road  
 Insurance Company: MSIA Insurance (Singapore) Pte Ltd

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

1. Police report T/201907/2014 Jurong West A.P.O.
2. Injury 1st time 3 days  
Seri Medikal Raffles Medical (Jurong Point Shopping Centre)
3. Describe Circumstances of the Accident Add On -  
Vehicle B made an illegal U Turn and had turn over forward and bang onto my left hand side first then my right hand side front portion of vehicle

Policyholder / Driver's Signature  
 Date: \_\_\_\_\_

Reporting Centre Personnel's Signature  
 Name: \_\_\_\_\_  
 NRIC/FIN No: \_\_\_\_\_  
 Date: \_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































PRI
















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2019 17:51 <a href="#">Edit Reg</a>		08 Aug 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>ANG KWANG PING</b> , ID: S8002090B								
Vehicle Reg. No.:	<b>SJM288A</b>	Date of Loss:	06/08/2019 13:00 - :59 [34 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>SHD3123T</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Alpha Car Services Pte Ltd (HQ)</b> Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>PARASURAM SHANMUGAM</b> ] ... [Final Rpt due 21/08/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJM288A  
[SHD3123T]  
TP  
ANG KWANG PING  
Aug 6 2019 1:00PM  
[-]  
Alpha Car Services Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
2	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
3	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
22	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
29	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
30	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/08/19 18:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/08/19 09:11	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	19/08/19 09:12	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	19/08/19 09:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 10:53	Singapore Accident Statement IV SHD3123T	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19013932/FCD3E2

Date: 23/08/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJM288A

Insured Vehicle No : SHD3123T

Date of Loss: 06/08/2019

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJM288A

Make &amp; Model: MERCEDES-BENZ C200, 1.8 (A)

Engine No: 27492030650781

Reg. Date: 13/09/2016 (Man. Year: 2016)

Chassis No: WDD2050422R185974

Colour: White

Odometer: 71730 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 245/35 R17

Rear Tyre Size: 275/30 R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 08/08/2019

Date Inspected: 08/08/2019 Inspected At:

Alpha Car Services Pte Ltd (HQ)  
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit  
Autobay  
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2019)
<b>Parts:</b>	143	MERCEDES-BENZ C200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJM288A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >