

Your Ref: DM18HO00801/JT

Date: 05th July 2022

Our Ref: CC6/EQI19013946/Apa3q2

M/s EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBF 3388G
INSURED VEHICLE: GBC 7973G
ACCIDENT DATE: 26/03/2018

We thank you for your instruction on 10/03/2022.

We acknowledge receipt of the following documents:-

- a) Repair Estimate of GBF 3388G from M/s Sin Fatt diesel motor.
- b) Singapore Accident Statement of Vehicles GBF 3388G and GBC 7973G.
- c) Colour damaged vehicle photographs of GBF 3388G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF 3388G
Make & Model	: NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Chassis Number	: JN1SC2F24Z0858884
Year of Registration	: 2016
Engine Capacity	: 2953 cc

- 2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.