

ASS. REC. BY:

REF: CS/CTI 19013962/09632

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Ten Kah Leongof CTIDate/Time: 10.52am 13/8/19

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 492T

Insured:

SJF 441K

at Workshop m/s

Zoom Autowerks

Tel:

9450 7920

of

15 Kelai Bukit Rd 4 #01-53

Policy No:

mpcN 3044561900

Claim No:

SNM19D203709

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:11am 13/8/19

Person Contacted:

ElinVehicle ☒ IN / OUT

Date/Time	Action/Instruction	Estimated
	YN 492T-X	
	SJF 441K - NA / CTI 19013963/24	DOA - 22/07/2019

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

G/A / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31-8-2014 LTA 13341

21/8/19 4/5 @ 5000 contact with Elin. (Red 6/2014.89, 71%)

RECEIVED 23 AUG 2019

Date/Time, File Pass to?

1) 23/8/19

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.R. (\$

MER-TP

5000

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2019		13 Aug 2019 11:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:		REGAL LAMINATION PTE LTD, Co. Reg. No.: 198903727D							
Vehicle Reg. No.:		YN492T	Date of Loss:	07/08/2019 00:00 - :59					
Claim Type:		TP / SNM19D203709-SJF441K-TKL	Policy/Cover Note No.:	DMPCSN3044561900 (Comprehensive)					
Vehicle Reg. No. (Insured):		SJF441K	Policy No. (Claimant):	VCA/P0826189					
			Excess:	S\$1,000.00					
Repairer:		Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 94507920							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/08/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Tuesday, 13 August 2019 10:52 AM
To: Zoom Autowerks; assignments
Subject: RE: OUR REF: SNM19D203709-SJF441K-TKL & YR REF: YN492T - Pre-Repair Inspection for YN 492 T // Accident on 07/08/2019 @ 09:10HR at along Airport Road Entrance to KPE(ECP) involving Vehicle Number YN 492 T & SJF 441 K

WITHOUT PREJUDICE

Dear Elin,

We refer to your email of 10.08.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]
Sent: Saturday, 10 August, 2019 6:22 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D203709-SJF441K-TKL & YR REF: YN492T - Pre-Repair Inspection for YN 492 T // Accident on 07/08/2019 @ 09:10HR at along Airport Road Entrance to KPE(ECP) involving Vehicle Number YN 492 T & SJF 441 K

Dear All,

Kindly arrange Marcus Chua for the survey.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road

#08-1339 Singapore 470130

9450 7920

zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Thu, Aug 8, 2019 at 12:00 PM Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear Elin,

We refer to your email dated 8 August 2019.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards

Tan Kah Leong

Assistant Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, 8 August, 2019 11:32 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; zoomautowerks@gmail.com

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

Subject: OUR REF: SNM19D203709-SJF441K-TKL & YR REF: YN492T - Pre-Repair Inspection for YN 492 T // Accident on 07/08/2019 @ 09:10HR at along Airport Road Entrance to KPE(ECP) involving Vehicle Number YN 492 T & SJF 441 K

Dear Kah Leong,

Please conduct PRS-YN492T soonest possible.

File with Officer In Charge –Tan Kah Leong -DID: 6389 6193

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Thursday, 8 August, 2019 10:54 AM

To: Claims Dept of CTI

Subject: Pre-Repair Inspection for YN 492 T // Accident on 07/08/2019 @ 09:10HR at along Airport Road Entrance to KPE(ECP) involving Vehicle Number YN 492 T & SJF 441 K

Dear Sir/Madam,

We are instructed by Regal Lamination Pte Ltd to notify you of a road traffic accident on 07/08/2019 at about 09:10HR at along Airport Road Entrance to KPE(ECP) involving our client's vehicle registration number YN 492 T and vehicle registration number SJF 441 K driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Das WeltAuto.
Used cars you can trust. Guaranteed.

Visit the sgCarMart Carnival @ Downtown East
for exclusive deals on our certified pre-owned cars!
From 31 Aug to 1 Sep 2019



isuzu npr75

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » KSL Automotive Pte Ltd » Isuzu NPR75U (COE till 05/2024)

Isuzu NPR75U (COE till 05/2024)

Overview

Financial

Accessories

Similar

Research

Photos

Map



KSL Automotive
Your Trusted Partner in Automotive.

Price	\$27,777	Lifespan	25-May-2029
Depreciation ?	\$5,810 /yr	Reg Date	26-May-2009 (4yrs 9mths 11days COE left)
Mileage	N.A.	Manufactured ?	2009
Road Tax ?	N.A.	Transmission	Manual
Dereg Value ?	\$13,308 as of today (change)	OMV ?	\$39,317
COE ?	\$13,910	ARF ?	\$1,966
Engine Cap	5,193 cc	No. of Owners ?	1
Curb Weight ?	2,500 kg		
Type of Vehicle	Truck		

Features

Super Good Condition ISUZU NPR75! Vehicle Fully Repair! Worry Free! Warranty Will Be Given!

Accessories

CD Player, New Paint Works, New Seats, New Tyres.

Description

\$0 Drive Away! No Gimmick! All Must Go! Isuzu Npr75 High Deck Class 3 Driveable, Able To Carry All You Heavy Duty Goods! Free 6 Months VPC High Trade In, Low Interest Rate, Cheap Insurance! Call Our Friendly Sales Person For Viewing Now! Door Step Viewing Available!

Category

COE Car, Premium Ad Car

Compare



Shortlist

Com

Report Error

M

Seller Information

Company	KSL » dea » 29
Address	2A Ki Searc
Office No	6266

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	727D
Vehicle Details	
Vehicle No.:	YN492T
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	4HK1742776
Chassis No.:	JAANPR75H97101824
Maximum Power Output:	-
Open Market Value:	\$38,534.00
Original Registration Date:	18 Jun 2009
First Registration Date:	18 Jun 2009
Transfer Count:	0
Actual ARF Paid:	\$1,927.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$13,910.00
COE Rebate Amount:	\$13,341.00
Total Rebate Amount:	\$13,341.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 14 Aug 2019

OK

MALP19104132 / Alpine Motors Pte Ltd - HQ
 ENTRY DATE & TIME: 08/08/2019 12:27
 SUBMITTED BY: Mohd Suhaimi Bin Mohd Suadi Ong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2019 12:27
Date Of Accident	07/08/2019 09:10
Exact Location Of Accident	AIRPORT RD ENTRANCE TO KPE(ECP)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN492T
Insured/Policyholder	
Name Of Registered Owner	REGAL LAMINATION PTE LTD
Co Reg No	198903727D
Email Address	INFO@REGALLAMINATION.COM
Mobile Phone No	
Alternative Phone No	Office-96710335

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR75UH5A
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P0826189
Cover Note Number	

Driver

Name of Driver	LIU WEI
Passport No/FIN	G8232309R
Date Of Birth	10/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	24/07/2018

Driving Experience	1 YEAR AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96710335
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	71 DEFU LANE 12, SINGAPORE 539152
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : LIM CHENG HENG Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF441K
-----------------------------	---------

Vehicle Make/Model/Colour

CHEVROLET / AVEO 1.4L AT

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *L. S. Lim*
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Vehicle A: YN492T

Vehicle B: SJF441K

Airport Road entrance to KPE (KCP)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle 'A', YN492T, was travelling straight along the stated venue. Front vehicle braked and I braked as well. Suddenly, vehicle 'B', SJF441K, came and hit into my stationary vehicle's rear portion. I am an employee of Regal Lamination Pte Ltd and I was driving the vehicle for work purpose.

my passenger: Lim Cheng Heng
NRIC: S7639827E

email: info@regallamination.com

DECLARATION

I/We declare the foregoing particulars are true in every respect



Policyholder's Signature
Date & Time:

Lin Wei

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lim
NRIC/HIN No:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

13-Aug-19

REG NO.: YN 492 T
MAKE/MODEL: ISUZU LORRY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY DESCRIPTION AMT(S\$)

SPECIAL NETT ITEMS

1	Rear tailgate "25 PAX" sticker	\$ 11	25.00	a
1	Rear tailgate "60KM/H" sticker	\$ 11	25.00	a
1	Rear company sticker (1 set)	\$ 11	300.00	a
2	Rear taillamps	\$ cre	963.26	
2	Rear taillamp panels	\$ 25	721.90	x
1	Rear step panel - Wooden	\$ cre	850.00	350 s.w
1	Rear number plate	\$ Bent	50.00	145 s.w
1	Rear number plate bracket	\$ Bent	120.65	
1	Rear number plate lamp	\$ Daye	89.45	
2	Rear chassis member side brackets	\$ Bent	768.00	500 s.w
1	Rear centre chassis crossmember	\$ Dis	641.63	600 s.w
1	Rear wooden tailgate	\$ 11	1,800.00	x
1	Rear wooden lower member	\$ cre	1,500.00	900 s.w
2	Rear wooden chassis planks	\$ cre	3,600.00	2200 s.w
		\$	11,454.89	

S/N LABOUR CHARGES

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring.	\$	80.00	20
2	Panel beating.	\$	2,500.00	480
3	To re-spray painting on the affected areas.	\$	2,200.00	250
4	To straighten rear chassis frame member and re-align chassis frame.	\$	850.00	400
		\$	5,630.00	

GRAND TOTAL :

\$ 17,084.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

PAGE 1 OF 1

p- 6601
152
p- 561.08
s.w 4564.00
106w- 1150.00
6275.08

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013962/UQF3N2

Date: 27/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3044561900
Claimant Vehicle No :	YN492T	Insured Vehicle No :	SJF441K
Date of Loss:	07/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203709-SJF441K-TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN492T	Engine No:	4HK1742776
Make & Model:	ISUZU NPR75UH5A, 5.2 D (M)	Chassis No:	JAANPR75H97101824
Reg. Date:	18/06/2009 (Man. Year: 2009)	Odometer:	222804 km
Colour:	Blue		
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17.5	Rear Tyre Size:	215/55R17.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,454.89	5,125.08	6,329.81	55.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,630.00	1,150.00	4,480.00	79.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,084.89	6,275.08	10,809.81	63.27
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	17,084.89	5,000.00	12,084.89	70.73

INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	13/08/2019 Inspected At:	Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Aug 2019)	
Parts:	N/A	ISUZU NPR75UH5A 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN492T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE 25PAX STICKER	Not Necessary	25.00 F	*- FL
2	1		*REAR TAILGATE 60KM/H STICKER	Not Necessary	25.00 F	*- FL
3	1		*SET REAR COMPANY STICKER	Not Necessary	300.00 F	*- FL
4	2		*REAR TAILLAMPS	Cracked	963.26 F	*450.00 FL
5	2		*REAR TAILLAMP PANELS	No such part	721.90 F	*- FL
6	1		*REAR NUMBER PLATE BRACKET	Bent	120.65 F	*120.65 FL
7	1		*REAR NUMBER PLATE LAMP	Damaged	89.45 F	*89.45 FL
8	1		*REAR WOODEN TAILGATE	Not Necessary	1,800.00 F	*- FL
9	1		*REAR STEP PANEL-WOODEN	Cracked	850.00 FS	*350.00 FS
10	1		*REAR NUMBER PLATE	Bent	50.00 FS	*14.00 FS
11	2		*REAR SAFETY BAR BRACKETS	Bent	768.00 FS	*500.00 FS
12	1		*REAR SAFETY BAR	Distorted	641.63 FS	*600.00 FS
13	1		*REAR WOODEN LOWER MEMBER	Cracked	1,500.00 FS	*900.00 FS
14	2		*REAR WOODEN CHASSIS PLANKS	Cracked	3,600.00 FS	*2,200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	11,454.89	5,224.10
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	99.02
Total Parts (\$\$)	11,454.89	5,125.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	20.00
2	PANEL BEATING	New	2,500.00	480.00
3	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,200.00	250.00
4	TO STRAIGHTEN REAR CHASSIS FRAME MEMBER AND RE-ALIGN CHASSIS FRAME,LIFT UP CARGO DECK	New	850.00	400.00
Gross Labour Cost (\$\$)			5,630.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >