


12/15/2018
 ASS. REC. BY: _____ REF: C1/TAD19013965/P2 Special Instruction: _____
 Surveyor: _____ **ASSIGNMENT (Office)** Date/Time: 22/8/2019
 From (Person): Kamiliah Kamle of SPF Bill to: _____
 Estimated Cost: _____ Insured: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No.: GZ.3294.D Tel: _____
 At Workshop m/s _____
 of _____
 Policy No: MHASPF06000023265/1 Claim No: TP/IP/H7433/2019
 Sum Insured: _____ Excess: _____
 Make of Vch: _____ D.O.A. 1/8/2019
 (Client's Record)
 CA / REV / REP. / REV 24 HRS
 Date/Time: _____ Person Contacted: _____ H.O.D. Endorsement: _____
 Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>GZ.3294.D-X</u>


 500/19

ES9
 NOK

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Thursday, 22 August, 2019 9:52 AM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Tiak Yee PHUA (SPF)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 9 vehicles below:

a) Case IAFP-IB-20190820 - Mechanical Inspection of Police Hilux, GZ3294D (TP/IP/47933/2019)

On 1 August 2019 (Thursday) sometime before 4.05 pm, the Police Hilux, GZ3294D, was travelling on left of 2 lanes and negotiating a right bend. After the right bend, driver applied her brakes and discover it was not working. Driver was unable to stop in time and collided into a stationary taxi causing it to surged forward and collided onto a stationary motor car ahead. The driver then claimed mechanical fault to the FRV. She informed the vehicle was fine while attending to a case but heard a "Gear Box Rattling Sound " coming from the engine. She did not report the matter to her Transport in charge hence she proceeded to the next case and the RTA occurred. Due to the RTA, rear passenger, Female /77 Years Old /Malay, of the taxi sustained a back pain, conveyed to CGH by ambulance a. She was treated as outpatient with 4 days of medical leave.

Vehicles to be inspected: GZ3294D - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

b) Case IAFP-IB-20190820 - Mechanical Inspection of Motor Taxi, SHC7245D (TP/IP/23457/2019)

On 7 April 2019 (Sunday) at or about 12.02 a.m., the Deceased who was walking alone in an unsteady manner and was hailing a taxi from the pavement along Sentosa Gateway. The Deceased then took a step forward when he tripped and fell off the pavement. The Deceased landed on the road, lying in between lanes 3 and lane 4 of the 4-lanes road. The Accused's motor taxi was travelling on lane 3 when he ran over the Deceased. After collision, the Accused stopped by the side of the road and alighted from his motor taxi. However, he left the scene shortly after without reporting the accident. Due to the collision, the Deceased was pronounced dead at the scene by AB121, Paramedic SGT Ken at 12.11 a.m.

Vehicles to be inspected: SHC7245D - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

c) Case IAFP-IB-20190820 - Mechanical Inspection of Motor Van, GBB4314J (TP/IP/46503/2019)

On the 27 July 2019 (Saturday) sometime around 5.09 p.m., the motor van was driving inside multi-story car park on single lane on-way road (up slope) in which he claimed that the steering wheel of his motor van was not functioning. The driver was unable to steer right of his motor van and the motor van automatically swerve to the left. The said motor van then side-swiped onto the side wall on the left side.

Vehicles to be inspected: GBB4314J - Driver (Potential Defendant)

IO In-Charge: IO Phua Tiak Yee