

ASS. REC. BY:

REF: CS3 / SMO / 1013967 / Ac-f 30K

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): AGUS Chan stu lui

of SMO

Date/Time: 13.8.19 11:11 a.m

Estimated Cost:

Bill to:

OD ~~(TP)~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PA 5121G

Insured:

SKB 2878E

at Workshop m/s YSK Auto workshop

Tel:

96402541

of NO 1 Kaki Bukit Ave 6 #01-71

Policy No: D19MTPV01006454

Claim No:

CNT12 1903753

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.8.2019

14.8.19 11:19 a.m

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 13.8.19 11:23 a.m

Person Contacted:

Danny

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: NO 1 Kaki Bukit Ave 6 #01-49
	PA 5121 G - NA1 INC 19013697 / 24 DOA - 05/08/2019
	SKB 2878E - NA1 INC 19013697 / 24 DOA - 05/03/2019
5/08 @ 12:01pm	sent menmen pending estimate from repairer.
	Adrian say not claiming already, even. Sompo claim also will reject. No estimate.

ASSIGNMENT

From: _____ Date: 14/8/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PA 5121G

at Workshop m/s YSK Auto

of 1 Kaki Bukit Ave 6 # 01-68

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{rup}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PA 5121G Yr Regn: 2005 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mini Bus

Make: Nissan Urvan C.C 2953

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 327059 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1TG4E2S 20701970

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bessway.

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 14/08/19

Survey held at YSK.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Sampo.
	Dismantle: 14/8/2019
	After repair: 16/8/2019.
	MV:
	PV: 3K
	Nett:
	COE Expiry: 12/01/20
	Pending COE Renewal.
	Repair Range: 4K-5K.
	07 Days.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format: PR2.

Lump Sum / L.B.R. (\$)

100

60

60

11

231

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Aug 2019		13 Aug 2019 11:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS <div style="float: right;">[Created by insurer]</div>									
Insured:	CHOW JIAHUI RACHEL, ID: S9134176Z, Tel: +6583636167, Email: rachel.jiahui@gmail.com								
Main Claimant:	CHAN TRANSPORT SERVICE, Co. Reg. No.: 50498900J								
Vehicle Reg. No.:	PA5121G	Date of Loss:	05/08/2019 13:00 - :59						
Claim Type:	TP / CMTD1903753	Policy/Cover Note No.:	D19MTPV01006454 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKB2878E	Policy No. (Claimant):							
		Excess:							
Repairer:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-71 Autobay, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/08/2019]								
Driver/Custodian (Insured):	CHOW JIAHUI RACHEL (27 / Female), NRIC: S9134176Z, Tel: +6583636167 Email: rachel.jiahui@gmail.com								
Adj Asg. Remarks:	WS: DANNY 96402541/ 1 Kaki Bukit Avenue 6, #01-68 Autobay								
ASSOCIATED MAIL RECEIVED <div style="float: right;"> View All Compose Case Mail </div>									
There are no mail for this case.									
<div> </div> ALL ASSOCIATED TASKS <div style="float: right;"> View All Search Tasks Create New Task Complete </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***PA5121G (CMTD1903753)**
[SKB2878E]

TP
CHAN TRANSPORT SERVICE
Aug 5 2019 1:00PM
[CHOW JIAHUI RACHEL]
Ysk Auto Workshop

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **15/08/2019 12:01 PM.**
To agnes.chan@sompo.com.sg
Subject **PA5121G (CMTD1903753) [SKB2878E] TP**

Dear Sir/Madam,

Please be informed that we have inspected the vehicle PA 5121G on 14/08/2019
We are pending estimate from repairer.

Regards,
Denise
LKK Auto

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	900J
Vehicle Details	
Vehicle No.:	PA5121G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	URVAN 3.0 M
Primary Colour:	White
Manufacturing Year:	2004
Engine No.:	ZD30045451
Chassis No.:	JN1TG4E25Z0701970
Maximum Power Output:	-
Open Market Value:	\$23,735.00
Original Registration Date:	13 Jan 2005
First Registration Date:	13 Jan 2005
Transfer Count:	1
Actual ARF Paid:	\$1,187.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$29,933.00
COE Rebate Amount:	\$2,978.00
Total Rebate Amount:	\$2,978.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 14 Aug 2019

OK

Don't miss this offer from



McDelivery
24 hours/7 days

► **SEARCH**

► Used Car Comparison

--- Comparing 3 Vehicles ---

Nissan Urvan (COE till 03/2024)

Nissan Urvan (COE till 07/2023)

Nissan Urvan (COE till 04/2024)



Clear All

Use search bar above to see to compare.

[Back to search result](#)

CAR DETAILS

Price	\$32,800	\$23,800	\$28,800	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	14-May-2004	04-Jul-2008	14-Apr-2009	-
Manufactured	2004	2008	2008	-
Mileage	66,900 km	-	112,000 km	-
Transmission	Manual	Manual	Auto	-
Engine Cap	2,389 cc	2,953 cc	2,953 cc	-
Road Tax	-	-	-	-
Power	-	-	-	-
Curb Weight	1,500 kg	2,000 kg	2,000 kg	-
Features	-	-	-	-
Accessories	-	-	11 Seater Van! New Cushion! Like New Condition!	-
Description	Super Low Mileage, Super Rare Urvan Mini-Bus! Very Well Kept Condition As Ex-Owner Is A Semi-Retiree! Now Looking To Sell This Well Kept Beauty! Call Us Now! Loan Can Be Easily Arranged!	Good Condition Mini Bus. Well Maintained, Ferry Up To 9 Passenger, Wide And Spacious. Call Now To View!	11 Seater PA Bus. Low Downpayment Available! Low Mileage, Hardly Used By Previous Owner As Its A Spare Vehicles. Excellent Condition With Almost New Looking Seats. Call To View Now Before It Is Too Late. In House Loan Available.	-
COE	\$50,316	\$16,100	\$13,380	-
OMV	\$22,786	\$26,721	\$37,517	-
ARF	\$1,140	\$1,337	\$1,876	-
Depreciation	\$7,080 /yr	\$6,120 /yr	\$6,170 /yr	-
No. of Owners	1	2	2	-
Type of Vehicle	Bus	Bus	Bus	-
Category	COE Car, Premium Ad Car, Low Mileage Car	COE Car	COE Car	-
Availability	Available	Available	Available	-
Remarks	Fuel type Petrol COE expiry date 2024-04-13	Fuel type Diesel COE expiry date 2024-04-13	Fuel type Diesel COE expiry date 2024-04-13	-

SELLER INFORMATION

Seller	ABWIN Bus Pte Ltd	MK Vehicle Enterprise	Hui Hua Credit Pte Ltd	-
--------	-------------------	-----------------------	------------------------	---

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/08/2019 16:39
Date Of Accident	05/08/2019 13:55
Exact Location Of Accident	TELOK KURAU RD ROUNDABOUT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PA5121G
Insured/Policyholder	
Name Of Registered Owner	CHAN TRANSPORT SERVICE
Co Reg No	50498900J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96618718
Alternative Phone No	OFFICE-96618718
Vehicle Particulars	
Manufacturer	NISSAN
Model	URVAN 3.0 M
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5070144147-04
Cover Note Number	
Driver	
Name of Driver	HENG THEE KUN
NRIC No	S1211799Z
Date Of Birth	19/09/1955
Occupation	OUTDOOR
Date Of Driving Pass	20/04/2012
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96221738
Fax Number	
Contact Number	OFFICE-96221738
EMail Address	NOEMAIL

Address	BLK 511 SERANGOON NORTH AVENUE 4 #04-324
Postcode	550511
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - ROUNDABOUT
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. SUDDENLY VEHICLE B CUT ONTO MY LANE FROM MY RIGHT SIDE. AS A RESULT, VEHICLE B HIT ONTO MY VEHICLE FRONT RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB2878E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHOW JIAHUI, RACHEL
NRIC/Passport Number	S9134176Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Statement 1.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Aug 2019		13 Aug 2019 11:11 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case



































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHOW JIAHUI RACHEL , ID: S9134176Z, Tel: +6583636167, Email: rachel.jiahui@gmail.com									
Main Claimant: CHAN TRANSPORT SERVICE , Co. Reg. No.: 50498900J									
Vehicle Reg. No.:	PA5121G	Date of Loss:	05/08/2019 13:00 - :59 [174 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1903753	Policy/Cover Note No.:	D19MTPV01006454 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKB2878E	Policy No. (Claimant):							
		Excess:							
Repairer: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-71 Autobay, 417883 Kaki Bukit - Tel:									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 22/08/2019]									
Driver/Custodian (Insured):	CHOW JIAHUI RACHEL (27 / Female) , NRIC: S9134176Z, Tel: +6583636167 Email: rachel.jiahui@gmail.com								
Adj Asg. Remarks:	WS: DANNY 96402541/ 1 Kaki Bukit Avenue 6, #01-68 Autobay								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents








*PA5121G (CMTD1903753)
[SKB2878E]
TP
CHAN TRANSPORT SERVICE
Aug 5 2019 1:00PM
[CHOW JIAHUI RACHEL]
Ysk Auto Workshop

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	13/08/19 11:09	Accident Statement From: SC - Reg. No: SKB2878E, Claimant: CHOW JIAHUI RACHEL	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	27/08/19 11:14	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
34	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
35	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
36	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
37	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
38	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
39	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
40	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
41	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
42	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
43	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
44	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
45	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
46	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
47	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
48	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
49	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
50	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
51	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
52	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
53	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
54	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
55	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
56	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
57	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
58	27/08/19 11:14	General View		Load JPG <input checked="" type="checkbox"/>
59	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
60	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
61	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
62	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
63	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
64	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
65	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
66	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
67	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
68	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
69	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
70	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
71	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
72	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
73	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
74	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
75	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
76	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
77	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
78	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
79	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
80	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
81	27/08/19 11:14	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
82	27/08/19 11:17	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
83	27/08/19 11:17	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
84	27/08/19 11:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	27/08/19 11:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	27/08/19 11:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	27/08/19 11:17	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	13/08/19 10:03	Pre-Repair Survey	 Load PDF	
2	13/08/19 10:21	Third Party E-filed GIA report(M) - PA5121G	 Load PDF	
3	13/08/19 11:13	Pre-Repair Survey - AGREED LKK/MARCUS	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19013967/ACF3E2

Date: 30/08/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTPV01006454

Claimant Vehicle No : PA5121G Insured Vehicle No : SKB2878E

Date of Loss: 05/08/2019 Nature of Claim: TP Claim No: CMTD1903753

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PA5121G
 Make & Model: NISSAN URVAN, 3.0 D (M) Engine No: ZD30045451
 Reg. Date: 13/01/2005 (Man. Year: 2004) Chassis No: JN1TG4E25Z0701970
 Colour: White Odometer: 327059 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Bearway 6 mm Rear Left Side: Bearway 6 mm
 Front Right Side: Bearway 6 mm Rear Right Side: Bearway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 14/08/2019 Inspected At:

No 1 Kaki Bukit Ave 6 #01-49

Repairer : Ysk Auto Workshop (HQ)

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Aug 2019)

Parts: N/A NISSAN URVAN 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PA5121G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >